

Building 47 RFP Questions

Submitted May 2, 2019

	Question/Comment	Answer
1.	For a proposer to estimate the cost of mitigating the high levels of arsenic and heavy metals in the sump (basement of the pool building), it would be helpful to know the source of the contamination.	Please see the Sump Room report previously posted on the RFP website under Haz Mat Reports.
2.	Is the sump collecting groundwater runoff?	No. There is a small drain at the bottom of stairs at the entrance to the basement. There is also a roof drain tied to it.
3.	There is pipe coming out a window that appears to direct water to a storm drain. Can you elaborate?	SPR is aware of a hose coming out of this window. The hose is connected a small sump pump that is used if the put pumps fail.