


DRB RECOMMENDATION MEETING September 01, 2010

STOCK&ASSOCIATES
architecture . interiors




**1165 EAST LAKE AVENUE
DESIGN REVIEW BOARD
SECTION 1: SITE & CONTEXT**



Project Location

South Lake Union Urban Boundary


Aerial Site Map




Zoning Map / High Water Line




Context Surroundings



West Elevation
Current figure-ground of site



West Elevation
Proposed figure-ground of site



ZymoGenetics




ZymoGenetics / Steam Plant



Hydro House




Gunn Building - Retained



Office Building




Silver Cloud Inn




1144 Building


Site Conditions




Site Opportunities



Shoreline Datum



Zoning Overlays



IC-45

urban maritime

C2-40
urban stable

C2-65
urban stable


site

C2-65

STOCK&ASSOCIATES
architecture . interiors

**1165 EASTLAKE AVENUE
DESIGN BOARD
SECTION 2: ORIGINAL MASSING**


East Eastlake Avenue Elevation



Eastlake Streetscape




View of Eastlake Entry




Section at restaurant

sections




Cross Section through site




STOCK&ASSOCIATES
architecture.interiors

卷之三

West Fairview Avenue Elevation





Elevation South



Silver Cloud stairs at Eastlake



Silver Cloud stairs existing



Silver Cloud stairs at Fairview



Silver Cloud stairs existing



Green Roof

1165 EASTLAKE AVENUE DESIGN REVIEW BOARD


SECTION 3: EDG, SLU, CODE, & DRB FEEDBACK

EDG

Recommendation

Early Design Guidance Board Recommendations		Design Review Guidelines	EDG Recommendation from Board	Response from Architect Revised Massing
A Site Planning				
A-1 Responding to Site Characteristics	The siting of buildings should respond to specific site conditions and opportunities.	The Board requested a design solution preserving a public pedestrian route between the two streets; either internally or by enhancing the existing stair on the Silver Cloud property to the south.		The revised plans would provide an improved, much wider stair linking Eastlake and Fairview through a publicly accessible plaza.
A-2 Streetscape Compatibility	The siting of the buildings should acknowledge and reinforce the existing desirable spatial characteristics of the right-of-way.	The Board suggested the exploration of street level design options to provide protection and visual interest and encourage human activity at the sidewalk.		The main building entry has been sited off the plaza; a retail space is located on the Eastlake front of the plaza, with windows onto both the street and the plaza. The loading dock is relocated in the revised plans to the Fairview level which will provide a better pedestrian experience on Eastlake. There is a canopy along Eastlake which extends from the plaza along the new building and ties into the Gunn facade. At Fairview the stair has been widened and landscaped. The garage entry utilizes the existing curb cut. A restaurant is located along the Fairview facade at the plaza level as a view overlook which will provide eyes on the street.
A-4 Human Activity	New development should be sited and designed to encourage human activity on the street	The Board suggested site development to encourage human activity on the street.		The primary pedestrian traffic at the site is along Eastlake Avenue. The main entry has been sited on Eastlake level. The Owner is giving up the existing area way under the Eastlake sidewalk in order to provide more street trees. Canopies will provide rain protection and will have wood soffits and downlights. The retail and restaurant spaces, as well as the plaza and stair, should promote pedestrian activity.
A-5 Respect for Adjacent sites	Buildings should respect adjacent properties by being located on their site to minimize disruption of the privacy and outdoor activities of residents in adjacent buildings.	The Board was concerned with the proximity to the Silver Cloud Inn and the privacy between the two buildings.		The building has been pulled back from the property line approximately 70 feet and the resulting plaza is landscaped for visual interest. The plaza will be accessible to the public and the restaurant and retail uses will be easily accessed by Silver Cloud guests from either Eastlake or Fairview.
C Architectural Elements and Materials				
C-1 Architectural Context	New buildings proposed for existing neighborhoods with a well-defined and desirable character should be compatible with or complement the architectural pattern and siting pattern of neighboring buildings.	The Board requested the team study the neighboring buildings and the Gunn building and provide a building character compatible with the existing forms.		The neighborhood's newer buildings are typically composed in brick and glass; the revised massing similarly features brick, glass, and metal panels. The existing Gunn building will be stripped back to its concrete frame and will also have brick panels.
C-2 Architectural Concept and Consistency	Building design elements, details and massing should create a well-proportioned and unified building form and exhibit an overall architectural concept.	The Board asked for high quality finish materials.		Finish materials include brick, concrete, metal panel, glass, and ipe wood.
D Pedestrian Environment	Buildings should exhibit form and features identifying the functions within the building.	Architecture to present a strong concept.		The building form ties the Gunn building and new construction together but still expresses the Gunn. The massing is pulled in at the restaurant and retail space to accent them.
D-2 Blank Walls	In general, the roofline or top of the structure should be clearly distinguished from its facade walls.	Show a consistency of facades and materials		A unified material palette is used to tie the existing Gunn building together with the new construction. The roof line is capped by a cantilevered slab.
D-7 Personal Safety and Security	The building should avoid large blank walls facing the street, especially near sidewalks. Where blank walls are unavoidable, they should receive design treatment to increase pedestrian comfort and interest.	The Board requested that the wall along the Silver Cloud Inn be designed with public safety in mind and noted it should not be a blank wall.		The building has been pulled back from the property line approximately 70 feet and the resulting plaza is landscaped for visual interest. The plaza will be accessible to the public and the restaurant and retail uses will be easily accessed by Silver Cloud guests from either Eastlake or Fairview.
E Landscaping	Project design should consider opportunities for enhancing personal safety and security in the environment under review.	The Board suggested that the Silver Cloud stair and the area under the bridge should incorporate design solutions that enhance personal safety and security.		The area at the stair has been widened significantly. Good lighting will be provided and the restaurant and retail space will provide "eyes" on the space. The area under the bridge will be cleaned and rocks added to stabilize the lake edge, as permitted by SDOT.
E-3 Landscape Design to Address Special Site Conditions	The landscape design should take advantage of special on-site conditions such as high-bank front yards, steep slopes, view corridors, or existing significant trees and off-site conditions such as greenbelts, ravines, natural areas, and boulevards.			The revised massing places the roof top garden at the Eastlake level where it will be accessible to the public. The landscape features native plants, basalt boulders and low walls for seating. There is a cantilevered overlook for views of the lake and Space Needle. The restaurant also has an outdoor seating area with lake views.

SLU Guidelines



Design Guidelines – City wide South Lake Union supplemental

A. Site Planning

A-1 Responding to Site characteristics

The siting of buildings should respond to site specific conditions
Storm water run-off, detention and filtration systems
Sustainable landscaping

Currently run-off flows directly into the lake, the project will collect it
properly. The landscaping will be primarily native plants.

A-2 Streetscape compatibility

Siting should acknowledge and reinforce existing characteristics of the right away.
Provide pedestrian friendly amenities
Encourage street level spaces that vary in size, width and depth
Place retail where it will be conducive to use
Configure retail so that it can spill out to the sidewalk
Pedestrian amenities such as canopies, tree grates, lighting, bike racks and benches will be provided along Eastlake Avenue. The plaza and stair will provide an interesting exterior space. The retail space has been located at the corner of the plaza on Eastlake Avenue so that it can utilize outdoor space on two sides. The restaurant has an outdoor seating area.

A-3 Entrances visible from the Street

Entries should be clearly identifiable and visible from the street.
The main entry is off the landscaped plaza and accessible from both Eastlake and Fairview via the enhanced stair.

A-4 Human Activity

New development should be sited and designed to encourage human activity on the street.
Create graceful transitions from public to private spaces
Design facades to encourage activity to spill out from the building
Reinforce pedestrian connections
Design for safe, well-lit connections to link high activity areas
The entry has been located off the plaza to provide a transition space between the sidewalk and the building lobby.
The retail space has windows onto the street and the plaza and it has a covered exterior area. The restaurant has an outdoor seating area on the plaza.

The sidewalk along Eastlake will be enhanced with canopies, planters and lighting. The stair between Eastlake and Fairview will be substantially widened and landscaped.

A-5 Respect for adjacent sites

Buildings should respect adjacent properties by being located to minimize disruption of the privacy and outdoor activity of residents of adjacent buildings. The revised massing has been pulled back from the south property line and an approximately 70 foot wide plaza created to provide a greater level of privacy for the adjacent hotel rooms.

B. Height, Bulk and Scale

B-1 Height, Bulk and Scale compatibility

Projects should be compatible with the scale of development anticipated by Land

transition to nearby, less intensive zones.

Address both pedestrian and auto experience with building placement scale and detail

Articulate the facade vertically or horizontally in intervals that relate to the existing structures in the vicinity.

Consider using architectural features to reduce building scale

The revised massing integrates well with the overall scale and texture of the neighborhood. The height variance will allow the addition of the plaza in order to reduce the overall scale compared to the original proposal. The plaza overlook not only provides views from above but creates a canopy to denote the parking entry off Fairview.

C. Architectural Elements and Materials

C-1 Architectural Context

New buildings proposed for an existing neighborhood with a well defined character should be compatible with or complement the architectural character and styling patterns of neighboring buildings.

Reuse and preserve important buildings where possible
Respond to history and character in the adjacent vicinity in terms of patterns, style and scale

Respond to working class, maritime, commercial and industrial character in the waterfront area

The existing Gunn Building will be renovated. The Gunn will be integrated into the new construction through the use of materials in common. The building will be composed of brick, glass and metal panel as is characteristic of the other biotech building in the area. The revised massing is more in scale with the buildings along Eastlake and Fairview.

C-2 Architectural concept and consistency

Building elements, details and massing should create a well proportioned and unified building form and exhibit an overall architectural concept. Buildings should exhibit form and features identifying the functions within the building.

Design the roofscape in addition to the streetscape

The roof edge is designed as a cantilevered slab to provide some sun shading as well as visual interest. The roof top mechanical equipment will be enclosed or screened from view.

C-4 Exterior finish materials

Exterior should be constructed of durable and maintainable materials that are attractive even when viewed up close. Materials that have texture, pattern or lend themselves to a high quality of detailing are encouraged. Materials will include brick, glass, metal panel, concrete, with ipe wood, concrete pavers and walls and basalt boulders at the plaza space for both Fairview and Eastlake.

D. Pedestrian Environment

D-1 Pedestrian open spaces and entrances


Convenient and attractive access to the building entry should be provided; paths and entry areas should be well lit and entry areas should be protected from the weather. Opportunities for creating lively pedestrian oriented open space should be considered.
The proposed plaza will provide a much needed landscaped open space for both Fairview and Eastlake.

D-2 Blank walls

Buildings should avoid large blank walls facing the street especially near sidewalks. Where blank walls are unavoidable, they should be designed to reduce their impact on pedestrian comfort and interest.
There are no blank walls in the revised massing. The openings at the parking ramp along Fairview will have decorative screening to provide interest.

D-4 Design of parking lots near sidewalks

Parking lots near sidewalks should provide adequate security and lighting, avoid encroachment of vehicles on the sidewalk and minimize visual clutter.
Parking below grade is preferred
Parking is below grade, sloping down from the Fairview level.



D-6 Screening of dumpsters, utilities and service areas

Buildings should locate service elements such as dumpsters, loading docks and mechanical equipment away from the street front where possible.

Dumpsters will be located in a closed loading dock. Loading dock has opaque doors to screen it from the street. Most mechanical equipment is located at the rooftop and integrated into the architecture.

D-7 Personal safety and security

Project should consider opportunities for enhancing personal safety and security.

Enhance public safety

The area at the stair has been substantially widened. The restaurant and retail spaces will provide "eyes" on the plaza and street. The area under the bridge is under discussion with SDOT regarding better access control.

E. Landscaping

E-1 Reinforce existing landscape character of neighborhood

Where there is not an overriding concern, landscaping should reinforce the character of neighboring properties and abutting streetscape.

E-2 Encourage landscaping that meets LEED criteria

Where appropriate install indigenous trees and plants
Most plantings will be native plants. The landscape will be part of the LEED strategy for the building. The planter beds and street trees will reinforce the plantings at nearby properties.

E-3 Landscape design to address special site conditions

The landscape design should take advantage of special on-site conditions such as high-bank front yards, steep slopes, view corridors or existing significant trees and off site conditions such as greenbelts, ravines, natural areas, and boulevards.

E-4 Landscaping should be designed to take advantage of views to waterfront and downtown.

The plaza will provide with a Shoreline Height Variance will provide the public and occupants with excellent views of Lake Union and the Space Needle.

Code Checklist

Land Use Code Review		Required	Provided	Departure Requested	Page #
Code Section					
SMC 23.47A.004 Permitted Use	Zone is C-2:55.	Permitted	Uses cited are anticipated; Project is shell and core only.		
SMC 23.47A.005 Street Level Use	Eastlake Avenue East is NOT located in a pedestrian designated zone at this location	Permitted, limited to FAR or 35,000 unless it meets 2.54 FAR/35,000			
Use - Offices - C-8		Permitted			
Use - Restaurant - C-2:b		Permitted			
Use - Retail - C-10:a					
SNC 23.47A.008 Street Level Development Standards	Project does not have residential units and there are no adjacent residential units, therefore the provisions are only applicable as related to 23.47A.010 below.				
SNC 23.47A.010 Maximum size of non-residential use	Blank facades; Blank facades shall not exceed 20 feet in width and the total of all segments shall not exceed 40% of the width of the facade along the street.		Street front elevations comply		
SNC 23.47A.011 Outdoor Activities	Transparency: 60% of the street facing facades shall be transparent, with 2 feet and 3 feet above the sidewalk and allow unobstructed views from the outside into the structure.		Both the Eastlake and Fairview facades have the required percentage of openings. The Eastlake facades are glassed, at Fairview the openings are unglazed but have the building standard mullion pattern with perforated metal first at 6' on center perpendicular to the street to provide a view into the building while screening the parking ramp.		
SNC 23.47A.012 Structure Height	Access to Parking per 23.47A.032		Parking is located within the building along Fairview and is not separated from the street-facing facade, although the building is separated from the sidewalk bridge structure by another street-facing facade. By another permitted use.		
SNC 23.47A.013 Maximum size of non-residential use			Request confirmation that office uses by R&D have not yet been identified. Project meets the requirements of 23.47A.032 within a structure street level parking shall be regarded from street level, street-facing facade, by another permitted use.		
SNC 23.47A.014 Floor Area Ratio	Office Use is limited to (1) FAR or 35,000 sq ft, whichever is greater unless the following standards of 23.47A.008 are met.		Tenants have not yet moved in. The building are accessory to the lab use and permitted to exceed the size limits of this section.		
SNC 23.47A.015 Floor Area Ratio			There are no outdoor activities planned for the site.		
SNC 23.47A.016 View Corridors			Structure is partially in the shoreline therefore height is governed by 23.50, see below.		
SNC 23.47A.017A.015 Setback Requirements	FAR is 4.25 in the 65' zone. All parking is below grade.		The project is below FAR limit.		
SNC 23.47A.017A.016 Landscaping and screening standards	Project is not adjacent to a residential zone.		Project is on South Lake Union therefore 15% of gross floor area may be reduced or mechanical equipment.		
SNC 23.47A.017A.017 Green Factor score of .30 required	No view corridors are required on the site.		Green Factor score is .37		


SMC 23.47A.033 Transportation concurrency level of service	The Eastlake planting strip is over 5' away or over 50% of its length. Street trees are required; if not feasible, landscaping other than trees may be provided in the planting strip if approved by SDOT.	Raised planter beds will be provided on the Eastlake and additional trees will be planted in the proposed southern planter to add trees to the site.	Per 23.52.	
SMC 23.51.004 Requirement to meet transportation concurrency levels of service standards	Demonstrate that forecasted traffic will not cause LOS issues as applicable screeners.	Per submitted Traffic Study, there are no LOS issues.		
SMC 23.51.015 Improvement requirements for existing streets in residential and commercial zones		Street improvements may be required.	This is under discussion with SDOT, SDOT #36491.	
SMC 23.51.035 Structural Building Overhangs		Vertical clearance shall be 8' above the sidewalk.	Canopies along Eastlake Avenue extend 1' feet from the building and are 4' above the sidewalk. (height varies with the slope of the street).	
		Projections such as balconies that do not increase the space enclosed by the building may have a maximum horizontal projection of 3 feet at the roof level.	As part of the public amenity proposed in the request for a shoreline variance we would like to extend the balcony to 5 feet deep, 10' x 35' feet deep to provide greater views of the lake and space for shade.	
SMC 23.51.045 Required Parking		No parking for motor vehicles is required for uses in commercial zones in urban centers.	The balcony proposed at the Fairview overlook is 5' feet deep.	
		Per Chart E and based on projected 50 stalls of bike parking are provided in the parking garage.	Project includes 82 stalls of parking.	
SMC 23.51.055 Loading Berth Requirements	A. The rental of spaces must be at least 10' above sidewalk grade.	Two berths are required.	Per Chart A, two berths are provided.	
		No Major Odor Sources are banned.	Berths are 10 feet wide x 35' feet long.	
SMC 23.51.608 Permitted Uses on upland lots in the US Environment		Per Chart E and based on projected 50 stalls of bike parking are provided.	Per Chart E and based on projected 50 stalls of bike parking are provided.	
SMC 23.51.632 Height in the US Environment		Permitting of parking garages must be shielded and directed away from adjacent uses.	Permitting of parking garages must be shielded and directed away from adjacent uses.	
		Exterior lighting must be shielded and directed away from adjacent uses.	Exterior lighting must be shielded and directed away from adjacent uses.	
SMC 23.60.632 Height in the US Environment		Parking along the Fairview frontage is on a ramp that slopes slowly from street level and has a solid wall 1' 5" above the parking surface, and lights will be shielded.	Parking along the Fairview frontage is on a ramp that slopes slowly from street level and has a solid wall 1' 5" above the parking surface, and lights will be shielded.	
		Interior lights in parking garages must be shielded and parking areas must be screened to at least 5' feet or the elevation of the parking area is different from the elevation at the lot line to 3 feet.	Interior lights in parking garages must be shielded and parking areas must be screened to at least 5' feet or the elevation of the parking area is different from the elevation at the lot line to 3 feet.	
SMC 23.61.632 Height in the US Environment		No reflective coated glazing or highly reflective materials will be utilized. Structure is approximately 43' feet high at Eastlake and approximately 61' feet at Fairview.	No reflective coated glazing or highly reflective materials will be utilized. Structure is approximately 43' feet high at Eastlake and approximately 61' feet at Fairview.	
SMC 23.62.632 Height in the US Environment		Glare diagram is required for structures using reflective coated glass or for new or expanded structures over 65' feet when their facade is over 30% clear or tinted glazing and is oriented toward a major arterial.	Glare diagram is required for structures using reflective coated glass or for new or expanded structures over 65' feet when their facade is over 30% clear or tinted glazing and is oriented toward a major arterial.	
SMC 23.63.632 Height in the US Environment		Height from average elevation (shoreline datumline) is approximately 57' feet to top of mechanical penthouse.	Height from average elevation (shoreline datumline) is approximately 57' feet to top of mechanical penthouse.	
SMC 23.64.632 Height in the US Environment		Per request for a shoreline variance proposed height exceeds the shoreline limit.	Per request for a shoreline variance proposed height exceeds the shoreline limit.	
SMC 23.65.632 Height in the US Environment		Per the request for the Shoreline Variance, the area of 10' has been reduced therefore the combined height of rooftop features is increased to 15'. Roof top features have been restricted to the new construction only so that the total roof height is 65'. If it is allowed by the lower Gann nor may provide a view to the lake if any future construction across Eastlake, it still is well under the 65' limit.	Per the request for the Shoreline Variance, the area of 10' has been reduced therefore the combined height of rooftop features is increased to 15'. Roof top features have been restricted to the new construction only so that the total roof height is 65'. If it is allowed by the lower Gann nor may provide a view to the lake if any future construction across Eastlake, it still is well under the 65' limit.	
SMC 23.66.632 Height in the US Environment		The following rooftop features may extend up to 15' feet above the maximum roof height so long as the roof area if the total includes mechanical equipment.	The following rooftop features may extend up to 15' feet above the maximum roof height so long as the roof area if the total includes mechanical equipment.	
SMC 23.67.632 Height in the US Environment		Parapels comply with this.	Parapels comply with this.	
SMC 23.68.632 Height in the US Environment		Roof coverage is approximately 40% for these elements. Height of all rooftop features is limited to 15'. Roof top features have been restricted to the new construction only so that the total roof height is 65'. If it is allowed by the lower Gann nor may provide a view to the lake if any future construction across Eastlake.	Roof coverage is approximately 40% for these elements. Height of all rooftop features is limited to 15'. Roof top features have been restricted to the new construction only so that the total roof height is 65'. If it is allowed by the lower Gann nor may provide a view to the lake if any future construction across Eastlake.	
SMC 23.69.632 Height in the US Environment		Structures are permitted to occupy 100% of an upland lot.	Structures covers 100% of the lot.	
SMC 23.70.632 Height		Height shall be calculated per this section.	Calculations provided.	
SMC 23.80.606 Structure Height		When any portion of a structure falls within the shoreline district the height of the structure was calculated thusly.	When any portion of a structure falls within the shoreline district the height of the structure was calculated thusly.	

DRB Comments

Design Review Board Recommendation Meeting July 2, 2008	Response - Original Massing Proposal	Response - Revised Massing Proposal
Will the building skin of the existing Gunn building be stripped?	The existing skin may be stripped back to the concrete structure and skin coated or clad. There would be a joint or reveal in the envelope separating existing building from new construction.	The concrete frame of the Gunn would be stripped of the existing stucco, to the Fairview elevation. There is an overall continuity to the elevation. The Eastlake elevation on the street level retains a similar structural pattern along the facade but is broken up with the loading dock, retail and the building's recessed entry.
Design continuity: Did you want the existing Gunn building to read separate from the new construction?		
Loading Dock: Why is the dimension of the driveway so wide?	Stock & Associates, Inc. had several meetings and conversations with DPD and SDOT concerning the loading dock configuration. Given the narrow width of the site, internal truck maneuvering was not possible. PPD therefore granted back in, exit forward maneuvering for the dock, provided a flagger is present and hours are restricted to avoid conflict with the bus layover zone. With this configuration and code minimum of two loading berths required, the proposed loading dock driveway with an intermediate maneuvering area is the least dimension possible to achieve truck maneuvering.	The revised massing possible with a Shoreline Height Variance would allow the loading dock to be entered off Fairview using the existing curb cut. Eastlake Avenue would not require any curb cut under this proposal.
Why doesn't the restaurant facade along Eastlake have the same raised planter beds as the remainder of the facade?		Discontinuing the planter bed at the restaurant allows for sidewalk/caf� seating along Eastlake. The street facades of the restaurant are intended to be glazed panel folding door systems that open up the restaurant interior or to the seating area along the Eastlake sidewalk.
Green roof: Will this be a traditional green roof with the ability to handle storm water retention?		Yes. The main green roof on the third level will be composed of planters with depths up to 18 inches and be designed to handle storm water retention.
Security: The depth of the street of Fairview entrance is a security concern. Further security measures, such as a gate, are encouraged.		The EDG board requested that Stuck & Associates, Inc. look into recessing the building entrances off Fairview and Eastlake. Lighting choices should also be made with security in mind, to keep the space well lit.
Wall System: What is the wall system at the tower?		Currently, a curtain wall system will be used at the latter, east and west facades and portion of the north facade. Aluminum storefront will be used at the north facade projections and at the Gunn Building.
Retail: What is planned for retail use?		At this time, a particular tenant is unknown. The intent is to enrich the street life along Eastlake with a restaurant and retail space. The property owner is pursuing talks with potential tenants.
Perspective at Stairs: Why is core projection not shown?		The rendering was completed prior to very recent plan changes shifting the core projection east to further open up the view corridor for the Silver Cloud hotel rooms at the hotel's north facade.
LEED: Where are points being generated within the checklist? Are you using photovoltaic panels?		The green roof, and native plants are one area for points. Photovoltaic panels were value engineered out of the project for budgetary reasons. Many of the points are deriving from energy categories. Others are reuse of the Gunn Building, job site recycling of waste, low VOC products, local products, etc. Fish habitat under the bridge seems to also be a possible source for points.
Is there an agreement with the Silver Cloud for maintenance of the existing stairway?		The property owner is in conversation with the Silver Cloud owners on this topic. The plans currently show all landscaping within the property lines for this project and it would therefore be maintained by the property owner and not the Silver Cloud.


With potential low light levels, are you concerned with the landscape's viability?	The landscape architects for this project have allocated native understory plants that require low light levels at this location. Their experience with these plants at a separate, very similar location has been successful. Although the section is narrow, limited direct sunlight will reach the space in the afternoon hours.	No longer applicable; the wider plaza provides plenty of sun.
Security concern for pedestrians.	With security in mind, lighting at the stair level and overhead will be provided along the path from Eastlake to Fairview to insure the area is well lit. By making use of the option for 25% of the facade to be glazed, windows have been located in areas like the elevator lobby and stairs to allow for "eyes" to be on the travel path to increase safety.	The plaza is much more open than the original stair. The retail space, restaurant, building lobby and hotel rooms all face onto the plaza which should provide plenty of "eyes" on the travel path.
What is the dimension of stairs and distance from the Silver Cloud north elevation?		The revised stair is 14 feet at the Fairview level and 9 1/2 feet at the plaza level. The plaza's width varies from 6'7 to 7'4 feet wide.
Restroom core projection: What is the purpose of pushing the restrooms out past the face of the rest of the south facade?		Given the shoreline height restrictions on the site, the width of the tower is restricted. The maximum allowable shape dictated by the Fairview and zoning restrictions leaves the floor plate narrow at Eastlake, wider at Eastlake with structural columns further dividing up the narrow plan. Given the programmed use for the building being research and development labs, a rectilinear floor plate is the most desirable shape. By pushing out core elements like the restrooms, the floor plate is freed up to allow for more functional lab layouts.
Façade modulation: The façade modulation on the north side of the tower is an interesting portion of the south facade. Why does the modulation only occur on this facade?		The revised massing provides modulation on the street facades. There was an opportunity at this facade to literally follow the curved shoreline boundary for that north wall or modulate the elevation, creating cube-like projections that push out to meet that boundary line. To increase view opportunities on each floor and take advantage of a given zoning restriction, we chose to modulate the elevation and let this portion of the tower be unique to the adjacent elevations.
Roof Landscaping: What will be planted on the roof?		The main green roof on level three will be primarily a medicinal herb garden with raised planters and approximately 18 inch soil depths. The higher roofs will be planted with a modular, shallow pan system of lightweight soil and drought tolerant vegetation, such as sedums.
Lab locations: On which floor of the taller section will the lab space start, in relationship to the restroom projection?		Labs will start on level 03.
Requested Departures:	Rationale	No longer applicable; taller section is eliminated in the revised massing.
Original Massing: One development standard departure was requested: allow mechanical penthouse at the building edge along Eastlake Ave E.	This allows the street facade to be more in scale with the development along the street.	No longer applicable; planting have been moved to the plaza level.
Departure was supported by the Board		
Recommended conditions:		The restroom core projection at the south facade (at the stairway next to the Silver Cloud), will need to be eliminated on levels 01 and 02, but can remain on levels 03, 04, 05 and 06.
		The recessed Fairview entrance will require further security. A security gate was suggested. The Eastlake entrance was seen as more active and would not require further security considerations.
		The corner of the building on the Eastlake facade near the stairway passageway will need to be carved back at the ground level to ease the pedestrian transition to and from the stairwell. The change of form would be from the ground level to the first lab floor.

Elevation West




Fairview Avenue

Plan 01




Elevation East




Eastlake Avenue


Plan B1



Elevation South & North




South View




North View

Section South to North




West to East Section




Top of Mechanical & Elevator Shaft	15'-0"	Roof Level: 10'-10"
Top of Parapet	42'	Top of Slab: 86'-10"
Top of Gunn		
03 Level	72'-10"	
02 Level	56'-10"	
01 Courtyard	+/- 44'-5"	
B1 Level	29'-0"	
B2 Level	20'-4"	
B3 Level	8'-0"	
		Base Slab

Plan 02, 03

Gunn Building:
Office / Lab Space





02: Office / Lab Space



03: Office / Lab Space

Plan B2, B3




B3: Lab Space


Eastlake



Landscape Plants





Fairview



Fairview Stair




Plaza




Landscape Plaza Material Detail




Ipe Wood




Basalt Stone Seating



Wood Bench



Concrete Pavers



Stepped Planters



Vine Maple Trees



Birch Trees