
NCH at Pike Market

Neighborcare Health Exterior Improvements



Virgina St Through Time





NCH at Pike Market

Neighborcare Health Exterior Improvements

ARCHITECT

Miller Hayashi Architects PLLC 118 N 35th Street, Suite 200 Seattle, WA 98103 t: 206 634 0177

CLIENT

Neighborcare Health 6200 13th Ave S. Seattle, WA 98108

SITE ADDRESS

1930 Post Alley Seattle, WA 98101

PROPERTY OWNER


Pike Place Market PDA 85 Pike Street, #500 Seattle, WA 98101

SCOPE OF WORK:

- 1st & 2nd Floor Door Replacment
- Replace 1st (003A)& 2nd floor(212B) exterior door with new hollow metal doors and hardware.
- Exterior Stairwell Security Improvement
- Provide enclosure over entire stairwell with gate for security control and safety.

Table of Contents


Site Map	1
Scope of work	2
Site Observation of Exterior Stairwell	3
Code Observation	
Code Analysis	
Stairwell Enclosure Design Proposal	
Proposed Color Samples	12
Site Observation of Exit 212B Door.	
Design Proposal of Exit 212B Door	14
Site Observation of Exit 003A Door.	
Design Proposal of Exit 003A Door	16




SCOPE OF WORK AT VIRGINIA STREET




VIRGINIA ST - WEST ELEVATION



SITE OBSERVATION







SITE OBSERVATION:

LEVEL 2 DOOR 212B EXITS INTO BELOW GRADE STAIRWELL. ADJACENT TO VIRGINIA STREET RIGHT OF WAY, HANDRAIL AND **GUARD RAIL APPEAR IN DECENT** CONDITION.

BASEMENT EXIT CONCEALED BY STAIR RETAINING WALL WHICH MAKE IT SUBJECT TO VANDALISIM DUE TO CONCEALED CONDITION, AND A SAFETY ISSUE FOR STAFF **EXITING THIS DOOR**

PROPOSED SOLUTION:

PROVIDE PAINTED METAL **ENCLOSURE AND EGRESS ONLY** GATE FOR STAIRWELL TO IMPROVE SECURITY AND SAFETY. REPLACE DOOR 212B WITH HOLLOW METAL FOR DURABILITY.

RECOMMEND CLEANING DEBRIS FROM SURFACE DRAIN.

CODE OBSERVATION - GUIDELINE 3.4.1


GUIDELINE AS WRITTEN:

SECURITY DOORS, GATES AND COVERS ARE DISCOURAGED. WHERE PERMITTED, THEY SHALL BE FINISHED AND UNOBTRUSIVE. THEY SHOULD MAINTAIN VISIBILITY THROUGH STALL SPACES, REMAIN BETWEEN COLUMNS AND WINDOWS, BE RELATIVELY INCONSPICUOUS DURING THE DAY AND BE FULLY RETRACTABLE.


RESPONSE TO GUIDELINE:

PROPOSED DOOR AND STAIRWELL ENCLOSURE SCOPE ADDRESSES ONGOING SECURITY INCIDENTS AT NEIGHBORCARE'S PIKE MARKET HEALTH. DOOR 212B IS AT THE BOTTOM OF AN OPEN NARROW STAIRWELL. SURVEILLANCE FROM THE PUBLIC IS OBSCURED BY THIS, WHICH POSES A SECURITY RISK TO THE BUILDING AND IT'S STAFF. THE PROPOSED GATE, AND STAIRWELL ENCLOSURE WILL BE PAINTED AND DESIGNED TO MATCH EXISTING WINDOW GUARDS AND GATES PREVALENT ALONG POST ALLEY ON NEIGHBORING BUILDING FACADES AND ACCESS POINTS (REFER TO ATTACHED PHOTOS ON PAGE 03). PROPOSED GATE TO BE INSTALLED IN ALIGNMENT WITH THE EXISTING RECESS SO AS TO NOT OBSTRUCT OR PROTRUDE FURTHER INTO THE EXISTING SIDEWALK RIGHT-OF-WAY. THE STAIRWELL ENCLOSURE WILL BE DESIGNED TO MAINTAIN THE EXISTING SIDEWALK WIDTH CLEARANCE CURRENTLY IN PLACE AND MINIMIZE SIGHTLINE IMPEDENCES TO NEIGHBORING STRUCTURES AND BUSINESS.

CODE ANALYSIS



STAIRWELL ENCLOSURE DESIGN PROPOSAL



SITE OBSERVATION:

THERE IS A STAIRWELL ALONG VIRGINIA STREET IN THE NORTHWEST CORNER OF THE BUILDING, CONNECTING TO DOOR 212B, PARTIALLY BELOW GRADE

PROPOSED SOLUTION:


ADD ORNAMENTAL STAIRWELL ENCLOSURE FOR SECURITY AND SAFETY. PROPOSED ENCLOSURE TO ALIGN NEAR THE BOTTOM OF EXISTING CAFE WINDOW TO AVOID VIEW OBSTRUCTION, AND EXTEND TO 7'6" ABOVE GRADE AT STAIRWELL GATE.

SEE FOLLOWING PAGES FOR DESIGN PROPOSAL.


STAIRWELL ENCLOSURE DESIGN PROPOSAL



STAIRWELL ENCLOSURE DESIGN PROPOSAL 3D VIEW LOOKING EASTTOWARD THE CORNER OF 1ST & VIRGINIA STREET




STAIRWELL ENCLOSURE DESIGN PROPOSAL 3D VIEW LOOKING WEST TOWARD THE CORNER OF 1ST & VIRGINIA STREET




PRECEDENT AT PIKE PLACE MARKET PHOTO TAKEN FROM POST ALLEY **FACING NORTHWEST**

STAIRWELL ENCLOSURE DESIGN PROPOSAL - ENCLOSURE




STAIRWELL ENCLOSURE DESIGN PROPOSAL - ELEVATIONS




EAST ELEVATION SCALE 1/2"=1'-0"

NORTH ELEVATION SCALE 1/2"=1'-0" WEST ELEVATION SCALE 1/2"=1'-0"

STAIRWELL ENCLOSURE DESIGN PROPOSAL - GATE



STAIRWELL ENCLOSURE DESIGN PROPOSAL - ATTACHEMENT



ENLARGED SECTION SCALE 1/4"=1'-0"

Proposed Color Samples

ORNAMENTAL IRON



RUST-RESISTANT TAMPER RESISTANT DRIVE **ANCHORS**



RUST RESISTANT MATTE BLACK PAINT



SITE OBSERVATIONS - EXIT 212B DOOR







SITE OBSERVATION:


EXISTING LITE AT EXTERIOR DOOR IS SHATTERED AND TEMPORARILY SECURED WITH PLYWOOD. ADJACENT LITES APPEAR NOT DAMAGED. EXISTING DOOR SWINGS OUT, WITH CLOSER INTO STAIRWELL.

PROPOSED SOLUTION:


REPLACE DOOR AND HARDWARE, PAINT TO MATCH EXISTING FINISH.

Correction #3

DOOR DESIGN PROPOSAL - EXIT 212B DOOR



SITE OBSERVATIONS - EXIT 003A DOOR








SITE OBSERVATION:

EXISTING EXTERIOR DOOR IS CHIPPED AND FLAKING OF EXISTING PAINT AND MARKINGS OF GRAFFITI **REMAIN WHERE UNABLE TO** REMOVE.


PROPOSED SOLUTION:

REPLACE DOOR AND HARDWARE. PAINT TO MATCH EXISTING FINISH.

DOOR DESIGN PROPOSAL - EXIT 003A DOOR



ENLARGED FLOOR PLAN SCALE 1/2"=1'-0"



ENLARGED EXTERIOR ELEVATION SCALE 1/2"=1'-0"