





EXISTING CONDITIONS AT ROOF DECK LEVEL




EXISTING CONDITIONS AT ROOF DECK LEVEL



(ABOVE) ENLARGED
PLAN

(RIGHT) SCOPE OF WORK
PLAN



FIRST AVE

WINDOWS BEYOND VIEW




ALASKAN WAY

EXISTING CONDITIONS AT STREET LEVEL (CANNOT SEE SCOPE FROM STREET)



WINDOW BEYOND VIEW

FIRST AVE
STREET VIEW



VIEW FROM FARTHER SOUTH ON
ALASKAN WAY

ONLY FIRST
WINDOW IS IN VIEW



PROPOSED WINDOW REPLACEMENT DESIGN




RENDERING OF TALLER OPENING WITH NEW DOOR AND PAVER PLATFORM




EXISTING
LIGHTING, PROVIDE
(2) NEW TO MATCH
AT NEW PATHWAY

NEW PATHWAY TO HAVE
PAVERS TO MATCH EXISTING,
AND BLACK METAL (SIMILAR
TO EXISTING PLANTERS)
WHERE NEEDED




EXISTING LIGHTING,
PROVIDE (2) NEW TO
MATCH AT NEW
PATHWAY



Brick Masonry Wall Opening

5201
5

SEE DETAIL 5/S-3.0 FROM STRUCTURAL DRAWINGS FOR NEW STEEL LINTEL



5202
10

SEE DETAIL 10/S-3.0 FROM STRUCTURAL DRAWINGS FOR NEW STEEL LINTEL