



Morrison Hotel

SXS

Side x Side Architects
510 Maynard Ave S
Seattle, WA 98104



1908 - original construction for Arctic Club & Seward Hotel

1973 - 1979 – Seattle Housing Authority alterations:

- create offices on level 2

- added floor-to-wall ties with rosettes

- converted level 2 to a shelter

1984 – renovations of level 3-7 apartments

2002 – DESC renovation of 3-7 apartments, major seismic upgrade, and addition of major fire and life safety features.



Morrison Hotel

D.E.S.C. - Vision

- DESC helps people with the complex needs of homelessness, substance use disorders, and serious mental illness achieve their highest potential for health and well-being through comprehensive services, treatment, and housing.
- The infrastructure DESC is building is the infrastructure the community should have built decades ago.
- Over the last century, the Morrison Hotel's role evolved from hotel to SRO housing, and, today, permanent supportive housing.
- This project reflects DESC's willingness to build and maintain these services for the traditionally unserved and do it for the for the long-term.



Morrison Hotel

Rehabilitation — Overview

- Built in 1908, The Morrison has not undergone a major renovation since 2002.
- Project will make critical building upgrades, improve residents' quality of life, and increase energy efficiency.
 - Maintain an important historic resource.
 - Renovations to residential floors incl. replacement of unit finishes and adding wall insulation.
 - Upgrades to mechanical and plumbing systems.
 - Gas-fired mechanical systems will be replaced with electric systems.
 - Window replacement.
 - Additional seismic improvements to remove the building from City's Unreinforced Masonry list.
 - Minimize resident displacement by employing a 20-month 15-phase construction schedule.

Morrison Hotel

Exterior Scope Overview

Rooftop Mechanical

Existing ventilation risers will be connected to new ducts run exposed on the roof to three new ERVs. New domestic hot water heat pumps will also be installed on the roof.

Replacement of Sheet Metal

- Replace deteriorated sheet metal cap at upper water table



Masonry/Stucco Restoration

- Selective cleaning & repointing per spec. to preserve distinctive features


Window Replacement

- Replace deteriorated wood windows at levels 3-7 at all elevations.



Morrison Hotel

Window Scope




Morrison Hotel

Certificate of Approval Application, Window Survey

4. INSPECT ALL AREAS & REPORT DEFECTIVE MORTAR JOINTS. POWER TOOLS PERMITTED - TAKE ALL PRECAUTIONS NECESSARY TO PREVENT ANY DAMAGE TO MASONRY & TERRAZZO. USE TYPE "M" MORTAR & MATCH COLOR OF ADJACENT EXISTING MORTAR TO REMAIN.

4. PATCH ANY MODERATELY DECAYED WOOD SILL, FRAME & SAND SMOOTH, REPAIR LOOSE OR OVERCAULDED RAILS WITH NEW SCHELS. WHERE PIECES ARE DECAYED BEYOND REPAIR, REPLACE WITH NEW PIECES MATCHING ORIGINAL PROFILE.

5. REPLACE INTERIOR HARDWARE WHERE MISSING.



EXISTING DECORATIVE METAL CATWALK TO REPAIR. REPLACE IN KIND ANY DETERIORATED MEMBERS. SCRAPE, PREP ALL LOOSE PAINT DOWN TO SOUND SUBSTRATE & REPAIR - TYPICAL.

EXISTING FLOOR TO WALL TIES - TYPICAL - SEE STRUCTURAL.

EXISTING WOOD WINDOWS WITH INSULATED GLAZING - TYPICAL 3RD THROUGH 7TH FLOORS.

TYPICAL @ ALL EXISTING WINDOW / FRAMES (ALL FLOORS) & ALL ELEVATIONS SCRAPE LOOSE PAINT DOWN TO SOUND SUBSTRATE & REPAIR. REPLACE ALL BROKEN GLAZING.

EXISTING DECORATIVE SHEET METAL. REPLACE IN KIND ANY DETERIORATED MEMBERS. TYPICAL.

EXISTING SECOND FLOOR WINDOWS TO REMAIN. TYPICAL.

EXISTING TRANSOMS TO REMAIN. TYPICAL.


SEE ENLARGED STOREFRONT ELEVATIONS - SHEETS A-4.5, A-4.6 & A-4.7 TYPICAL.

Summary:

The survey team attempt to look at every window on levels 3 through 7. However, The Morrison Hotel presents several obstacles to completing a full window survey. Some residents find it challenging to trust people inside their units and the survey team was denied entry to many units. Also, because of some residents' possessions and the difficulty in relocating them, some windows were not accessible.

Good:	6	Total surveyed:	372	171 on primary elevation windows (3rd Ave and Jefferson)
Fair:	108	# of windows:	490	215 on primary elevation windows (3rd Ave and Jefferson)
Poor:	258	% Surveyed:	76%	80 % on primary elevation windows (3rd Ave and Jefferson)



X01.1 - Not Surveyed
X01.1 - Surveilled
X01.1* - Surveilled, photo missing or unclear




SEE PLANS FOR
OF PROPOSED AND
ING USES.

RENT

IUE







MORRISON HOTEL REHABILITATION

PSPB MEETING
TECHNICAL DETAILS
11/04/26

Pella® Reserve™

Traditional Wood & Clad/Wood



Exquisitely designed windows and doors with unparalleled historical detailing.

Double-Hung Interior



Double-Hung Exterior






15 PEOPLE MOVE OUT

PHASING

15 SHORT DURATION PHASES,
1.5 MONTHS EACH,
20 MONTHS OVERALL, TO
AVOID DISPLACEMENT





15 PEOPLE
MOVE BACK IN



15 PEOPLE
MOVE OUT



15 PEOPLE
MOVE BACK IN



15 PEOPLE
MOVE OUT



15 PEOPLE
MOVE OUT




15 PEOPLE
MOVE BACK IN



INSTALL FROM INSIDE IN- NO
SCAFFOLDING/SWING STAGE-
AVOID EXTERIOR WINDOW SEAL
AFTER WINDOW IS SET IN PLACE

MULTIPLE SHORT
DURATIONS FOR
INSTALLATION





SUBFRAME INSTALLATION SYSTEM


Allows for inside installation

Allows for rapid multiple phases

Safer installation- window seal to exterior is a pressure bulb vs leaning out the window to seal, or multiple phased swingstages.








PRIMARY AND SECONDARY FACADES

PRIMARY FACADES



EXISTING AND REPLACEMENT WINDOWS



VARIANCE IN REPLACEMENT
WINDOW SASH LOCATION

NEW TRIM TO MATCH
EXISTING PROFILE

NEW WINDOW FRAME


SUBFRAME
ATTACHMENT SYSTEM

1 3/8"

1 7/8"
SASH

1 5/8"
FRAME
5 7/8"

2 3/8"
BRICK
MOLD




NOTE: FRAME DIMENSION SHOWN IS
TYPICAL, BUT CAN VARY 1/4" +/- AT
SPECIFIC LOCATIONS DUE TO EXISTING
BUILDING TOLERANCES. OTHER
DEPENDENT DIMENSIONS MAY ALSO VARY
ACCORDINGLY AT SPECIFIC LOCATIONS

1 3/4"
SASH

3/4"
4 1/2"

2"
BRICK
MOLD




REMOVE PORTION OF
FRAME BACK TO WEIGHT
POCKET


EXISTING BRICK MOLD TO
REMAIN (TO BE COVERED BY
NEW EXTRUSION

SASH POCKET


REMOVE MIDDLE STOP

TRANSOMS





ELEVATIONS



RENDERING FOR REFERENCE ONLY




2 PROPOSED WINDOW EXTERIOR ELEVATION
SCALE: 1/8" = 1'-0"

1 EXISTING WINDOW EXTERIOR ELEVATION
SCALE: 1/8" = 1'-0"



PHOTOGRAPH OF EXISTING STREETCARTS INCORP

ELEVATIONS




2 PROPOSED WINDOW EXTERIOR ELEVATION
SCALE: 1/16" = 1'-0"

1 EXISTING WINDOW EXTERIOR ELEVATION
SCALE: 1/16" = 1'-0"





SECONDARY FACADES: COURTYARD and ALLEY








WATER TABLE



CUSTOM COLOR MATCH TO EXISTING PAINT


MASONRY REPAIR






ROOFTOP

REPLACE 3 ROOFTOP GAS
UNITS WITH HIGH EFFICIENCY
ERV'S AND CONNECT TO
BATHROOM EXHAUST FANS



GREENHECK RVE 85 and 40
H: 72.5/52.5 (6' + CURB)
W: 68.2/52.5
L: 150/165





MORRISON HOTEL REHABILITATION

PSPB MEETING
TECHNICAL DETAILS
11/04/26