## EROSION AND GEOLOGIC HAZARDS AT PROJECT FACILITIES AND TRANSMISSION LINE RIGHT-OF-WAY STUDY INTERIM REPORT

## ATTACHMENT E

## **SUMMARY TABLE AND MAPBOOK**

Table E-1. Sites grouped into Special Concern Zones based on proximity of City Light facilities to mapped mass wasting features.

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
	MW-1	Ross Dam Right Abutment	Rockfall	0	900	1, 1a	Unknown age of movement	Less than 100 ft from multiple rockfall features with fresh surfaces
am	MW-2	Ross Dam Powerhouse	Rockfall	300	887	1, 1a	2014?	Periodic rockfall in vicinity of Ross Powerhouse, noted in Golder Associates (2014), near rockfall 887
Ross Dam	MW-3	Ross Dam Haul Rd, Towers B90/48N B91/8N	Rockfall	0	887	1, 1a	2010	Rockfall reported in Landslide Tech FAR 06-19-13 and Landslide Tech (2011); within rockfall 887
	MW-4	Ross Dam Powerhouse	Debris flow fan	300	3203	1, 1a	Unknown age of movement	Two debris flow fans mapped within 300 ft W of powerhouse; although opposite side of river could be sources of large boulders and rock blocks
Arm Bridge	MW-5	SR 20 Bridge over Thunder Arm	Landslide-rock flow	350	3403	1a	Unknown age of movement	N approach of bridge within 350 ft of 3403 rock flow with freshened surfaces
Thunder Arm E	MW-6	SR 20 and Colonial Cr. Rec Area/Campground, S end of Thunder Arm bridge	Debris Flow	0	3201	1a	2017	WSDOT USMS reported 2017 debris flow, rubble on road; 3201 debris flow fan extends SE across recreation area
	MW-7	Diablo Dam Rd, North Cascades Learning Ctr, docks, tourist facilities	Rockfall, debris flow/flood fans	0	3207	1, 2a	Unknown age of movement	Multiple facilities within footprints of 3212, 3210, 3207 debris flow/flood fans and 879 rockfall; mapped features show fresh surfaces
Downstream	MW-8	Diablo Dam Rd, North Cascades Learning Ctr, docks, tourist facilities	Rockfall, debris flow fans	0	879	1, 2a	Unknown age of movement	Multiple facilities within or near footprints of 3212, 3210, 3207 debris flow fans and 879 and 880 rockfall; mapped features show fresh surfaces
am and Down	MW-9	Diablo Dam Rd, North Cascades Learning Ctr, docks, tourist facilities	Rockfall, debris flow fans	0	879	1, 2a	Unknown age of movement	Multiple facilities within 879 rockfall; mapped features show fresh surfaces
Upstre	MW-10	SR 20 and Left abutment of Diablo Dam	Rockfall	0	944	1, 2a	1992?	WSDOT USMS note recent rockfall, wedge and planar failures, mitigated by scaling
Diablo Dam,	MW-11	Diablo Dam right abutment, tower B87/46N	Rockfall	0	878	1a, 2, 2a	1996?	Mapped rockfall area reported in Raytheon Constructors Inc. (1996), mapped talus deposits (878) have freshened surfaces
	MW-12	Diablo Intake, Diablo dam right abutment	Rockfall	0	1002	1a, 2, 2a	Unknown age of movement	facilities within footprints of rockfall 1002 and 878 with freshened surfaces
	MW-13	Diablo Powerhouse	Rockfall	250	873	1a, 2, 2a	2021	Rockfall reported 10/2021 (City Light) and 2007 (Landslide Tech, 2007); near rockfall 873 and 870, freshened surfaces
	MW-14	Diablo Powerhouse, tower B87/23N	Rockfall	200	873	1a, 2, 2a	1999?	Rockfall reported in Shannon & Wilson Inc. (1999), near rockfall 873

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
	MW-15	Town of Diablo facilities, Diablo Road	Rockfall	100	874	1a, 2, 2a	2021? or earlier	City Light reported slope 'between tennis court and Davis powerhouse' has periodic rockfall, near rockfall 874
Downstream	MW-16	Town of Diablo (including homes), Diablo and Stetattle Cr. Rd	Debris flow	0	3218	1a, 2, 2a	Unknown age of movement	Town footprint within debris flow 3218 and 3215; town downstream of multiple debris chutes in Stetattle Cr. channel
Upstream and	MW-17	Tower D86/32N, SR 20 Bridge over Skagit R downstream of Diablo Dam	Debris Flow, rockfall	0	3195	1a, 2, 2a	Unknown age of movement	Tower below 820 rockfall; east approach of Gorge Lake bridge crosses 3195 debris flow fan
Dam,	MW-18	Diablo Road	Debris flow, rockfall	0	3219	1a, 2, 2a	Unknown age of movement	Approx. 4000 ft section of Diablo R, crosses rockfall 998, 999, 866 and debris flow fans 3220, 3221, 3219
Diablo	MW-19	Tower B86/12N, Diablo Rd	Rockfall	0	998	1a, 2, 2a	1992	WSDOT USMS reported chronic rockfall area, mitigated with rock debris retaining mesh; below rockfall 998
_	MW-20	Towers D86/13N D86/25N, access road	Debris flow, rockfall	0	3194	1a, 2, 2a	Unknown age of movement	Towers located on small ridges adjacent to and above debris flow fan 3194 and rockfall 819
	MW-21	Towers B85/44N D85/39N	Rockfall	0	864	2	Recent	Towers located near rockfall 865 and 864, WSDOT (USMS) reported rockfall along SR20 directly downslope
	MW-22	City Light access roads and SR 20	Debris Flow, rockfall	0	3223	2	Recent	WSDOT (USMS) reported rockfall and debris flow activity near debris flow 3223; rockfall 1000, 859, 858
itream	MW-23	City Light access roads and SR 21	Debris Flow, rockfall	0	3224	2, 3a, 3	Recent	WSDOT (USMS) reported rockfall near rockfall 863 and debris flow near fan 3224
Gorge Dam, Upstream and Downs	MW-24	Gorge Dam left abutment, Gorge Dam Rd, Towers B83/44N D83/38N	Landslide, debris flow, rockfall	0	3218	2, 3a, 3	Unknown age of movement	Facilities near rock avalanche 3218, debris flow 3175, rockfall 805
	MW-25	Gorge Dam right abutment	Closest mapped rockfall 1000ft upslope (847)		NA	2, 3a, 3	2001?	Golder Associates (2001) reported periodic rockfall near right abutment
	MW-26	Gorge Dam Rd, SR 20	Debris flow, rockfall, rock avalanche	0	845	2, 3a, 3	debris flow activity recent	Facilities cross debris flow 3227 (activity reported by WSDOT [USMS]) and rockfall 845, all downslope of rock flow 3354; rock avalanche 3220 located across (SE) Skagit R.
	MW-26a	Towers B83/3N, B83/11N, City Light access roads	Rockfall	100-300	842	2, 3a, 3	Unknown age of movement	Towers cross below mapped rockfall 842 and 843

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
	MW-27	SR 20, City Light access roads and SR 20	Debris flow, rock avalanche, rockfall	0	3404	2, 3a, 3	Rock avalanche (2003), debris flow recent activity	Site downslope of 2003 Afternoon Cr. rock avalanche that crossed SR 20 (Strouth, 2006) (Inventory landslide 3456); Strouth (2006) noted history of rockfall and debris flows; WSDOT (USMS) reported rockfall and debris flows; Inventory debris flows 3373, 3230, 3232 and rockfall 841
ırea	MW-28	SR 20 N side of town of Newhalem	Debris flow, rockfall	0	Multiple	2, 3a, 3	Recent	Site located within approx. 1-mile-long segment of SR20 that crosses multiple debris flow fans, and rockfall with recently reported periodic activity (City Light, WSDOT [USMS])
alem A	MW-29	SR 20 N side of town of Newhalem	Debris flow, rockfall	0	Multiple	2, 3a, 3, 3b	Recent	Site located within approx.1-mile-long segment of SR20 that crosses multiple debris flow fans, and rockfall with recently reported periodic activity (City Light, WSDOT [USMS])
Newh	MW-30	SR 20 N side of town of Newhalem	Debris flow, rockfall	0	Multiple	2, 3a, 3, 3b	Recent	Site located within approx.1-mile-long segment of SR20 that crosses multiple debris flow fans, and rockfall with recently reported periodic activity (City Light, WSDOT [USMS])
Gorge Dam to Newhalem Area	MW-31	Gorge powerhouse, suspension bridges	Debris flow, rockfall	0	3158	2, 3a, 3, 3b	Unknown age of movement	South end of Gorge powerhouse located near debris flow fan 3158 and rockfall 792 and 793
Gorge	MW-32	Tower B81/24N, Newhalem Townsite facilities N of SR 20	Rockfall	0	797	2, 3a, 3, 3b, 5	Unknown age of movement	facilities below ~2000-ft-long rockfall scarps and talus (797)
	MW-33	Tower B81/24N, Newhalem Townsite facilities N of SR 20	Rockflow / Rockfall	0	3200	3, 3b, 5	Unknown age of movement	Tower and Newhalem located at toe of rockflow with rockfall (3200) with some refreshened surfaces
Thornton Cr.	MW-34	D78/33N	Landslide, rockfall	NA	No mapped features	4, 5	Recent	WSDOT reported recent landslide and rockfall near tower and City Light access roads., no mapped features in Inventory; slope failures could be small events along river terrace with small incised channel N side of SR20
Thorn	MW-35	Tower D77/45N, City Light access road (unnamed)	Debris flow	0	3267	4, 5	Unknown age of movement	Tower alignment crosses debris flow fan 3267
mnation Cr. to n Cr., Right Bank of Skagit R.	MW-36	Towers D75/28N, D75/37N, City Light access road (unnamed)	Debris flow	0	3274	5, 6, 7a	Unknown age of movement	Tower alignment crosses debris flow fan 3274
Damnation Cr. Bacon Cr., Right I of Skagit R.	MW-37	Tower D75/5N, City Light access roads	Rockfall	0	730	5, 6, 7a	Unknown age of movement	Tower alignment crosses small rockfall zones upslope of SR 20

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
	MW-38	Tower D74/45N, City Light access road (unnamed)	Debris flow	0	3375	6, 7, 7a	Recent	Tower alignment crosses debris flow 3375; near site WSDOT (USMS) report debris flow material on SR 20
of Skagit R.	MW-39	Tower B74/42N, City Light access road (unnamed)	Landslide, rockfall	0	3405	6, 7, 7a	Historic	Tower located below toe of mapped landslide 3405; tower alignment crosses ~4000-ft-wide landslide/rockfall/debris flow complex; nested slides are likely historic (3193, 3192)
ight Bank of	MW-40	Towers D74/31N, City Light access roads	Landslide, rockfall, debris flow	0	3227	6, 7, 7a	Unknown age of movement	Tower alignment crosses debris flow 3136, rock avalanche 3227, and below rockfall 742
to Bacon Cr., Right Bank	MW-41	Tower D73/47N, City Light access roads	Landslide	0	3179	6, 7, 7a	Unknown age of movement	Tower alignment crosses large landslide complex including nested landslides with refreshened surfaces; tower located within 3179
Damnation Cr. to	MW-42	Towers B73/36N and D73/38N, City Light access roads	Landslide	0	3179	6, 7, 7a	Unknown age of movement	Tower alignment crosses large landslide complex including nested landslides with refreshened surfaces; tower located within 3179
Dam	MW-43	Tower D78/9N, City Light access roads	Landslide	100	3174	7, 8	Unknown age of movement	Tower alignment crosses large landslide complex (3174) with refreshened surfaces; tower located downslope and adjacent to landslides within complex
	MW-44	Towers D72/32N, B72/34N, City Light access roads	Rockfall	0	724	7, 8	Unknown age of movement	Tower alignment crosses mapped rockfall 724 on N side of SR20
÷	MW-45	Towers B71/11N, D71/11N, City Light access roads	Rockfall	150	688	7, 8	Unknown age of movement	Rockfall 688 mapped upslope or tower alignment
Jr. to Olsen Cr.	MW-46	Towers B70/47N, D70/47N City Light access roads	Rockfall	100	692	7, 8	Unknown age of movement	Rockfall 692 mapped upslope or tower alignment
Bacon Cr.	MW-47	TowersB67/48N, D67/48N, B67/35N, D67/35N, City Light access roads	Debris flow	0	3301	9, 10	Unknown age of movement	Tower alignment crosses large debris flow 3301at distal end of Olsen Cr.

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
Mitigation Parcel P-553	MW-48	Mitigation parcel P- 553	Landslide	0	3378	13	Unknown age of movement	Site located within the eastern and southern portions of the mitigation parcel P-553; parcel includes large complex of landslides (e.g., 3378); some of the nested landslides within the complex show freshened surfaces
above Left Bank of Skagit R.	MW-49	Towers B58/4N and D58/4N, City Light access roads (unnamed)	Rockfall	0	529	16, 17	Unknown age of movement	Towers located on top of rockfall scarp 529
Hilt Lake, above Le	MW-50	Towers B57/44N and D57/42N, City Light access roads (unnamed)	Rockfall	0	528	16, 17	Unknown age of movement	Towers located on top of rockfall scarp 528
Vicinity of Sauk - Suiattle R. Confluence	MW-51	Towers B50/24N, D50/24N, B50/13N, D50/13N, City Light access roads (unnamed)	Debris flow	0	3076	19, 20	Unknown age of movement	Tower alignment crosses a complex of debris flows (e.g., 3076) located directly downslope from multiple landslides.
French Cr, NF Stilliguamish R.	MW-52	Towers B39/29N D39/30N	Landslide	100	11517	23, 26	Recent	Towers located on top of scarp/landslide 11517; City Light reported failure along French Cr. bank and a lost tower

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
Bank between Boulder R. and Fry Cr.	MW-53	Towers B37/16N D37/16N, City Light access roads	Landslide	0	11498	24, 24a, 27	Unknown age of movement	Tower alignment crosses ~5 mi-long zone of landslides and debris flows; towers located with mapped landslide 11498
	MW-54	Towers D36/34N B36/34N D36/29N B36/29N	Landslide	0	11478	24, 24a, 27	Recent	Towers located on top of landslide 11478 with freshened surface and that is undercutting access road;  City Light reports site is monitored with inclinometers
	MW-55	Towers D36/17N, B36/18N, City Light access roads	Landslide	0	11500	24, 24a, 27	Unknown age of movement	Towers located within landslide 11500 with possible shallow sloughing along E and W flanks
	MW-56	Towers D36/9N, B36/10N, City Light access roads	Landslide	0	11497	24, 24a, 27	Unknown age of movement	Towers located within a complex of landslides and above headscarp for landslide 11477
R., South	MW-57	Tower B35/47N, City Light access roads	Landslide	0	11474	24, 24a, 27	Unknown age of movement	Tower located within a complex of landslides and above headscarp for landslide 11474
NF Stilliguamish	MW-58	Towers D35/33N B35/33N, City Light access roads	Landslide, debris flow	0	11531	24, 24a, 27	Recent	Towers located at distal end of 2104 Oso landslide to north and at base of multiple debris flows and landslide 12038 upslope
	MW-59	Towers D35/22N, B35/22N, City Light access roads	Landslide	0	12035	24, 24a, 27	Unknown age of movement	Towers located at distal end of 2104 Oso landslide to north and within distal end of landslide 12035, tower B35/22N located where toe of 12035 appears steepened and subject to shallow sloughing

Special Interest Zones	Site ID	City Light Facilities	Nearest Mass Wasting Feature to Project Site and Facilities	Distance to Feature (Feet)	Inventory Feature ID	Mapbook Page	Most Recent Reported Slope Failure	Descriptions of Reported Slope Failures and/or Mass Wasting Features Mapped Near Project Site and Facilities
	MW-60	Towers D35/7N, B35/7N, City Light access roads	Landslide	0	12031	24, 24a, 24b, 27	Unknown age of movement	Towers located within landslide 12031
R. and Fry Cr.	MW-61	Towers B34/48N D34/48N	Landslide	0	12025	24, 24a, 24b, 27	2004	Towers located above landslide with recent movement reported by WSDOT (2004), emergency repairs and soldier pile wall installed
Bank between Boulder R.	MW-62	Towers B34/34N D34/38N	Landslide	0	12026	24, 24a, 24b, 27	Unknown age of movement	Towers located within landslide 12026
NF Stilliguamish R., South Ban	MW-63	TowersD34/11N, B34/11N, B34/4N	Landslide	100	3426	24, 24a, 24b, 24c, 27	Unknown age of movement	Tower alignment crosses large landslide complex 12024, also crosses headscarps of multiple shallow landslides along Montague Cr.
Stilligua	MW-64	Towers D33/35N, B34/11N, B33/34N	Landslide, debris flow	0	4687	24, 24c, 27	Recent?	Tower alignment crosses multiple debris flows and the toe of large landslide complex 11415; City Light report notes WSDOT monitoring slope
N	MW-65	Tower D33/15N	Landslide	0	11415	24, 24c, 27	Recent?	Tower alignment crosses toe of large landslide complex 11415 and smaller nested landslides; City Light report notes WSDOT monitoring slope
amish Bank y Lk	MW-66	Tower B31/22N	Landslide	0	12428	29	Unknown age of movement	Tower located on headscarp of shallow landslide 12428
NF Stilliguamish R., South Bank Near Riley Lk	MW-67	Towers D30/51N B30/51N	Landslide	0	12434	29	Unknown age of movement	Towers located above small landslide 12434: City Light reports shallow sloughing below towers































































































