



Bangor Avenue South – 51st Ave S to 55th Ave S



Bangor Avenue South – 51st Ave S to 55th Ave S



Project ID # 2007-253

Type of Improvement: Street Resurfacing
Neighborhood: Rainier Beach

Approximate Length: 1330 feet
Street Classification: Minor Arterial

Applicant Description of Problem and/or Project:

Problem: There are potholes all over and is in dire need of repaving, not just fixing potholes.
Suggested Project: Repaving of Bangor Ave S.

Potential Solution and/or Comments:

Bangor Avenue South from 51st Ave S to 55th Ave S

- Grind and overlay existing street between 51st Ave S and 55th Ave S
- Adjust existing manholes and catch basins

The street section between 55th Ave S and 57th Ave S has concrete panels that are in good condition and do not warrant repaving at this time.

Challenges/Tradeoffs:

- Pavement analysis and design are necessary to determine most appropriate rehabilitation technique. This estimate assumes grind and overlay. A more intensive reconstruction method, if appropriate, could cost upwards of \$400,000.
- Repaving between 55th Ave S and 57th Ave S is not included in this estimate, as the existing pavement is in good condition.

Preliminary Range of Cost: \$ 240,000 to \$ 300,000