



DELL-WA001-002-R00

505 First Avenue South 4th Floor
Seattle, Washington 98104
United States of America

WALL REPAIR GUIDELINES

Exterior

Corrugated

To be discussed with client. End result should ensure holes are filled or patched prior to installing new sign.

Brick

Holes to be filled with *QUICKRETE* mortar repair sealant or paintable caulk. Clean wall as required and quoted.

Concrete

Holes to be filled with *QUICKRETE* concrete repair sealant. Pressure wash wall.

Sidings

Patch holes with pre-approved painted aluminum.

Stucco and EIFS

Patch holes or re-mediate wall with *DAP ALEX PLUS* all-purpose acrylic latex caulk. Prep and paint wall with approved paint color (*SHERWIN WILLIAMS* or *BENJAMIN MOORE*).

Interior

Drywall

Patch holes or re-mediate wall with *DAP ALEX PLUS* all-purpose acrylic latex caulk. Prep and paint wall to a Level 4 finish with approved paint color (*SHERWIN WILLIAMS* or *BENJAMIN MOORE*).

Wood, Marble, Glass, and Granite

To be discussed with client prior to budget presentation.


Wallpaper

Wallpaper to be removed and reapplied. PM to consult with client as they may have access to matching wallpaper.

* Paint must cure for a minimum of 48 hours prior to graphics installation. Gassing and/or peeling of graphic can occur otherwise.

* Electrical is to be brought to signage area prior to sign installation by GC or owner.

SITE MAP



SIGN INVENTORY

L#	EXISTING	RECOMMENDATION	QTY
1	Letterset	Letterset	1
2	Vinyl	No Action by Colite	-

Surveyor: -

LOCATION 1

Existing: Letterset



EXISTING SIGN DETAILS:

Quantity	Depth	Sign Sq. Ft.	Illumination
1	2" [51mm]	29.39	See Notes
Mounting		Fabrication	
Frame		Fabricated Letterset	

SURVEY NOTES:

Illumination: Existing uplighting is to remain.

CONTEXT PHOTOS:



Recommendation: Letterset



RECOMMENDATION DETAILS:

Quantity	Sign Sq.Ft.	Illumination	Estimated Paint Sq.Ft.
1	21.67	None	-
Mounting		Fabrication	
Frame		Flat Cut Out Letterset	


INSTALLATION/REPAIR NOTES:

Remove existing letterset. Install new letterset as shown.

PART #:

DELL-LTR-109-NL-EX-020H-X

SIGN DETAIL:



LOCATION 2


Existing: Vinyl



Recommendation: No Action by Colite



SURVEY NOTES:
No survey information provided for this location.



**NO ACTION
BY COLITE**

SURVEY PHOTOS



PHOTO 001



PHOTO 002



PHOTO 003



PHOTO 004

SURVEY PHOTOS



PHOTO 005



PHOTO 006



PHOTO 007



PHOTO 008

