

Project Website: https://www.seattle.gov/parks/about-us/projects/view-ridge-playfield-playground-renovation

Online User Survey: https://seattle.surveymonkey.com/r/ViewRidgePF2

Project Team



Colin Campbell
Project Planner



Shwu-jen Hwang Landscape Architect, Sr.



Jessica Michalak Capital Project Coordinator







SCOPE OF WORK:

- Replace existing play equipment and meet accessible play area standard
- Provide accessible route to connect play area to restroom and sidewalk
- Improve other accessibility items

TOTAL BUDGET: \$730,000

SCHEDULE: Planning – Winter 2022

Design - 2023 ~ 2024


Construction – 2024 ~ 2025

PROJECT TEAM: Colin Campbell, Project Planner


Shwu-jen Hwang, Landscape Architect, Sr. Jessica Michalak, Capital Project Coordinator




Q1 What do you like about the existing play equipment? Check all that apply




Q2 What play equipment characteristics would you like for the play area? Please choose one.



Answered: 57 Skipped: 0 Q4 Sand Play Area: The existing picnic shelter is crowded with picnic tables and sand box. The sand spills over to the adjacent paving and creates maintenance safety issues. Please choose one.



Q3 Please select your top six most desired types of play equipment suggest your own.



ACCESSIBILITY CONSIDERATIONS



Playground Grass





- Meet accessible play area standard.
- Provide accessible route to connect play area to restroom and sidewalk.
- Provide accessible route within play area to elevated & ground level play events.
- Improve restroom accessibility
- Provide accessible drinking fountain

Improve accessible entrance from NE 70th St. Match grade to sidewalk. Regrade and replace asphalt with concrete walk to restrooms.



Use playground grass safety accessible surfacing under play structures.

Use engineer wood fiber for swing area but provide accessible route to accessible swing.



Lack of accessible route to the picnic areas. If budget allows, add concrete paving to picnic area, replace with accessible picnic tables and BBQs.








Provide accessible drinking fountain




Accessible compartment is too small in restroom. Future project.









Options Comparison


Options Comparison										
	Α		В		С		D		E	
	2~5	5~12	2~5	5~12	2~5	5~12	2~5	5~12	2~5	5~12
TOTAL PLAY EVENTS	14	27	11	20	8	19	16	22	16	24
(ELEVATED/GROUND)	8/6	19 /8	4 /7	6 /14	5/3	14/ 5	7/9	17 /5	5/11	8/ 16
MAX. FALL HEIGHT	4'	8.5'	4'	10'	4'	6'	4'	6'	4'	6'8"
SLIDE	2	5	2	3	1	4	3	4	3	1
COST W/O TAX	\$200K		\$172K		\$216K		\$227K		\$206K	
NOTES	elevated events, Max. use beneath, 8.5' & 8' high, Many slides, Good social space Wood Structure, Tree trunk, Shade cover		Fewer elevated		Many events,		2nd most		Many events,	
			events,		Canyon rock,		elevated events,		Many ground	
			points, Up to 10' high,		Curved wave walk, Animal tracks, Music,		Many slides,		level events,	
									1 slide for 5-12, Good climbing events,	
			level events,		Sand digger &		Sand digger &		Good social	
			Many ground level events, Least cost		Shade				space,	
									Coco Swing,	
									More modern,	
									Long lif	e time


Option E


https://seattle.surveymonkey.com/r/ViewRidgePF2




▲ TRANSFER STATION

















UPRIGHT: WOOD/BRONZE ACCENT: VANILLA/CHARTREUSE DECK: WOOD/GRAY ROTO: BEIGE/GRAY/CHARTREUSE/GREEN HDPE: BROWN/BEIGE/GREEN HDPE 2-COLOR: GREEN/WHITE BT CAP & BASE: GREEN



















































Option A









Option C

Option D

Option E









Existing age 2~5 play area echoes the design of bigger play structure.



Existing age 5~12 play area

The existing age 5~12 play equipment offers varieties of play events, many access points, and many play routes. Space underneath the deck is well used.





Existing tall swing is aging & exceeds maintenance height. Toddler bucket swing exceed maximum 8' high. Lack of accessible route to existing benches.



Park users use the area west of existing swing area for adult exercise.



The existing picnic shelter is too crowded with picnic tables and a sand box. The sand spilled over to adjacent paving and created maintenance issues