

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/14/2025	3/14/2025	Business inspection: during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.	Yes, Notified Ecology	309 s cloverdale st	seattle	98108	47.525492	-122.330648	Soap or cleaning chemicals: during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.	Other: during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.	Not applicable: during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.	Clean-up: during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.	during a business inspection, soapy water was found in a private drain. owner of the property hired a contractor to clean the drain. ecology was notified.
WAR044503	5/19/2025	5/19/2025	MS4 inspection or screening: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.	Yes, Notified Ecology	s garden st & 48th ave s	seattle	98118	47.537635	-122.272645	Sewage/septage/pet waste/human waste: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.	Construction activity: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project., Other: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.	Not applicable: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.	Clean-up: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project., Other: spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.	Complaint. spu dry weather screening identified elevated fecal levels in the ms4. the investigation resulted in an internal referral to the pipe assessment team. issue will be resolved through a mainline pipe rehab project.
WAR044503	7/31/2025	7/31/2025	Business inspection: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.	Yes, Notified Ecology	659 ne northlake way	seattle	98105	47.654310	-122.321116	Fuel and/or vehicle related fluids: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.	Other accident/spill: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.	Not applicable: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.	Clean-up: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body., Education/technical assistance: oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.	oil spill at private boat repair business discovered during routine inspection. the business delayed reporting per staff accounts. the business staff and spu staff cleaned the catch basin with boom. no observed impact to water body.
WAR044503	5/12/2025	5/12/2025	Direct report to your staff: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.	Yes, No Notice Required	1521 nw 50th st	seattle	98107	47.684752	-122.377426	Sediment/soil: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.	Other: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.	Not applicable: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.	Clean-up: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad., Education/technical assistance: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad., Other: i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.	Complaint. i checked on a catch basin which had been affected by a december trackout complaint where we noticed a dirt piling yard sheet flowing to said cb. saw turbid water surrounding the cb and ponding on the asphalt, showing signs of an illicit discharge. provided technical assistance to the site owners, and saw that an adjacent business sharing the alley had installed a concrete spill pad.
WAR044503	1/2/2025	1/2/2025	Pollution hotline (phone, web, app): report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.	Yes, Notified Ecology	6301 65th ave ne	seattle	98115	47.674638	-122.259544	Sewage/septage/pet waste/human waste: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.	Other accident/spill: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.	Not applicable: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.	Clean-up: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event., Referred to other agency or department: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event., Other: report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.	report of sewage surfacing at an apartment. a small trickle of sewage was seen entering a private catch basin at a rate of 1 gallon per hour. a plumber relieved the blockage. no beach closure initiated for this event.
WAR044503	1/3/2025	1/3/2025	Pollution hotline (phone, web, app): report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.	Yes, No Notice Required	2521 e mcgraw st	seattle	98112	47.640061	-122.299349	Fuel and/or vehicle related fluids: report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.	Unconfirmed, unspecified, or not identified: report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.	Not applicable: report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.	Other: report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.	report of oil spilled to street. only sheen found. nothing to recover. only sheen entering the catch basin similar to other streets during a rain event. not clearly attributable to the construction site.
WAR044503	1/3/2025	1/3/2025	Direct report to your staff: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.	Yes, Notified Ecology	3100 airport way s	seattle	98134	47.576538	-122.320481	Fuel and/or vehicle related fluids: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.	Other accident/spill: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.	Not applicable: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.	Clean-up: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill., Education/technical assistance: construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.	construction equipment leaked diesel in a parking lot. responsible party hired a contractor to clean up the spill.
WAR044503	1/4/2025	1/4/2025	Pollution hotline (phone, web, app): hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.	Yes, Notified Ecology	13201 aurora ave n	seattle	98133	47.725456	-122.346604	Fuel and/or vehicle related fluids: hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.	Other accident/spill: hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.	Not applicable: hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.	Clean-up: hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen., Other: hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.	hydraulic system on a trash compactor was damaged and drained the hydraulic oil to the pavement and private catch basin. business hired a spill contractor to clean the spill and dispose of the waste. no impact to the ms4 was seen.
WAR044503	1/7/2025	1/7/2025	Pollution hotline (phone, web, app): report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.	Yes, Notified Ecology	2470 s columbian way	seattle	98108	47.560915	-122.300559	Sewage/septage/pet waste/human waste: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.	Other accident/spill: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.	Not applicable: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.	Clean-up: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties., Education/technical assistance: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties., Referred to other agency or department: report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.	report of sewage surfacing at a private residence. confirmed sewage was impacting the ms4 at a rate of 1-gpm. this was referred to wwsf for assistance with the responsible parties.
WAR044503	1/7/2025	1/7/2025	Pollution hotline (phone, web, app): reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.	Yes, No Notice Required	e john st & 36th ave e	seattle	98112	47.620137	-122.286916	Other: reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.	Vehicle-related business: reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.	Not applicable: reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.	Other: reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report., Other: reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.	reporting party stated that a commercial van is spilling paint from a spill inside the van. she decided to clean this up herself. she stated no need to respond to her report.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	1/9/2025	1/9/2025	ERTS referral: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.	Yes, Notified Ecology	7801 detroit ave sw	seattle	98106	47.532199	-122.336414	Fuel and/or vehicle related fluids: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.	Other: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.	Not applicable: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.	Clean-up: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection. , Education/technical assistance: we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.	we received a report of a diesel spill at a gas station. site visit confirmed the spill had not been cleaned up properly. it entered a private drain that leads to our ms4. i could not verify if it made it past the cb. i will follow up with a business inspection.
WAR044503	1/9/2025	1/9/2025	Pollution hotline (phone, web, app): received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.	Yes, Notified Ecology	8340 rainier ave s	seattle	98118	47.528267	-122.269563	Sewage/septage/pet waste/human waste: received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.	Other accident/spill: received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.	Not applicable: received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.	Clean-up: received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.	received a report about sewage seeping up from private property and entering a drain. site visit confirmed a small amount of sewage entered the ms4. due to this location having history of this exact situation, the drain has a mechanical plug in it. this site has been referred to wastewater source control.
WAR044503	1/9/2025	1/9/2025	ERTS referral: no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.	Yes, Notified Ecology	7201 west marginal way sw	seattle	98106	47.538222	-122.340484	Fuel and/or vehicle related fluids: no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.	Other accident/spill: no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.	Not applicable: no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.	Clean-up: no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.	no impact to ms4. all impact was to private drainage that discharges to sanitary. spill was cleaned up and compactor was fixed. nfa.
WAR044503	1/9/2025	1/9/2025	Pollution hotline (phone, web, app): received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.	Yes, No Notice Required	1455 ne 106th st	seattle	98125	47.706272	-122.312833	Other: received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.	Unconfirmed, unspecified, or not identified: received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.	Not applicable: received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.	Other: received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.	received a report about sheen along the sidewalk. the report was from a few days prior. during my site visit i saw no sheen or source, therefore no drain impact. no further investigation is necessary.
WAR044503	1/6/2025	1/6/2025	ERTS referral: called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.	Yes, Notified Ecology	rainier ave s / i-90 fwy	seattle	98144	47.590378	-122.307340	Other: called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.	Construction activity: called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.	Not applicable: called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.	no downstream involvement. ms4 drains go to sanitary. , Other: called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.	called to get pictures of clean up and to make sure no slurry made it down stream. clean up complete.
WAR044503	1/10/2025	1/10/2025	Pollution hotline (phone, web, app): received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.	Yes, Notified Ecology	22nd ave nw / shilshole ave nw	seattle	98107	47.666465	-122.384760	Other: received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.	Intentional dumping: received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.	Not applicable: received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.	Clean-up: received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.	received a report of a paint spill. site visit confirmed there was a 5 gallon bucket of paint spilled to pavement with no ms4 impact. i cleaned the paint with on hand materials and disposed of the waste properly. no further investigation is necessary.
WAR044503	1/13/2025	1/13/2025	Pollution hotline (phone, web, app): received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.	Yes, Notified Ecology	14th ave s & s oregon st	seattle	98108	47.563499	-122.314795	Fuel and/or vehicle related fluids: received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.	Vehicle-related business: received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.	Not applicable: received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.	Clean-up: received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.	received a report about sheen getting into the drains. site visit confirmed there was sheen for about two blocks. it did impact the ms4, i notified ecology and placed boom in two drains. no further cleanup is necessary.
WAR044503	1/12/2025	1/12/2025	Pollution hotline (phone, web, app): received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.	Yes, Notified Ecology	7 s idaho st	seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.	Vehicle-related business: received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.	Not applicable: received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.	Clean-up: received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.	received a report about a vehicle leaking transmission fluid to pavement with no drain impact. responsible party cleaned the spill up and sent me pictures of the process.
WAR044503	1/12/2025	1/12/2025	Pollution hotline (phone, web, app): received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.	Yes, No Notice Required	2525 14th ave s	seattle	98144	47.580234	-122.315178	Fuel and/or vehicle related fluids: received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.	Vehicle-related business: received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.	Not applicable: received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.	Education/technical assistance: received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.	received a report about some sheen in a private parking lot of an apartment complex. during my site visit i found very minimal sheen with no drain impact. i left a message with the front office about addressing spills and their requirement to clean them. no further investigation is necessary.
WAR044503	1/13/2025	1/13/2025	Pollution hotline (phone, web, app): we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.	Yes, Notified Ecology	nw 107th st & greenwood ave nw	seattle	98117	47.706898	-122.355487	Fuel and/or vehicle related fluids: we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.	Vehicle collision: we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.	Not applicable: we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.	Clean-up: we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.	we received a report of a car fire causing automotive fluids to enter a drain. site visit confirmed gasoline and fire fighting foam had hit a cb in the ms4, and a little bit of foam hit a swale. a contractor was hired to clean the drain, and the foam. wemnd and ecology were notified.
WAR044503	1/13/2025	1/13/2025	Pollution hotline (phone, web, app): received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.	Yes, No Notice Required	rainier ave s & ithaca pl s	seattle	98118	47.520350	-122.260720	Sewage/septage/pet waste/human waste: received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.	Vehicle collision: received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.	Not applicable: received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.	Other: received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.	received a report about an rv leaking sewage. there were 3 crashed cars at this location including the rv. some sewage entered a cb that flows the combined sewer. i filed a report for abandoned vehicles, and another inspector did a site visit and confirmed the cars and sewage was no longer there.
WAR044503	1/13/2025	1/13/2025	Pollution hotline (phone, web, app): received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.	Yes, Notified Ecology	47th ave ne & ne 54th st	seattle	98105	47.667806	-122.277385	Fuel and/or vehicle related fluids: received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.	Vehicle-related business: received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.	Not applicable: received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.	Clean-up: received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.	received a report about a trash truck leaking hydraulic fluid to pavement with no drain impact. responsible party cleaned and disposed of the waste. no further investigation is necessary.
WAR044503	1/14/2025	1/14/2025	Pollution hotline (phone, web, app): received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.	Yes, Notified Ecology	25th ave sw / sw barton st	seattle	98119	47.521022	-122.364558	Fuel and/or vehicle related fluids: received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.	Vehicle-related business: received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.	Not applicable: received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.	Clean-up: received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.	received a report about a couple gallon coolant spill. the spill did enter a drain in the ms4. the responsible party reported it to ecology and cleaned out the drain. no further response is necessary.
WAR044503	1/14/2025	1/14/2025	Pollution hotline (phone, web, app): received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.	Yes, Notified Ecology	2916 sw avalon way	seattle	98126	47.570754	-122.371034	Sewage/septage/pet waste/human waste: received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.	Construction activity: received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.	Not applicable: received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.	Clean-up: received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.	received a report of an sso entering the ms4. the sewer mainline was blocked. crews relieved the blockage and i followed sso reporting protocol. no signage was put out per king county guidance.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	1/14/2025	1/14/2025	Pollution hotline (phone, web, app): pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.	Yes, Notified Ecology	1910 nw 100th st	seattle	98177	47.702006	-122.381860	Other: pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.	Other: pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.	Not applicable: pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.	Education/technical assistance: pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed. . Enforcement: pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.	pressure washing company found not implementing bmps with chlorinated wash water. chlorine not neutralized even after traveling through soil. company stopped work and implemented bmps. ms4 impacted but chlorine dissipated prior to outfall. business inspection completed.
WAR044503	1/14/2025	1/14/2025	Staff referral: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.	Yes, Notified Ecology	3rd ave s / s holgate st	seattle	98134	47.586159	-122.330027	Fuel and/or vehicle related fluids: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.	Other accident/spill: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa. Intentional dumping: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.	Not applicable: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.	Clean-up: planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.	Complaint. planned rv remediation. inspected 11 structures and found one with unrecoverable sheen from previous fill. boom applied. ms4 impacted but no downstream impact. nfa.
WAR044503	1/16/2025	1/16/2025	Pollution hotline (phone, web, app): spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup	Yes, Notified Ecology	900 poplar pl s	seattle	98144	47.593881	-122.311252	Fuel and/or vehicle related fluids: spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup	Vehicle-related business: spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup	Not applicable: spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup	Clean-up: spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup	spill of gasoline to pavement and catch basin due drilled gas tank. fuel confined to catch basin 567361. spu contractor activated for cleanup
WAR044503	1/17/2025	1/17/2025	Pollution hotline (phone, web, app): report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.	Yes, Notified Ecology	ne 143rd st & 20th ave ne	seattle	98125	47.732055	-122.307328	Other: report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.	Construction activity: report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.	Not applicable: report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.	Education/technical assistance: report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections. . Referred to other agency or department: report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.	report of white color in ms 4. investigation found active construction activity upstream at two adjacent construction sites. spu spills cleaned a single catch basin of an unknown turbid discharge and approximately 1-gallon of contaminated water. construction sites referred to sdcf for follow-up inspections.
WAR044503	1/21/2025	1/21/2025	Pollution hotline (phone, web, app): no impact to ms4. referred to lime bikes. they will work to retrieve.	Yes, No Notice Required	1901 n northlake way	seattle	98103	47.645840	-122.335974	Solid waste/trash: no impact to ms4. referred to lime bikes. they will work to retrieve.	Intentional dumping: no impact to ms4. referred to lime bikes. they will work to retrieve.	Not applicable: no impact to ms4. referred to lime bikes. they will work to retrieve.	Referred to other agency or department: no impact to ms4. referred to lime bikes. they will work to retrieve.	Complaint. no impact to ms4. referred to lime bikes. they will work to retrieve.
WAR044503	1/21/2025	1/21/2025	ERTS referral: ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.	Yes, Notified Ecology	westlake ave / halladay st	seattle	98109	47.642793	-122.342880	Sediment/soil: ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.	Construction activity: ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.	Not applicable: ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.	Clean-up: ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.	Complaint. ms4 (mostly pavement) impacted by turbid water but sock filter was in place. no downstream impacts. nfa.
WAR044503	1/22/2025	1/22/2025	Direct report to your staff: contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.	Yes, Notified Ecology	3614 linden ave n	seattle	98103	0	0	Unconfirmed, unspecified, or not identified: contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.	Other: contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.	Not applicable: contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.	Education/technical assistance: contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.	Complaint. contractor discharging water from an unknown source into the street and it impacted a cb in a separated area. ms4 impacted.
WAR044503	1/23/2025	1/23/2025	Pollution hotline (phone, web, app): report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.	Yes, No Notice Required	19901 cedar falls rd se	north bend	98045	47.425844	-121.775793	Other: report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.	Vehicle-related business: report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.	Not applicable: report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.	Clean-up: report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody. . Other: report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.	report of four quarts of oil that spilled onto pavement from an unknown source. cleaned up by personnel at cedar falls. no impact to ms4 or to any waterbody.
WAR044503	1/27/2025	1/27/2025	Pollution hotline (phone, web, app): report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.	Yes, Notified Ecology	4350 53rd ave ne	seattle	98105	47.660957	-122.270646	Other: report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.	Vehicle-related business: report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.	Not applicable: report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.	Clean-up: report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4. . Other: report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.	report of a commercial vehicle that had a mechanical failure and spilled two gallons of hydraulic fluid onto roadway. responsible party cleaned up. no impact to ms4.
WAR044503	1/29/2025	1/29/2025	ERTS referral: report of commercial vehicle that leaked a large stain in alley.	Yes, Notified Ecology	3509 sw monroe st	seattle	98126	47.531026	-122.377243	Other: report of commercial vehicle that leaked a large stain in alley.	Vehicle-related business: report of commercial vehicle that leaked a large stain in alley.	Not applicable: report of commercial vehicle that leaked a large stain in alley.	Other: report of commercial vehicle that leaked a large stain in alley.	report of commercial vehicle that leaked a large stain in alley.
WAR044503	1/29/2025	1/29/2025	Pollution hotline (phone, web, app): spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.	Yes, No Notice Required	1401 broadway	seattle	98122	47.613179	-122.321227	Food-related oil/grease: spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.	Other: spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.	Not applicable: spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.	Clean-up: spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted. . Other: spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.	Complaint. spill of used cooking at a shared accumulation area at the loading dock. area cleaned by property management company. floor drain also cleared of a clog. follow-up inspections of area restaurants also conducted.
WAR044503	1/29/2025	1/29/2025	Pollution hotline (phone, web, app): a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.	Vehicle-related business: a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.	Not applicable: a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.	Clean-up: a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts. . Other: a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.	a spill of diesel fuel from a tractor at a private commercial facility. cleanup completed by the property manager ehs. impact to the private wastewater treatment system. no ms4 or water impacts.
WAR044503	1/30/2025	1/30/2025	Direct report to your staff: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.	Yes, Notified Ecology	2520 westlake ave n	seattle	98109	47.642967	-122.343206	Fuel and/or vehicle related fluids: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.	Other accident/spill: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.	Not applicable: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.	Education/technical assistance: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues. . Referred to other agency or department: no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.	Complaint. no impact to ms4. diesel found spilled on dock. business inspection performed. will work to send multi department enforcement letter as business continues to present issues.
WAR044503	1/31/2025	1/31/2025	Pollution hotline (phone, web, app): oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills	Yes, No Notice Required	50th ave s & s dawson st	seattle	98118	47.554853	-122.270919	Fuel and/or vehicle related fluids: oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills	Unconfirmed, unspecified, or not identified: oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills	Not applicable: oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills	Clean-up: oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills	oil sheen reported in a gravel alley . no source located. spill cleaned up by spu spills

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments	
WAR044503	2/1/2025	2/1/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	Yes, Notified Ecology	11057 40th ave ne	seattle	98125	47.709962	-122.285711	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	Vehicle-related business: spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	Not applicable: spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	Clean-up: spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	nfa_spills, Other: spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.	spill of hydraulic oil to pavement. no drainage impacts. cleanup completed by responsible party.
WAR044503	2/4/2025	2/4/2025	Pollution hotline (phone, web, app): construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	Yes, No Notice Required	4836 s graham st	seattle	98118	47.546253	-122.271034	Other: construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	Construction activity: construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	Not applicable: construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	Education/technical assistance: construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	nfa_spills, Other: construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw	Complaint. construction company dewatering a trench to the public right of way to allow for an inspection. no evidence of high turbidity water or sediment in the stormdrain system. situation already reviewed by sdcI. warning issued regarding construction dewatering permits with sdcI and kciw
WAR044503	2/5/2025	2/5/2025	ERTS referral: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	Yes, Notified Ecology	10330 meridian ave n	seattle	98133	47.704490	-122.332735	Fuel and/or vehicle related fluids: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	Construction activity: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	Not applicable: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	Clean-up: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	nfa_spills, Other: construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.	construction equipment leaked hydraulic fluid to the ground. no drains impacted. responsible party hired a contractor to clean up the spill and dispose of the waste. cleanup contractor applied degreaser which did impact the drainage system. ms4 cleaned by the cleanup contractor.
WAR044503	2/6/2025	2/6/2025	Pollution hotline (phone, web, app): sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	Other accident/spill: sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	Not applicable: sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	Education/technical assistance: sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	sheen on pavement. drain involvement but trap installed. no waterbody involvement. secondary permittee owned ms4 involved. sheen was cleaned up. nfa.	
WAR044503	2/7/2025	2/7/2025	Pollution hotline (phone, web, app): drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	Yes, Notified Ecology	47th ave sw & sw hotgate st	seattle	98116	47.586854	-122.391717	Fuel and/or vehicle related fluids: drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	Intentional dumping: drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	Not applicable: drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	Clean-up: drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	nfa., Other: drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.	drilled gas tank. sheen made its way to a downstream ms4 catch basin. no downstream impacts. boom applied to unrecoverable sheen. nfa.
WAR044503	2/10/2025	2/10/2025	Pollution hotline (phone, web, app): cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	Yes, Notified Ecology	52nd ave sw & sw charlestown st	seattle	98116	47.570335	-122.398796	Solid waste/trash: cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	Intentional dumping: cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	Not applicable: cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	Clean-up: cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	nfa., Other: cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.	cleaned up gasoline along curb line, inlet and cb. no downstream impact. provided homeowner plug and dike. boom deployed. ms4 impacted. nfa.
WAR044503	2/11/2025	2/11/2025	ERTS referral: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	Yes, Notified Ecology	nw 100th st/8th ave nw	seattle	98117	47.701505	-122.366058	Fuel and/or vehicle related fluids: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	Other accident/spill: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	Not applicable: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	Clean-up: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	nfa., Other: cleaned small oil spill in curb line in ms4. no downstream impact. nfa.	cleaned small oil spill in curb line in ms4. no downstream impact. nfa.
WAR044503	2/12/2025	2/12/2025	Pollution hotline (phone, web, app): sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	Yes, Notified Ecology	4120 11th ave ne	seattle	98105	47.657755	-122.316421	Sewage/septage/pet waste/human waste: sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	Other accident/spill: sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	Not applicable: sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	Clean-up: sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	nfa., Other: sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.	sewage found pooling on property. buckets of sewage were poured in the alley to attempt a repair. no active flow to row. apartments unclogged side sewer. sewage was cleaned from ms4. nfa.
WAR044503	2/13/2025	2/13/2025	Pollution hotline (phone, web, app): concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	Yes, Notified Ecology	32nd ave s & s charles st	seattle	98144	47.594621	-122.291582	Other: concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	Other accident/spill: concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	Not applicable: concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	Clean-up: concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	nfa., Other: concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.	concrete back fill material was spilled on steep hill during construction. slurry was cleaned. sweeper was dispatched. ms4 impacted but no downstream involvement. nfa.
WAR044503	2/13/2025	2/13/2025	Direct report to your staff: spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	Yes, Notified Ecology	2708 s judkins st	seattle	98144	47.592204	-122.297269	Other: spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	Construction activity: spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	Not applicable: spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	Clean-up: spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	spill of concrete slurry material to pavement and stormwater inlet and catch basin. responsible party hired a contractor to clean the street and drainage system.	
WAR044503	2/14/2025	2/14/2025	Pollution hotline (phone, web, app): release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	Yes, Notified Ecology	3813 fremont ave n	seattle	98103	47.653172	-122.350390	Sewage/septage/pet waste/human waste: release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	Other accident/spill: release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	Not applicable: release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	Clean-up: release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	release of sewage from a private side sewer. no impact to ms4 or water body. case referred to side sewer program.	
WAR044503	2/14/2025	2/14/2025	Pollution hotline (phone, web, app): spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to creek. company did not report spill to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	Yes, Notified Ecology	13025 8th ct ne	seattle	98125	47.723970	-122.321281	Fuel and/or vehicle related fluids: spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to creek. company did not report spill to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	Other accident/spill: spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to creek. company did not report spill to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	Not applicable: spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	Clean-up: spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to creek. company did not report spill to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	spill of heating oil, from a vendors supply truck, to pavement and separated drainage system. estimated 5 gallons made it to a spu catch-basin which outfalls to hillside above thorton creek. due to darkness and slope, unable to verify impact to creek. company did not report spill to ecology or spu. company was required to hire contractor for cleanup of the street, inlet and cb.	

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/17/2025	2/17/2025	Pollution hotline (phone, web, app): spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.	Yes, Notified Ecology	7131 beach dr sw	seattle	98136	47.538180	-122.396462	Fuel and/or vehicle related fluids: spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.	Vehicle-related business: spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.	Not applicable: spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.	Clean-up: spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.	spill of hydraulic fluid from garbage truck. sheen entered a few private driveway drains that direct discharge to puget sound. no spu drains in area so ms4 not impacted. spu put bilge boom into private drains and used absorbent on street.
WAR044503	2/18/2025	2/18/2025	Pollution hotline (phone, web, app): report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.	Yes, No Notice Required	ne 123rd st & sand point wy ne	seattle	98125	47.717375	-122.283937	Fuel and/or vehicle related fluids: report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.	Unconfirmed, unspecified, or not identified: report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.	Not applicable: report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.	Referred to other agency or department: report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4. , Other: report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.	report of sheen in row. arrived at location and found sheen but no source. referred to sdot for cleaning with sweeper. no impact to ms4.
WAR044503	2/21/2025	2/21/2025	Pollution hotline (phone, web, app): found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.	Yes, Notified Ecology	4951 sw hinds st	seattle	98116	47.573910	-122.397007	Sewage/septage/pet waste/human waste: found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.	Other accident/spill: found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.	Not applicable: found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.	Clean-up: found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa. , Other: found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.	Complaint. found sewage escaping force main. crews dispatched to clean and fix break. no downstream ms4 impact. nfa.
WAR044503	2/21/2025	2/21/2025	Direct report to your staff: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.	Yes, Notified Ecology	alaskan wy / seneca st	seattle	98101	47.605165	-122.339746	Fuel and/or vehicle related fluids: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.	Other accident/spill: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.	Not applicable: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.	Clean-up: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa. , Other: rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.	Complaint. rp spilled hydraulic fluid on the pier and coordinated clean up. no impact to ms4. no impact to puget sound. nfa.
WAR044503	2/21/2025	2/21/2025	Pollution hotline (phone, web, app): used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.	Yes, Notified Ecology	s washington st & alaskan ways	seattle	98104	47.600880	-122.335941	Food-related oil/grease: used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.	Intentional dumping: used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.	Not applicable: used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.	Clean-up: used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.	used cooking oil dumped on a parked car. cleaned up used cooking oil affected two drains in the ms4. traps installed. no impact downstream. nfa.
WAR044503	2/22/2025	2/22/2025	Pollution hotline (phone, web, app): unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.	Yes, Notified Ecology	11th ave ne / ne 42nd st	seattle	98105	47.658339	-122.316670	Fuel and/or vehicle related fluids: unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.	Unconfirmed, unspecified, or not identified: unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.	Not applicable: unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.	Clean-up: unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa. , Other: unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.	Complaint. unknown sheen in roadway due to rains. place boom in cb just in case. ms4 impacted by unrecoverable sheen. nfa.
WAR044503	2/24/2025	2/24/2025	Direct report to your staff: forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.	Yes, No Notice Required	river mile 3-5	seattle	98108	0	0	Other: forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.	Unconfirmed, unspecified, or not identified: forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.	Not applicable: forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.	Other: forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.	Complaint. forwarded two nrc reports for sheen on duwamish to potential responsible party. rp confirmed no sheen originating from dredging.
WAR044503	2/24/2025	2/24/2025	ERTS referral: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.	Yes, Notified Ecology	california ave sw / sw college st	seattle	98116	47.582994	-122.386489	Fuel and/or vehicle related fluids: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.	Vehicle-related business: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.	Not applicable: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.	Clean-up: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa. , Education/technical assistance: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa. , Other: motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.	Complaint. motor vehicle parked in alley leaking fluids and causing sheen. cleaned up spill and asked apartment to work with tenant to fix the situation. ms4 impacted by unrecoverable sheen. nfa.
WAR044503	2/25/2025	2/25/2025	Pollution hotline (phone, web, app): crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.	Yes, No Notice Required	401 alaskan way s	seattle	98104	47.597018	-122.336580	Fuel and/or vehicle related fluids: crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.	Other accident/spill: crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.	Not applicable: crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.	Referred to other agency or department: crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa. , Other: crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.	crews on cleaned up site. it was contained to the private catch basin and treatment system. no waterbody impact. no impact to ms4. nfa.
WAR044503	2/26/2025	2/26/2025	Staff referral: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.	Yes, Notified Ecology	1350 n northlake way	seattle	98103	47.647672	-122.340007	Sewage/septage/pet waste/human waste: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.	Other accident/spill: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.	Not applicable: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.	Clean-up: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa. , Other: sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.	sewage was found on pavement from a broken pipe. ms4 not impacted by sewage. crews fixed the pipe. nfa.
WAR044503	2/26/2025	2/26/2025	Pollution hotline (phone, web, app): hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.	Yes, Notified Ecology	11th ave nw / nw 64th st	seattle		47.675270	-122.371404	Fuel and/or vehicle related fluids: hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.	Intentional dumping: hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.	Not applicable: hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.	Clean-up: hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.	hired contractor to clean gasoline from ms4. gasoline did not leave cb. nfa.
WAR044503	2/26/2025	2/26/2025	Pollution hotline (phone, web, app): a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.	Yes, Notified Ecology	6th ave s / s massachusetts st	seattle	98119	47.588249	-122.325965	Fuel and/or vehicle related fluids: a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.	Intentional dumping: a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.	Not applicable: a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.	Clean-up: a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.	a diesel pickup truck fuel tank was drilled and minimal if any fuel was stolen. diesel drained into gravel/soil and traveled along pavement into a combined storm drain. a contractor was hired to wash and recover the diesel and vacuum the storm drain; then the referral led to the affected area being assessed, regraded, and gravel covered.
WAR044503	2/26/2025	2/26/2025	Pollution hotline (phone, web, app): approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.	Yes, Notified Ecology	university way ne / ne 45th st	seattle	98105	47.661268	-122.313140	Fuel and/or vehicle related fluids: approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.	Intentional dumping: approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.	Not applicable: approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.	Clean-up: approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste. , Other: approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.	approx. 20 gallons of motor oil spilled and entered two catch basins; motor oil contained to catch basins and did not outfall to water body. contractor cleaned catch basins and disposed waste.
WAR044503	2/28/2025	2/28/2025	ERTS referral: multi family residence had blocked sewer, cleared it but left cleanup for weekend.	Yes, Notified Ecology	2607 14th ave w	seattle	98119	47.643157	-122.375090	Sewage/septage/pet waste/human waste: multi family residence had blocked sewer, cleared it but left cleanup for weekend.	Other accident/spill: multi family residence had blocked sewer, cleared it but left cleanup for weekend.	Not applicable: multi family residence had blocked sewer, cleared it but left cleanup for weekend.	Other: multi family residence had blocked sewer, cleared it but left cleanup for weekend.	Complaint. multi family residence had blocked sewer, cleared it but left cleanup for weekend.
WAR044503	2/28/2025	2/28/2025	Pollution hotline (phone, web, app): recology truck spilled 2 cups hydraulic fluid and cleaned it up.	Yes, Notified Ecology	11050 durland ave ne	seattle	98125	47.710570	-122.279307	Fuel and/or vehicle related fluids: recology truck spilled 2 cups hydraulic fluid and cleaned it up.	Vehicle-related business: recology truck spilled 2 cups hydraulic fluid and cleaned it up.	Not applicable: recology truck spilled 2 cups hydraulic fluid and cleaned it up.	Clean-up: recology truck spilled 2 cups hydraulic fluid and cleaned it up. , Other: recology truck spilled 2 cups hydraulic fluid and cleaned it up.	recology truck spilled 2 cups hydraulic fluid and cleaned it up.
WAR044503	3/2/2025	3/2/2025	Pollution hotline (phone, web, app): source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa	Yes, Notified Ecology	10372 rainer ave s	seattle	98178	47.510517	-122.238221	Fuel and/or vehicle related fluids: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa	Unconfirmed, unspecified, or not identified: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa	Not applicable: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa	Clean-up: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa , Referred to other agency or department: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa , Other: source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa	source tracing determined responsible party. ms4 and lake washington impacted by home heating oil. referred to proper regulatory agencies. nfa
WAR044503	3/2/2025	3/2/2025	Pollution hotline (phone, web, app): bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.	Yes, No Notice Required	800 occidental ave s	seattle	98104	47.595437	-122.331603	Other: bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.	Vehicle-related business: bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.	Not applicable: bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.	Other: bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.	bus leaked fuel on pavement at stadium. cleanup complete prior to spu arrival. no drain involvement. no impact to ms4. no further action required.
WAR044503	2/27/2025	2/27/2025	Pollution hotline (phone, web, app): mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.	Yes, Notified Ecology	2728 s iving st	seattle	98144	47.591472	-122.296218	Fuel and/or vehicle related fluids: mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.	Vehicle collision: mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.	Not applicable: mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.	Clean-up: mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned. , Other: mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.	mva caused approx 1/2gal of motor oil to spill to pavement and inlet/grate. placed absorbent material down to pavement and swept. installed small boom inside inlet. no outfall from inlet or catch basin. no further impacts--spill cleaned.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/28/2025	2/28/2025	ERTS referral: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.	Yes, Notified Ecology	westlake ave n & galer st	seattle	98109	47.632270	-122.340964	Sediment/soil: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union., Other wastewater: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.	Construction activity: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.	Not applicable: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.	Education/technical assistance: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union., Enforcement: groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.	Complaint, groundwater pumped from trench to storm drain. educational meeting held with contractors. sdot and spu inspectors provided guidance. ms4 may have been impacted with turbidity and outfall to lake union.
WAR044503	3/3/2025	3/3/2025	ERTS referral: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.	Yes, Notified Ecology	222 s holgate st	seattle	98134	47.586793	-122.331700	Fuel and/or vehicle related fluids: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.	Other accident/spill: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.	Not applicable: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.	Clean-up: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa., Other: responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.	responsible party cleaned spill on private property which drains to the combined. no downstream impact. nfa.
WAR044503	3/3/2025	3/3/2025	Direct report to your staff: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.	Yes, No Notice Required	occidental ave s & s walker st	seattle	98134	47.583981	-122.333277	Other: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.	Intentional dumping: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.	Not applicable: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.	Clean-up: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact. Other: 1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.	1 gallon latex paint spill. cleaned up with pads and granular absorbent. no ms4 impact.
WAR044503	3/3/2025	3/3/2025	Pollution hotline (phone, web, app): spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.	Yes, Notified Ecology	12th ave ne / ne 42nd st	seattle	98105	47.658341	-122.315532	Food-related oil/grease: spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.	Other accident/spill: spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.	Not applicable: spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.	Clean-up: spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa., Education/technical assistance: spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.	spill was cleaned by hand and boom deployments. new container installed. no product made it to outfall. ms4 impacted. nfa.
WAR044503	3/4/2025	3/4/2025	Pollution hotline (phone, web, app): responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.	Yes, Notified Ecology	38th ave ne / ne 73rd st	seattle	98144	47.681248	-122.287197	Fuel and/or vehicle related fluids: responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.	Other accident/spill: responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.	Not applicable: responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.	Clean-up: responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa. Other: responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.	responsible party cleaned up motor oil spill to pavement in ms4. no drain impact. nfa.
WAR044503	3/4/2025	3/4/2025	Pollution hotline (phone, web, app): motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371	Yes, Notified Ecology	rainier ave s & s bayview st	seattle	98144	47.580993	-122.300177	Fuel and/or vehicle related fluids: motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371	Vehicle collision: motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371	Not applicable: motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371	Clean-up: motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371, Other: motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371	motor vehicle accident release motor oil to roadway. clogged inlet trapped oil to the pavement and puddles. cleaned by spu spills with absorbents and granular. nfa spills 737371
WAR044503	3/4/2025	3/4/2025	Pollution hotline (phone, web, app): did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.	Yes, No Notice Required	sw 98th st / 51st ave sw	seattle	98136	47.515288	-122.395599	Other: did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.	Vehicle-related business: did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.	Not applicable: did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.	Referred to other agency or department: did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa. Other: did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.	Complaint, did not find sheen due to late reporting. referred to solid waste. no impact to ms4. nfa.
WAR044503	9/9/2025	9/9/2025	Direct report to your staff: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.	Yes, Notified Ecology	14325 aurora ave n	seattle	98133	47.733011	-122.346090	Fuel and/or vehicle related fluids: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.	Other: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.	Not applicable: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.	Clean-up: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing., Other: a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.	a truck repair company was cutting metal outside without implementing bmps for their quenching process water. staining from old uncleaned motor oil spills picked up the process runoff and had a petroleum sheen as it made its way to a private drain. the private infiltrating drain did not connect to ms4 but is clogged and contaminated, needing a vector service which the responsible party is providing.
WAR044503	3/7/2025	3/7/2025	ERTS referral: spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.	Yes, Notified Ecology	7303 8th ave s	seattle	98108	47.536751	-122.323977	Fuel and/or vehicle related fluids: spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.	Other accident/spill: spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.	Not applicable: spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.	Clean-up: spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.	spiller cleaned impacted pavement. no inlets or cbs impacted in ms4. nfa.
WAR044503	3/9/2025	3/9/2025	Pollution hotline (phone, web, app): property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.	Yes, Notified Ecology	5446 48th ave sw	seattle	98136	47.552627	-122.393291	Sewage/septage/pet waste/human waste: property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.	Intentional dumping: property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.	Not applicable: property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.	Clean-up: property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.	property owner dumped approximately one gallon of sewage into inlet. cleaned by gail spencer, seattle public utilities crew. ms4 impacted.
WAR044503	3/7/2025	3/7/2025	Pollution hotline (phone, web, app): report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.	Yes, Notified Ecology	4414 s frontenac st	seattle	98118	47.539963	-122.277357	Sediment/soil: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.	Construction activity: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.	Not applicable: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.	Clean-up: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted., Education/technical assistance: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted., Referred to other agency or department: report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.	report of company allowing sediment and muddy water to leave property and impact cb, sidewalk and street. ms4 impacted.
WAR044503	4/10/2025	4/10/2025	Pollution hotline (phone, web, app): a hydraulic hose for a trash compactor, broke.	Yes, Notified Ecology	402 s dawson st	seattle	98108	47.642967	-122.329023	Fuel and/or vehicle related fluids: a hydraulic hose for a trash compactor, broke.	Other: a hydraulic hose for a trash compactor, broke.	Not applicable: a hydraulic hose for a trash compactor, broke.	Clean-up: a hydraulic hose for a trash compactor, broke. Other: a hydraulic hose for a trash compactor, broke.	a hydraulic hose for a trash compactor, broke.
WAR044503	3/7/2025	3/7/2025	Pollution hotline (phone, web, app): report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.	Yes, Notified Ecology	5012 baker ave nw	seattle	98107	47.665518	-122.359410	Sewage/septage/pet waste/human waste: report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.	Other accident/spill: report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.	Not applicable: report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.	Clean-up: report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted., Other: report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.	report of sewage exiting a mh and discharging downhill on sidewalk and street then into cb that outfalls at the 14th street boat ramp. ms4 impacted.
WAR044503	3/10/2025	3/10/2025	Pollution hotline (phone, web, app): sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.	Yes, Notified Ecology	2520 westlake ave n	seattle	98109	47.642967	-122.343206	Fuel and/or vehicle related fluids: sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.	Unconfirmed, unspecified, or not identified: sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.	Not applicable: sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.	Other: sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.	Complaint, sheen did not come from local business activities or from spu outfall. no impact to or from ms4. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/11/2025	3/11/2025	Direct report to your staff: fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.	Yes, Notified Ecology	linden ave n & n 128th st	seattle	98133	47.722318	-122.348270	Fuel and/or vehicle related fluids: fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.	Other accident/spill: fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.	Not applicable: fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.	Clean-up: fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.	Complaint. fuel spill from cracked weld on outlet pipe. spill was contained to private property. spill was completely cleaned. no downstream impacts to ms4. nfa.
WAR044503	3/12/2025	3/12/2025	Pollution hotline (phone, web, app): responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.	Other accident/spill: responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.	Not applicable: responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.	Clean-up: responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.	responsible party cleaned up hydraulic spill. no impact to conveyance system in ms4. nfa.
WAR044503	3/12/2025	3/12/2025	Pollution hotline (phone, web, app): found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.	Yes, Notified Ecology	nw 85th st & 6th ave nw	seattle	98117	47.690626	-122.363328	Fuel and/or vehicle related fluids: found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.	Unconfirmed, unspecified, or not identified: found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.	Not applicable: found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.	Clean-up: found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa. Other: found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.	found gasoline in a separated catch basin. cleaned with on hand materials. no downstream ms4 impact. nfa.
WAR044503	3/13/2025	3/13/2025	Pollution hotline (phone, web, app): report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.	Yes, Notified Ecology	2520 westlake ave n	seattle	98109	47.642967	-122.343206	Fuel and/or vehicle related fluids: report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.	Unconfirmed, unspecified, or not identified: report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.	Not applicable: report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.	Referred to other agency or department: report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.	report of sheen around boat slip. some sheen found on water, checked nearby catch basins and drainage outfall, did not find any material. no ms4 involvement, referred.
WAR044503	3/14/2025	3/14/2025	Pollution hotline (phone, web, app): motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.	Yes, No Notice Required	beacon ave s / orcas st	seattle		47.551014	-122.301751	Fuel and/or vehicle related fluids: motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.	Vehicle collision: motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.	Not applicable: motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.	Clean-up: motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.	motor oil spill after auto accident reported on right of way. sdot started to clean up with oil sorb but couldn't capture oil from large puddle. did not impact ms4. cleaned up by spu spill team.
WAR044503	3/16/2025	3/16/2025	Pollution hotline (phone, web, app): report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.	Yes, Notified Ecology	1017 s snoqualmie st	seattle	98108	47.561498	-122.319586	Sewage/septage/pet waste/human waste: report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.	Other accident/spill: report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.	Not applicable: report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.	Referred to other agency or department: report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway. Other: report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.	report of sewage coming out of a drain. approximately 300 gallons of rainwater/sewage was discharged from a private side sewer. 150 gallons of diluted sewage left cb and impacted ms4/waterway.
WAR044503	3/16/2025	3/16/2025	Pollution hotline (phone, web, app): report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.	Yes, Notified Ecology	1514 sw holden st	seattle	98106	47.533956	-122.354786	Soap or cleaning chemicals: report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.	Other accident/spill: report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.	Not applicable: report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.	Clean-up: report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.	report of soapy water running down street into ms4 catch basin. catch basin was pumped out. no downstream impact.
WAR044503	3/17/2025	3/17/2025	Pollution hotline (phone, web, app): report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.	Yes, Notified Ecology	11310 lake city way ne	seattle	98125	47.710941	-122.299877	Sediment/soil: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted. Other: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.	Other: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.	Not applicable: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.	Education/technical assistance: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted. Other: report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.	report of kramer creek having turbid water. demolition work being conducted to repair ss. no permits on file and no bmps in place. extreme safety issues exist on property. ms4 impacted.
WAR044503	3/18/2025	3/18/2025	Pollution hotline (phone, web, app): report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.	Yes, Notified Ecology	2401 utah ave s	seattle	98134	47.581811	-122.335353	Fuel and/or vehicle related fluids: report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.	Intentional dumping: report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.	Not applicable: report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.	Clean-up: report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.	report of gasoline spilled due to drilled fuel tank. approximately 1 cup of gasoline found on pavement and cleaned. no ms4 / drain impact.
WAR044503	3/18/2025	3/18/2025	Pollution hotline (phone, web, app): report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.	Yes, Notified Ecology	130 s kenyon st	seattle	98108	47.533212	-122.333036	Fuel and/or vehicle related fluids: report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.	Vehicle-related business: report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.	Not applicable: report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.	Clean-up: report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.	report of 1 gallon of hydraulic fluid spilled. verified with reporting party that no drains were involved, and spill was cleaned up. no ms4 impact.
WAR044503	3/19/2025	3/19/2025	Pollution hotline (phone, web, app): customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.	Yes, Notified Ecology	5446 48th ave sw	seattle	98136	47.552627	-122.393291	Sewage/septage/pet waste/human waste: customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.	Intentional dumping: customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.	Not applicable: customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.	Clean-up: customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.	customer without toilet was dumping human waste onto an inlet in the separated system. after education, the individual will now use bags and dispose of waste into trash. neighbors will monitor.
WAR044503	3/19/2025	3/19/2025	Direct report to your staff: arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.	Yes, No Notice Required	8425 1st ave s	seattle	98108	47.527932	-122.336107	Fuel and/or vehicle related fluids: arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.	Vehicle-related business: arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.	Not applicable: arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.	Clean-up: arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.	Complaint. arrived at location and found an oil sheen in the parking lot. i cleaned with spill pads. no impact to ms4.
WAR044503	3/20/2025	3/20/2025	ERTS referral: found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.	Yes, Notified Ecology	n 115th st & meridian ave n	seattle	98133	47.712290	-122.334067	Solid waste/trash: found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.	Intentional dumping: found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.	Not applicable: found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.	Referred to other agency or department: found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.	Complaint. found no evidence of rv dumping, found area full of trash. no impact to ms4. nfa.
WAR044503	3/23/2025	3/23/2025	Pollution hotline (phone, web, app): vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.	Yes, Notified Ecology	4108 university way ne	seattle	98105	47.657215	-122.313008	Food-related oil/grease: vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.	Intentional dumping: vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa. Other: vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.	Not applicable: vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.	Clean-up: vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.	vandalism caused used cooking oil bin to fall over and leak onto pavement. spill response arrived just in time to prevent impact to cb. no downstream impact. ms4 impacted. nfa.
WAR044503	3/24/2025	3/24/2025	Pollution hotline (phone, web, app): put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.	Yes, Notified Ecology	34th ave nw & nw 75th st	seattle	98117	47.683122	-122.400422	Fuel and/or vehicle related fluids: put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.	Other accident/spill: put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.	Not applicable: put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.	Clean-up: put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.	put boom in downstream cb in attempt to capture unrecoverable sheen in curb line. unknown source. ms4 impacted but not downstream. nfa.
WAR044503	3/24/2025	3/24/2025	Direct report to your staff: garbage and other debris being illegally dumped on property.	Yes, No Notice Required	10516 lake city way ne	seattle	98125	47.705338	-122.301239	Solid waste/trash: garbage and other debris being illegally dumped on property.	Intentional dumping: garbage and other debris being illegally dumped on property.	Not applicable: garbage and other debris being illegally dumped on property.	Clean-up: garbage and other debris being illegally dumped on property. Referred to other agency or department: garbage and other debris being illegally dumped on property. Other: garbage and other debris being illegally dumped on property.	Complaint. garbage and other debris being illegally dumped on property.
WAR044503	3/24/2025	3/24/2025	Pollution hotline (phone, web, app): arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.	Yes, Notified Ecology	4217 university way ne	seattle	98105	47.659017	-122.313640	Food-related oil/grease: arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.	Other: arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.	Not applicable: arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.	Clean-up: arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa. Other: arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.	arrived to find defective container. 1 cup of used cooking oil made its way to the pavement. no drains impacted. requested hauler to replace container. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/25/2025	3/25/2025	Pollution hotline (phone, web, app): responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.	Yes, Notified Ecology	43rd ave w & w ruffner st	seattle	98199	47.652676	-122.413582	Fuel and/or vehicle related fluids: responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.	Other accident/spill: responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.	Not applicable: responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.	Clean-up: responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.	responsible party cleaned up hydraulic spill. ms4 impacted but no downstream involvement. nfa.
WAR044503	3/26/2025	3/26/2025	Pollution hotline (phone, web, app): blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.	Yes, Notified Ecology	6301 65th ave ne	seattle	98115	47.674638	-122.259544	Sewage/septage/pet waste/human waste: blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.	Other accident/spill: blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.	Not applicable: blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.	Clean-up: blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington. Referred to other agency or department: blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.	blockage in a private system caused a sewer overflow which impacted the ms4. the responsible party hired a contractor to restore function and spu implemented the beach closure procedure at the outfall to lake washington.
WAR044503	3/27/2025	3/27/2025	Pollution hotline (phone, web, app): accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.	Yes, Notified Ecology	10700 24th ave ne	seattle	98125	47.706157	-122.301995	Other: accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.	Other accident/spill: accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.	Not applicable: accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.	Clean-up: accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact. Other: accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.	accidental spill to pavement of an unknown oil from a waste collection truck during pickup. collection company hired a contractor to perform cleanup. no ms4 drain impact.
WAR044503	3/28/2025	3/28/2025	Pollution hotline (phone, web, app): vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.	Yes, Notified Ecology	13th ave sw / sw florida st	seattle	98119	47.584256	-122.352216	Fuel and/or vehicle related fluids: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall. Firefighting foam: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.	Other: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.	Not applicable: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.	Clean-up: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall. Other: vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.	vehicle fire in the row and emergency firefighting activity caused diesel fuel and other fluid impact to pavement and the ms4. spu and the responsible party's insurance coordinated follow up cleaning of pavement, the ms4, and containment measures at the outfall.
WAR044503	3/28/2025	3/28/2025	Pollution hotline (phone, web, app): self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	549 ne 126th st	seattle	98125	47.720388	-122.321451	Fuel and/or vehicle related fluids: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Vehicle-related business: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Not applicable: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Clean-up: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.
WAR044503	3/29/2025	3/29/2025	Pollution hotline (phone, web, app): spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.	Yes, Notified Ecology	910 boylston ave	seattle	98104	47.610425	-122.321145	Fuel and/or vehicle related fluids: spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor. Fuel and/or vehicle related fluids: spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.	Vehicle collision: spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.	Not applicable: spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.	Clean-up: spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.	spill of transmission and motor oil to pavement and an ms4 storm drain due to a motor vehicle accident. cleanup completed by a contractor.
WAR044503	3/29/2025	3/29/2025	Pollution hotline (phone, web, app): gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.	Yes, No Notice Required	852 rainier ave s	seattle	98144	47.594753	-122.310188	Fuel and/or vehicle related fluids: gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.	Intentional dumping: gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.	Not applicable: gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.	Clean-up: gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact. Other: gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.	gasoline spill to pavement at a fuel station due to a drilled fuel tank on a rental truck. cleanup contractor coordinated by the rental company. no ms4 drain impact.
WAR044503	3/31/2025	3/31/2025	ERTS referral: report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	3527 chelan ave sw	seattle	98106	47.571954	-122.361546	Fuel and/or vehicle related fluids: report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.	Vehicle-related business: report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.	Not applicable: report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.	Clean-up: report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.	Complaint. report of a hydraulic fluid spill to pavement due to a leaking waste collection truck. cleanup contractor coordinated by the responsible party. no ms4 drain impact.
WAR044503	4/1/2025	4/1/2025	ERTS referral: fuel station cleaned up accidental spill. no impact to ms4. nfa.	Yes, Notified Ecology	852 rainier ave s	seattle	98144	47.594753	-122.310188	Fuel and/or vehicle related fluids: fuel station cleaned up accidental spill. no impact to ms4. nfa.	Other accident/spill: fuel station cleaned up accidental spill. no impact to ms4. nfa.	Not applicable: fuel station cleaned up accidental spill. no impact to ms4. nfa.	Clean-up: fuel station cleaned up accidental spill. no impact to ms4. nfa.	Complaint. fuel station cleaned up accidental spill. no impact to ms4. nfa.
WAR044503	4/1/2025	4/1/2025	Pollution hotline (phone, web, app): report of sewage surfacing from private property and entering into row and cb. ms4 impacted.	Yes, Notified Ecology	3923 s sullivan st	seattle		0	0	Sewage/septage/pet waste/human waste: report of sewage surfacing from private property and entering into row and cb. ms4 impacted.	Other accident/spill: report of sewage surfacing from private property and entering into row and cb. ms4 impacted.	Not applicable: report of sewage surfacing from private property and entering into row and cb. ms4 impacted.	Other: report of sewage surfacing from private property and entering into row and cb. ms4 impacted.	report of sewage surfacing from private property and entering into row and cb. ms4 impacted.
WAR044503	4/1/2025	4/1/2025	Pollution hotline (phone, web, app): hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.	Yes, Notified Ecology	8333 55th ave ne	seattle	98115	47.688947	-122.269456	Fuel and/or vehicle related fluids: hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.	Vehicle-related business: hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.	Not applicable: hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.	Clean-up: hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact. Other: hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.	hydraulic fluid spill to pavement and a private storm drainage system due to a waste collection truck leak. cleanup coordinated by the responsible party. no observed downstream ms4 impact.
WAR044503	4/1/2025	4/1/2025	Pollution hotline (phone, web, app): coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.	Yes, Notified Ecology	7 s idaho st	seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.	Vehicle-related business: coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.	Not applicable: coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.	Clean-up: coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact. Other: coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.	coolant spill to pavement at a waste collection facility. cleanup completed by the responsible business. no ms4 drain impact.
WAR044503	4/2/2025	4/2/2025	Direct report to your staff: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.	Yes, Notified Ecology	n 115th st & meridian ave n	seattle	98133	47.712290	-122.334067	Sewage/septage/pet waste/human waste: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.	Other accident/spill: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa. Intentional dumping: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.	Not applicable: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.	Referred to other agency or department: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa. Other: rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.	rv was transferring waste from full tank to bucket and spilled some black water. some made it to ms4. non recoverable but non reportable to skcph. nfa.
WAR044503	4/2/2025	4/2/2025	Pollution hotline (phone, web, app): reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.	Yes, Notified Ecology	7001 seaweave ave nw	seattle	98117	47.680017	-122.405796	Fuel and/or vehicle related fluids: reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.	Unconfirmed, unspecified, or not identified: reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.	Not applicable: reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.	Referred to other agency or department: reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.	reporting party found gasoline and cleaned up. no waterbody impacts. contained to secondary permittee ms4. nfa.
WAR044503	4/3/2025	4/3/2025	Pollution hotline (phone, web, app): water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.	Yes, Notified Ecology	nw 100th st/8th ave nw	seattle	98117	47.701505	-122.366058	Sediment/soil: water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.	Other accident/spill: water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.	Not applicable: water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.	Clean-up: water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa. Other: water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.	water main break sends sediment and chlorinated water into pipers creek. ms4 impacted. structures cleaned of sediment. nfa.
WAR044503	4/3/2025	4/3/2025	Pollution hotline (phone, web, app): found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.	Yes, Notified Ecology	yale ave n / fairview ave n	seattle	98109	47.628712	-122.330917	Other: found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.	Other accident/spill: found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.	Not applicable: found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.	Clean-up: found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.	found paint in ms4. found no evidence at outfall. contractor cleaned all impacted structures. nfa.
WAR044503	4/4/2025	4/4/2025	Pollution hotline (phone, web, app): found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.	Yes, Notified Ecology	lake city way ne & ne 113th st	seattle	98125	47.710408	-122.300530	Other: found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.	Unconfirmed, unspecified, or not identified: found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.	Not applicable: found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.	Clean-up: found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc. Other: found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.	Complaint. found creek running milky. found that groundwater was contributing upstream. ms4 involved. also found defective pipes under lake city way. referred to dwrc.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	4/4/2025	4/4/2025	Direct report to your staff: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.	Yes, Notified Ecology	9211 holman rd nw	seattle	98117	47.698866	-122.372434	Sewage/septage/pet waste/human waste: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.	Other: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.	Not applicable: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.	Clean-up: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted. , Clean-up: restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.	restaurant washing food waste and degreaser into private storm drain. impacted catch basin cleaned with no down stream impact observed. business emptied the catch basin of wall washer. follow-up business inspection will be conducted.
WAR044503	4/5/2025	4/5/2025	Pollution hotline (phone, web, app): .5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.	Yes, Notified Ecology	university way ne / ne 45th st	seattle	98105	47.681288	-122.313140	Fuel and/or vehicle related fluids: .5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.	Other accident/spill: .5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.	Not applicable: .5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.	Clean-up: .5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.	.5 gallons of hydraulic oil cleaned up by spiller in ms4. nfa.
WAR044503	4/7/2025	4/7/2025	Pollution hotline (phone, web, app): tow company cleaned up accidental spill in ms4. no downstream impact. nfa.	Yes, Notified Ecology	15th ave s & mcclellan st	seattle	98144	47.578632	-122.313364	Fuel and/or vehicle related fluids: tow company cleaned up accidental spill in ms4. no downstream impact. nfa.	Vehicle-related business: tow company cleaned up accidental spill in ms4. no downstream impact. nfa. , Other accident/spill: tow company cleaned up accidental spill in ms4. no downstream impact. nfa.	Not applicable: tow company cleaned up accidental spill in ms4. no downstream impact. nfa.	Clean-up: tow company cleaned up accidental spill in ms4. no downstream impact. nfa. , Other: tow company cleaned up accidental spill in ms4. no downstream impact. nfa.	tow company cleaned up accidental spill in ms4. no downstream impact. nfa.
WAR044503	4/7/2025	4/7/2025	Pollution hotline (phone, web, app): spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.	Yes, Notified Ecology	7001 seawave ave nw	seattle	98117	47.680017	-122.405796	Fuel and/or vehicle related fluids: spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.	Other accident/spill: spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.	Not applicable: spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.	Clean-up: spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.	spiller cleaned up oil spill contained to cb. no waterbody impacts. nfa.
WAR044503	4/8/2025	4/8/2025	Pollution hotline (phone, web, app): portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.	Yes, No Notice Required	9724 rainier ave s	seattle	98118	47.515766	-122.253226	Solid waste/trash: portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa. , Sewage/septage/pet waste/human waste: portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.	Intentional dumping: portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.	Not applicable: portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.	Clean-up: portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.	portable toilet vendor will clean up burnt plastic and encapsulated waste. no impact to waterbody. nfa.
WAR044503	4/10/2025	4/10/2025	ERTS referral: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.	Yes, Notified Ecology	7201 west marginal way sw	seattle	98106	47.538222	-122.340484	Fuel and/or vehicle related fluids: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.	Other: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.	Not applicable: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.	Clean-up: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted. , Other: report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.	report of a hydraulic rod on a compactor blowing causing approximately 50 gallons of hydraulic fluid to spill into cbs, ows and onto the pavement. responsible party hired contractor for clean up. ms4 impacted.
WAR044503	4/10/2025	4/10/2025	Pollution hotline (phone, web, app): sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.	Yes, Notified Ecology	4750 45th ave sw	seattle	98116	47.559627	-122.389130	Sewage/septage/pet waste/human waste: sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.	Other accident/spill: sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.	Not applicable: sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.	Clean-up: sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures. , Other: sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.	sewage/rainwater and green dye exiting from a void in street. twenty gallons impacted a cb and an inlet. ms4 impacted. dwr cleaned row and impacted structures.
WAR044503	4/12/2025	4/12/2025	Pollution hotline (phone, web, app): report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.	Yes, No Notice Required	3832 ne 113th st	seattle	98125	47.710299	-122.286516	Fuel and/or vehicle related fluids: report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.	Vehicle-related business: report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.	Not applicable: report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.	Clean-up: report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4. , Other: report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.	report of four gallons of hydraulic fluid spilled to pavement due to mechanical problem on commercial vehicle. spill left stain. no impact to ms4.
WAR044503	4/12/2025	4/12/2025	Pollution hotline (phone, web, app): report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.	Yes, Notified Ecology	7147 18th ave sw	seattle	98106	47.537435	-122.357630	Fuel and/or vehicle related fluids: report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.	Other accident/spill: report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.	Not applicable: report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.	Clean-up: report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted. , Other: report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.	report of diesel spilled from a tank that fell from a private vehicle. ms4 impacted.
WAR044503	6/16/2025	6/16/2025	Pollution hotline (phone, web, app): dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.	Yes, Notified Ecology	1959 ne pacific st	seattle	98195	47.650343	-122.309083	Other wastewater: dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.	Other accident/spill: dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.	Not applicable: dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.	Clean-up: dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa. , Other: dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.	dirty fire suppression system water (not foam) was released into a private separated drainage system. no downstream impacts. contractor was hired to clean impacted structure. nfa.
WAR044503	4/14/2025	4/14/2025	Pollution hotline (phone, web, app): report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.	Yes, Notified Ecology	2324 bonair pl sw	seattle	98116	47.582666	-122.401084	Sewage/septage/pet waste/human waste: report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.	Other accident/spill: report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.	Not applicable: report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.	Clean-up: report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4. , Other: report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.	report of toilet paper coming out of cb. investigated and possible issues with private ss. cb goes to combined. no impact to ms4.
WAR044503	4/15/2025	4/15/2025	Pollution hotline (phone, web, app): report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.	Yes, No Notice Required	4336 s holden st	seattle	98118	47.533605	-122.277204	Fuel and/or vehicle related fluids: report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.	Vehicle-related business: report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.	Not applicable: report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.	Other: report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.	report of spill that occurred several days ago involving commercial vehicle. material is non recoverable but the streets impacted need to be swept with a mechanical sweeper. no impact to ms4.
WAR044503	4/15/2025	4/15/2025	Pollution hotline (phone, web, app): report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact	Yes, Notified Ecology	4214 university way ne	seattle	98105	47.658750	-122.312872	Food-related oil/grease: report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact	Intentional dumping: report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact	Not applicable: report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact	Clean-up: report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact. , Other: report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact	report of used cooking oil spilled in alley. arrived at location of where approximately 45 gallons of used cooking oil was spilled. ms4 impacted. spilled oil cleaned by spu spill response. no water body impact
WAR044503	4/17/2025	4/17/2025	Pollution hotline (phone, web, app): received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.	Yes, No Notice Required	3033 ne 86th st	seattle	98115	47.690745	-122.294612	Fuel and/or vehicle related fluids: received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.	Vehicle-related business: received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.	Not applicable: received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.	Clean-up: received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.	received a spill report about a hydraulic spill with no drain involvement. responsible party cleaned and disposed of the waste. no further action is necessary.
WAR044503	4/17/2025	4/17/2025	Pollution hotline (phone, web, app): received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.	Yes, Notified Ecology	west seattle bridge	seattle		47.571091	-122.345776	Fuel and/or vehicle related fluids: received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.	Vehicle-related business: received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.	Not applicable: received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.	Clean-up: received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.	received a spill report about a coolant spill from a bus. the responsible party cleaned and disposed of the waste. no further response is necessary.
WAR044503	4/17/2025	4/17/2025	Pollution hotline (phone, web, app): received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.	Yes, Notified Ecology	5135 s director st	seattle	98118	47.521740	-122.268366	Other: received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.	Unconfirmed, unspecified, or not identified: received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.	Not applicable: received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.	Other: received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.	received a spill report about a mysterious puddle over a broken sewer line. tested the puddle twice for ammonia and it came back negative both times. there was no indication of the puddle being sewage. broken sewer line is pipe assessment for repair.
WAR044503	4/15/2025	4/15/2025	Pollution hotline (phone, web, app): report of hydraulic fluid spilled onto road. no impact to ms4.	Yes, No Notice Required	4336 s holden st	seattle	98118	47.533605	-122.277204	Fuel and/or vehicle related fluids: report of hydraulic fluid spilled onto road. no impact to ms4.	Vehicle-related business: report of hydraulic fluid spilled onto road. no impact to ms4.	Not applicable: report of hydraulic fluid spilled onto road. no impact to ms4.	Clean-up: report of hydraulic fluid spilled onto road. no impact to ms4. , Other: report of hydraulic fluid spilled onto road. no impact to ms4.	Complaint. report of hydraulic fluid spilled onto road. no impact to ms4.
WAR044503	4/21/2025	4/21/2025	Pollution hotline (phone, web, app): received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.	Yes, No Notice Required	n 106th st & bagley ave n	seattle	98133	47.705932	-122.332614	Fuel and/or vehicle related fluids: received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.	Intentional dumping: received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.	Not applicable: received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.	Clean-up: received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.	received a spill report about a drilled gas tank. 2-3 gallons of gas spilled to the pavement with no drain involvement. cleaned with on hand materials, and placed boom in downstream cb for possible future sheen. no further action is necessary.
WAR044503	4/22/2025	4/22/2025	Pollution hotline (phone, web, app): received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.	Yes, No Notice Required	nw 60th st & 22nd ave nw	seattle	98107	47.672369	-122.384753	Solid waste/trash: received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.	Other: received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.	Not applicable: received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.	Referred to other agency or department: received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary. , Other: received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.	Complaint. received a report of garbage falling out of a garbage truck. referred this issue to sdot. no further action is necessary.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	4/22/2025	4/22/2025	Pollution hotline (phone, web, app): received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.	Yes, Notified Ecology	3601 2nd ave s	seattle	98134	47.570228	-122.332419	Sewage/septage/pet waste/human waste: received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.	Other accident/spill: received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.	Not applicable: received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.	Clean-up: received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system. . Other: received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.	received a report about a sewer backup. the issue was with a private side sewer system. it entered their private drainage system, but did not make it our ms4. responsible party hired a contractor to clean and cctv their system.
WAR044503	4/23/2025	4/23/2025	ERTS referral: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.	Yes, Notified Ecology	4008 42nd ave s	seattle	98118	47.567275	-122.280401	Fuel and/or vehicle related fluids: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.	Vehicle-related business: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.	Not applicable: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.	Clean-up: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes. . Referred to other agency or department: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes. . Other: report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.	Complaint. report of a vehicle in the row leaking oil to pavement. spu observed no ms4 impact, cleaned the pavement, and deployed containment. a note was left on the vehicle requesting they resolve the leak and properly dispose of wastes.
WAR044503	4/24/2025	4/24/2025	Pollution hotline (phone, web, app): report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.	Yes, Notified Ecology	1836 westlake ave n	seattle	98109	47.635732	-122.339897	Unconfirmed, unspecified, or not identified: report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.	Unconfirmed, unspecified, or not identified: report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.	Not applicable: report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.	Other: report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.	report of unrecoverable waterbody impact from paint. spu investigation noted probable impact but was unable to confirm a responsible party. no ms4 drain impact.
WAR044503	4/18/2025	4/18/2025	Direct report to your staff: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.	Yes, No Notice Required	1521 nw 50th st	seattle	98107	47.664752	-122.377426	Sediment/soil: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.	Other: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.	Not applicable: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.	Clean-up: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4. . Education/technical assistance: track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.	Complaint. track-out was reported at the stockpile company, a visible but minor amount of trackout was found while on site, and i spoke with the owner, who instructed a staff member to start sweeping it up. they said their practices were to sweep at the end of each day and when they would see excessive accumulation. the trackout did not reach the ms4.
WAR044503	4/25/2025	4/25/2025	Pollution hotline (phone, web, app): self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	12715 27th ave ne	seattle	98125	47.721601	-122.299420	Fuel and/or vehicle related fluids: self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.	Vehicle-related business: self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.	Not applicable: self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.	Clean-up: self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact. . Other: self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.	self report of a waste collection truck hydraulic fluid leak to pavement. cleanup completed by the responsible party. no ms4 drain impact.
WAR044503	4/28/2025	4/28/2025	Pollution hotline (phone, web, app): report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.	Yes, No Notice Required	3rd ave ne & ne 112th st	seattle	98125	47.709600	-122.325991	Sewage/septage/pet waste/human waste: report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.	Intentional dumping: report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.	Not applicable: report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.	Clean-up: report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact. . Other: report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.	report of sewage dumped in the row by an unknown party. spu responded and completed cleanup of the affected sidewalk pavement and planting strip with on hand supplies. no ms4 drain impact.
WAR044503	4/29/2025	4/29/2025	Pollution hotline (phone, web, app): self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.	Yes, Notified Ecology	3918 18th ave w	seattle	98119	47.655457	-122.379982	Sewage/septage/pet waste/human waste: self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.	Other accident/spill: self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.	Not applicable: self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.	Clean-up: self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact. . Other: self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.	self report of an sso from a port of seattle sanitary lift station with impact to their separated storm drainage system. port of seattle will resolve the issue and perform cleanup. no city ms4 drain impact.
WAR044503	4/30/2025	4/30/2025	ERTS referral: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.	Yes, Notified Ecology	beach dr sw & sw beach drive ter	seattle	98116	47.558453	-122.401881	Fuel and/or vehicle related fluids: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.	Vehicle collision: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.	Not applicable: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.	Clean-up: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa. . Other: transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.	Complaint. transformer oil spilled as a result of a motor vehicle accident. no drains impacted in the ms4. spill was cleaned up. nfa.
WAR044503	4/30/2025	4/30/2025	Pollution hotline (phone, web, app): spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.	Yes, Notified Ecology	1631 15th ave w	seattle	98119	47.634485	-122.376616	Fuel and/or vehicle related fluids: spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.	Other accident/spill: spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.	Not applicable: spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.	Clean-up: spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit. . Education/technical assistance: spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.	spu spill received report of motor oil spill at private property. spu responded, no drains impacted; spill contained to private property. erts issued as pollutant was motor oil. no drains or ms4 impacted. property manager cleaned affected area of oil with granular and small sweeper unit.
WAR044503	5/1/2025	5/1/2025	Pollution hotline (phone, web, app): plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.	Yes, Notified Ecology	5914 sw stevens st	seattle	98116	47.577901	-122.408845	Sewage/septage/pet waste/human waste: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.	Other accident/spill: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.	Not applicable: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.	Clean-up: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa. . Education/technical assistance: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa. . Other: plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.	plumber put sewage in the right of way. plumber cleaned sewage. no downstream impact in ms4. nfa.
WAR044503	5/4/2025	5/4/2025	Pollution hotline (phone, web, app): small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.	Yes, Notified Ecology	ne 145th st/lake city way ne	seattle	98125	47.733754	-122.292497	Fuel and/or vehicle related fluids: small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.	Vehicle collision: small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.	Not applicable: small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.	Clean-up: small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.	small spill of motor oil after a vehicle accident made it to a catch basin in city of shoreline but that connects to system that flows south into city of seattle. cleaned with pads and boom, and granular used on pavement. no oil left the cb - no impact to ms4.
WAR044503	5/4/2025	5/4/2025	Pollution hotline (phone, web, app): sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).	Yes, Notified Ecology	4516 2nd ave nw	seattle	98107	47.662021	-122.358707	Sewage/septage/pet waste/human waste: sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).	Other accident/spill: sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).	Not applicable: sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).	Clean-up: sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw). . Other: sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).	sewage seeping to sidewalk from private side sewer and flowing down curb into an inlet and then cb on separated system. spu plugged cb, pumped it out and put a monitor on it until owner fixes side sewer. spu side sewer program staff to follow up with owner. unknown how much sewage entered spu stormwater mainline (ms4). this system has an outfall to ship canal (14th ave nw).
WAR044503	5/7/2025	5/7/2025	Pollution hotline (phone, web, app): report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.	Yes, Notified Ecology	1800 westlake ave n	seattle	98109	47.635021	-122.339866	Fuel and/or vehicle related fluids: report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.	Unconfirmed, unspecified, or not identified: report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.	Not applicable: report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.	Other: report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.	report of sheen in lake union. spu found sheen, likely diesel, near a dock but was unrecoverable and did not find the source. checked drainage outfalls in area and no flow, sheen or odor observed.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	5/7/2025	5/7/2025	Staff referral: inspected 11 drainage structures, found one with signs of cooking oil and sewage. applied pads to soak up oil, and submitted work order for spu crews to clean the cb with a vacuum truck.	Yes, Notified Ecology	9400 myers way s	seattle	98108	47.518671	-122.333283	Food-related oil/grease: inspected 11 drainage structures, found one with signs of cooking oil and sewage. applied pads to soak up oil, and submitted work order for spu crews to clean the cb with a vacuum truck.	Intentional dumping: inspected 11 drainage structures, found one with signs of cooking oil and sewage.	Not applicable: inspected 11 drainage structures, found one with signs of cooking oil and sewage.	Clean-up: inspected 11 drainage structures, found one with signs of cooking oil and sewage. applied pads to soak up oil, and submitted work order for spu crews to clean the cb with a vacuum truck.	Complaint. inspected 11 drainage structures, found one with signs of cooking oil and sewage.
WAR044503	5/7/2025	5/7/2025	Pollution hotline (phone, web, app): report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.	Yes, Notified Ecology	nesbit ave n / n 90th st	seattle	98104	47.694178	-122.33499	Sewage/septage/pet waste/human waste: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.	Construction activity: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb. , Other accident/spill: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.	Not applicable: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.	Clean-up: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb. , Other: report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.	report of sewage surfacing from a maintenance hole. no surfacing sewage was observed on site, but an ms4 catch basin tested positive for ammonia. confirmed that there was no downstream ms4 impact, resolved mainline blockage, and cleaned cb.
WAR044503	5/9/2025	5/9/2025	Pollution hotline (phone, web, app): report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.	Yes, Notified Ecology	2461 4th ave s	seattle	98134	47.580162	-122.329589	Food-related oil/grease: report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts. , Soap or cleaning chemicals: report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.	Intentional dumping: report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.	Not applicable: report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.	Clean-up: report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.	report of cooking oil being dumped in a catch basin. food truck wastewater was found in an ms4 catch basin. catch basin was washed down and pumped out; no downstream impacts.
WAR044503	5/11/2025	5/11/2025	Pollution hotline (phone, web, app): report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.	Yes, Notified Ecology	madison st & 7th ave	seattle	98104	47.607478	-122.329592	Fuel and/or vehicle related fluids: report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.	Vehicle-related business: report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.	Not applicable: report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.	Clean-up: report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.	report of .5 gallons of hydraulic fluid spilled on road. spiller cleaned with peat moss, no drains impacted. no ms4 impact.
WAR044503	5/13/2025	5/13/2025	Pollution hotline (phone, web, app): report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.	Yes, Notified Ecology	1501 21st ave s	seattle	98144	47.589368	-122.305655	Firefighting foam: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.	Vehicle collision: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa. , Other: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.	Not applicable: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.	Clean-up: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa. , Other: report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.	report of fire fighting foam use in i-90 tunnel. fire fighting foam found in downstream water quality structure. reporting party cleaned from containment vault to the incident location. no evidence of foam in the ms4. nfa.
WAR044503	5/13/2025	5/13/2025	Staff referral: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.	Yes, Notified Ecology	phinney ave n & n 54th st	seattle	98103	47.667751	-122.354426	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.	Other accident/spill: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa. , Intentional dumping: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa. , Intentional dumping: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.	Not applicable: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.	Clean-up: planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.	Complaint. planned rv remediation. inspected 12 structures and found one in the ms4 with sewage. we created to clean. nfa.
WAR044503	5/13/2025	5/13/2025	ERTS referral: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.	Yes, Notified Ecology	825 eastlake ave e	seattle	98109	47.626671	-122.329661	Fuel and/or vehicle related fluids: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.	Vehicle collision: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa. , Other accident/spill: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.	Not applicable: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.	Clean-up: motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.	Complaint. motor vehicle accident caused automotive fluids to spill onto pavement. business cleaned up spill on their property. no downstream impact. nfa.
WAR044503	5/13/2025	5/13/2025	ERTS referral: sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.	Yes, Notified Ecology	4536 delridge ave sw	seattle	98106	47.561764	-122.362687	Sewage/septage/pet waste/human waste: sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.	Other accident/spill: sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.	Not applicable: sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.	Other: sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.	Complaint. sso contained to private property. spu to monitor to make sure sewage will not leave property. no impact to ms4. nfa.
WAR044503	5/15/2025	5/15/2025	Pollution hotline (phone, web, app): spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.	Yes, Notified Ecology	rainier ave s/s cloverdale st	seattle	98118	47.526170	-122.269994	Fuel and/or vehicle related fluids: spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.	Vehicle-related business: spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.	Not applicable: spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.	Clean-up: spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.	spill of heating oil to pavement. no impact to ms4. responsible party hired a contractor to assist sdot with roadway cleaning.
WAR044503	5/16/2025	5/16/2025	Pollution hotline (phone, web, app): spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.	Yes, No Notice Required	400 s 96th st	seattle	98108	47.517651	-122.328920	Other: spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.	Intentional dumping: spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.	Not applicable: spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.	Referred to other agency or department: spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue. , Other: spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.	spu spills received report of illegal dumping of chemicals at parcel outside of city of seattle. referred to dept of ecology via phone call. doe advised king county drainage of issue.
WAR044503	5/19/2025	5/19/2025	ERTS referral: mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.	Yes, Notified Ecology	7861 62nd ave ne	seattle	98115	47.688832	-122.264956	Soap or cleaning chemicals: mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.	Unconfirmed, unspecified, or not identified: mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.	Not applicable: mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.	Referred to other agency or department: mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.	Complaint. mop water was found in the citys ms4. the spill was cleaned with a vector. no impacts to the outfall were observed. nfa.
WAR044503	5/17/2025	5/17/2025	Pollution hotline (phone, web, app): spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.	Yes, No Notice Required	5209 shilshole ave nw	seattle	98107	47.664262	-122.383409	Fuel and/or vehicle related fluids: spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.	Unconfirmed, unspecified, or not identified: spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.	Not applicable: spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.	Other: spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.	spu spill response dispatched to coast guard report of sheen on ship canal. spu checked area spu outfalls. no evidence that sheen came from spu assets. as coast guard was aware of issue, no erts submitted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	5/19/2025	5/19/2025	Pollution hotline (phone, web, app): spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.	Yes, No Notice Required	602 e harrison st	seattle	98102	47.622140	-122.323762	Sewage/septage/pet waste/human waste: spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.	Intentional dumping: spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.	Not applicable: spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.	Clean-up: spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.	spu spill response received a report and photo of dog waste near a stormwater drainage inlet. spu spills dispatched, generated a work order to clean the dog waste as well as the drainage inlet and d/s cb. erts submitted, no direct evidence that ms4 was impacted by spill, but generated erts as waste was accessible to public.
WAR044503	4/8/2025	4/8/2025	Direct report to your staff: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.	Yes, No Notice Required	2609 s mclellan st	seattle	98144	47.578048	-122.299028	Solid waste/trash: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.	Other: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.	Not applicable: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.	Clean-up: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection. , Education/technical assistance: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection. , Other: observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.	Complaint. observation of garbage littering private property and migrating to the public right of way. inspector conducted a business inspection.
WAR044503	5/19/2025	5/19/2025	Pollution hotline (phone, web, app): spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.	Yes, No Notice Required	942 e harrison st	seattle		0	0	Food-related oil/grease: spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.	Intentional dumping: spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.	Not applicable: spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.	Other: spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.	Complaint. spu and sdot responded to this issue evening of 5.16.25. row grease spill. spoke with rp, he advised he submitted find it fix it, friday day. rp was advised of spu and sdot actions. rp was provided orc spill number for future more acute issues. essentially spill was a duplicate report.
WAR044503	5/20/2025	5/20/2025	Pollution hotline (phone, web, app): spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.	Yes, No Notice Required	1412 ne 40th st.	seattle		0	0	Fuel and/or vehicle related fluids: spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.	Other accident/spill: spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.	Not applicable: spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.	Clean-up: spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.	spu spills received self report of coolant spill. rp cleaned spill. no drains impacted.
WAR044503	5/21/2025	5/21/2025	Pollution hotline (phone, web, app): spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.	Yes, Notified Ecology	933 lake washington blvd s	seattle	98144	47.593596	-122.289591	Sewage/septage/pet waste/human waste: spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.	Other accident/spill: spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.	Not applicable: spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.	Clean-up: spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.	spu spill response dispatched to report of sewage in the row. found sewage had issued from private clean out, likely cause failed private side sewer. a nearby cb had been impacted with minimal amount of sewage. downstream drainage line showed non-detect for ammonia. row and impacted cb were cleaned. erts filed. skcph notified. the spu side sewer group is actively working with owners of failed side sewer. no further follow-up required.
WAR044503	5/21/2025	5/21/2025	Pollution hotline (phone, web, app): waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.	Yes, No Notice Required	747 broadway	seattle	98122	47.608841	-122.321938	Fuel and/or vehicle related fluids: waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.	Other accident/spill: waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.	Not applicable: waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.	Clean-up: waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.	waste hauler spilled 1 cup of hydraulic fluid. hauler cleaned spill. no drains impacted. photos provided.
WAR044503	5/11/2025	5/11/2025	Pollution hotline (phone, web, app): spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.	Yes, No Notice Required	dexter ave n & galer st	seattle	98109	47.632299	-122.342292	Fuel and/or vehicle related fluids: spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.	Unconfirmed, unspecified, or not identified: spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.	Not applicable: spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.	Referred to other agency or department: spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts. , Other: spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.	Complaint. spu spill response dispatched to report of product sheening on row. no odor. drainage combined. referred to sdot as they were arriving on site. no erts.
WAR044503	5/21/2025	5/21/2025	Pollution hotline (phone, web, app): customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.	Yes, No Notice Required	3605 ne 155th st	lake forest park	98155	47.740624	-122.289726	Unconfirmed, unspecified, or not identified: customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.	Unconfirmed, unspecified, or not identified: customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.	Not applicable: customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.	Referred to other agency or department: customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.	customer reporting gel like substance in grass. location is out of city jurisdiction referred customer to correct jurisdiction. no impact to city drains or ms4.
WAR044503	5/22/2025	5/22/2025	Pollution hotline (phone, web, app): report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.	Yes, Notified Ecology	1450 s donovan st	seattle	98108	47.525804	-122.313020	Sewage/septage/pet waste/human waste: report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.	Other accident/spill: report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.	Not applicable: report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.	Clean-up: report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.	report of sewage surfacing out of cleanout located in easement. site is being investigated to find source; bmp's implemented. no sewage impact to drains or ms4.
WAR044503	5/22/2025	5/22/2025	Pollution hotline (phone, web, app): spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.	Yes, Notified Ecology	1617 sw lander st	seattle	98134	47.580208	-122.357105	Fuel and/or vehicle related fluids: spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.	Other accident/spill: spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.	Not applicable: spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.	Clean-up: spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.	spiller cleaned diesel from pavement at fuel station. no downstream impact. nfa.
WAR044503	5/22/2025	5/22/2025	Pollution hotline (phone, web, app): spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.	Yes, Notified Ecology	2113 n 107th st	seattle	98133	47.706652	-122.333348	Fuel and/or vehicle related fluids: spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.	Vehicle collision: spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.	Not applicable: spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.	Clean-up: spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.	spill of transformer oil to pavement and catch basin due to motor vehicle accident. spill cleaned up by hired contractor. no downstream impacts.
WAR044503	5/22/2025	5/22/2025	Staff referral: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.	Yes, Notified Ecology	utah ave s & s stacy st	seattle	98134	47.581894	-122.335135	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.	Vehicle-related business: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa. , Intentional dumping: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa. , Intentional dumping: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.	Not applicable: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.	Clean-up: planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.	Complaint. planned rv remediation. inspected 14 structures and found one impacted by sewage in the ms4. wo created to clean. nfa.
WAR044503	5/22/2025	5/22/2025	Pollution hotline (phone, web, app): process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.	Yes, Notified Ecology	4850 beacon ave s	seattle	98108	47.559418	-122.303929	Other wastewater: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.	Other: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.	Not applicable: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.	Clean-up: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa. , Education/technical assistance: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa. , Enforcement: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa. , Other: process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.	process wastewater from fish market dumped. cb cleaned. overflow rerouted. nfa.
WAR044503	5/22/2025	5/22/2025	Pollution hotline (phone, web, app): spiller cleaned up. no downstream impact. nfa.	Yes, Notified Ecology	ne 90th st / 1st ave ne	seattle		47.694084	-122.328424	Fuel and/or vehicle related fluids: spiller cleaned up. no downstream impact. nfa.	Other accident/spill: spiller cleaned up. no downstream impact. nfa.	Not applicable: spiller cleaned up. no downstream impact. nfa.	Clean-up: spiller cleaned up. no downstream impact. nfa.	spiller cleaned up. no downstream impact. nfa.
WAR044503	5/23/2025	5/23/2025	Pollution hotline (phone, web, app): spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.	Yes, Notified Ecology	3913 18th ave w	seattle		46.807974	-127.390431	Fuel and/or vehicle related fluids: spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.	Vehicle-related business: spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.	Not applicable: spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.	Clean-up: spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.	spill of oil from a leaking motor vehicle to pavement and blind sump. no water or ms4 impact. spiller cleaned up the spill.
WAR044503	5/23/2025	5/23/2025	Pollution hotline (phone, web, app): dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.	Yes, Notified Ecology	5151 s kenyon st	seattle		46.807974	-127.390431	Fuel and/or vehicle related fluids: dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.	Vehicle-related business: dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.	Not applicable: dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.	Clean-up: dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response. , nfa_spills. Other: dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.	dumping of motor oil to pavement and separated stormdrain system. no responsible party identified. impact to a single catch basin with no outlet trap. no oil detected downstream or in lake washington. spill cleaned up by spu spill response.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	5/26/2025	5/26/2025	Pollution hotline (phone, web, app): report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.	Yes, No Notice Required	760 sw cloverdale st	seattle	98106	0	0	Sewage/septage/pet waste/human waste: report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.	Other accident/spill: report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.	Not applicable: report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.	Education/technical assistance: report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.	Complaint. report of rv leaking blackwater. spiller cleaned up spill, and rv was no longer leaking.
WAR044503	5/28/2025	5/28/2025	Pollution hotline (phone, web, app): delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.	Yes, No Notice Required	14377 midvale ave n	seattle	98116	46.807974	-127.390430	Fuel and/or vehicle related fluids: delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.	Other: delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.	Not applicable: delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.	Other: delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.	Complaint. delayed report of sheen emitting from an automotive repair operation on private property. no pollutants were found, though the parking lot is stained from presumably many oil/vehicle fluid leaks. followed up with a business inspection at the adjacent auto parts supplier, as a tipped over oil container was found and cleaned up by the store manager and me.
WAR044503	5/28/2025	5/28/2025	Pollution hotline (phone, web, app): report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.	Yes, Notified Ecology	3039 63rd ave sw	seattle	98116	47.577107	-122.413653	Sediment/soil: report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.	Other: report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.	Not applicable: report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.	Clean-up: report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.	report of property owner draining swimming pool. property owner found to be discharging wash water from pool cleaning including algae, dirt, paint chips, and residual pool water to the right of way and an spu catch basin. spu crews activated to clean the impacted structure. notice of violation issued to the responsible party.
WAR044503	5/29/2025	5/29/2025	Pollution hotline (phone, web, app): it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.	Yes, Notified Ecology	10409 aurora ave n	seattle	98133	47.704617	-122.345067	Sewage/septage/pet waste/human waste: it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.	Intentional dumping: it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.	Not applicable: it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.	Clean-up: it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.	it was reported that a private drainage structure was being used as a toilet. site was investigated and concerns were verified. spill response started structure cleaning, and property management hired a contractor to perform a complete cleaning.
WAR044503	5/30/2025	5/30/2025	Pollution hotline (phone, web, app): spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.	Yes, Notified Ecology	4727 california ave sw	seattle	98116	47.560441	-122.387113	Food-related oil/grease: spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.	Unconfirmed, unspecified, or not identified: spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.	Not applicable: spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.	Clean-up: spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.	spill of used cooking oil to alleyway likely from a restaurants used oil container. cleaned using absorbent and referred to sdot for sweeper. no impacts to drainage or ms4.
WAR044503	5/30/2025	5/30/2025	Pollution hotline (phone, web, app): spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control	Yes, Notified Ecology	10th ave/e pike st	seattle	98122	47.614114	-122.319447	Food-related oil/grease: spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control	Unconfirmed, unspecified, or not identified: spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control	Not applicable: spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control	Other: spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control	spill of used cooking oil to ms4 drainage, asset #964545. cleaned by spu crews. no obvious source. area inspections of restaurants refer to wastewater source control
WAR044503	5/30/2025	5/30/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.	Yes, No Notice Required	3651 s edmunds st	seattle	0	0	nfa_spills	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.	Vehicle-related business: spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.	Not applicable: spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.	nfa_spills Other: spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.	spill of hydraulic oil to pavement from a construction vehicle. no drainage impacts and spill cleaned up by spiller.
WAR044503	5/30/2025	5/30/2025	Direct report to your staff: used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.	Yes, No Notice Required	10th ave/e pike st	seattle	98122	47.614114	-122.319447	Food-related oil/grease: used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.	Other: used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.	Not applicable: used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.	Clean-up: used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.	used cooking oil containers over full and leaking small amount of oil to pavement. used oil hauler contacted to empty the totes and cleanup the area. no drainage impact.
WAR044503	6/2/2025	6/2/2025	Pollution hotline (phone, web, app): coolant was cleaned up in ms4. no downstream impact. nfa.	Yes, Notified Ecology	e pine st / nagle pl	seattle	0	0	0	Fuel and/or vehicle related fluids: coolant was cleaned up in ms4. no downstream impact. nfa.	Other accident/spill: coolant was cleaned up in ms4. no downstream impact. nfa.	Not applicable: coolant was cleaned up in ms4. no downstream impact. nfa.	Clean-up: coolant was cleaned up in ms4. no downstream impact. nfa.	coolant was cleaned up in ms4. no downstream impact. nfa.
WAR044503	6/3/2025	6/3/2025	Pollution hotline (phone, web, app): spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.	Yes, No Notice Required	9500 myers way s	seattle	98108	47.517733	-122.331827	Fuel and/or vehicle related fluids: spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.	Vehicle-related business: spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.	Not applicable: spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.	Referred to other agency or department: spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.	spill of motor oil from a vehicle towing a sfd trailer. oil went to about 100 yards of pavement but no impact to drains or ms4. spu requested sdot assistance and they cleaned the street using absorbent and sweeper.
WAR044503	6/3/2025	6/3/2025	Pollution hotline (phone, web, app): spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.	Yes, Notified Ecology	4337 university way ne	seattle	98105	47.660926	-122.313600	Food-related oil/grease: spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.	Other: spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.	Not applicable: spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.	Clean-up: spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.	spiller cleaned used cooking oil spill. pavement only in ms4. no downstream impact. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	6/4/2025	6/4/2025	Pollution hotline (phone, web, app): spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.	Yes, Notified Ecology	2207 fairview ave	seattle	98102	47.638586	-122.330068	Other: spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.	Other accident/spill: spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.	Not applicable: spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.	Clean-up: spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.	spu pump station crew reported two house boats had disconnected pipes allowing lake water to go to pump station. on guidance of skcph, two beach closure signs were placed. pipes associated with house boats were repaired. signage was removed seven days after completion of repair as per skcph directive.
WAR044503	6/4/2025	6/4/2025	Pollution hotline (phone, web, app): report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.	Yes, Notified Ecology	3100 w commodore way	seattle	98199	47.664011	-122.397023	Fuel and/or vehicle related fluids: report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.	Unconfirmed, unspecified, or not identified: report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.	Not applicable: report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.	Referred to other agency or department: report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.	report of an unknown sheen on lake union at salmon bay. spu investigation found no ms4 impact or source. referred to ecology spills who was onsite.
WAR044503	6/4/2025	6/4/2025	Pollution hotline (phone, web, app): wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.	Yes, Notified Ecology	5146 25th ave ne	seattle	98105	47.667757	-122.300390	Solid waste/trash: wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.	Other: wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.	Not applicable: wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.	Clean-up: wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up. Clean-up: wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.	wastewater overflow due to a failed pump system which caused impact to the row and ms4. spu cleaned the row and an ms4 drain. responsible party hired a contractor to repair the pump and perform clean-up.
WAR044503	6/5/2025	6/5/2025	Pollution hotline (phone, web, app): surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.	Yes, Notified Ecology	5126 s kenyon st	seattle	98118	47.531883	-122.268755	Sewage/septage/pet waste/human waste: surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.	Unconfirmed, unspecified, or not identified: surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.	Not applicable: surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.	Clean-up: surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program. Education/technical assistance: surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.	surfacing sewage from a private side sewer problem. impact to the row pavement and planting strip. no ms4 drain impact. referred internally to the side sewer program.
WAR044503	6/6/2025	6/6/2025	Direct report to your staff: direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.	Yes, No Notice Required	215 10th ave e	seattle	98102	47.620559	-122.319855	Other: direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.	Other accident/spill: direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.	Not applicable: direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.	Education/technical assistance: direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.	direct report of damage to a private irrigation system from a waste collection truck. repair coordinated by the responsible party. no ms4 drain impact.
WAR044503	6/7/2025	6/7/2025	Pollution hotline (phone, web, app): report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.	Yes, Notified Ecology	1013 ne 45th st	seattle	98105	47.660986	-122.317067	Fuel and/or vehicle related fluids: report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.	Other accident/spill: report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.	Not applicable: report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.	Clean-up: report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.	report of a gasoline spill at a fuel station during fuel delivery. cleanup of the impact to private property pavement and a private separated storm drain coordinated by the responsible party. no ms4 impact.
WAR044503	6/9/2025	6/9/2025	Pollution hotline (phone, web, app): passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.	Yes, Notified Ecology	4835 west marginal way sw	seattle	98106	47.558321	-122.352398	Other: passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.	Other accident/spill: passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.	Not applicable: passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.	Clean-up: passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.	passenger vehicle fire in the row. emergency fire fighting activity caused foam and unknown material impact to pavement and an ms4 drain. spu coordinated follow up cleaning.
WAR044503	6/9/2025	6/9/2025	Pollution hotline (phone, web, app): emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.	Yes, Notified Ecology	14th ave nw / nw 54th st	seattle	98107	47.667897	-122.373676	Firefighting foam: emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.	Other: emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.	Not applicable: emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.	Clean-up: emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.	emergency fire fighting activity at an electrical substation caused foam impact to pavement and an ms4 cb. spu coordinated follow up storm drain cleaning.
WAR044503	6/10/2025	6/10/2025	Pollution hotline (phone, web, app): report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.	Yes, No Notice Required	6718 rainier ave s	seattle	98118	47.541905	-122.272130	Other: report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.	Unconfirmed, unspecified, or not identified: report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.	Not applicable: report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.	Other: report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.	report of algae in the row. spu investigation found algae is due to private drainage flow through a curb weep hole to pavement. no evidence of a prohibited discharge to the ms4.
WAR044503	6/12/2025	6/12/2025	Pollution hotline (phone, web, app): spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.	Yes, No Notice Required	12300 riviera pl ne	seattle	98125	47.717492	-122.278657	Other: spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.	Unconfirmed, unspecified, or not identified: spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.	Not applicable: spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.	Education/technical assistance: spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.	Complaint. spu spill response received report of muddy liquid near sidewalk. inspectors are familiar with site as it has iron bacteria associated with it. spu advised reporting party that iron bacteria is naturally occurring, especially in their area.
WAR044503	6/12/2025	6/12/2025	Pollution hotline (phone, web, app): spiller cleaned oil spilled to pavement only. no drains impacted. nfa.	Yes, Notified Ecology	blakely pl nw & nw blakely ct	seattle	98177	47.722410	-122.373315	Fuel and/or vehicle related fluids: spiller cleaned oil spilled to pavement only. no drains impacted. nfa.	Other accident/spill: spiller cleaned oil spilled to pavement only. no drains impacted. nfa.	Not applicable: spiller cleaned oil spilled to pavement only. no drains impacted. nfa.	Clean-up: spiller cleaned oil spilled to pavement only. no drains impacted. nfa.	spiller cleaned oil spilled to pavement only. no drains impacted. nfa.
WAR044503	6/13/2025	6/13/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.	Vehicle-related business: spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.	Not applicable: spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.	Clean-up: spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.	spill of hydraulic oil to pavement on a private facility with an industrial stormwater permit. no impacts to private or public drainage systems or water of the state. spilled material cleaned up by facility staff and a hired contractor.
WAR044503	6/14/2025	6/14/2025	Pollution hotline (phone, web, app): spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.	Yes, No Notice Required	7 s idaho st	seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.	Other accident/spill: spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.	Not applicable: spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.	Clean-up: spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.	spu spill response received a report regarding hydraulic release at waste hauler yard. hauler cleaned spill. spu did not submit erts, as no drains impacted.
WAR044503	6/18/2025	6/16/2025	MS4 inspection or screening: routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Yes, Notified Ecology	nw 130th st / 12th ave nw	seattle	98119	47.723312	-122.371741	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Not applicable: routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Other: routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Complaint. routine dry weather screening identified trigger level surfactant concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.
WAR044503	6/17/2025	6/17/2025	Pollution hotline (phone, web, app): material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.	Yes, Notified Ecology	3508 s holly st	seattle	98118	47.542721	-122.288240	Food-related oil/grease: material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.	Intentional dumping: material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.	Not applicable: material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.	Enforcement: material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.	Complaint. material dumped into ditch and culvert and was not recoverable. no downstream impact. educated customer on how to properly dispose of waste.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	6/17/2025	6/17/2025	Pollution hotline (phone, web, app): paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.	Yes, Notified Ecology	28th ave nw & nw 59th st	seattle	98107	47.671649	-122.392880	Other: paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.	Intentional dumping: paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.	Not applicable: paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.	Other: paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.	paint poured into a cb. the paint did not impact the water in the cb but did impact the grating and walls of cb. ms4 impacted.
WAR044503	6/17/2025	6/17/2025	Pollution hotline (phone, web, app): dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.	Yes, Notified Ecology	n 85th st & greenwood ave n	seattle	98103	47.690594	-122.355312	Sediment/soil: dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.	Other accident/spill: dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.	Not applicable: dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.	Other: dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.	dry concrete mix spilled to road. no drains impacted. crews cleaned surface. nfa.
WAR044503	6/17/2025	6/17/2025	Pollution hotline (phone, web, app): spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.	Yes, No Notice Required	belmont ave e / e harrison st	seattle	98102	47.621988	-122.324034	Fuel and/or vehicle related fluids: spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.	Other accident/spill: spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.	Not applicable: spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.	Clean-up: spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.	spu spill responders dispatched to report of kitty litter with chemical. found partially cleaned gasoline spill. finalized clean-up. no drains impacted. no recoverable product. no erts, given small volume of spill.
WAR044503	6/21/2025	6/21/2025	Pollution hotline (phone, web, app): spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.	Yes, Notified Ecology	702 spring st	seattle	98104	47.608503	-122.330014	Fuel and/or vehicle related fluids: spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.	Vehicle collision: spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.	Not applicable: spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.	Clean-up: spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.	spill of gasoline to pavement and catch basin from motor vehicle accident. gasoline contained to basin by outlet trap. cleaned up by spu spill response; did not reach the receiving waterbody, as it was fully contained in one catch basin.
WAR044503	6/22/2025	6/22/2025	Pollution hotline (phone, web, app): a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.	Yes, No Notice Required	9050 seaward park ave s	seattle	98118	47.521697	-122.263918	Unconfirmed, unspecified, or not identified: a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.	Other: a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.	Not applicable: a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.	Other: a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.	Complaint. a pleasure boat (17ft motorboat) went down in lake washington, adjacent to seaward park. an ecological protection group called it in procedurally and took the lead on the investigation and potential cleanup. no mobilization was needed from spu.
WAR044503	6/23/2025	6/23/2025	Pollution hotline (phone, web, app): a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.	Yes, Notified Ecology	900 sw holden st	seattle	98106	47.534449	-122.347755	Firefighting foam: a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.	Other: a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.	Not applicable: a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.	Other: a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.	a foodtruck fire led to firefighters administering foam. this got into the adjacent catch basin. we arranged for a contractor to vactor this catch basin out.
WAR044503	6/23/2025	6/23/2025	Staff referral: accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.	Yes, No Notice Required	11th ave sw & sw webster st	seattle	98106	47.535499	-122.349248	Sewage/septage/pet waste/human waste: accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.	Other accident/spill: accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.	Not applicable: accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.	Clean-up: accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.	accidental spill of approximately 10 gallons of rv sewage. used granular absorbent, bleach, water, and a vacuum truck to clean up. no ms4 impact.
WAR044503	6/23/2025	6/23/2025	ERTS referral: spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.	Yes, Notified Ecology	4017 whitman ave n	seattle	98103	47.656054	-122.346420	Other: spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.	Intentional dumping: spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.	Not applicable: spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.	Clean-up: spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.	spill of roofing tar to alley pavement. no drain or water impacts. no source identified. cleaned by spu spills.
WAR044503	6/24/2025	6/24/2025	Pollution hotline (phone, web, app): spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.	Yes, No Notice Required	4500 west marginal way sw	seattle	98106	47.563193	-122.350679	Fuel and/or vehicle related fluids: spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.	Other accident/spill: spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.	Not applicable: spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.	Clean-up: spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.	spu system maintenance rehab crew had an excavator which ruptured a hydraulic line at a job site. rehab lead worker used granular absorbent and spill pads to clean up the bulk oil, and washed the equipment at a wash rack with simple green and a pressure washer for final cleaning. spill response team provided additional spill supplies and provided technical guidance for best cleanup method. no impact to ms4.
WAR044503	6/24/2025	6/24/2025	Pollution hotline (phone, web, app): minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.	Yes, Notified Ecology	6016 39th ave ne	seattle	98115	47.672706	-122.285578	Fuel and/or vehicle related fluids: minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.	Other: minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.	Not applicable: minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.	Clean-up: minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.	minor hydraulic fluid leak in a garbage truck route, from a line coming apart. the driver reported it to their hq, who mobilized to conduct spill response. did not reach any drains, and did not require spu mobilization.
WAR044503	6/25/2025	6/25/2025	Pollution hotline (phone, web, app): report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.	Yes, No Notice Required	28700 se 252nd pl	ravensdale	98038	47.376039	-121.961887	Fuel and/or vehicle related fluids: report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.	Intentional dumping: report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.	Not applicable: report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.	Clean-up: report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.	report of approximately two gallons of oil spilled from illegal dumping of oil containers. no impact to ms4.
WAR044503	6/27/2025	6/27/2025	Pollution hotline (phone, web, app): report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.	Yes, No Notice Required	1909 s charles st	seattle	98144	47.594302	-122.306838	Other: report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.	Vehicle-related business: report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.	Not applicable: report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.	Clean-up: report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.	report of commercial vehicle experiencing a mechanical failure. three gallons of hydraulic fluid spilled into row. contractor hired for clean up. no impact to ms4.
WAR044503	6/28/2025	6/28/2025	Pollution hotline (phone, web, app): report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.	Yes, No Notice Required	1501 e olive way	seattle	98122	47.617933	-122.325860	Food-related oil/grease: report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.	Intentional dumping: report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.	Not applicable: report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.	Clean-up: report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.	report of grease tote knocked over spilling approximately 10 gallons of grease into the street and sidewalk. sdot assisted me with cleanup by using a sweeper. no impact to ms4.
WAR044503	7/3/2025	7/3/2025	Pollution hotline (phone, web, app): approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.	Yes, Notified Ecology	w stevens way ne & george washington ln ne	seattle	98195	47.655226	-122.311417	Soap or cleaning chemicals: approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.	Construction activity: approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.	Not applicable: approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.	Clean-up: approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.	approx. 5 gallons of construction wash water discharge to road and private catch basin. spill cleaned via vactor truck- no impacts to ms4.
WAR044503	7/7/2025	7/7/2025	MS4 inspection or screening: routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Yes, Notified Ecology	32nd ave s & s dearborn st	seattle	98144	47.595743	-122.291498	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Not applicable: routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Other: routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Complaint. routine dry weather screening identified trigger level fecal sample results in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.
WAR044503	7/4/2025	7/4/2025	Pollution hotline (phone, web, app): 5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.	Yes, Notified Ecology	4111 sw admiral way	seattle	98116	47.581003	-122.384452	Fuel and/or vehicle related fluids: 5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.	Vehicle-related business: 5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.	Not applicable: 5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.	Clean-up: 5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.	5 gallon spill of antifreeze to pavement and private catch basin. pavement and catch basin cleaned; no impact to ms4.
WAR044503	7/5/2025	7/5/2025	Pollution hotline (phone, web, app): 2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.	Yes, Notified Ecology	802 newton st	seattle	98109	47.636745	-122.341165	Fuel and/or vehicle related fluids: 2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.	Vehicle-related business: 2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.	Not applicable: 2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.	Clean-up: 2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.	2 gallons of antifreeze spill to pavement; spill cleaned. no impact to ms4.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/7/2025	7/7/2025	MS4 inspection or screening: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Yes, Notified Ecology	nw 130th st / 12th ave nw	seattle	98119	47.723312	-122.371741	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Not applicable: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Other: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Complaint. routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.
WAR044503	7/7/2025	7/7/2025	MS4 inspection or screening: routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.	Yes, Notified Ecology	nw blue ridge dr / nw neptune pl	shoreline	98177	47.742629	-122.370491	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.	Not applicable: routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.	Other: routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.	Complaint. routine dry weather screening identified trigger level potassium results in the ms4. source tracing efforts found no prohibited discharge.
WAR044503	7/7/2025	7/7/2025	ERTS referral: release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.	Yes, Notified Ecology	1445 s cloverdale st	seattle	98108	47.526203	-122.313089	Sewage/septage/pet waste/human waste: release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.	Other accident/spill: release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.	Not applicable: release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.	Clean-up: release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.	release of sewage from a shared side sewer into an ms gis bioswale. no downstream impacts, no water body impacts, and no stormwater drainage impacts. spu dww work crews are monitoring the discharge and the spu side sewer group is working with the property owners on a repair.
WAR044503	7/12/2025	7/12/2025	Pollution hotline (phone, web, app): report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.	Yes, Notified Ecology	2525 14th ave s	seattle	98144	47.580234	-122.315178	Sewage/septage/pet waste/human waste: report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.	Other accident/spill: report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.	Not applicable: report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.	Clean-up: report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.	report of unknown liquid with odor seeping from sidewalk into grass. liquid tested positive for ammonia; no issue found with mainline. property management hired contractor to inspect and fix private side sewer. no impact to ms4 drainage structures.
WAR044503	7/14/2025	7/14/2025	MS4 inspection or screening: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Yes, Notified Ecology	500 lakeside ave s,	seattle	0	0	0	Other: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Not applicable: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Other: routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.	Complaint. routine dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue was not ongoing and a source was not able to be identified.
WAR044503	7/17/2025	7/17/2025	Pollution hotline (phone, web, app): received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.	Yes, No Notice Required	ne 117th st/1st ave	seattle	0	0	0	Solid waste/trash: received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.	Other accident/spill: received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.	Not applicable: received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.	Referred to other agency or department: received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.	Complaint. received a report about trash falling out of a trash truck. site visit concluded there was no drain impact and minimal trash. i referred this to sdot to sweep up some of the gross organic material. no further action is necessary.
WAR044503	7/18/2025	7/18/2025	Pollution hotline (phone, web, app): received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.	Yes, Notified Ecology	deltbridge way sw & sw orchard st	seattle	98106	47.537953	-122.361102	Firefighting foam: received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.	Other: received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.	Not applicable: received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.	Other: received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.	received a report of fire fighting foam being used near a creek. site visit concluded it was a direct discharge into the creek. per guidance from ecology we decided to let the foam dissipate naturally and come back to do an encampment restoration cleanup.
WAR044503	7/19/2025	7/19/2025	Pollution hotline (phone, web, app): received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.	Yes, Notified Ecology	4500 lake washington blvd s	seattle	98118	47.563515	-122.268956	Other: received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.	Construction activity: received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.	Not applicable: received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.	Other: received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.	received a report of chlorinated water making to the lake washington due to a broken water service line. it sounded like it was a direct discharge with no ms4 impact. water got shut off and plans for a repair were underway. no further action is necessary.
WAR044503	7/21/2025	7/21/2025	Pollution hotline (phone, web, app): received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.	Yes, No Notice Required	4519 beach dr sw	seattle	98116	47.562479	-122.405982	Other: received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.	Unconfirmed, unspecified, or not identified: received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.	Not applicable: received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.	Referred to other agency or department: received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.	received a report of a possible oil barrel floating in the sound. the barrel is around 150-200 feet out in the water. i referred this to ecology, and they sent it to the coast guard. no further action is necessary.
WAR044503	7/22/2025	7/22/2025	Pollution hotline (phone, web, app): received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.	Yes, No Notice Required	s jackson st & 25th ave s	seattle	98144	47.599267	-122.299894	Fuel and/or vehicle related fluids: received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.	Vehicle collision: received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.	Not applicable: received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.	Clean-up: received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.	received a spill report about a car accident with automotive fluids heading towards a drain. site visit concluded there was no drain impact. we helped sdot sweep up the fluids. no further action is necessary.
WAR044503	7/22/2025	7/22/2025	MS4 inspection or screening	Yes, Notified Ecology	205 ne northlake way	seattle	98105	47.653652	-122.325991	Unconfirmed, unspecified, or not identified	Unconfirmed, unspecified, or not identified	Not applicable	Other, Other	Complaint.
WAR044503	7/23/2025	7/23/2025	ERTS referral: transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.	Yes, Notified Ecology	lake washington blvd / e jefferson st	seattle	98105	47.605914	-122.283617	Fuel and/or vehicle related fluids: transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.	Other accident/spill: transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.	Not applicable: transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.	Referred to other agency or department: transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.	Complaint. transformer oil was cleaned up. less than 1 ppm pcb. no drain impact. nfa.
WAR044503	7/22/2025	7/22/2025	Pollution hotline (phone, web, app): received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.	Yes, Notified Ecology	s mount baker blvd & s mcclellan st	seattle	98144	47.578339	-122.288737	Other: received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.	Other accident/spill: received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.	Not applicable: received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.	Clean-up: received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.	received a report about a yellow powder outside of a school with no drain impact. after narrowing it down to what we think it is, we determined it was safe to clean with on hand materials. swept it up and bagged it for proper disposal.
WAR044503	7/23/2025	7/23/2025	Pollution hotline (phone, web, app): parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.	Yes, Notified Ecology	2234 lake washington blvd s	seattle	98144	47.583105	-122.287347	Firefighting foam: parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.	Other: parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.	Not applicable: parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.	Referred to other agency or department: parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.	parks cleaned up firefighting foam and debris from building fire. lake washington impacted by foam. no impact to ms4.
WAR044503	7/24/2025	7/24/2025	Pollution hotline (phone, web, app): spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.	Yes, Notified Ecology	faunterroy ave sw & sw spokane st	seattle	98126	47.571949	-122.373486	Fuel and/or vehicle related fluids: spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.	Other accident/spill: spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.	Not applicable: spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.	Clean-up: spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.	spiller cleaned transformer oil spill from pavement only spill using a full pallet of granular and a sweeper. no drain impact. nfa.
WAR044503	7/24/2025	7/24/2025	ERTS referral: anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.	Yes, Notified Ecology	i-5 hwy/ne northlake way	seattle	98105	47.653770	-122.322529	Other: anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.	Other accident/spill: anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.	Not applicable: anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.	Other: anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.	Complaint. anonymous report of slurry from i5 repair work made its way to a drain. referred to responsible party. nfa.
WAR044503	7/25/2025	7/25/2025	ERTS referral: spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.	Yes, Notified Ecology	7303 8th ave s	seattle	98108	47.536751	-122.323977	Fuel and/or vehicle related fluids: spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.	Other accident/spill: spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.	Not applicable: spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.	Clean-up: spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.	spill was cleaned up by responsible party. pavement only. no impact to drains. nfa.
WAR044503	7/27/2025	7/27/2025	Direct report to your staff: contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.	Yes, Notified Ecology	1800 s weller st	seattle	98144	47.597742	-122.306605	Fuel and/or vehicle related fluids: contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.	Intentional dumping: contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.	Not applicable: contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.	Clean-up: contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.	contractor cleaned up diesel spill from vandalism. private drain with trap impacted but no downstream involvement in sanitary line no impact to ms4. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/27/2025	7/27/2025	Direct report to your staff: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.	Yes, Notified Ecology	41st ave sw / sw edmunds st	seattle		47.559313	-122.384199	Fuel and/or vehicle related fluids: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.	Other accident/spill: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.	Not applicable: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.	Clean-up: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa., Other: spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.	spill was cleaned up by contractor. coolant did not leave the private parking lot and did not enter any drains. no impact to ms4. nfa.
WAR044503	7/28/2025	7/28/2025	Pollution hotline (phone, web, app): spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.	Yes, No Notice Required	n 130th st/stone ave	seattle	98133	47.723209	-122.342290	Fuel and/or vehicle related fluids: spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.	Intentional dumping: spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.	Not applicable: spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.	Clean-up: spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.	spill of motor oil to pavement right of way. no responsible party identified. no impact to ms4 or waters of the state. cleaned by spu spills.
WAR044503	7/28/2025	7/28/2025	Direct report to your staff: fill station on private dock was overfilled. company cleaned spill and is looking at root cause. no impact to ms4. nfa.	Yes, No Notice Required	1801 16th ave sw	seattle	98134	47.586026	-122.353148	Fuel and/or vehicle related fluids: fill station on private dock was overfilled. company cleaned spill and is looking at root cause. no impact to ms4. nfa.	Other accident/spill: fill station on private dock was overfilled. company cleaned spill and is looking at root cause. no impact to ms4. nfa.	Not applicable: fill station on private dock was overfilled. company cleaned spill and is looking at root cause. no impact to ms4. nfa.	Other: fill station on private dock was overfilled. company cleaned spill and is looking at root cause.	Complaint. fill station on private dock was overfilled. company cleaned spill and is looking at root cause. no impact to ms4. nfa.
WAR044503	7/31/2025	7/31/2025	ERTS referral: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.	Yes, Notified Ecology	2700 w hayes st	seattle	98199	47.634469	-122.391734	Sewage/septage/pet waste/human waste: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.	Other accident/spill: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.	Not applicable: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.	Clean-up: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck. no impact to ms4., Education/technical assistance: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck. no impact to ms4., Referred to other agency or department: erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.	erts report of 100 gallons of sewage in the row caused by a broken/blocked side sewer. spu dwrc crews investigated and cleaned up the sewage with a vac truck.
WAR044503	8/1/2025	8/1/2025	Pollution hotline (phone, web, app): small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.	Yes, No Notice Required	1st ave nw & nw 58th st	seattle	98107	47.670645	-122.357727	Fuel and/or vehicle related fluids: small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.	Other accident/spill: small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.	Not applicable: small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.	Clean-up: small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.	small spill of coolant to pavement only. reporting party did cleanup. unknown cause. did not enter drains. no impact to ms4.
WAR044503	8/1/2025	8/1/2025	Pollution hotline (phone, web, app): vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.	Yes, No Notice Required	2701 alaskan way	seattle	98121	47.613998	-122.353758	Fuel and/or vehicle related fluids: vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.	Other: vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.	Not applicable: vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.	Clean-up: vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water. Other: vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.	vehicle fire at port of seattle property. trench drain, roadway and elliot bay impacted. port of seattle crew on site for land cleanup. nrc notified for water.
WAR044503	8/3/2025	8/3/2025	Pollution hotline (phone, web, app): spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.	Yes, Notified Ecology	6301 35th ave sw	seattle	98126	47.546337	-122.376826	Fuel and/or vehicle related fluids: spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.	Vehicle-related business: spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.	Not applicable: spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.	Clean-up: spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.	spill of antifreeze to a private catch-basin at a car wash business. unknown how spill occurred. private cb is connected to spu drainage system and found evidence that a small amount of antifreeze had entered spu mainline (ms4). spu used adsorbent in mainline and also partially emptied the cb to prevent further discharge. business owner completed cleanup a few days later.
WAR044503	8/5/2025	8/5/2025	Pollution hotline (phone, web, app): customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.	Yes, No Notice Required	5126 s kenyon st	seattle	98118	47.531883	-122.268755	Sewage/septage/pet waste/human waste: customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.	Other accident/spill: customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.	Not applicable: customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.	Clean-up: customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.	customer reported sewage on the sidewalk. spill response and side sewer program already aware of site from an earlier complaint. property owner has been issued an enforcement notice requiring discharge to stop and for unpermitted plumbing work to either be connected to side sewer or permanently capped. spu crews have site under a monitor wo and are preventing any sewage from entering spu drainage system. no impact to ms4 related to this report.
WAR044503	8/5/2025	8/5/2025	Staff referral: cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.	Yes, Notified Ecology	6th ave s / s snoqualmie st	seattle	98108	47.561975	-122.326699	Food-related oil/grease: cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.	Intentional dumping: cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.	Not applicable: cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.	Clean-up: cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.	cooking oil found in spu catch basin following removal of encampment. used adsorbent boom to remove majority of oil and then requested pumping of cb by crews. no evidence that oil left cb.
WAR044503	8/5/2025	8/5/2025	Pollution hotline (phone, web, app): report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.	Yes, No Notice Required	utah ave s / s holgate st	seattle	98134	47.585794	-122.336101	Other: report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.	Intentional dumping: report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.	Not applicable: report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.	Other: report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.	report of four bags of sewage next to dumpster. the bags are leaking onto the gravel pavement. referred to unified care team. no impact to ms4.
WAR044503	8/7/2025	8/7/2025	Pollution hotline (phone, web, app): report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.	Yes, Notified Ecology	8612 ravenna ave ne	seattle	98115	47.691545	-122.301907	Other wastewater: report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.	Construction activity: report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.	Not applicable: report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.	Referred to other agency or department: report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.	report of plume in a creek with an adjacent construction site led to investigation. conducted a dye test at the construction site location where water was being pumped to, and it was found in the ditch running to the creek within ten minutes. referred to sdci, but the reported pollution was unrecoverable.
WAR044503	8/7/2025	8/7/2025	Staff referral: planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.	Yes, Notified Ecology	6th ave s / s snoqualmie st	seattle	98108	47.561975	-122.326699	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.	Intentional dumping: planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.	Not applicable: planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.	Clean-up: planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.	Complaint. planned rv remediation. inspected 42 structures. 2 impacted by sewage. ms4 impacted. no downstream impacts observed. all impacted structures have been cleaned.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	8/8/2025	8/8/2025	Pollution hotline (phone, web, app): a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.	Yes, No Notice Required	1000 madison st	seattle	98104	47.609135	-122.326104	Fuel and/or vehicle related fluids: a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.	Vehicle-related business: a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.	Not applicable: a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.	Clean-up: a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.	a report was received of approximately two gallons of diesel spilled onto the pavement at the intersection of madison street and boren avenue due to a bus breakdown. a supervisor responded promptly and applied absorbent material, and a sweeper was dispatched to complete the cleanup. no impacts to the ms4 or nearby waterbodies were observed or reported; spu spill response crew did not mobilize.
WAR044503	8/9/2025	8/9/2025	Pollution hotline (phone, web, app): mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.	Yes, No Notice Required	10th ave/e pike st	seattle	98122	47.614114	-122.319447	Fuel and/or vehicle related fluids: mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.	Unconfirmed, unspecified, or not identified: mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.	Not applicable: mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.	Clean-up: mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.	mobilized to a gasoline spill from an unknown source which sdot had cleaned up some of, beyond what was under a car; no waterbody was affected, but the gasoline reached one drain: fea_key - 8,264,644. granular absorbant was already in place a car parked on top of the cleanup location when we were grabbing materials, so we circled back in the morning, swept up all the absorbent, and shoveled out the catch basin, adding more pads to the cb and cleaning/removing them at that time.
WAR044503	8/10/2025	8/10/2025	Pollution hotline (phone, web, app): vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.	Yes, No Notice Required	2629 sw andover st	seattle	98126	47.567967	-122.367123	Fuel and/or vehicle related fluids: vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.	Intentional dumping: vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.	Not applicable: vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.	Clean-up: vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.	vandals drilled the gas tank of a jeep in a private parking garage, and employees found it while it was still spilling and put a bucket out to catch the flow. they had no spill kit on hand, so spu crews provided them with additional supplies for cleanup. no drains were impacted, no ms4 or waterbodies affected.
WAR044503	8/11/2025	8/11/2025	Pollution hotline (phone, web, app): a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.	Yes, No Notice Required	1141 broadway ct	seattle	98122	47.612482	-122.320291	Fuel and/or vehicle related fluids: a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.	Vehicle-related business: a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.	Not applicable: a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.	Clean-up: a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.	a cup of hydraulic fluid was observed spilling from a garbage truck by the driver. they performed spill response and reporting. no ms4 or waterbody was impacted.
WAR044503	8/11/2025	8/11/2025	Pollution hotline (phone, web, app): motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.	Yes, No Notice Required	7721 12th ave sw	seattle	98106	47.533353	-122.350846	Fuel and/or vehicle related fluids: motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.	Intentional dumping: motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.	Not applicable: motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.	Clean-up: motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.	motor vehicle which had been vandalized leaked some time in the past, and motor oil was dry on arrival. spill was concentrated around the car, with no impact to drains. with rain expected this week, we put granular absorbents down on the staining areas and put a sock in the closest drain.
WAR044503	8/12/2025	8/12/2025	Pollution hotline (phone, web, app): a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.	Yes, No Notice Required	5237 25th ave sw	seattle	98106	47.553873	-122.364605	Sewage/septage/pet waste/human waste: a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.	Intentional dumping: a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.	Not applicable: a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.	Referred to other agency or department: a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.	Complaint. a private telephone pole contracting responder left cones on the site of the bagged sewage which was dumped. we mobilized to check the drains and verify no impact to drains or ms4. referred to the sdot incident response crew to remove the bag of human feces.
WAR044503	8/15/2025	8/15/2025	Pollution hotline (phone, web, app): duplicate inspection please refer to inspection 168468	Yes, No Notice Required	35th ave sw and sw graham st	seattle	0	0		Sediment/soil: duplicate inspection please refer to inspection 168468	Other: duplicate inspection please refer to inspection 168468	Not applicable: duplicate inspection please refer to inspection 168468	Other: duplicate inspection please refer to inspection 168468	Complaint. duplicate inspection please refer to inspection 168468
WAR044503	8/15/2025	8/15/2025	Pollution hotline (phone, web, app): report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.	Yes, Notified Ecology	6301 35th ave sw	seattle	98126	47.546337	-122.376826	Other wastewater: report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.	Other: report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.	Not applicable: report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.	Other: report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.	Complaint. report of a business dumping wastewater and sediment generated from cleaning the private drains at their site into the public alley separated drains and the drains on the neighboring property. case referred to king county industrial waste and spu stormwater source control for a follow-up business inspection.
WAR044503	8/15/2025	8/15/2025	Pollution hotline (phone, web, app): received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.	Yes, No Notice Required	2360 43rd ave e	seattle	98112	47.640708	-122.276133	Other: received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.	Unconfirmed, unspecified, or not identified: received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.	Not applicable: received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.	Other: received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.	Complaint. received a report about a white sudsy substance in lake washington. during my site visit, i was not able to locate the white substance. i did check the drains in the upstream parking lot and saw no evidence of a spill. no further actions are necessary.
WAR044503	8/18/2025	8/18/2025	Pollution hotline (phone, web, app): received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.	Yes, Notified Ecology	w barrett st & 43rd ave w	seattle	98199	47.646798	-122.411964	Fuel and/or vehicle related fluids: received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.	Vehicle-related business: received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.	Not applicable: received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.	Clean-up: received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.	received a spill report about a small coolant spill with no drain impact. responsible party cleaned the material and sent me pictures. no further actions are necessary.
WAR044503	8/18/2025	8/18/2025	ERTS referral: received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.	Yes, Notified Ecology	920 n 137th st	seattle	98133	47.729117	-122.346784	Other: received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.	Unconfirmed, unspecified, or not identified: received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.	Not applicable: received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.	Education/technical assistance: received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.	Complaint. received a report about a spigot attached to a business discharging turbid looking water. during my site visit it was confirmed to be tap water from how their plumbing is designed. i spoke with an employee about de-chlor tabs and not allowing chlorinated water to enter the drainage system. no further actions are necessary.
WAR044503	8/18/2025	8/18/2025	Pollution hotline (phone, web, app): received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.	Yes, No Notice Required	ne 130th st & 30th ave ne	seattle	98125	47.722898	-122.296369	Fuel and/or vehicle related fluids: received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.	Vehicle-related business: received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.	Not applicable: received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.	Clean-up: received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.	received a spill report about a hydraulic oil spill that entered a drain. responsible party hired contractors to wash the pavement and clean out the drain. pictures were sent to me. no further actions are necessary.
WAR044503	8/19/2025	8/19/2025	Pollution hotline (phone, web, app): received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.	Yes, Notified Ecology	ne northgate way & 3rd ave ne	seattle	98125	47.708610	-122.325965	Fuel and/or vehicle related fluids: received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.	Intentional dumping: received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.	Not applicable: received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.	Clean-up: received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.	received a spill report of around 30-40 gallons of mineral oil from a transformer got released to the pavement due to vandalism. responsible party took care of the cleanup and reporting. no drain impact, and no further actions are necessary.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	8/19/2025	8/19/2025	ERTS referral: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.	Yes, Notified Ecology	s weller st & 20th pl s	seattle	98144	47.597477	-122.304865	Food-related oil/grease: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.	Other accident/spill: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa., Other: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.	Not applicable: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.	Clean-up: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa., Clean-up: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa., Education/technical assistance: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa., Enforcement: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa., Other: hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.	Complaint. hood washing activity impacted the ms4. no downstream impacts. company cleaned cb and jetted lines. nfa.
WAR044503	8/20/2025	8/20/2025	Pollution hotline (phone, web, app): received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.	Yes, Notified Ecology	alaskan wy s / s dearborn st	seattle	98134	47.576938	-122.336943	Fuel and/or vehicle related fluids: received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.	Vehicle-related business: received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.	Not applicable: received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.	Clean-up: received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary., Other: received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.	received a report about a small coolant spill with no drain involvement. responsible party took care of the cleanup. site visit confirmed it had been cleaned with no ms4 impact. no further actions are necessary.
WAR044503	8/20/2025	8/20/2025	Pollution hotline (phone, web, app): a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.	Yes, Notified Ecology	nw leary way & 15th ave nw	seattle	98107	47.663662	-122.376331	Other: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.	Vehicle-related business: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.	Not applicable: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.	Clean-up: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party., Clean-up: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party., Other: a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.	a report was received of a coolant spill from a bus that entered a storm drain at 15th avenue nw and leary way nw. a vactor truck was dispatched to clean the affected drain and check the downstream drain for potential impacts. the ms4 was impacted (one catch basin), but no waterbody was affected, with everything facilitated by the responsible party.
WAR044503	8/20/2025	8/20/2025	Pollution hotline (phone, web, app): a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.	Yes, Notified Ecology	2344 shoreland dr s	seattle	98144	47.581744	-122.286060	Sewage/septage/pet waste/human waste: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.	Other accident/spill: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.	Not applicable: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.	Clean-up: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage., Referred to other agency or department: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage., Other: a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.	a report was received which was ultimately determined to be an offset 8" sanitary sewer mainline causing sewage to surface near a roadway adjacent to lake washington. dye testing confirmed flow to two catch basins, after which 24/7 monitoring and containment were established, beach closure signs were posted, and the offset was repaired by the responsible party. the ms4 and lake washington were impacted by approximately 1,250 gallons of sewage.
WAR044503	8/20/2025	8/20/2025	Pollution hotline (phone, web, app): spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.	Yes, Notified Ecology	1617 sw lander st	seattle	98134	47.582744	-122.357599	Fuel and/or vehicle related fluids: spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.	Intentional dumping: spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.	Not applicable: spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.	Clean-up: spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.	spu spill response dispatched to report of coolant spill to pavement and cb. property owner cleaned cb and pavement. outfall pipe to cb was dry, no evidence left cb. erts submitted.
WAR044503	8/21/2025	8/21/2025	Pollution hotline (phone, web, app): spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.	Yes, Notified Ecology	3201 sw avalon way	seattle	98126	47.564435	-122.372359	Sewage/septage/pet waste/human waste: spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.	Other accident/spill: spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.	Not applicable: spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.	Education/technical assistance: spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.	spu spill response and wastewater source control dispatched to private side sewer issue impacting the ms4 and longfellow creek. beach closure signs were placed in public areas along the creek. a private contractor jetted private side sewer line, improving flow in the line and eliminating sewage discharge to the creek.
WAR044503	8/21/2025	8/21/2025	Pollution hotline (phone, web, app): source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.	Yes, Notified Ecology	1744 nw market st	seattle	98107	47.668941	-122.380911	Food-related oil/grease: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.	Other accident/spill: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.	Not applicable: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.	Clean-up: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only., Education/technical assistance: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only., Other: source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.	source traced to restaurant. manager assisted responder in cleanup. downstream drains not impacted. pavement only.
WAR044503	8/21/2025	8/21/2025	Pollution hotline (phone, web, app): spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.	Yes, No Notice Required	7549 24th ave sw	seattle	98106	47.534071	-122.363557	Sewage/septage/pet waste/human waste: spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.	Other accident/spill: spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.	Not applicable: spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.	Clean-up: spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.	spu spill response dispatch to side sewer issue flowing to curb line and public drainage inlet. inlet is tied to ms4. sewage was contained to inlet and downstream cb. no evidence that sewage left cb. spu field crews cleaned catch basin and inlet.
WAR044503	8/22/2025	8/22/2025	Pollution hotline (phone, web, app): spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.	Yes, No Notice Required	6033 42nd ave sw	seattle	98136	47.547531	-122.386107	Solid waste/trash: spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.	Other accident/spill: spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.	Not applicable: spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.	Clean-up: spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.	spu spill response dispatch to report of garbage in alley. spu spills cleaned garbage with on hand materials. no drains impacted. no erts filed.
WAR044503	8/22/2025	8/22/2025	Pollution hotline (phone, web, app): business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.	Yes, Notified Ecology	7208 east green lake dr n	seattle	98115	47.680594	-122.325807	Food-related oil/grease: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed., Other wastewater: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.	Other: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.	Not applicable: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.	Clean-up: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed., Education/technical assistance: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed., Enforcement: business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.	Complaint. business was washing mats in the alley. business corrected practice and cleaned affected structure. ms4 impacted but no downstream impacts observed.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	8/25/2025	8/25/2025	Direct report to your staff: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.	Yes, Notified Ecology	ne northgate way/roosevelt way	seattle	98125	47.708559	-122.317863	Food-related oil/grease: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.	Intentional dumping: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.	Not applicable: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.	Clean-up: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted., Clean-up: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted., Enforcement: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted., Other: closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.	Complaint. closed lot impacted by unlicensed food stand. property owner to better secure lot and clean impacted private structure. no downstream impacts observed. ms4 impacted.
WAR044503	8/19/2025	8/19/2025	MS4 inspection or screening: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.	Yes, Notified Ecology	3670 east marginal way s	seattle	98134	47.568947	-122.337757	Sewage/septage/pet waste/human waste: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.	Other accident/spill: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.	Not applicable: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.	Clean-up: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup., Other: routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.	Complaint. routine dry weather screening identified trigger level fecal and ammonia sample results in the ms4 determined to be from an inoperable private side sewer impacting the onsite drainage system and eventually the ms4. responsible party referred internally to the business inspection process to restore side sewer function and complete cleanup.
WAR044503	8/26/2025	8/26/2025	Pollution hotline (phone, web, app): spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed	Yes, Notified Ecology	6415 32nd ave nw	seattle	98107	47.675532	-122.398543	Food-related oil/grease: spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed	Other accident/spill: spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed	Not applicable: spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed	Clean-up: spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed	spu spill response dispatched to self report of waste hauler spilling 10 gallons of cooking grease to alley. no drains impacted. waste hauler hired contractor who cleaned the affected alley and private property. erts filed
WAR044503	8/27/2025	8/27/2025	ERTS referral: spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.	Yes, No Notice Required	916 w raye st	seattle	98119	47.643341	-122.369644	Fuel and/or vehicle related fluids: spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.	Other accident/spill: spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.	Not applicable: spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.	Clean-up: spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.	spu spills received report of local waste hauler spilling 3-4 cups of oil. hauler cleaned spill and provided photos. no drains impacted. no erts filed by spu, given quantity of release.
WAR044503	9/1/2025	9/1/2025	Pollution hotline (phone, web, app): home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.	Yes, Notified Ecology	4202 dayton ave n	seattle	0	0	0	Other: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.	Construction activity: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.	Not applicable: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.	Clean-up: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa., Education/technical assistance: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa., Education/technical assistance: home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.	home construction project spilled onto street. homeowner corrected and cleaned spill. no downstream impact to ms4. nfa.
WAR044503	9/2/2025	9/2/2025	Pollution hotline (phone, web, app): motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.	Yes, Notified Ecology	15th ave s / s grand st	seattle	47.587002	-122.313538		Fuel and/or vehicle related fluids: motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.	Vehicle collision: motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.	Not applicable: motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.	Clean-up: motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.	motor vehicle accident caused automotive fluids including oil to spill onto bike lane. bike lane was swept and absorbent boom was placed into catch basin with trap. ms4 impacted but no downstream impact.
WAR044503	9/2/2025	9/2/2025	Pollution hotline (phone, web, app): home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.	Yes, Notified Ecology	2000 nw market st	seattle	98107	47.668938	-122.382425	Fuel and/or vehicle related fluids: home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.	Intentional dumping: home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.	Not applicable: home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.	Clean-up: home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen., Education/technical assistance: home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.	home heating oil tank in alley was vandalized. ms4 impacted. alley was swept. no downstream impact was detected. outfall had no sheen.
WAR044503	9/3/2025	9/3/2025	Pollution hotline (phone, web, app): hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.	Yes, Notified Ecology	7303 8th ave s	seattle	98108	47.536751	-122.323977	Fuel and/or vehicle related fluids: hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.	Other accident/spill: hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.	Not applicable: hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.	Clean-up: hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.	hydraulic spill on private property that is a direct discharger. spill was cleaned. no impact to ms4. nfa.
WAR044503	9/3/2025	9/3/2025	Pollution hotline (phone, web, app): small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.	Yes, Notified Ecology	10th ave sw / sw henderson st	seattle	47.522818	-122.348011		Fuel and/or vehicle related fluids: small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.	Other accident/spill: small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.	Not applicable: small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.	Enforcement: small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue., Other: small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.	Complaint. small oil leak on garbage truck. unrecoverable spill. letter sent to company to fix issue.
WAR044503	9/4/2025	9/4/2025	Pollution hotline (phone, web, app): investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.	Yes, Notified Ecology	13530 linden ave n	seattle	98133	47.728409	-122.346914	Sewage/septage/pet waste/human waste: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.	Other accident/spill: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.	Not applicable: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.	Clean-up: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out., Education/technical assistance: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out., Education/technical assistance: investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.	investigated sewage spill and found a trench drain overflowing with toilet paper-laden liquid. found three adjacent manholes overflow with sewage, including a drainage vault and a sanitary line. no spu ms4 affected; compelled apartment complex to call in a vector crew to pump out, and then returned to pump more out.
WAR044503	9/4/2025	9/4/2025	Pollution hotline (phone, web, app): a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.	Yes, No Notice Required	1222 harbor ave sw	seattle	98116	47.592432	-122.382121	Fuel and/or vehicle related fluids: a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.	Vehicle collision: a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.	Not applicable: a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.	Referred to other agency or department: a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.	a report was received of a sunken boat at a launch site releasing gasoline into the water. response was managed by parks, the coast guard, and ecology, including plans to float and pump the vessel before dive operations. the ms4 was not impacted, but a waterbody was affected.
WAR044503	9/4/2025	9/4/2025	Pollution hotline (phone, web, app): a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.	Yes, No Notice Required	16th ave s / s dakota st	seattle	98108	47.567221	-122.311553	Fuel and/or vehicle related fluids: a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.	Vehicle-related business: a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.	Not applicable: a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.	Clean-up: a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted., Other: a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.	a report was received of approximately three gallons of coolant spilled at 15th avenue south and south dakota street. the reporting party stated they completed the cleanup and confirmed no material reached any drains. the ms4 was not impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	9/5/2025	9/5/2025	Pollution hotline (phone, web, app): a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.	Vehicle-related business: a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.	Not applicable: a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.	Other: a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.	a report was received of an estimated two-gallon motor oil spill from a trailer due to engine failure. spill pads were placed, and a cleanup contractor was called to complete the response. the ms4 was not impacted.
WAR044503	9/5/2025	9/5/2025	Staff referral: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.	Yes, Notified Ecology	diagonal ave s / s spokane st	seattle	0	0	0	Food-related oil/grease: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot. . Solid waste/trash: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot. . Sewage/septage/pet waste/human waste: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.	Intentional dumping: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.	Not applicable: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.	Referred to other agency or department: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot. . Other: planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.	Complaint. planned rv remediation. inspected 5 structures. 1 polluted by sewage, oil and needles. impacted ms4. referred to wsdot.
WAR044503	9/11/2025	9/11/2025	Pollution hotline (phone, web, app): report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.	Yes, No Notice Required	1924 bonair dr sw	seattle	98116	47.585918	-122.395704	Other: report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.	Vehicle-related business: report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.	Not applicable: report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.	Other: report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.	report of wm yard waste truck leaking hydraulic fluid on private property on private road. no impact to ms4.
WAR044503	9/11/2025	9/11/2025	Pollution hotline (phone, web, app): hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.	Yes, Notified Ecology	1st ave ne & ne 137th st	seattle	98125	47.728197	-122.328881	Fuel and/or vehicle related fluids: hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.	Other accident/spill: hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.	Not applicable: hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.	Clean-up: hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa. Other: hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.	hydraulic fluid spill was cleaned up in the separated system. no downstream impacts in ditch and culvert system. nfa.
WAR044503	9/8/2025	9/8/2025	Direct report to your staff: track out occurring into row. no impact to ms4.	Yes, No Notice Required	n 107th st & stone ave n	seattle	98133	47.706885	-122.342046	Sediment/soil: track out occurring into row. no impact to ms4.	Other accident/spill: track out occurring into row. no impact to ms4.	Not applicable: track out occurring into row. no impact to ms4.	Clean-up: track out occurring into row. no impact to ms4. . Other: track out occurring into row. no impact to ms4.	Complaint. track out occurring into row. no impact to ms4.
WAR044503	9/12/2025	9/12/2025	Pollution hotline (phone, web, app): coolant was cleaned in the ms4. pavement only spill. nfa.	Yes, Notified Ecology	ne 41st st & 42nd ave ne	seattle	98105	47.658415	-122.282762	Fuel and/or vehicle related fluids: coolant was cleaned in the ms4. pavement only spill. nfa.	Vehicle collision: coolant was cleaned in the ms4. pavement only spill. nfa.	Not applicable: coolant was cleaned in the ms4. pavement only spill. nfa.	Referred to other agency or department: coolant was cleaned in the ms4. pavement only spill. nfa.	coolant was cleaned in the ms4. pavement only spill. nfa.
WAR044503	9/12/2025	9/12/2025	Pollution hotline (phone, web, app): uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.	Yes, No Notice Required	3919 18th ave w	seattle	98119	47.655611	-122.380643	Other: uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.	Construction activity: uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.	Not applicable: uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.	Other: uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.	uncontaminated groundwater sent to cb with an insert that went into the ship canal. permissible discharge per 22.0802.030b. nfa.
WAR044503	9/16/2025	9/16/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.	Yes, Notified Ecology	6528 32nd ave ne	seattle	98115	47.676456	-122.292765	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.	Vehicle-related business: spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.	Not applicable: spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.	Clean-up: spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.	spill of hydraulic oil to pavement from a garbage truck. no drain or water impacts. responsible party cleaned up the spill.
WAR044503	9/16/2025	9/16/2025	Pollution hotline (phone, web, app): spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Other wastewater: spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.	Other accident/spill: spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.	Not applicable: spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.	Clean-up: spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.	spill of process wastewater with alkaline ph from a temporary wastewater holding and pre-treatment system. contamination of private stormwater detention and treatment system with no flow offsite to public drainage system, right of way, or waters of the state. facility repaired and cleaned both the wastewater and stormwater treatment systems.
WAR044503	9/16/2025	9/16/2025	Pollution hotline (phone, web, app): sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.	Yes, No Notice Required	7th ave s / s oregon st	seattle	98104	47.563053	-122.324090	Sewage/septage/pet waste/human waste: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.	Intentional dumping: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.	Not applicable: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.	Clean-up: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program. . Educational/technical assistance: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program. . Referred to other agency or department: sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.	sewage found to be leaking from an rv. no drain or water impacts. right of way pavement cleaned by spu. case referred to rv wastewater program.
WAR044503	9/17/2025	9/17/2025	Pollution hotline (phone, web, app): report of vehicle leaking oil into nearby drain.	Yes, No Notice Required	2300 w newton st	seattle	98199	47.637144	-122.386363	Fuel and/or vehicle related fluids: report of vehicle leaking oil into nearby drain.	Vehicle-related business: report of vehicle leaking oil into nearby drain.	Not applicable: report of vehicle leaking oil into nearby drain.	Clean-up: report of vehicle leaking oil into nearby drain. . Other: report of vehicle leaking oil into nearby drain.	report of vehicle leaking oil into nearby drain.
WAR044503	9/17/2025	9/17/2025	Pollution hotline (phone, web, app): report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.	Yes, No Notice Required	3844 ne 87th st	seattle	98115	47.691853	-122.285981	Other: report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.	Vehicle-related business: report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.	Not applicable: report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.	Clean-up: report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4. . Other: report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.	report of commercial vehicle having a mechanical failure causing two cups of hydraulic fluid to spill into row. no impact to ms4.
WAR044503	9/17/2025	9/17/2025	Pollution hotline (phone, web, app): report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.	Yes, Notified Ecology	3220 ne 91st st	seattle	98115	47.694944	-122.292391	Other: report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.	Vehicle-related business: report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.	Not applicable: report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.	Clean-up: report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4. . Other: report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.	report of commercial vehicle having a mechanical failure resulting in spill of hydraulic fluid. no impact to ms4.
WAR044503	9/18/2025	9/18/2025	Staff referral: planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.	Yes, Notified Ecology	martin luther king jr way s & s dearbourn st	seattle	98144	47.595525	-122.297581	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.	Unconfirmed, unspecified, or not identified: planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.	Not applicable: planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.	Clean-up: planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.	Complaint. planned rv remediation. inspected 4 structures, found 1 impacted by sewage. impact to ms4. requested cleaning. nfa.
WAR044503	9/19/2025	9/19/2025	Pollution hotline (phone, web, app): report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.	Yes, No Notice Required	6415 32nd ave nw	seattle	98107	47.675532	-122.398543	Other: report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.	Other accident/spill: report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.	Not applicable: report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.	Clean-up: report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4. . Other: report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.	report of waste company knocked over grease tote spilling five gallons of used cooking oil in alley. they hired a contractor for clean up. no impact to ms4.
WAR044503	9/17/2025	9/17/2025	ERTS referral: report of sunken vessel at fisherman's terminal	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: report of sunken vessel at fisherman's terminal	Other: report of sunken vessel at fisherman's terminal	Not applicable: report of sunken vessel at fisherman's terminal	Other: report of sunken vessel at fisherman's terminal	report of sunken vessel at fisherman's terminal
WAR044503	9/20/2025	9/20/2025	Pollution hotline (phone, web, app): report of vehicle leaking motor oil into cb.	Yes, No Notice Required	2525 14th ave s	seattle	98144	47.580234	-122.315178	Fuel and/or vehicle related fluids: report of vehicle leaking motor oil into cb.	Vehicle-related business: report of vehicle leaking motor oil into cb.	Not applicable: report of vehicle leaking motor oil into cb.	Education/technical assistance: report of vehicle leaking motor oil into cb. . Other: report of vehicle leaking motor oil into cb.	Complaint. report of vehicle leaking motor oil into cb.
WAR044503	9/23/2025	9/23/2025	Pollution hotline (phone, web, app): report of an oil sheen in creek. none found.	Yes, No Notice Required	3020 ne 113th st	seattle	98125	47.710396	-122.295172	Other: report of an oil sheen in creek. none found.	Unconfirmed, unspecified, or not identified: report of an oil sheen in creek. none found.	Not applicable: report of an oil sheen in creek. none found.	Other: report of an oil sheen in creek. none found.	report of an oil sheen in creek. none found.
WAR044503	9/22/2025	9/22/2025	Pollution hotline (phone, web, app): report of person working on vehicle and spilling oil.	Yes, No Notice Required	7205 45th ave ne	seattle	98115	0	0	Fuel and/or vehicle related fluids: report of person working on vehicle and spilling oil.	Vehicle-related business: report of person working on vehicle and spilling oil.	Not applicable: report of person working on vehicle and spilling oil.	Education/technical assistance: report of person working on vehicle and spilling oil. . Other: report of person working on vehicle and spilling oil.	Complaint. report of person working on vehicle and spilling oil.
WAR044503	9/23/2025	9/23/2025	ERTS referral: report of drilled fuel tank spilling gas onto pavement. no impact to ms4.	Yes, Notified Ecology	5516 2nd ave nw	seattle	98107	47.669243	-122.358789	Fuel and/or vehicle related fluids: report of drilled fuel tank spilling gas onto pavement. no impact to ms4.	Intentional dumping: report of drilled fuel tank spilling gas onto pavement. no impact to ms4.	Not applicable: report of drilled fuel tank spilling gas onto pavement. no impact to ms4.	Clean-up: report of drilled fuel tank spilling gas onto pavement. no impact to ms4. . Other: report of drilled fuel tank spilling gas onto pavement. no impact to ms4.	report of drilled fuel tank spilling gas onto pavement. no impact to ms4.
WAR044503	9/26/2025	9/26/2025	Pollution hotline (phone, web, app): received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Yes, No Notice Required	boren ave / university st	seattle	98101	47.611459	-122.327159	Fuel and/or vehicle related fluids: received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Vehicle-related business: received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Not applicable: received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Clean-up: received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	received a report about a truck leaking transmission fluid. pictures were sent of the cleanup, no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.
WAR044503	9/28/2025	9/28/2025	Pollution hotline (phone, web, app): received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.	Yes, No Notice Required	fairview ave e & e boston st	seattle	98102	47.638246	-122.329415	Fuel and/or vehicle related fluids: received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.	Unconfirmed, unspecified, or not identified: received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.	Not applicable: received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.	Other: received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.	received a report about sheen of unknown origin in lake union. appeared to be old sheen, we checked the nearby outfall and maintenance hole, no sheen from the ms4. no further action is necessary.
WAR044503	9/29/2025	9/29/2025	Pollution hotline (phone, web, app): received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.	Yes, No Notice Required	w smith st / 33rd ave w	seattle	98199	47.640536	-122.399658	Other: received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.	Unconfirmed, unspecified, or not identified: received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.	Not applicable: received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.	Other: received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.	Complaint. received a report about a white milky substance all over the road. site visit confirmed this to be natural powdery mildew that happens after the first big rain after summer. no further action is necessary.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	9/29/2025	9/29/2025	Pollution hotline (phone, web, app): received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.	Yes, Notified Ecology	1058 e mercer st	seattle	98102	47.624422	-122.318389	Sewage/septage/pet waste/human waste: received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.	Other accident/spill: received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.	Not applicable: received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.	Clean-up: received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control. , Other: received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.	received a report about a backed up side sewer. site visit concluded the sewage has stopped. sewage entered a cb in the ms4, but did not make it past the structure. vactor crew cleaned the area and pumped the structure. i reported it to ecology, kcph, and shellfish. refer to wastewater source control.
WAR044503	9/30/2025	9/30/2025	Pollution hotline (phone, web, app): received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.	Yes, No Notice Required	3926 ne surber dr	seattle	98105	47.656076	-122.285168	Fuel and/or vehicle related fluids: received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.	Vehicle-related business: received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.	Not applicable: received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.	Clean-up: received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no further action is necessary. , Other: received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.	received a spill report about a hydraulic fluid spill from a trash truck. pictures were sent to me of the cleanup. no drain impact. no further action is necessary.
WAR044503	10/1/2025	10/1/2025	Pollution hotline (phone, web, app): report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.	Yes, Notified Ecology	500 e pike st	seattle	98122	47.614258	-122.325308	Fuel and/or vehicle related fluids: report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.	Vehicle-related business: report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.	Not applicable: report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.	Other: report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.	report of coolant spill from a garbage truck. responsible party did cleanup. no impacts to ms4.
WAR044503	10/4/2025	10/4/2025	Pollution hotline (phone, web, app): less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.	Yes, No Notice Required	7060 38th ave ne	seattle	98115	47.681093	-122.286907	Other: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.	Other accident/spill: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.	Not applicable: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.	Clean-up: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains. , Clean-up: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains. , Other: less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.	less than one gallon spill of gel base that is used in portable basketball equipment; non hazardous. spill cleaned by responsible party; no impact to drains.
WAR044503	10/6/2025	10/6/2025	Pollution hotline (phone, web, app): mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.	Yes, Notified Ecology	renton ave s & s kenyon st	seattle	98118	47.531542	-122.278314	Fuel and/or vehicle related fluids: mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.	Vehicle collision: mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.	Not applicable: mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.	Clean-up: mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned. Other: mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.	mva caused spill of less than a gallon of motor oil/automobile fluids to impact road. no impact to drains or ms4. spill has been cleaned.
WAR044503	10/5/2025	10/5/2025	Pollution hotline (phone, web, app): mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.	Yes, No Notice Required	4th ave s / s spokane st	seattle		47.571420	-122.329088	Fuel and/or vehicle related fluids: mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.	Vehicle collision: mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.	Not applicable: mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.	Other: mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.	mva caused motor oil (less than one gallon) to spill to road. no drains were impacted. spill was cleaned with absorbent material.
WAR044503	10/6/2025	10/6/2025	Pollution hotline (phone, web, app): report of drilled gas tank.	Yes, No Notice Required	10711 aurora ave n	seattle	98133	47.707086	-122.345321	Fuel and/or vehicle related fluids: report of drilled gas tank.	Intentional dumping: report of drilled gas tank.	Not applicable: report of drilled gas tank.	Clean-up: report of drilled gas tank. , Education/technical assistance: report of drilled gas tank. , Other: report of drilled gas tank.	report of drilled gas tank.
WAR044503	10/7/2025	10/7/2025	Pollution hotline (phone, web, app): private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.	Yes, Notified Ecology	802 n 43rd st	seattle	98103	47.659561	-122.348483	Sewage/septage/pet waste/human waste: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.	Other accident/spill: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.	Not applicable: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.	Clean-up: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested. , Clean-up: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested. , Other: private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.	private side sewer blocked causing sewage (approx 10 gal) to discharge from clean out and flow into road. no impacts to drains or ms4. cleanup requested.
WAR044503	10/7/2025	10/7/2025	Pollution hotline (phone, web, app): report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.	Yes, Notified Ecology	5625 40th ave ne	seattle	98105	47.670038	-122.285155	Fuel and/or vehicle related fluids: report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.	Vehicle-related business: report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.	Not applicable: report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.	Clean-up: report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.	report of 1 gallon hydraulic fluid spill to the road. spiller cleaned pavement with peat moss and absorbent pads. no drainage or ms4 impact.
WAR044503	10/7/2025	10/7/2025	Pollution hotline (phone, web, app): report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.	Yes, No Notice Required	10108 33rd ave sw	seattle	98146	47.512597	-122.373757	Fuel and/or vehicle related fluids: report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.	Vehicle-related business: report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.	Not applicable: report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.	Clean-up: report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact. , Other: report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.	report of 1 gallon of hydraulic fluid spilled to pavement. reporting party hired a contractor to clean pavement. no drainage or ms4 impact.
WAR044503	10/6/2025	10/6/2025	Pollution hotline (phone, web, app): approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.	Yes, No Notice Required	1431 ne boat st	seattle	98105	47.649843	-122.313339	Sewage/septage/pet waste/human waste: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.	Other accident/spill: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.	Not applicable: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.	Clean-up: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4. , Clean-up: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4. , Other: approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.	approximately 2.5 gallon sewage spill to waterbody. responsible party notified doe and public health. no impact to ms4.
WAR044503	10/8/2025	10/8/2025	Pollution hotline (phone, web, app): report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.	Yes, Notified Ecology	1617 sw lander st	seattle	98134	47.582744	-122.357599	Fuel and/or vehicle related fluids: report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.	Other accident/spill: report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.	Not applicable: report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.	Clean-up: report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact. , Other: report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.	report of a diesel spill at a commercial fuel station due to customer error. fuel station staff performed cleanup. no ms4 drain impact.
WAR044503	10/8/2025	10/8/2025	Pollution hotline (phone, web, app): spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.	Yes, No Notice Required	13001 martin luther king jr way s	seattle	98178	47.485746	-122.257033	Fuel and/or vehicle related fluids: spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.	Other accident/spill: spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.	Not applicable: spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.	Referred to other agency or department: spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction. , Other: spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.	spu received a report of a fuel spill which was determined to be outside of the city limits with no ms4 impact. spu referred the issue back to ecology to assign to the appropriate jurisdiction.
WAR044503	10/8/2025	10/8/2025	Pollution hotline (phone, web, app): report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.	Yes, No Notice Required	10th ave/e pike st	seattle	98122	47.614114	-122.319447	Other: report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.	Unconfirmed, unspecified, or not identified: report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.	Not applicable: report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.	Clean-up: report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined. , Other: report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.	report of a paint spill to the paved row from an unknown source. spu found no ms4 drain impact and performed clean up with on hand absorbents. no responsible party was determined.
WAR044503	10/9/2025	10/9/2025	Pollution hotline (phone, web, app): a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.	Yes, No Notice Required	3819 fremont ave n	seattle	98103	47.653269	-122.350436	Unconfirmed, unspecified, or not identified: a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.	Construction activity: a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.	Not applicable: a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.	Referred to other agency or department: a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation. , Other: a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.	Complaint. a report was received of construction wastewater draining down an alley from a property under construction. the inspector confirmed dried white staining consistent with concrete wastewater but found no impacted storm drains. the issue was referred to sdci for follow-up on site housekeeping and bmp implementation.
WAR044503	10/10/2025	10/10/2025	Pollution hotline (phone, web, app): self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	10311 sand point way ne	seattle	98125	47.703262	-122.277953	Fuel and/or vehicle related fluids: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.	Vehicle-related business: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.	Not applicable: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.	Clean-up: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact. , Other: self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.	self report of a hydraulic fluid spill to pavement from a leaking waste collection truck. cleanup by the responsible party. no ms4 drain impact.
WAR044503	10/10/2025	10/10/2025	Staff referral: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.	Yes, Notified Ecology	21st ave s / s plum st	seattle	98144	47.585499	-122.305577	Sewage/septage/pet waste/human waste: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted. , Intentional dumping: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.	Intentional dumping: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted. , Intentional dumping: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.	Not applicable: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.	Clean-up: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted. , Other: inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.	Complaint. inspected 31 drainage structures. 2 tested positive for ammonia. 2 were contaminated with tracing dye. crews dispatched to clean all 4 structures with a vacuum truck. ms4 impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/3/2025	7/3/2025	MS4 inspection or screening: routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Yes, Notified Ecology	32nd ave s & s dearborn st	seattle	98144	47.595743	-122.291498	Unconfirmed, unspecified, or not identified: routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Not applicable: routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Other: routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.	Complaint. routine dry weather screening identified a trigger level ammonia sample result in the ms4. source tracing efforts determined the issue was not ongoing and a source was unable to be identified.
WAR044503	10/14/2025	10/14/2025	ERTS referral: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.	Yes, Notified Ecology	1310 n 131st st	seattle	98133	47.724705	-122.341212	Other: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.	Construction activity: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.	Not applicable: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.	Clean-up: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination. Education/technical assistance: report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.	Complaint. report of discharge from commercial property found to be a failure of the fire sprinkler system. property manager affected repairs and ceased discharge. no cleanup warranted based on low volume and rate of discharge with no turbidity or signs of contamination.
WAR044503	10/14/2025	10/14/2025	Pollution hotline (phone, web, app): report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.	Yes, No Notice Required	2521 15th ave s	seattle	98144	47.580452	-122.313675	Sewage/septage/pet waste/human waste: report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.	Other accident/spill: report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.	Not applicable: report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.	Clean-up: report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program. Education/technical assistance: report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.	report of sewage surfacing to pavement on private property from a private side sewer problem. no ms4 impact. responsible party hired a contractor and spu referred the issue internally to the side sewer program.
WAR044503	10/14/2025	10/14/2025	Pollution hotline (phone, web, app): report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.	Yes, No Notice Required	2801 sw thistle st	seattle	98126	47.528005	-122.369188	Fuel and/or vehicle related fluids: report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.	Vehicle-related business: report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.	Not applicable: report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.	Clean-up: report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.	report of vehicle leaking fluid to pavement. spu determined the spill was motor oil and confirmed no ms4 drain impact. spu cleaned with on hand materials and seattle parks coordinated fleet pickup and repair.
WAR044503	10/15/2025	10/15/2025	ERTS referral: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.	Yes, Notified Ecology	s royal brougham way / 4th ave s	seattle	98134	47.592393	-122.329059	Fuel and/or vehicle related fluids: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.	Other accident/spill: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.	Not applicable: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.	Clean-up: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa. Other: hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.	hydraulic fluid cleaned on the tracks. no impact to ms4 or any drains. nfa.
WAR044503	7/23/2025	7/23/2025	MS4 inspection or screening: routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.	Yes, Notified Ecology	32nd ave s & s dearborn st	seattle	98144	47.595743	-122.291498	Unconfirmed, unspecified, or not identified: routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.	Unconfirmed, unspecified, or not identified: routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.	Not applicable: routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.	Other: routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.	Complaint. routine dry weather screening identified a trigger level potassium sample result in the ms4. a source tracing investigation determined the issue was not ongoing and a source was not able to be identified.
WAR044503	10/16/2025	10/16/2025	Pollution hotline (phone, web, app): responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.	Vehicle-related business: responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.	Not applicable: responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.	Clean-up: responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.	responsible party cleaned up hydraulic fluid from sweeper malfunction. drains minimally impacted and cleaned. no waterbody impact. nfa.
WAR044503	10/17/2025	10/17/2025	Direct report to your staff: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.	Yes, Notified Ecology	2208 15th ave w	seattle	98119	47.638922	-122.375831	Food-related oil/grease: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.	Other accident/spill: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.	Not applicable: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.	Clean-up: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted. Other: while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.	while conducting a sw inspection, I found used cooking oil in a cb. project manager at property said he has video footage showing waste management spilled it while emptying dumpster. ms4 impacted.
WAR044503	10/18/2025	10/18/2025	Pollution hotline (phone, web, app): cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.	Yes, No Notice Required	40th ave sw & sw willow st	seattle	98136	47.541251	-122.383206	Fuel and/or vehicle related fluids: cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.	Other accident/spill: cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.	Not applicable: cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.	Clean-up: cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa. Other: cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.	Complaint. cleaned small oil spill on pavement. no drain impact. no downstream impact. nfa.
WAR044503	10/18/2025	10/18/2025	Pollution hotline (phone, web, app): referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.	Yes, No Notice Required	water body duwamish	seattle		47.560815	-122.346250	Fuel and/or vehicle related fluids: referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.	Unconfirmed, unspecified, or not identified: referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.	Not applicable: referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.	Referred to other agency or department: referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.	Complaint. referred sheen on duwamish. confirmed it was not due to dredging. no impact to or from ms4. nfa.
WAR044503	10/18/2025	10/18/2025	Pollution hotline (phone, web, app): fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.	Yes, Notified Ecology	24th ave sw / sw willow st	seattle	98106	47.541586	-122.363423	Fuel and/or vehicle related fluids: fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.	Intentional dumping: fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.	Not applicable: fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.	Clean-up: fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.	fuel spilled during vandalism event. pavement only. removed impacted soil. no downstream impact. no stream impact. nfa.
WAR044503	10/18/2025	10/18/2025	Pollution hotline (phone, web, app): provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.	Yes, Notified Ecology	9th ave sw & sw henderson st	seattle	98106	47.522809	-122.346737	Sewage/septage/pet waste/human waste: provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.	Vehicle-related business: provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.	Intentional dumping: provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.	Clean-up: provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa. Education/technical assistance: provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.	provided parts to rv to fix leak. cleaned up spill. ms4 impacted by gray water. no downstream impact. nfa.
WAR044503	10/20/2025	10/20/2025	Pollution hotline (phone, web, app): unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.	Yes, Notified Ecology	2445 4th ave s	seattle	98134	47.580316	-122.329814	Food-related oil/grease: unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.	Other accident/spill: unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.	Not applicable: unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.	Clean-up: unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.	unknown reason why container tipped. parking lot and one affected drain was cleaned. no downstream impact. no impact to public ms4. nfa.
WAR044503	10/20/2025	10/20/2025	ERTS referral: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.	Yes, Notified Ecology	fremont ave n & n 35th st	seattle	98103	47.650430	-122.349845	Sediment/soil: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.	Construction activity: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.	Not applicable: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.	Clean-up: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa. Education/technical assistance: uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.	uncovered pile lead to gravel fines traveling downstream. inlet socks were in place and caught the fines. no downstream impact. nfa.
WAR044503	10/20/2025	10/20/2025	Pollution hotline (phone, web, app): load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.	Yes, Notified Ecology	ne northgate wy & 5th ave ne	seattle	98125	47.708597	-122.323296	Other: load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.	Other accident/spill: load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.	Not applicable: load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.	Clean-up: load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.	load fire was dumped and fire was extinguished. waste water made it to private drain that was pumped out. no downstream impact observed. nfa.
WAR044503	10/21/2025	10/21/2025	Pollution hotline (phone, web, app): sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.	Yes, Notified Ecology	1420 s walker st	seattle	98144	47.583869	-122.313616	Sewage/septage/pet waste/human waste: sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.	Other accident/spill: sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.	Not applicable: sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.	Clean-up: sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.	sanitary sewer overflow made it to sidewalk. plumbers fixed the problem and crews cleaned up affected sidewalk. no impact to ms4. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments	
WAR044503	10/21/2025	10/21/2025	Pollution hotline (phone, web, app): vector truck accidentally released dechlorinated water and sediment into row going down 4 drains, no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	Yes, Notified Ecology	16th ave sw / w brandon st	seattle	98106	47.553690	-122.354807	Sediment/soil: vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	Other accident/spill: vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	Not applicable: vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	Clean-up: vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa. Other: vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	vector truck accidentally released dechlorinated water and sediment into row going down 4 drains. no downstream impact. crews cleaned up sediment in row and catch basins. nfa.	
WAR044503	10/21/2025	10/21/2025	Pollution hotline (phone, web, app): property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	Yes, No Notice Required	1105 33rd ave s	seattle	98144	47.593239	-122.290625	Sediment/soil: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	Construction activity: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	Not applicable: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	Clean-up: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa. Education/technical assistance: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa. Other: property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	property being used for lay down yard. poor housekeeping lead to sediment flushing into street. owner cleaned up. no impact to drains. pavement only. nfa.	
WAR044503	10/22/2025	10/22/2025	Pollution hotline (phone, web, app): illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	Yes, No Notice Required	1426 broadway	seattle	98122	47.613747	-122.320607	Food-related oil/grease: illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	Intentional dumping: illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	Not applicable: illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	Clean-up: illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures. Other: illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	illegal dumping of used cooking oil by a street food vendor into an electrical vault and drainage catch basin. investigated the site and coordinated cleanup of both structures. ms4 was impacted, but no evidence of impact downstream of the two structures.	
WAR044503	10/24/2025	10/24/2025	Pollution hotline (phone, web, app): a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure.	Yes, Notified Ecology	40th ave ne / ne 75th st	seattle	98115	47.683042	-122.285168	Fuel and/or vehicle related fluids: a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure.	Vehicle collision: a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure.	Not applicable: a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin in the ms4, no impact downstream of the structure.	Clean-up: a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure. Other: a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure.	a spill of motor oil due to a motor vehicle accident was reported. granular and absorbent pads were deployed to capture oil in the catch basin and on the pavement. 1 quart of oil impacted a catch basin in the ms4, no impact downstream of the structure.	
WAR044503	10/24/2025	10/24/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	Yes, Notified Ecology	301 22nd ave	seattle	98122	47.604502	-122.304115	Fuel and/or vehicle related fluids: spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	Vehicle-related business: spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	Not applicable: spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	Clean-up: spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	Complaint. spill of hydraulic oil to separated stormwater system from a garbage truck. oil trapped at local catch basins due to outlet trap with no evidence of downstream impact. responsible party hired a contractor to clean the impacted structures.	
WAR044503	10/24/2025	10/24/2025	Pollution hotline (phone, web, app): report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	Yes, Notified Ecology	4201 stone way n	seattle	98103	47.658151	-122.342557	Fuel and/or vehicle related fluids: report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	Vehicle-related business: report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	Not applicable: report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	Clean-up: report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact. Other: report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	report of turbid water and oil sheen leaving a construction site and entering drains. investigation found that the excavation contractor had overfilled their excavation with cdf and stormwater running over the trench caused turbid water to leave the site. there was also dump truck on site that leaked a few drips of oil casing a sheen. excavation contractor hired a vac truck company for cleanup. turbid water and sheen impacted 2 catch basins in the ms4. no evidence of d/s impact.	
WAR044503	10/26/2025	10/26/2025	Pollution hotline (phone, web, app): report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	Yes, Notified Ecology	4100 sw admiral way	seattle	98116	47.581460	-122.384193	Fuel and/or vehicle related fluids: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	Vehicle-related business: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	Intentional dumping: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	Not applicable: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	Clean-up: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4. Education/technical assistance: report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.	report of gasoline spill at fuel station. investigated the site and cleaned up gasoline with pads and granular from pavement, some gasoline was also captured by oil/water separator. impact to private drainage, no impact to city ms4.
WAR044503	10/26/2025	10/26/2025	Pollution hotline (phone, web, app): report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	Yes, No Notice Required	4116 ne 60th st	seattle	98115	47.672349	-122.282622	Sewage/septage/pet waste/human waste: report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	Other: report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	Not applicable: report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	Clean-up: report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	report of a porta-potty knocked over by the wind. approximately 1 -gallon of waste spilled to grass and sidewalk. cleaned up by spu spills. no drainage impacts. porta-potty company notified.	
WAR044503	10/26/2025	10/26/2025	Pollution hotline (phone, web, app): report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	Yes, Notified Ecology	13514 riviera pl ne	seattle	98125	47.726888	-122.280839	Fuel and/or vehicle related fluids: report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	Other accident/spill: report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	Not applicable: report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	Clean-up: report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies. Other: report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	report of transformer oil spill from electric utility. some evidence of oil on the pavement, but unable to determine if it was transformer oil, or leaking motor oil from the vehicle parked nearby. responsible party will clean with pad once the vehicle is moved. no impact ms4 or water bodies.	
WAR044503	10/27/2025	10/27/2025	Pollution hotline (phone, web, app): report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	Yes, Notified Ecology	rainier ave s / s hanford st	seattle	98144	47.574965	-122.295578	Sewage/septage/pet waste/human waste: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	Construction activity: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington. Other accident/spill: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	Not applicable: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	Clean-up: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington. Other: report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	report of sewage surfacing from a maintenance hole. spill responders investigated and system maintenance crews stopped the sso, by removing a blockage in the city mainline pipe. ms4 was impacted with 100 gallons of sewage, which discharged into lake washington.	

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	10/27/2025	10/27/2025	ERTS referral: spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.	Yes, Notified Ecology	6326 faunteroy way sw	seattle	98136	47.545733	-122.383425	Fuel and/or vehicle related fluids: spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.	Vehicle-related business: spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.	Not applicable: spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.	nfa_spills, Clean-up: spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.	spill of antifreeze to pavement from leaking vehicle. no drain impacts. spill cleanup by responsible party with spu assistance.
WAR044503	10/27/2025	10/27/2025	Pollution hotline (phone, web, app): hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.	Yes, Notified Ecology	7 s idaho st	seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.	Vehicle-related business: hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.	Not applicable: hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.	Clean-up: hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa. Other: hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.	hydraulic spill on private property cleaned up by spiller. no impact to ms4. nfa.
WAR044503	10/27/2025	10/27/2025	ERTS referral: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.	Yes, Notified Ecology	hwy-520 hwy & i-5 wy	seattle	98102	47.642972	-122.322443	Sediment/soil: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.	Construction activity: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.	Not applicable: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.	Referred to other agency or department: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa. Other: construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.	Complaint. construction site overwhelmed by rain. immediate action corrected the overflow into non-spu structures. referral made. no impact to spu ms4. nfa.
WAR044503	10/28/2025	10/28/2025	Direct report to your staff: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.	Yes, No Notice Required	9053 1st ave nw	seattle	98117	47.695874	-122.358383	Sewage/septage/pet waste/human waste: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.	Vehicle-related business: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.	Not applicable: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.	Clean-up: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact. Referred to other agency or department: report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.	Complaint. report of rvs dumping blackwater near sandel park. spill responder investigated, and found a leaking fire hydrant, and a minor graywater leak on an rv. no ms4 impact.
WAR044503	10/30/2025	10/30/2025	Pollution hotline (phone, web, app): report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.	Yes, No Notice Required	east marginal way s & 1st ave s	seattle	98108	47.548270	-122.334319	Fuel and/or vehicle related fluids: report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.	Vehicle collision: report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.	Not applicable: report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.	Clean-up: report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.	report of coolant spill to drain from auto accident. investigated site, found no evidence coolant impacted drain, swept up some absorbent material that was left behind on pavement. no impact to ms4.
WAR044503	10/30/2025	10/30/2025	Pollution hotline (phone, web, app): report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.	Yes, No Notice Required	39th ave sw & w monroe st	seattle	98136	47.531359	-122.382009	Fuel and/or vehicle related fluids: report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.	Intentional dumping: report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.	Not applicable: report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.	Clean-up: report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.	report of vandalized gas tank leaking fuel in street. called reporting party to get info, no drains were impacted. referred to city transportation dept for clean up. no ms4 impact.
WAR044503	10/30/2025	10/30/2025	Direct report to your staff: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.	Yes, No Notice Required	1920 utah ave s	seattle	98134	47.585040	-122.335132	Other: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.	Intentional dumping: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.	Not applicable: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.	Clean-up: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4. Other: found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.	found paint spill while doing scouting for the rv wastewater program. investigated, used spills pump truck and on hand materials to clean up the spill. no impact to the ms4.
WAR044503	10/30/2025	10/30/2025	Pollution hotline (phone, web, app): report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.	Yes, Notified Ecology	12205 fremont ave n	seattle	98133	47.717971	-122.350612	Fuel and/or vehicle related fluids: report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.	Other accident/spill: report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.	Not applicable: report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.	Clean-up: report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.	report of 10 gallon spill of hydraulic fluid, no drain involvement. called responsible party and requested pictures and invoice for the clean up. no ms4 impact.
WAR044503	10/31/2025	10/31/2025	Pollution hotline (phone, web, app): vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.	Yes, Notified Ecology	sw kenyon st / 10th ave sw	seattle	98106	47.531938	-122.348149	Fuel and/or vehicle related fluids: vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.	Vehicle collision: vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.	Not applicable: vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.	Clean-up: vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.	vehicle accident resulted in coolant spilling to pavement. no drains impacted. sdot applied absorbent and swept up residual.
WAR044503	10/31/2025	10/31/2025	Pollution hotline (phone, web, app): unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.	Yes, Notified Ecology	8702 3rd ave nw	seattle	98117	47.692593	-122.360432	Other: unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.	Other: unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.	Not applicable: unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.	Other: unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.	unknown sewer contractor discharged hot water to sidewalk via hose during liner repair work at property. none of the discharge entered any drains - no ms4 impact.
WAR044503	10/31/2025	10/31/2025	Pollution hotline (phone, web, app): catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.	Yes, Notified Ecology	6301 35th ave sw	seattle	98126	47.546337	-122.376826	Fuel and/or vehicle related fluids: catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.	Unconfirmed, unspecified, or not identified: catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.	Not applicable: catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.	Clean-up: catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.	catch basin polluted with coolant. within ms4, but did not leave the basin. cleaned on site.
WAR044503	11/1/2025	11/1/2025	Pollution hotline (phone, web, app): leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Other: leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.	Construction activity: leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.	Not applicable: leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.	Other: leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.	leaching of a mastic substance from coated lumber at fisherman's terminal. port of seattle drainage system impacted which direct discharges. no impact to spu ms4. port of seattle coordinated cleanup.
WAR044503	11/3/2025	11/3/2025	Direct report to your staff: five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.	Yes, Notified Ecology	2840 nw market st	seattle	98107	47.668997	-122.394858	Food-related oil/grease: five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.	Intentional dumping: five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.	Not applicable: five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.	Clean-up: five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.	five gallons of cooking oil found in cb and ows. property owner hired contractor for cleaning. ms4 impacted.
WAR044503	11/4/2025	11/4/2025	Pollution hotline (phone, web, app): a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.	Yes, Notified Ecology	1502 nw 50th st	seattle	98107	47.685253	-122.376556	Fuel and/or vehicle related fluids: a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.	Vehicle-related business: a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.	Not applicable: a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.	Clean-up: a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup. Other: a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.	a garbage truck was leaking coolant on the road during their route. leaking 2-3 gal over approximately 150ft of road. no ms4 impact. the company hired a contractor to conduct a cleanup.
WAR044503	11/5/2025	11/5/2025	Pollution hotline (phone, web, app): a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.	Yes, Notified Ecology	1713 nw 97th st	seattle	98117	47.699507	-122.379131	Fuel and/or vehicle related fluids: a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.	Intentional dumping: a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.	Not applicable: a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.	Clean-up: a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.	a gas tank on a van was drilled with gasoline spilled to the road shoulder and a sandbox, and two junction boxes on the informal drainage system were impacted. gasoline had mixed with gravel and soil in each of the three structures - there was no liquid gasoline. mapping and in-field checks show no outlet or outfall for this section of the drainage system - it just appears to dead-end. gravel and soil was removed and boom was left in each of the structures.
WAR044503	11/5/2025	11/5/2025	Direct report to your staff: report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.	Yes, Notified Ecology	west marginal way sw / 2nd ave sw	seattle	98111	47.537400	-122.337096	Unconfirmed, unspecified, or not identified: report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.	Unconfirmed, unspecified, or not identified: report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.	Not applicable: report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.	Other: report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.	Complaint. report of green discharge in a stormwater retention pond. spill responder investigated, verified a green hue (darker shade of green than reported), and also noted a turbid water discharge into the pond. unable to determine a source. ms4 impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/5/2025	11/5/2025	Pollution hotline (phone, web, app): found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.	Yes, Notified Ecology	1521 nw 50th st	seattle	98107	47.684752	-122.377426	Sediment/soil: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.	Other: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.	Not applicable: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.	Clean-up: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge. Education/technical assistance: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge. Enforcement: found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.	found turbid run off from business impacting the ms4. temporary bmps put in place. business instructed to pull permits and modify property to follow bmp 26 and achieve compliance. nov being pursued for prohibited discharge.
WAR044503	11/5/2025	11/5/2025	Pollution hotline (phone, web, app): report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.	Yes, No Notice Required	12600 stone ave n	seattle	98133	47.721334	-122.341026	Fuel and/or vehicle related fluids: report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.	Other accident/spill: report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.	Not applicable: report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.	Clean-up: report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.	report of gasoline spill at fueling station. after investigating, it appeared to be sheen on the pavement that had accumulated near the fuel island from routine small drips from fueling vehicles. no impact to ms4.
WAR044503	11/5/2025	11/5/2025	Pollution hotline (phone, web, app): discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.	Yes, Notified Ecology	11702 8th ave nw	seattle	98177	47.714556	-122.365551	Sediment/soil: discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.	Construction activity: discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.	Not applicable: discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.	Clean-up: discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party. Education/technical assistance: discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.	discharge of sediment laden process wastewater from stone cutting to the gutter and catch basin. most sediment was deposited in the gutter and cleaned up by the responsible party with small amounts of process wastewater impacting the catch basin. a notice of violation with penalty will be pursued against the responsible party.
WAR044503	11/6/2025	11/6/2025	Pollution hotline (phone, web, app): report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.	Yes, Notified Ecology	2001 w garfield st	seattle	98119	47.630999	-122.382825	Soap or cleaning chemicals: report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.	Other accident/spill: report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.	Not applicable: report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.	Referred to other agency or department: report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.	report of soapy water discharge to privately owned cb and direct discharge to a water body. spill responder contacted the reporting party to ask if they needed assistance. no impact to city owned ms4.
WAR044503	11/7/2025	11/7/2025	ERTS referral: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.	Yes, Notified Ecology	816 23rd ave s	seattle	98144	47.594996	-122.301901	Fuel and/or vehicle related fluids: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.	Vehicle-related business: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.	Not applicable: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.	Clean-up: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4. Other: report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.	report of leaking motor oil from car into catch basin. investigated the site and confirmed report, catch basin was a privately owned asset. placed onion sack in cb to absorb oil. private separated drainage system impacted, no evidence of downstream impact to the spu ms4.
WAR044503	11/8/2025	11/8/2025	Pollution hotline (phone, web, app): report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.	Yes, No Notice Required	1113 ne 42nd st	seattle	98105	47.658228	-122.315998	Other: report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.	Unconfirmed, unspecified, or not identified: report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.	Not applicable: report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.	Other: report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.	report of antifreeze/coolant spill in a puddle. investigated the site, and odor and volume did not indicate the material was antifreeze/coolant, appeared to be water with tracing dye. city crews conducted cleanup with vacuum truck. no ms4 impact.
WAR044503	11/11/2025	11/11/2025	Pollution hotline (phone, web, app): report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.	Yes, Notified Ecology	1483 alaskan way	seattle	98101	47.607409	-122.342643	Fuel and/or vehicle related fluids: report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.	Other accident/spill: report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.	Not applicable: report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.	Clean-up: report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted. Other: report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.	report of glycol spill to a catch basin from chiller system. spill responders investigated and required the responsible party to clean the catch basin. ms4 and waterbody was impacted.
WAR044503	11/12/2025	11/12/2025	ERTS referral: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.	Yes, Notified Ecology	nw leary way & 15th ave nw	seattle	98107	47.663862	-122.376331	Sediment/soil: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.	Construction activity: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.	Not applicable: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.	Education/technical assistance: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa. Enforcement: construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.	construction pumped turbid water into ms4 while attempting to install a new catch basin. letter sent through business inspection. cb was cleaned. nfa.
WAR044503	11/13/2025	11/13/2025	Pollution hotline (phone, web, app): motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.	Yes, Notified Ecology	blakely pl nw & nw blakely ct	seattle	98177	47.722410	-122.373315	Fuel and/or vehicle related fluids: motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.	Other accident/spill: motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.	Not applicable: motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.	Clean-up: motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa. Other: motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.	motor oil was cleaned up from pavement only spill using a contractor. no downstream impact. nfa.
WAR044503	11/14/2025	11/14/2025	Pollution hotline (phone, web, app): freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa	Yes, No Notice Required	3904 42nd ave s	seattle	98118	47.588610	-122.280466	Other: freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa	Construction activity: freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa	Not applicable: freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa	Education/technical assistance: freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa. Other: freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa	Complaint. freshly poured asphalt patch was sheening, a short distance. no impact to drains. nfa
WAR044503	11/14/2025	11/14/2025	Pollution hotline (phone, web, app): sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.	Yes, Notified Ecology	1112 ne pacific st	seattle	98105	47.653832	-122.316498	Sewage/septage/pet waste/human waste: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.	Other accident/spill: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.	Not applicable: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.	Clean-up: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa. Clean-up: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa. Referred to other agency or department: sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.	sanitary sewer overflow affected portage bay with 9250 gallons of sewage. blockage relieved. nfa.
WAR044503	11/15/2025	11/15/2025	Direct report to your staff: found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.	Yes, Notified Ecology	fox ave s / s myrtle st	seattle	98108	47.539434	-122.325688	Fuel and/or vehicle related fluids: found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.	Unconfirmed, unspecified, or not identified: found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.	Not applicable: found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.	Other: found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.	Complaint. found sheen on duwamish river. found no pollution upstream. no impact to ms4. nfa.
WAR044503	11/16/2025	11/16/2025	Pollution hotline (phone, web, app): found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.	Yes, Notified Ecology	ravenna ave ne & ne 85th st	seattle	98115	47.690238	-122.301690	Sediment/soil: found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.	Construction activity: found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.	Not applicable: found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.	Clean-up: found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa. Other: found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.	found sediment in ms4 cb but not downstream. found sediment in sanitary mainline. wo created to clean. nfa.
WAR044503	11/17/2025	11/17/2025	Pollution hotline (phone, web, app): unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.	Yes, Notified Ecology	lake city way ne & ne 125th st	seattle	98125	47.719277	-122.295243	Fuel and/or vehicle related fluids: unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.	Unconfirmed, unspecified, or not identified: unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.	Not applicable: unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.	Clean-up: unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa. Other: unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.	Complaint. unknown sheen impacted catch basin with unrecoverable materials. ms4 impacted but not downstream. boom deployed as extra measure. nfa.
WAR044503	11/18/2025	11/18/2025	ERTS referral: referred 520 lid project discharge to state. no impact to ms4. nfa.	Yes, Notified Ecology	hwy-520 hwy & i-5 wy	seattle	98102	47.642972	-122.322243	Sediment/soil: referred 520 lid project discharge to state. no impact to ms4. nfa.	Construction activity: referred 520 lid project discharge to state. no impact to ms4. nfa.	Not applicable: referred 520 lid project discharge to state. no impact to ms4. nfa.	Referred to other agency or department: referred 520 lid project discharge to state. no impact to ms4. nfa.	Complaint. referred 520 lid project discharge to state. no impact to ms4. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/17/2025	11/17/2025	ERTS referral: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.	Yes, Notified Ecology	5213 8th ave nw	seattle	98107	47.666894	-122.366468	Sewage/septage/pet waste/human waste: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.	Other accident/spill: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.	Not applicable: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.	Clean-up: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa., Other: sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.	sewage was recaptured from sso. no downstream impacts in ms4. pavement only. nfa.
WAR044503	11/18/2025	11/18/2025	Pollution hotline (phone, web, app): diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.	Yes, Notified Ecology	2001 w garfield st	seattle	98119	47.630999	-122.382825	Fuel and/or vehicle related fluids: diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.	Other accident/spill: diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.	Not applicable: diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.	Clean-up: diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa., Other: diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.	diesel spill cleaned up by responsible party. no impact to spu ms4. no waterbody impact. nfa.
WAR044503	11/18/2025	11/18/2025	ERTS referral: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Other accident/spill: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Not applicable: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Clean-up: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa., Other: fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	fuel was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.
WAR044503	11/18/2025	11/18/2025	ERTS referral: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Yes, Notified Ecology	3919 18th ave w	seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Other accident/spill: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Not applicable: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	Clean-up: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa., Other: hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.	hydraulic fluid was cleaned up on private property by secondary permittee. no impact to spu ms4. nfa.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.	Yes, Notified Ecology	24th ave s / s mcclellan st	seattle		47.578349	-122.301308	Sewage/septage/pet waste/human waste: sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.	Other accident/spill: sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.	Not applicable: sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.	Clean-up: sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa., Other: sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.	sewage impacted the duwamish river from the ms4 due to a blockage in the pipe. the root ball was removed. sso sop. nfa.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): diesel was cleaned from pavement in the ms4. no downstream impact. nfa.	Yes, Notified Ecology	7303 8th ave s	seattle	98108	47.536751	-122.323977	Fuel and/or vehicle related fluids: diesel was cleaned from pavement in the ms4. no downstream impact. nfa.	Other accident/spill: diesel was cleaned from pavement in the ms4. no downstream impact. nfa.	Not applicable: diesel was cleaned from pavement in the ms4. no downstream impact. nfa.	Clean-up: diesel was cleaned from pavement in the ms4. no downstream impact. nfa., Other: diesel was cleaned from pavement in the ms4. no downstream impact. nfa.	diesel was cleaned from pavement in the ms4. no downstream impact. nfa.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.	Yes, Notified Ecology	4109 sw bradford st	seattle	98116	47.569078	-122.384686	Sewage/septage/pet waste/human waste: sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.	Other accident/spill: sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.	Not applicable: sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.	Clean-up: sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.	sewage release to the row sidewalk pavement with no ms4 drain impact due to a private side sewer problem. responsible property owner hired a contractor to resolve the problem. internal referral to the side sewer program.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.	Yes, Notified Ecology	3900 7th ave ne	seattle	98195	47.655278	-122.320325	Fuel and/or vehicle related fluids: gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.	Intentional dumping: gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.	Not applicable: gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.	Clean-up: gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4., Other: gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.	gasoline spill to pavement and a private storm drainage system due to theft/vandalism. cleanup completed by the responsible party. no impact to the ms4.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.	Yes, Notified Ecology	sw admiral way & sw stevens st	seattle	98116	47.577623	-122.402761	Soap or cleaning chemicals: washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.	Other: washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.	Not applicable: washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.	Clean-up: washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process., Education/technical assistance: washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.	washwater impact to the ms4 from a mobile detailing business. spu provided code education and the responsible party performed cleanup/recovery. internal referral to the business inspection process.
WAR044503	11/19/2025	11/19/2025	Pollution hotline (phone, web, app): self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.	Yes, No Notice Required	11th ave & e howell st	seattle	98122	47.617589	-122.318207	Fuel and/or vehicle related fluids: self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.	Vehicle-related business: self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.	Not applicable: self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.	Clean-up: self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact., Other: self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.	self report of an oil spill to row pavement from private auto repair. cleanup by sdot and the responsible party. no ms4 drain impact.
WAR044503	11/23/2025	11/23/2025	Pollution hotline (phone, web, app): reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.	Yes, Notified Ecology	21st ave s & s mcclellan st	seattle	98144	47.578353	-122.305380	Fuel and/or vehicle related fluids: reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.	Unconfirmed, unspecified, or not identified: reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.	Not applicable: reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.	Clean-up: reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery., Other: reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.	reported oil spill in the row confirmed to impact pavement and an ms4 drain. spu was not able to determine a responsible party and deployed on hand absorbents for recovery.
WAR044503	11/24/2025	11/24/2025	Pollution hotline (phone, web, app): sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.	Yes, Notified Ecology	4225 7th ave ne	seattle	98105	47.658283	-122.321256	Sewage/septage/pet waste/human waste: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.	Construction activity: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact., Other: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.	Not applicable: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.	Clean-up: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact., Other: sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.	sanitary sewer overflow to private property due to an spu mainline issue. flow restored by spu crews. no ms4 drain impact.
WAR044503	11/25/2025	11/25/2025	Pollution hotline (phone, web, app): received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.	Yes, No Notice Required	water body	seattle		47.636837	-122.333631	Fuel and/or vehicle related fluids: received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.	Unconfirmed, unspecified, or not identified: received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.	Not applicable: received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.	Referred to other agency or department: received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary., Other: received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.	received a report about sheen on lake union. spill responder checked all nearby outfalls and determined it is not coming from the ms4. a nearby boat was the culprit. nrc and ecology already notified. no other actions are necessary.
WAR044503	11/25/2025	11/25/2025	Pollution hotline (phone, web, app): spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.	Yes, Notified Ecology	1350 n 34th st	seattle	98103	47.648797	-122.340795	Fuel and/or vehicle related fluids: spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.	Vehicle-related business: spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.	Not applicable: spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.	Clean-up: spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4., Other: spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.	spill of hydraulic fluid from garbage truck at north transfer station. majority spilled in area that connects to sanitary sewer. some vehicle tracking to street but those drains connect to king county metro. no impact to ms4.
WAR044503	11/26/2025	11/26/2025	Pollution hotline (phone, web, app): an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.	Yes, Notified Ecology	3201 martin luther king jr way s	seattle	98144	47.574875	-122.297208	Fuel and/or vehicle related fluids: an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.	Unconfirmed, unspecified, or not identified: an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.	Not applicable: an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.	Clean-up: an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it., Other: an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.	an oily sheen was observed by a passerby, contaminating the sidewalk and street at an intersection. spu crews identified that oil had reached one ms4 catch basin, but did not reach the waterbody or progress further downstream. the street-level spill was cleaned with on-hand materials and the catch basin had an absorbent boom placed in it.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/27/2025	11/27/2025	Pollution hotline (phone, web, app): gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).	Yes, Notified Ecology	5909 31st ave sw	seattle	98126	47.549776	-122.372531	Fuel and/or vehicle related fluids: gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).	Intentional dumping: gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).	Not applicable: gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).	Clean-up: gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).	gas tank on a pickup truck was spilled and gasoline went onto street and into a spu bio-infiltration swale. absorbents were used on street and white pads used on surface water in swale. boom was placed in downstream mh overnight. no observed impact to ms4 (stormwater mainline or catch basin downstream).
WAR044503	11/28/2025	11/28/2025	Pollution hotline (phone, web, app): spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.	Yes, Notified Ecology	1400 discovery park blvd	seattle	98199	47.660931	-122.430364	Other: spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.	Other accident/spill: spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.	Not applicable: spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.	Clean-up: spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.	spill of treated effluent from kc west point treatment plant outfall pipe due to a valve failure. impacts to pavement. kc catch-basin and puget sound. spilled liquid is allowed to be discharged to puget sound but seattle-king county health department posted beach closed signs due to the shallower depth of this discharge than is permitted. king county did erts reporting. no impact to spu assets or ms4.
WAR044503	11/29/2025	11/29/2025	Pollution hotline (phone, web, app): sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.	Yes, Notified Ecology	6535 seaview ave nw	seattle	98117	47.676224	-122.408135	Sewage/septage/pet waste/human waste: sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.	Intentional dumping: sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.	Not applicable: sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.	Other: sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.	sewage/graywater leaked from rv parked on side of street. small amount found in a spu catch basin that goes to ms4 but level was below outfall of cb. no evidence it left cb. spu crews pumped out the cb later the same day.
WAR044503	12/1/2025	12/1/2025	Pollution hotline (phone, web, app): spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.	Yes, No Notice Required	2801 sw thistle st	seattle	98126	47.528005	-122.369188	Fuel and/or vehicle related fluids: spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.	Intentional dumping: spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.	Not applicable: spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.	Clean-up: spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.	spill of gasoline from a parks dept vehicle at a parks facility due to vandalism. spill only impacted pavement - no drains impacted. spu completed cleanup using pads and granular.
WAR044503	12/1/2025	12/1/2025	ERTS referral: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.	Yes, Notified Ecology	59th ave ne & ne 60th st	seattle	98105	47.672106	-122.264592	Fuel and/or vehicle related fluids: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.	Other accident/spill: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.	Not applicable: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.	Clean-up: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa. Other: hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.	hydraulic fluid cleaned from pavement. no downstream impact in the ms4. nfa.
WAR044503	12/3/2025	12/3/2025	Pollution hotline (phone, web, app): officer was shot. blood washed down by fire. nfa.	Yes, No Notice Required	s othello st / martin luther king jr wy s	seattle	98118	47.537046	-122.281328	Other: officer was shot. blood washed down by fire. nfa.	Other: officer was shot. blood washed down by fire. nfa.	Not applicable: officer was shot. blood washed down by fire. nfa.	Referred to other agency or department: officer was shot. blood washed down by fire. nfa.	officer was shot. blood washed down by fire. nfa.
WAR044503	11/24/2025	11/24/2025	Pollution hotline (phone, web, app): diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.	Vehicle-related business: diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.	Not applicable: diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.	Clean-up: diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.	diesel spill to private property pavement due to a leaking truck. property owner hired a cleanup contractor for recovery. no ms4 drain impact.
WAR044503	12/5/2025	12/5/2025	Pollution hotline (phone, web, app): report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.	Yes, No Notice Required	500 s sullivan st	seattle	98108	47.527522	-122.327258	Fuel and/or vehicle related fluids: report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.	Unconfirmed, unspecified, or not identified: report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.	Not applicable: report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.	Other: report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.	report of sheen on the public right of way. no source identified. sheen unrecoverable and no documented impacts to separated drainage system.
WAR044503	12/5/2025	12/5/2025	Pollution hotline (phone, web, app): spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.	Yes, Notified Ecology	852 rainier ave s	seattle	98144	47.594753	-122.310188	Fuel and/or vehicle related fluids: spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.	Vehicle-related business: spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.	Not applicable: spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.	Clean-up: spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.	spill to private pavement at a gas station from an outside vendor. no impacts to the stormwater drains. spill cleanup completed by responsible party.
WAR044503	12/5/2025	12/5/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills	Yes, Notified Ecology	12552 12th ave ne	seattle	98125	47.720920	-122.315131	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills	Vehicle-related business: spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills	Not applicable: spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills	Clean-up: spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills	spill of hydraulic oil to pavement. responsible party conducted cleanup with no impacts to stormdrains or thorton creek. nfa_spills
WAR044503	12/7/2025	12/7/2025	Pollution hotline (phone, web, app): sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.	Yes, Notified Ecology	24th ave nw & nw 95th st	seattle	98117	47.697866	-122.387574	Sewage/septage/pet waste/human waste: sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.	Construction activity: sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.	Not applicable: sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.	Clean-up: sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed. Other: sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.	sanitary mainline overflow to row and impact to drainage catch basin. sewage did not outfall to separated system and is contained in catch basin--cleanup completed.
WAR044503	12/6/2025	12/6/2025	Pollution hotline (phone, web, app): report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.	Yes, Notified Ecology	1001 ne boat st	seattle	98105	47.653401	-122.318106	Fuel and/or vehicle related fluids: report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.	Vehicle-related business: report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.	Not applicable: report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.	Referred to other agency or department: report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response. Other: report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.	report of sheen in portage bay. located boat at marina that is leaking. referred to state agency for response.
WAR044503	12/8/2025	12/8/2025	Pollution hotline (phone, web, app): unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.	Yes, Notified Ecology	17th ave nw & nw 49th st	seattle	98107	47.664396	-122.378901	Fuel and/or vehicle related fluids: unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.	Other accident/spill: unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.	Not applicable: unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.	Clean-up: unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa. Other: unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.	unknown sheen discovered and cleaned up. ms4 impacted. no downstream impact. nfa.
WAR044503	12/8/2025	12/8/2025	Pollution hotline (phone, web, app): report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.	Yes, Notified Ecology	2834 35th ave w	seattle	98199	47.646072	-122.402048	Fuel and/or vehicle related fluids: report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.	Vehicle-related business: report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.	Not applicable: report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.	Clean-up: report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.	report of a commercial vehicle having a mechanical failure, causing the hydraulic hose to break and spill approximately 3 - 4 gallons of fluid onto the pavement. the responsible party cleaned up the spilled material. no impact to ms4.
WAR044503	12/9/2025	12/9/2025	Pollution hotline (phone, web, app): houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.	Yes, Notified Ecology	2019 fairview ave e	seattle	98102	47.637250	-122.330704	Sewage/septage/pet waste/human waste: houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.	Other accident/spill: houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.	Not applicable: houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.	Clean-up: houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired. Other: houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.	houseboat sewer line disconnected. unknown quantity discharge to waterbody. resident ceased discharge and is getting sewer line repaired.
WAR044503	12/9/2025	12/9/2025	ERTS referral: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.	Yes, Notified Ecology	2623 ne university village st	seattle	98105	47.662463	-122.298985	Sewage/septage/pet waste/human waste: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.	Other accident/spill: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa. Other: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.	Not applicable: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.	Clean-up: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa. Referred to other agency or department: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa. Other: sso caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.	ss0 caused by a broken pump. union bay impacted by 1800 gallons of sewage. ms4 impacted. nfa.
WAR044503	12/10/2025	12/10/2025	Pollution hotline (phone, web, app): drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.	Yes, Notified Ecology	linden ave n & n 88th st	seattle	98103	47.692744	-122.347238	Solid waste/trash: drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.	Other: drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.	Not applicable: drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.	Clean-up: drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa. Other: drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.	drains were protected while waste company dealt with load fire. ms4 roadway and drains cleaned. no downstream impacts observed. nfa.
WAR044503	12/10/2025	12/10/2025	Pollution hotline (phone, web, app): found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.	Yes, Notified Ecology	ne 45th st & 12th ave ne	seattle	98105	47.661308	-122.315459	Other: found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.	Other accident/spill: found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.	Not applicable: found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.	Other: found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.	found no sign of pollutant at intersection or at outfall. coolant leak was likely a slow release over miles. nfa.
WAR044503	12/11/2025	12/11/2025	Pollution hotline (phone, web, app): report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.	Yes, Notified Ecology	7001 seaview ave nw	seattle	98117	47.680017	-122.405796	Fuel and/or vehicle related fluids: report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.	Vehicle-related business: report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.	Not applicable: report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.	Clean-up: report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact. Other: report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.	report of oil sheen in parking lot with impacted catch basin. reporting party cleaned with absorbent pads and did not observe any sheen left in non-spu catch basin, and never observed sheen near the non-spu outfall. no ms4 impact.
WAR044503	12/11/2025	12/11/2025	ERTS referral: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.	Yes, Notified Ecology	24808 hwy 99	kent	0	0	0	Fuel and/or vehicle related fluids: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.	Unconfirmed, unspecified, or not identified: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.	Not applicable: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.	Clean-up: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen. Other: sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.	Complaint. sheen was observed at satellite ms4. no source identified. proper agencies were notified. pond was boomed to collect sheen.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	12/11/2025	12/11/2025	Pollution hotline (phone, web, app): received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.	Yes, No Notice Required	holman rd nw & 14th ave nw	seattle	98117	47.695618	-122.374118	Fuel and/or vehicle related fluids: received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.	Other accident/spill: received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.	Not applicable: received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.	Other: received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.	received a report about sheen on the roadway. site visit concluded there was a small amount of unrecoverable sheen on the road with no drain impact. no action was taken.
WAR044503	12/11/2025	12/11/2025	Pollution hotline (phone, web, app): received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt	Yes, Notified Ecology	4528 13th ave s	seattle	98108	47.562619	-122.315793	Fuel and/or vehicle related fluids: received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt	Other accident/spill: received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt	Not applicable: received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt	Clean-up: received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt. Other: received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt	received a report about oil being spilled to the roadway. site visit confirmed oil had been spilled and made its way to a drain. i put boom in the drain and notified ecology no oil made its way past the drain. the source of the spill had been cleaned up. no further action is necessary. tt
WAR044503	12/11/2025	12/11/2025	Pollution hotline (phone, web, app): report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.	Yes, Notified Ecology	915 ne boat st	seattle	98105	47.653761	-122.318490	Fuel and/or vehicle related fluids: report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.	Unconfirmed, unspecified, or not identified: report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.	Not applicable: report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.	Clean-up: report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement. Referred to other agency or department: report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.	report of sheen and diesel odor in waterbody. checked outfall and upstream maintenance hole; did not see or smell any diesel/sheen in spu assets. referred to department of ecology, no ms4 involvement.
WAR044503	12/12/2025	12/12/2025	Pollution hotline (phone, web, app): report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.	Yes, No Notice Required	624 n 34th st	seattle	98103	47.649946	-122.350018	Other: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.	Construction activity: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4. Other: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.	Not applicable: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.	Education/technical assistance: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4. Enforcement: report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.	report of construction contractor stockpiling cold patch asphalt in the public row with no cover. spill responder investigated the site and educated the contractor about code. no impact to the ms4.
WAR044503	12/13/2025	12/13/2025	Pollution hotline (phone, web, app): report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.	Yes, Notified Ecology	416 randolph ave	seattle	98122	47.605638	-122.285332	Fuel and/or vehicle related fluids: report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.	Intentional dumping: report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.	Not applicable: report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.	Clean-up: report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact. Other: report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.	report of gasoline streak on street from vandalized vehicle. recovered a small amount of gasoline from the street; checked downstream catch basin, which had no gasoline or sheen in it; no sheen seen at the outfall. no ms4 impact.
WAR044503	12/14/2025	12/14/2025	Pollution hotline (phone, web, app): report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.	Yes, No Notice Required	904 alaskan way	seattle	98104	47.603775	-122.337418	Other: report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.	Unconfirmed, unspecified, or not identified: report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.	Not applicable: report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.	Clean-up: report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact. Other: report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.	report of vomit entering drain. investigation found no impact to any drains and was referred to private property management for cleanup. no ms4 impact.
WAR044503	12/8/2025	12/8/2025	Pollution hotline (phone, web, app): mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.	Yes, No Notice Required	32nd ave ne & ne 143rd st	seattle	98125	47.731948	-122.293840	Other: mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.	Vehicle collision: mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.	Not applicable: mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.	Other: mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.	mva caused oil to spill to ground. no impacts to drains or ms4. spill cleaned.
WAR044503	12/15/2025	12/15/2025	Pollution hotline (phone, web, app): report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.	Yes, Notified Ecology	nw 125th st / 1st ave nw	seattle		47.719617	-122.358258	Fuel and/or vehicle related fluids: report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.	Unconfirmed, unspecified, or not identified: report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.	Not applicable: report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.	Clean-up: report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted. Other: report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.	report of sheen from an unknown source impacting pavement and roadside ponding. spu was not able to determine a source and deployed absorbents to the at risk downstream ms4 drain which was not yet impacted.
WAR044503	12/16/2025	12/16/2025	Pollution hotline (phone, web, app): a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.	Vehicle-related business: a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.	Not applicable: a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.	Clean-up: a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled. Other: a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.	a milk distributor saw a semi truck driver leak diesel fuel down about a hundred yards, and hired a contractor with a sweeper to clean it up. no drains or ms4 were impacted, and about a gallon of diesel in total was spilled.
WAR044503	12/17/2025	12/17/2025	Pollution hotline (phone, web, app): report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.	Yes, No Notice Required	2470 s columbian way	seattle	98108	47.560915	-122.300559	Other: report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.	Unconfirmed, unspecified, or not identified: report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.	Not applicable: report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.	Clean-up: report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team. Other: report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.	report of sewage surfacing and impacting ms4 found to be ground water discharge. referral to spu drainage investigations team.
WAR044503	12/17/2025	12/17/2025	Pollution hotline (phone, web, app): spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.	Yes, Notified Ecology	852 rainier ave s	seattle	98144	47.594753	-122.310188	Fuel and/or vehicle related fluids: spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.	Vehicle-related business: spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.	Not applicable: spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.	Clean-up: spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party. Other: spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.	spill of gasoline at a gas station due to a punctured fuel tank on a clients vehicle. no impacts to drainage or water body, all gasoline was confined to the fueling area. spill cleanup initiated by gas station staff and completed by a response contractor hired by the responsible party.
WAR044503	12/18/2025	12/18/2025	ERTS referral: arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.	Yes, Notified Ecology	sand point way / ne 105th st	seattle		0	0	Fuel and/or vehicle related fluids: arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.	Unconfirmed, unspecified, or not identified: arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.	Not applicable: arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.	Other: arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.	Complaint. arrived on site and located the sheen. the sheen was along the side of the road with no drain involvement. sheen was a small amount that was unrecoverable.
WAR044503	12/18/2025	12/18/2025	Pollution hotline (phone, web, app): received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.	Yes, Notified Ecology	5126 s kenyon st	seattle	98118	47.531883	-122.268755	Unconfirmed, unspecified, or not identified: received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.	Unconfirmed, unspecified, or not identified: received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.	Not applicable: received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.	Other: received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.	received a report about possible sewage discharging from the sidewalk area. site visit concluded there to be no drain involvement and the water had a very slight ammonia hit. this address history so i referred them to the side sewer program.
WAR044503	12/18/2025	12/18/2025	Pollution hotline (phone, web, app): received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.	Yes, No Notice Required	ne 107th st & 17th ave ne	seattle	98125	47.706675	-122.309960	Other: received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.	Other: received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.	Not applicable: received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.	Clean-up: received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement. Other: received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.	received a report about a garbage truck fire. they had to dump their load. site visit confirmed it had been cleaned up properly and no drain involvement.
WAR044503	12/20/2025	12/20/2025	Pollution hotline (phone, web, app): received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.	Yes, No Notice Required	university way ne / ne 41st st	seattle	98105	47.656822	-122.313258	Sewage/septage/pet waste/human waste: received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.	Other: received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.	Not applicable: received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.	Referred to other agency or department: received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk. Other: received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.	Complaint. received a report about some feces near a bus stop with no drain involvement. i referred this complaint to sdot. they agreed to hire a bio clean company to clean the sidewalk.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	12/21/2025	12/21/2025	Pollution hotline (phone, web, app): received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.	Yes, Notified Ecology	1228 harbor ave sw	seattle	98116	47.592432	-122.382121	Fuel and/or vehicle related fluids: received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.	Vehicle-related business: received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.	Not applicable: received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.	Other: received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.	received a report about a vehicle being worked on outside. site visit found a little bit of sheen around parked car. it was not being worked on at the time. i put boom in the nearby drain and notified ecology. minimal sheen made it to the drain. no further action is necessary.
WAR044503	12/22/2025	12/22/2025	Pollution hotline (phone, web, app): received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.	Yes, No Notice Required	2700 airport way s	seattle	98134	47.579183	-122.320757	Fuel and/or vehicle related fluids: received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.	Vehicle-related business: received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.	Not applicable: received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.	Clean-up: received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary. Other: received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.	received a report about hydraulic fluid being spilled to the pavement with no drain involvement. the responsible party cleaned and disposed of the waste. no further action is necessary.
WAR044503	12/22/2025	12/22/2025	Pollution hotline (phone, web, app): received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.	Yes, No Notice Required	15th ave e & e valley st	seattle	98112	47.626069	-122.312590	Other: received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.	Intentional dumping: received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.	Not applicable: received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.	Clean-up: received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly. Other: received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.	received a report about a porta potty being knocked over the previous day with no drain involvement. reporting party was concerned about the odor lingering around. i tested the puddle along the curbline in multiple locations for ammonia and it came back negative. the spill had been cleaned up properly.
WAR044503	12/24/2025	12/24/2025	Pollution hotline (phone, web, app): a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.	Yes, Notified Ecology	sw spokane st / harbor ave sw	seattle	98126	47.571787	-122.370665	Fuel and/or vehicle related fluids: a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.	Vehicle-related business: a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.	Not applicable: a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.	Clean-up: a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated. Other: a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.	a motor oil sheen was reported on a roadway, and there are signs that a motor home was adding motor oil to their engine and left the two quarts under their vehicle, which leaked. sheen was visible down the roadside gutter and the oil looks to have reached a separated storm drain. we investigated further downstream and did not observe any impact; the contamination was cleaned with on-hand absorbents, the quarts were bagged and referred for removal, and a boom was left in the affected catch basin. the referral led to all spill items and motor home removed or relocated.
WAR044503	12/24/2025	12/24/2025	Pollution hotline (phone, web, app): a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.	Yes, No Notice Required	9447 rainier ave s	seattle	98118	47.519929	-122.263149	Food-related oil/grease: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.	Other: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.	Not applicable: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.	Education/technical assistance: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date. Enforcement: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date. Other: a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.	a health inspector contacted spu spill response relating to food spillage around a private drain in a parking lot behind a restaurant used as a commissary shared by two food trucks. spu spill responders found poor site maintenance and no ms4 impact, while another spu emergency responder dropped in as well. the site conditions warranted a follow-up joint inspection between spu and kc health at a later date.
WAR044503	12/24/2025	12/24/2025	Pollution hotline (phone, web, app): spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.	Yes, No Notice Required	12041 33rd ave ne	seattle	98125	47.716691	-122.293266	Fuel and/or vehicle related fluids: spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.	Vehicle-related business: spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.	Not applicable: spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.	Clean-up: spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.	spill of hydraulic oil to right of way, no drainage impact. spill cleaned up by responsible party's contractor, while support was provided by spu providing traffic control.
WAR044503	12/30/2025	12/30/2025	Pollution hotline (phone, web, app): a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.	Yes, Notified Ecology	sw barton pl / 22nd ave sw	seattle		47.522454	-122.361882	Fuel and/or vehicle related fluids: a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.	Vehicle-related business: a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.	Not applicable: a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.	Clean-up: a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize. Other: a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.	a municipal bus had a three-gallon coolant leak from a non-accident mechanical issue. they applied absorbant and had a separate internal crew clean it up, no drains were impacted and spu crews did not need to mobilize.
WAR044503	12/31/2025	12/31/2025	Pollution hotline (phone, web, app): report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4.	Yes, Notified Ecology	4058 rainier ave s	seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: Diesel leak from commercial vehicle. Contractor hired for cleanup. No impact to MS4.	Vehicle-related business: report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4.	Not applicable: report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4.	Clean-up: report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4. Other: report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4.	report of commercial vehicle leaking diesel. contractor was hired for cleanup. no impact to ms4.
WAR044503	12/31/2025	12/31/2025	Pollution hotline (phone, web, app): report of possible creosote bleeding from old dock pilings, into lake youngs.	Yes, No Notice Required	18015 se lake youngs rd	renton	98058	47.422691	-122.099235	Unconfirmed, unspecified, or not identified: report of possible creosote bleeding from old dock pilings, into lake youngs.	Other: report of possible creosote bleeding from old dock pilings, into lake youngs.	Not applicable: report of possible creosote bleeding from old dock pilings, into lake youngs.	Clean-up: report of possible creosote bleeding from old dock pilings, into lake youngs. Other: report of possible creosote bleeding from old dock pilings, into lake youngs.	report of possible creosote bleeding from old dock pilings, into lake youngs.
WAR044503	12/31/2025	12/31/2025	Pollution hotline (phone, web, app): report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.	Yes, No Notice Required	8540 greenwood ave n	seattle	98103	47.691400	-122.354709	Food-related oil/grease: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.	Other: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.	Not applicable: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.	Clean-up: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4. Education/technical assistance: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4. Other: report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.	report of used cooking oil (uco) spill in an alleyway. spill responder investigated and verified that the uco container was leaking into the alleyway pavement and a private catch basin. used absorbent pads, granular, and boom to clean. impact to combined sewer system, no impact to city ms4.