

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|-----------------------------------|---------|-----------|-------------|--|---|--|---|--|--|
| WAR044503 | 8/26/2024 | 8/26/2024 | MS4 inspection or screening: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. | Yes, Notified Ecology | 7101 m l king jr way s | Seattle | 98118 | 47.538461 | -122.283065 | Other: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. | Unconfirmed, unspecified, or not identified: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. | Not applicable: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. | Other: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. | Complaint. dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going. |
| WAR044503 | 10/28/2024 | 10/28/2024 | Pollution hotline (phone, web, app): approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. | Yes, No Notice Required | 65 s washington st | Seattle | 98104 | 0 | 0 | Food-related oil/grease: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. | Other accident/spill: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. | Not applicable: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. | Clean-up: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. , Referred to other agency or department: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. , Other: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. party completed a cleanup with absorbents and a sweeper truck. | approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. |
| WAR044503 | 6/5/2024 | 6/5/2024 | Direct report to your staff: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. | Yes, No Notice Required | nfa_spills 7507 38th ave ne | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. | Vehicle-related business: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. | Not applicable: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. | nfa_spills, Clean-up: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. | spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck. |
| WAR044503 | 2/27/2024 | 2/27/2024 | Direct report to your staff: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. | Yes, No Notice Required | 3845 aurora ave n | Seattle | 98103 | 0 | 0 | Sediment/soil: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. | Other: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. | Not applicable: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. | Other: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. | Complaint. report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4. |
| WAR044503 | 7/9/2024 | 7/9/2024 | Pollution hotline (phone, web, app): commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. | Yes, Notified Ecology | 4500 west marginal way sw | Seattle | 98106 | 47.563193 | -122.350679 | Fuel and/or vehicle related fluids: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. | Vehicle-related business: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. | Not applicable: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. | Clean-up: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. , Other: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. | commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. |
| WAR044503 | 11/21/2024 | 11/21/2024 | Pollution hotline (phone, web, app): self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Yes, Notified Ecology | 9075 51st ave ne | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Other accident/spill: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Not applicable: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Clean-up: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. , Referred to other agency or department: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. , Other: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. |
| WAR044503 | 8/12/2024 | 8/12/2024 | Pollution hotline (phone, web, app): coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. | Yes, Notified Ecology | 35th ave w & mcgraw st | Seattle | 98199 | 47.639548 | -122.402388 | Fuel and/or vehicle related fluids: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. | Other accident/spill: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. | Not applicable: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. | Clean-up: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. | coolant reported impacting pavement. clean up complete. no impact to ms4. nfa. |
| WAR044503 | 7/15/2024 | 7/15/2024 | Pollution hotline (phone, web, app): report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. | Yes, Notified Ecology | 1415 broadway | Seattle | 98122 | 47.613179 | -122.321227 | Food-related oil/grease: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. | Other accident/spill: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. | Not applicable: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. | Other: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. | report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4. |
| WAR044503 | 4/16/2024 | 4/16/2024 | Pollution hotline (phone, web, app): electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. | Yes, Notified Ecology | 13285 15th ave ne | Seattle | 98125 | 47.725398 | -122.313167 | Fuel and/or vehicle related fluids: electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. | Other accident/spill: electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. | Not applicable: electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. | Clean-up: electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. , Other: electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. | electrical vault thought to contain oil with pcb pumped to a private drain. pcs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. |
| WAR044503 | 9/9/2024 | 9/9/2024 | Pollution hotline (phone, web, app): undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. | Yes, No Notice Required | 5309 22nd ave nw | Seattle | 98107 | 47.667013 | -122.385029 | Food-related oil/grease: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. | Intentional dumping: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. | Not applicable: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. | Clean-up: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. , Education/technical assistance: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. | undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. |
| WAR044503 | 7/31/2024 | 7/31/2024 | Pollution hotline (phone, web, app): commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. | Yes, Notified Ecology | sw spokane st / delridge way sw | Seattle | 98106 | 47.572094 | -122.360020 | Fuel and/or vehicle related fluids: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. | Vehicle-related business: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. | Not applicable: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. | Clean-up: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. , Other: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. | commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. |
| WAR044503 | 6/2/2024 | 6/2/2024 | Pollution hotline (phone, web, app): spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. | Yes, No Notice Required | 3919 18th ave w | Seattle | 98119 | 47.655611 | -122.380643 | Fuel and/or vehicle related fluids: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. | Intentional dumping: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. | Not applicable: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. | Clean-up: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. , Referred to other agency or department: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. , Other: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. | spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. |
| WAR044503 | 5/29/2024 | 5/29/2024 | Business inspection: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. | Yes, No Notice Required | lake city way ne & ravenna ave ne | Seattle | 98115 | 47.696228 | -122.305747 | Solid waste/trash: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. | Intentional dumping: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. | Not applicable: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. | Referred to other agency or department: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. , Other: report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. | Complaint. report of over two dozen tires dumped into thornton creek. referred to parks department who will remove them. no impact to ms4. |
| WAR044503 | 2/15/2024 | 2/15/2024 | Pollution hotline (phone, web, app): vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | Yes, No Notice Required | 38th ave s / s andover st | Seattle | 47.567922 | -122.285061 | Fuel and/or vehicle related fluids: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | Vehicle collision: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | Not applicable: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | Clean-up: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. , Other: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. | |
| WAR044503 | 2/6/2024 | 2/6/2024 | Pollution hotline (phone, web, app): report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. | Yes, No Notice Required | 4553 university way ne | Seattle | 98105 | 47.662789 | -122.313414 | Food-related oil/grease: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. | Unconfirmed, unspecified, or not identified: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. | Not applicable: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. | Other: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. , Other: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. | Complaint. report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|--|--|--|
| WAR044503 | 7/13/2024 | 7/13/2024 | Pollution hotline (phone, web, app): received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. | Yes, Notified Ecology | 1930 pike pl | Seattle | 98101 | 47.610418 | -122.343147 | Other: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. | Vehicle collision: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. | Not applicable: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. | Other: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. | received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified. |
| WAR044503 | 4/12/2024 | 4/12/2024 | Pollution hotline (phone, web, app): truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. | Yes, No Notice Required | 2315 30th ave w | Seattle | 98199 | 47.639190 | -122.395685 | Fuel and/or vehicle related fluids: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. | Vehicle-related business: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. | Not applicable: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. | Clean-up: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. Other: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. | truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. |
| WAR044503 | 3/24/2024 | 3/24/2024 | Pollution hotline (phone, web, app): report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. | Yes, Notified Ecology | 4127 48th ave s | Seattle | 98118 | 47.565644 | -122.273645 | Fuel and/or vehicle related fluids: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. | Construction activity: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. | Not applicable: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. | Clean-up: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. Referred to other agency or department: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. | report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. |
| WAR044503 | 4/26/2024 | 4/26/2024 | ERTS referral: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. | Yes, No Notice Required | water body | Seattle | | 47.636837 | -122.333631 | Fuel and/or vehicle related fluids: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. | Other: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. | Not applicable: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. | Referred to other agency or department: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. | spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up. |
| WAR044503 | 10/4/2024 | 10/4/2024 | Pollution hotline (phone, web, app): report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. | Yes, Notified Ecology | 1406 e union st | Seattle | 98122 | 47.613114 | -122.313929 | Fuel and/or vehicle related fluids: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. | Vehicle collision: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. | Not applicable: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. | Clean-up: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. | report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents. |
| WAR044503 | 1/22/2024 | 1/22/2024 | Pollution hotline (phone, web, app): leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. | Yes, Notified Ecology | 13525 lake city way ne | Seattle | 98125 | 47.727174 | -122.292867 | Fuel and/or vehicle related fluids: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. | Vehicle-related business: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. | Not applicable: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. | Clean-up: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. | leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures. |
| WAR044503 | 12/27/2024 | 12/27/2024 | Pollution hotline (phone, web, app): no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. | Yes, Notified Ecology | s graham st & 31st ave s | Seattle | 98108 | 47.546163 | -122.292604 | Fuel and/or vehicle related fluids: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. | Vehicle collision: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. | Not applicable: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. | Clean-up: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. Other: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. | no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. |
| WAR044503 | 2/14/2024 | 2/14/2024 | Direct report to your staff: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. | Yes, Notified Ecology | 12301 stone ave n | Seattle | 98133 | 47.718839 | -122.342425 | Fuel and/or vehicle related fluids: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. | Intentional dumping: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. | Not applicable: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. | Clean-up: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. Other: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. | Complaint. approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. |
| WAR044503 | 9/16/2024 | 9/16/2024 | Pollution hotline (phone, web, app): motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted | Yes, Notified Ecology | 2425 sw barton st | Seattle | 98106 | 47.520858 | -122.364365 | Fuel and/or vehicle related fluids: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted | Intentional dumping: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted | Not applicable: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted | Clean-up: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted | motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted |
| WAR044503 | 6/4/2024 | 6/4/2024 | Pollution hotline (phone, web, app): windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. | Yes, Notified Ecology | 9025 cyrus ave nw | Seattle | 98117 | 47.695009 | -122.399060 | Fuel and/or vehicle related fluids: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. | Other: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. | Not applicable: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. | Clean-up: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. Other: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. | windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. |
| WAR044503 | 4/9/2024 | 4/9/2024 | Pollution hotline (phone, web, app): chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. | Yes, Notified Ecology | 12524 10th ave nw | Seattle | 98177 | 47.720336 | -122.368732 | Sediment/soil: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. | Construction activity: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. | Not applicable: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. | Education/technical assistance: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. | chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. |
| WAR044503 | 7/12/2024 | 7/12/2024 | Pollution hotline (phone, web, app): received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. | Yes, No Notice Required | 1st ave nw & nw 132nd st | Seattle | 98177 | 47.725062 | -122.358259 | Sewage/septage/pet waste/human waste: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. | Intentional dumping: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. | Not applicable: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. | Other: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. | received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary. |
| WAR044503 | 4/26/2024 | 4/26/2024 | ERTS referral: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. | Yes, Notified Ecology | 5228 shilshole ave nw | Seattle | 98107 | 47.665321 | -122.382858 | Other: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. | Other accident/spill: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. | Not applicable: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. | Other: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. | Complaint. report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4. |
| WAR044503 | 7/18/2024 | 7/18/2024 | Pollution hotline (phone, web, app): a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. | Yes, No Notice Required | 600 e pine st | Seattle | 98122 | 47.615595 | -122.324158 | Solid waste/trash: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. | Other accident/spill: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. | Not applicable: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. | Clean-up: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. Education/technical assistance: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. Other: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. | a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------------|---------|-------|-----------|-------------|---|--|---|---|---|
| WAR044503 | 2/26/2024 | 2/26/2024 | Pollution hotline (phone, web, app): spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. | Yes, No Notice Required | 1st ave s / s walker st | Seattle | | 47.583978 | -122.334209 | Fuel and/or vehicle related fluids: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. | Vehicle collision: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. | Not applicable: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. | Clean-up: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. | spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow. |
| WAR044503 | 6/4/2024 | 6/4/2024 | MS4 inspection or screening: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. | Yes, Notified Ecology | e lynn st / fairview ave e | Seattle | | 47.639726 | -122.329389 | Other: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. | Unconfirmed, unspecified, or not identified: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. | Not applicable: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. | Other: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. | Complaint. spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing. |
| WAR044503 | 8/2/2024 | 8/2/2024 | Pollution hotline (phone, web, app): spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. | Yes, No Notice Required | 1550 n 115th st | Seattle | 98133 | 47.714247 | -122.336898 | Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. | Vehicle-related business: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. | Not applicable: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. | Clean-up: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. | spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party. |
| WAR044503 | 8/17/2024 | 8/17/2024 | Pollution hotline (phone, web, app): spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. | Yes, No Notice Required | 18800 orillia rd s | Seattle | | 0 | 0 | Fuel and/or vehicle related fluids: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. | Other accident/spill: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. | Not applicable: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. | Clean-up: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. | spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required. |
| WAR044503 | 8/21/2024 | 8/21/2024 | Pollution hotline (phone, web, app): spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. | Yes, No Notice Required | 2420 westlake ave n | Seattle | 98109 | 47.640432 | -122.341344 | Fuel and/or vehicle related fluids: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. | Other accident/spill: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. | Not applicable: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. | Referred to other agency or department: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. | spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident. |
| WAR044503 | 8/13/2024 | 8/13/2024 | Business inspection: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 | Yes, Notified Ecology | 5146 25th ave ne | Seattle | 98105 | 47.667757 | -122.300390 | Food-related oil/grease: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 | Other: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 | Not applicable: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 | Clean-up: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 | Complaint. solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4 |
| WAR044503 | 12/18/2024 | 12/18/2024 | ERTS referral: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. | Yes, Notified Ecology | 4706 sw eddy st | Seattle | 98136 | 47.546015 | -122.393004 | Fuel and/or vehicle related fluids: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. | Vehicle-related business: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. | Not applicable: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. | Clean-up: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. Other: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. | Complaint. report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. |
| WAR044503 | 5/14/2024 | 5/14/2024 | Direct report to your staff: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. | Yes, Notified Ecology | 4766 1st ave s | Seattle | 98134 | 47.558775 | -122.333660 | Soap or cleaning chemicals: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. | Other: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. | Not applicable: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. | Education/technical assistance: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. Enforcement: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. Other: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. | company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity. |
| WAR044503 | 7/19/2024 | 7/19/2024 | Pollution hotline (phone, web, app): waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. | Yes, Notified Ecology | 11038 39th ave ne | Seattle | 98125 | 47.709492 | -122.286302 | Fuel and/or vehicle related fluids: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. | Vehicle-related business: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. | Not applicable: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. | Clean-up: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. | waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted. |
| WAR044503 | 12/27/2024 | 12/27/2024 | Pollution hotline (phone, web, app): mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. | Yes, Notified Ecology | 1st ave bridge | Seattle | | 0 | 0 | Fuel and/or vehicle related fluids: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. | Vehicle collision: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. | Not applicable: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. | Referred to other agency or department: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. | mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority. |
| WAR044503 | 11/2/2024 | 11/2/2024 | Pollution hotline (phone, web, app): drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. | Yes, Notified Ecology | 1011 sw klickitat way | Seattle | 98134 | 47.569654 | -122.348452 | Fuel and/or vehicle related fluids: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. | Intentional dumping: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. | Not applicable: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. | Referred to other agency or department: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. | drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa. |
| WAR044503 | 11/8/2024 | 11/8/2024 | ERTS referral: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. | Yes, Notified Ecology | 3701 ne 45th st | Seattle | 98105 | 47.661011 | -122.288007 | Food-related oil/grease: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. | Other accident/spill: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. | Not applicable: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. | Clean-up: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. Education/technical assistance: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. Other: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. | Complaint. restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. |
| WAR044503 | 1/31/2024 | 1/31/2024 | Pollution hotline (phone, web, app): self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. | Yes, Notified Ecology | 2001 w garfield st | Seattle | 98119 | 47.630999 | -122.382825 | Fuel and/or vehicle related fluids: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. | Unconfirmed, unspecified, or not identified: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. | Not applicable: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. | Clean-up: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. Other: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. | self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall. |
| WAR044503 | 12/16/2024 | 12/16/2024 | ERTS referral: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. | Yes, Notified Ecology | 12347 25th ave ne | Seattle | 98125 | 47.718908 | -122.302327 | Firefighting foam: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. | Other: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. | Not applicable: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. | nfa_spills, Other: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. | Complaint. li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup. |
| WAR044503 | 10/31/2024 | 10/31/2024 | Pollution hotline (phone, web, app): actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. | Yes, Notified Ecology | e montlake pt e & montlake bv off rp | Seattle | 98105 | 47.661247 | -122.296650 | Other: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. | Other accident/spill: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. | Not applicable: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. | Referred to other agency or department: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. Other: actually referred to rp. | actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|---|---------|-------|-----------|-------------|--|---|--|---|--|
| WAR044503 | 3/21/2024 | 3/21/2024 | Pollution hotline (phone, web, app): self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. | Yes, Notified Ecology | 1701 ne 96th st | Seattle | 98115 | 47.698288 | -122.309230 | Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. , Sediment/soil: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. | Vehicle-related business: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. | Not applicable: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. | Clean-up: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. , Other: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. | self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. |
| WAR044503 | 10/29/2024 | 10/29/2024 | Pollution hotline (phone, web, app): received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. | Yes, No Notice Required | poplar pl s & s dean st | Seattle | 98144 | 47.595446 | -122.312569 | Fuel and/or vehicle related fluids: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. | Intentional dumping: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. | Not applicable: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. | Other: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. | received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed. |
| WAR044503 | 8/9/2024 | 8/9/2024 | Pollution hotline (phone, web, app): found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. | Yes, No Notice Required | 2114 30th ave s | Seattle | 98144 | 47.584008 | -122.293760 | Unconfirmed, unspecified, or not identified: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. | Vehicle-related business: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. | Not applicable: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. | Clean-up: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. | found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa. |
| WAR044503 | 2/7/2024 | 2/7/2024 | Pollution hotline (phone, web, app): spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. | Yes, Notified Ecology | 12354 24th ave ne | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. | Other accident/spill: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. , Other: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. | Not applicable: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. | Clean-up: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. , Referred to other agency or department: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. | spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. |
| WAR044503 | 1/6/2024 | 1/6/2024 | Pollution hotline (phone, web, app): received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. | Yes, Notified Ecology | s norfolk st & martin luther king jr wy s | Seattle | 98118 | 47.513356 | -122.278919 | Fuel and/or vehicle related fluids: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. | Vehicle collision: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. | Not applicable: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. | Clean-up: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. | received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary. |
| WAR044503 | 7/29/2024 | 7/29/2024 | Pollution hotline (phone, web, app): self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. | Yes, Notified Ecology | 5000 fauntleroy way sw | Seattle | 98136 | 47.557364 | -122.381110 | Fuel and/or vehicle related fluids: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. | Intentional dumping: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. | Not applicable: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. | Clean-up: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. , Education/technical assistance: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. | self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. |
| WAR044503 | 9/3/2024 | 9/3/2024 | Direct report to your staff: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. | Yes, Notified Ecology | 1st ave s / denver ave s | Seattle | 98146 | 47.561211 | -122.334213 | Other: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. | Other accident/spill: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. , Intentional dumping: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. | Not applicable: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. | Clean-up: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. , Other: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. | white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. |
| WAR044503 | 4/28/2024 | 4/28/2024 | Pollution hotline (phone, web, app): report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. | Yes, No Notice Required | sw admiral way/63rd ave sw | Seattle | 98116 | 47.575917 | -122.413460 | Fuel and/or vehicle related fluids: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. | Vehicle collision: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. | Not applicable: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. | Referred to other agency or department: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. , Other: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. | report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. |
| WAR044503 | 12/30/2024 | 12/30/2024 | Pollution hotline (phone, web, app): home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. | Yes, Notified Ecology | 5029 harold pl ne | Seattle | 98105 | 47.665484 | -122.272097 | Fuel and/or vehicle related fluids: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. | Vehicle-related business: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. | Not applicable: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. | Clean-up: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. | home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. |
| WAR044503 | 2/13/2024 | 2/13/2024 | Pollution hotline (phone, web, app): received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. | Yes, No Notice Required | 1st ave ne / ne 100th st | Seattle | 98115 | 47.701362 | -122.328512 | Fuel and/or vehicle related fluids: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. | Vehicle collision: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. | Not applicable: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. | Clean-up: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. | received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. |
| WAR044503 | 9/26/2024 | 9/26/2024 | Pollution hotline (phone, web, app): caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. | Yes, Notified Ecology | 3323 walingford ave n | Seattle | 98103 | 47.647334 | -122.336721 | Fuel and/or vehicle related fluids: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. | Unconfirmed, unspecified, or not identified: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. | Not applicable: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. | Clean-up: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. , Clean-up: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. | caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. |
| WAR044503 | 12/20/2024 | 12/20/2024 | Pollution hotline (phone, web, app): report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. | Yes, Notified Ecology | 2540 westlake ave n | Seattle | 98109 | 47.643160 | -122.343248 | Fuel and/or vehicle related fluids: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. | Vehicle collision: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. | Not applicable: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. | Clean-up: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. | report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. |
| WAR044503 | 8/26/2024 | 8/26/2024 | Pollution hotline (phone, web, app): spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. | Yes, Notified Ecology | 7215 sand point way ne | Seattle | 98115 | 47.681287 | -122.264110 | Fuel and/or vehicle related fluids: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. | Intentional dumping: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. | Not applicable: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. | Clean-up: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. | spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|---------------------------------|------------|-------|-----------|-------------|---|--|---|---|---|
| WAR044503 | 3/28/2024 | 3/28/2024 | Pollution hotline (phone, web, app): spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. | Yes, No Notice Required | 28700 se 252nd pl | ravensdale | 98038 | 47.376039 | -121.961887 | Fuel and/or vehicle related fluids: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. | Vehicle-related business: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. | Not applicable: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. | Clean-up: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4., Other: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. | spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4. |
| WAR044503 | 6/11/2024 | 6/11/2024 | Pollution hotline (phone, web, app): report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. | Yes, No Notice Required | 2425 sw webster st | Seattle | 98106 | 47.534758 | -122.364701 | Fuel and/or vehicle related fluids: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. | Vehicle-related business: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. | Not applicable: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. | Clean-up: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. | report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4. |
| WAR044503 | 9/30/2024 | 9/30/2024 | Pollution hotline (phone, web, app): side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. | Yes, No Notice Required | 9020 35th ave sw | Seattle | 98126 | 47.522119 | -122.376355 | Sewage/septage/pet waste/human waste: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. | Other accident/spill: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. | Not applicable: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. | Clean-up: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Clean-up: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Referred to other agency or department: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Other: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. | side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral. |
| WAR044503 | 7/23/2024 | 7/23/2024 | Pollution hotline (phone, web, app): report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. | Yes, No Notice Required | 4247 greenwood ave n | Seattle | 98103 | 47.659055 | -122.355722 | Other: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. | Unconfirmed, unspecified, or not identified: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. | Not applicable: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. | Other: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. | report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4. |
| WAR044503 | 1/5/2024 | 1/5/2024 | Pollution hotline (phone, web, app): received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. | Yes, Notified Ecology | 7109 18th ave sw | Seattle | 98106 | 47.538803 | -122.35342 | Fuel and/or vehicle related fluids: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. | Vehicle-related business: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. | Not applicable: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. | Clean-up: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary., Other: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. | Complaint, received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemnd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary. |
| WAR044503 | 7/26/2024 | 7/26/2024 | Pollution hotline (phone, web, app): self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Yes, Notified Ecology | ne 125th st & 38th ave ne | Seattle | 98125 | 47.719223 | -122.287344 | Fuel and/or vehicle related fluids: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Vehicle-related business: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Not applicable: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Clean-up: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. |
| WAR044503 | 1/26/2024 | 1/26/2024 | Pollution hotline (phone, web, app): spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. | Yes, No Notice Required | 3012 nw 63rd st | Seattle | 98107 | 47.674695 | -122.396350 | Sediment/soil: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. | Construction activity: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. | Not applicable: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. | Education/technical assistance: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet., Other: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. | spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdci and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet. |
| WAR044503 | 1/29/2024 | 1/29/2024 | Pollution hotline (phone, web, app): spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. | Yes, No Notice Required | 8602 12th ave sw | Seattle | 98106 | 47.526327 | -122.350275 | Fuel and/or vehicle related fluids: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. | Intentional dumping: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. | Not applicable: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. | Clean-up: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. | spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil. |
| WAR044503 | 5/31/2024 | 5/31/2024 | ERTS referral: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. | Yes, Notified Ecology | 10409 aurora ave n | Seattle | 98133 | 47.704617 | -122.345067 | Fuel and/or vehicle related fluids: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. | Vehicle-related business: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. | Not applicable: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. | Referred to other agency or department: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. | Complaint, investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4. |
| WAR044503 | 6/20/2024 | 6/20/2024 | Pollution hotline (phone, web, app): received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. | Yes, No Notice Required | 722 n 95th st | Seattle | 98103 | 47.698018 | -122.348805 | Fuel and/or vehicle related fluids: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. | Vehicle-related business: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. | Not applicable: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. | Clean-up: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. | received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly. |
| WAR044503 | 4/27/2024 | 4/27/2024 | Pollution hotline (phone, web, app): report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. | Yes, No Notice Required | delridge way sw / sw andover st | Seattle | 98106 | 47.568346 | -122.363293 | Other: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. | Vehicle-related business: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. | Not applicable: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. | Clean-up: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4., Other: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. | report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4. |
| WAR044503 | 6/23/2024 | 6/23/2024 | Pollution hotline (phone, web, app): report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. | Yes, No Notice Required | 410 broadway e | Seattle | 98102 | 47.622446 | -122.320612 | Sewage/septage/pet waste/human waste: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. | Unconfirmed, unspecified, or not identified: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. | Not applicable: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. | Clean-up: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains., Other: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. | report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains. |
| WAR044503 | 2/21/2024 | 2/21/2024 | Pollution hotline (phone, web, app): grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa | Yes, Notified Ecology | 9999 holman rd nw | Seattle | 98177 | 47.701899 | -122.363749 | Food-related oil/grease: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa | Other accident/spill: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa | Not applicable: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa | Clean-up: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa. Clean-up: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa. | grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-----------|-------------|---|---|---|--|---|--|
| WAR044503 | 11/26/2024 | 11/26/2024 | ERTS referral: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. | Yes, Notified Ecology | 5029 harold pl ne | Seattle | 98105 | 47.665484 | -122.272097 | Fuel and/or vehicle related fluids: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. | Unconfirmed, unspecified, or not identified: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. | Not applicable: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. | Other: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. | Complaint. report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed. |
| WAR044503 | 6/20/2024 | 6/20/2024 | Direct report to your staff: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. | Yes, Notified Ecology | 2400 westlake ave n | Seattle | 98109 | 47.639747 | -122.340910 | Fuel and/or vehicle related fluids: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. | Unconfirmed, unspecified, or not identified: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. | Not applicable: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. | Referred to other agency or department: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. | spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions. |
| WAR044503 | 4/16/2024 | 4/16/2024 | Pollution hotline (phone, web, app): report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. | Yes, No Notice Required | 14115 aurora ave n | Seattle | 98133 | 47.731405 | -122.345805 | Other: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. | Vehicle-related business: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. | Not applicable: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. | Other: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. | report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris. |
| WAR044503 | 8/2/2024 | 8/2/2024 | Pollution hotline (phone, web, app): a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. | Yes, Notified Ecology | 12028 31st ave ne | Seattle | 98125 | 47.716332 | -122.294928 | Fuel and/or vehicle related fluids: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. | Intentional dumping: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. | Not applicable: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. | Clean-up: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. | a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4. |
| WAR044503 | 1/20/2024 | 1/20/2024 | Pollution hotline (phone, web, app): rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. | Yes, No Notice Required | n 143rd st / fremont ave n | Seattle | 98133 | 47.732313 | -122.350492 | Firefighting foam: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. | Other: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. | Not applicable: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. | Other: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. | rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken. |
| WAR044503 | 9/11/2024 | 9/11/2024 | Pollution hotline (phone, web, app): spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. | Yes, No Notice Required | 39th ave ne & ne 110th st | Seattle | 98125 | 47.708325 | -122.286751 | Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. | Vehicle-related business: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. | Not applicable: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. | nfa_spills, Clean-up: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. | spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup. |
| WAR044503 | 11/27/2024 | 11/27/2024 | Pollution hotline (phone, web, app): report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. | Yes, Notified Ecology | 7th ave s & s monroe st | Seattle | 98108 | 47.531259 | -122.325518 | Fuel and/or vehicle related fluids: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. | Unconfirmed, unspecified, or not identified: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. | Not applicable: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. | Other: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. | report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa. |
| WAR044503 | 10/7/2024 | 10/7/2024 | ERTS referral: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. | Yes, Notified Ecology | 4659 25th ave ne | Seattle | 98105 | 0 | 0 | Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. | Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. | Not applicable: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. | Clean-up: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. | Complaint, oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. |
| WAR044503 | 1/7/2024 | 1/7/2024 | Pollution hotline (phone, web, app): received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. | Yes, Notified Ecology | 23rd ave / e yesler way | Seattle | 98122 | 47.601666 | -122.302349 | Fuel and/or vehicle related fluids: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. | Vehicle-related business: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. | Not applicable: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. | Clean-up: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. | received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary. |
| WAR044503 | 12/16/2024 | 12/16/2024 | Pollution hotline (phone, web, app): report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. | Yes, Notified Ecology | 4700 50th ave s | Seattle | 98118 | 0 | 0 | Other: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. | Intentional dumping: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. | Not applicable: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. | Clean-up: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. | Complaint. report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. |
| WAR044503 | 10/31/2024 | 10/31/2024 | Pollution hotline (phone, web, app): petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | Yes, Notified Ecology | 15th ave s / s holgate st | Seattle | 47.586361 | -122.313373 | Other: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | Unconfirmed, unspecified, or not identified: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | Not applicable: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | Other: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa. | |
| WAR044503 | 4/6/2024 | 4/6/2024 | Pollution hotline (phone, web, app): gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. | Yes, No Notice Required | 5601 rainier ave s | Seattle | 98118 | 47.551803 | -122.278329 | Unconfirmed, unspecified, or not identified: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. | Unconfirmed, unspecified, or not identified: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. | Not applicable: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. | Education/technical assistance: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Referred to other agency or department: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. | gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. |
| WAR044503 | 7/18/2024 | 7/18/2024 | Pollution hotline (phone, web, app): report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. | Yes, No Notice Required | 3600 s judkins st | Seattle | 98144 | 47.592223 | -122.287312 | Sewage/septage/pet waste/human waste: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. | Unconfirmed, unspecified, or not identified: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. | Not applicable: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. | Other: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. | Complaint. report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead. |
| WAR044503 | 7/22/2024 | 7/22/2024 | MS4 inspection or screening: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. | Yes, Notified Ecology | s kenyon st & 39th ave s | Seattle | 98118 | 47.531541 | -122.283203 | Other: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. | Unconfirmed, unspecified, or not identified: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. | Not applicable: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. | Other: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. | Complaint. spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. |
| WAR044503 | 2/8/2024 | 2/8/2024 | Pollution hotline (phone, web, app): spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. | Yes, Notified Ecology | 102 n 132nd st | Seattle | 98133 | 47.725577 | -122.357813 | Sewage/septage/pet waste/human waste: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. | Intentional dumping: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. | Not applicable: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. | Education/technical assistance: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. | spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|---|---|---|
| WAR044503 | 6/28/2024 | 6/28/2024 | Pollution hotline (phone, web, app): please see 166157 | Yes, No Notice Required | 4611 shilshole ave nw | Seattle | 98107 | 47.661662 | -122.379343 | Fuel and/or vehicle related fluids: please see 166157 | Other accident/spill: please see 166157 | Not applicable: please see 166157 | Referred to other agency or department: please see 166157 | please see 166157 |
| WAR044503 | 11/13/2024 | 11/13/2024 | Pollution hotline (phone, web, app): report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. | Yes, No Notice Required | 9215 34th ave sw | Seattle | 98126 | 47.520498 | -122.375761 | Fuel and/or vehicle related fluids: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. | Intentional dumping: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. | Not applicable: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. | Clean-up: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. | report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered. |
| WAR044503 | 1/27/2024 | 1/27/2024 | Pollution hotline (phone, web, app): spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. | Yes, No Notice Required | 12354 24th ave ne | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. | Other accident/spill: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. | Not applicable: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. | Referred to other agency or department: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. | spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek. |
| WAR044503 | 11/13/2024 | 11/13/2024 | Pollution hotline (phone, web, app): side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up | Yes, Notified Ecology | 5040 9th ave ne | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up | Other accident/spill: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up | Not applicable: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up | Referred to other agency or department: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up | side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up |
| WAR044503 | 11/27/2024 | 11/27/2024 | Pollution hotline (phone, web, app): found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. | Yes, Notified Ecology | 8th ave nw & nw 63rd st | Seattle | 98107 | 47.674535 | -122.366092 | Fuel and/or vehicle related fluids: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. | Intentional dumping: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. | Not applicable: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. | Clean-up: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. Referred to other agency or department: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. | found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. |
| WAR044503 | 4/16/2024 | 4/16/2024 | Direct report to your staff: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. | Yes, No Notice Required | 13285 15th ave ne | Seattle | 98125 | 47.725398 | -122.313167 | Fuel and/or vehicle related fluids: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. | Other accident/spill: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. | Not applicable: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. | Clean-up: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. | spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted. |
| WAR044503 | 2/1/2024 | 2/1/2024 | ERTS referral: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. | Yes, Notified Ecology | 582 s riverside dr | Seattle | 98108 | 47.535594 | -122.326631 | Other: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. | Vehicle-related business: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. | Not applicable: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. | Other: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. | Complaint. report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4. |
| WAR044503 | 2/7/2024 | 2/7/2024 | Pollution hotline (phone, web, app): received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. | Yes, Notified Ecology | 24th ave ne / ne 54th st | Seattle | 0 | 0 | 0 | Other: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. | Other accident/spill: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. | Not applicable: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. | Clean-up: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. | received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb. |
| WAR044503 | 5/7/2024 | 5/7/2024 | Staff referral: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. | Yes, Notified Ecology | 3rd ave s / s holgate st | Seattle | 98134 | 47.586159 | -122.330027 | Fuel and/or vehicle related fluids: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. | Unconfirmed, unspecified, or not identified: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. | Not applicable: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. | Clean-up: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. | Complaint, planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa. |
| WAR044503 | 6/29/2024 | 6/29/2024 | Direct report to your staff: found spill clean up complete after large accident. no drains involved. nfa. | Yes, Notified Ecology | s stacy st / 4th ave s | Seattle | 98134 | 47.581892 | -122.329066 | Fuel and/or vehicle related fluids: found spill clean up complete after large accident. no drains involved. nfa. | Vehicle collision: found spill clean up complete after large accident. no drains involved. nfa. | Not applicable: found spill clean up complete after large accident. no drains involved. nfa. | Referred to other agency or department: found spill clean up complete after large accident. no drains involved. nfa. | found spill clean up complete after large accident. no drains involved. nfa. |
| WAR044503 | 11/27/2024 | 11/27/2024 | ERTS referral: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. | Yes, Notified Ecology | dayton ave n & n 143rd st | Seattle | 98133 | 47.732313 | -122.353035 | Fuel and/or vehicle related fluids: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. | Intentional dumping: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. | Not applicable: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. | Other: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. | Complaint. found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa. |
| WAR044503 | 6/4/2024 | 6/4/2024 | Staff referral: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. | Yes, Notified Ecology | 9902 rainier ave s | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. | Construction activity: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. | Not applicable: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. | Clean-up: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. | public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening. |
| WAR044503 | 12/2/2024 | 12/2/2024 | ERTS referral: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. | Yes, Notified Ecology | 5315 tallman ave nw | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. | Vehicle-related business: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. | Not applicable: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. | Clean-up: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. nfa_spills, Education/technical assistance: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. | spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|---|---|--|
| WAR044503 | 7/22/2024 | 7/22/2024 | MS4 inspection or screening: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Yes, Notified Ecology | s kenyon st & 39th ave s | Seattle | 98118 | 47.531541 | -122.283203 | Other: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Not applicable: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Other: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Complaint. spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. |
| WAR044503 | 5/22/2024 | 5/22/2024 | Pollution hotline (phone, web, app): report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. | Yes, No Notice Required | 2419 nw 65th st | Seattle | 98117 | 47.675782 | -122.388505 | Fuel and/or vehicle related fluids: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. | Vehicle-related business: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. | Not applicable: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. | Education/technical assistance: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. , Other: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. | Complaint. report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4. |
| WAR044503 | 6/11/2024 | 6/11/2024 | Pollution hotline (phone, web, app): fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. | Yes, No Notice Required | 2051 nw 60th st | Seattle | 98107 | 47.672222 | -122.384364 | Fuel and/or vehicle related fluids: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. | Intentional dumping: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. | Not applicable: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. | Clean-up: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. | fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact. |
| WAR044503 | 4/9/2024 | 4/9/2024 | Direct report to your staff: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. | Yes, No Notice Required | 922 e pike st | Seattle | 98122 | 47.614264 | -122.319782 | Food-related oil/grease: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. , Solid waste/trash: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. | Intentional dumping: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. | Not applicable: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. | Clean-up: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. , Clean-up: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. | Complaint. garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. |
| WAR044503 | 4/15/2024 | 4/15/2024 | ERTS referral: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. | Yes, Notified Ecology | 1800 s jackson st | Seattle | 98144 | 47.599381 | -122.308760 | Fuel and/or vehicle related fluids: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. | Vehicle-related business: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. , Other accident/spill: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. | Not applicable: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. | Clean-up: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. , Education/technical assistance: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. , Other: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. | Complaint. arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4. |
| WAR044503 | 10/3/2024 | 10/3/2024 | Pollution hotline (phone, web, app): self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. | Yes, Notified Ecology | 1350 n 34th st | Seattle | 98103 | 47.648797 | -122.340795 | Fuel and/or vehicle related fluids: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. | Other accident/spill: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. | Not applicable: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. | Clean-up: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. , Other: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. | self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact. |
| WAR044503 | 11/1/2024 | 11/1/2024 | Direct report to your staff: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. | Yes, Notified Ecology | nesbit ave n / n 88th st | Seattle | | 47.692372 | -122.343478 | Fuel and/or vehicle related fluids: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. | Intentional dumping: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. | Not applicable: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. | Clean-up: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. | Complaint. spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one. |
| WAR044503 | 7/26/2024 | 7/26/2024 | ERTS referral: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. | Yes, Notified Ecology | 5763 s oaklawn pl | Seattle | 98118 | 47.543277 | -122.259657 | Other: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. | Other: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. | Not applicable: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. | Education/technical assistance: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. | Complaint. home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided. |
| WAR044503 | 5/13/2024 | 5/13/2024 | Pollution hotline (phone, web, app): report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. | Yes, Notified Ecology | 125 ne 94th st | Seattle | 98115 | 47.696656 | -122.327201 | Other: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. | Intentional dumping: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. | Not applicable: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. | Clean-up: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. , Enforcement: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. , Other: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. | report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted. |
| WAR044503 | 2/2/2024 | 2/2/2024 | Pollution hotline (phone, web, app): spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. | Yes, No Notice Required | 7th ave s / s oregon st | Seattle | | 47.563053 | -122.324090 | Fuel and/or vehicle related fluids: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. | Unconfirmed, unspecified, or not identified: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. | Not applicable: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. | Clean-up: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. | spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact. |
| WAR044503 | 3/22/2024 | 3/22/2024 | Pollution hotline (phone, web, app): report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. | Yes, No Notice Required | 11030 8th ave ne | Seattle | 98125 | 47.709896 | -122.320200 | Fuel and/or vehicle related fluids: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. | Vehicle-related business: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. | Not applicable: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. | Clean-up: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. , Education/technical assistance: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. , Other: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. | report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact. |
| WAR044503 | 11/5/2024 | 11/5/2024 | ERTS referral: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. | Yes, Notified Ecology | nw 100th st/7th ave nw | Seattle | | 47.701504 | -122.364772 | Fuel and/or vehicle related fluids: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. | Other accident/spill: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. | Not applicable: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. | Clean-up: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. | spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed. |
| WAR044503 | 2/6/2024 | 2/6/2024 | Pollution hotline (phone, web, app): report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. | Yes, Notified Ecology | 1300 university st | Seattle | 98101 | 47.612725 | -122.324824 | Sewage/septage/pet waste/human waste: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. | Other accident/spill: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. | Not applicable: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. | Clean-up: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. , Clean-up: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. , Referred to other agency or department: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. | report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|--|---|--|---|
| WAR044503 | 12/28/2024 | 12/28/2024 | Pollution hotline (phone, web, app): hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. | Yes, No Notice Required | 12801 aurora ave n | Seattle | 98133 | 47.722559 | -122.345377 | Fuel and/or vehicle related fluids: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. | Vehicle-related business: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. | Not applicable: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. | Clean-up: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa., Other: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. | hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa. |
| WAR044503 | 3/16/2024 | 3/16/2024 | Pollution hotline (phone, web, app): received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. | Yes, No Notice Required | 10616 marine view dr sw | Seattle | 98146 | 47.507783 | -122.387423 | Fuel and/or vehicle related fluids: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. | Construction activity: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. | Not applicable: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. | Clean-up: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. | received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code. |
| WAR044503 | 9/27/2024 | 9/27/2024 | Pollution hotline (phone, web, app): a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. | Yes, No Notice Required | 3509 ne 137th st | Seattle | 98125 | 46.807974 | -122.390431 | Fuel and/or vehicle related fluids: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. | Intentional dumping: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. | Not applicable: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. | Clean-up: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped., Clean-up: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped., Education/technical assistance: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. | a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped. |
| WAR044503 | 2/14/2024 | 2/14/2024 | Direct report to your staff: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. | Yes, No Notice Required | 130 s kenyon st | Seattle | 98108 | 47.533212 | -122.333036 | Other: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. | Other accident/spill: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. | Not applicable: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. | Clean-up: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. | small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up. |
| WAR044503 | 5/3/2024 | 5/3/2024 | Pollution hotline (phone, web, app): an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. | Yes, Notified Ecology | 4144 university way ne | Seattle | 98105 | 47.658136 | -122.313003 | Food-related oil/grease: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. | Intentional dumping: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. | Not applicable: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. | Clean-up: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted., Other: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. | an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted. |
| WAR044503 | 6/28/2024 | 6/28/2024 | Pollution hotline (phone, web, app): hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. | Yes, Notified Ecology | 9131 10th ave s | Seattle | 98108 | 47.521101 | -122.320811 | Fuel and/or vehicle related fluids: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. | Other accident/spill: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. | Not applicable: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. | Clean-up: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa., Referred to other agency or department: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa., Other: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. | hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa. |
| WAR044503 | 2/18/2024 | 2/18/2024 | Pollution hotline (phone, web, app): car vandalized to steal gasoline. provided assistance to the owner. no drains affected. | Yes, No Notice Required | 7304 51st ave ne | Seattle | 98115 | 47.681392 | -122.272671 | Fuel and/or vehicle related fluids: car vandalized to steal gasoline. provided assistance to the owner. no drains affected. | Intentional dumping: car vandalized to steal gasoline. provided assistance to the owner. no drains affected. | Not applicable: car vandalized to steal gasoline. provided assistance to the owner. no drains affected. | Education/technical assistance: car vandalized to steal gasoline. provided assistance to the owner. no drains affected., Other: car vandalized to steal gasoline. provided assistance to the owner. no drains affected. | car vandalized to steal gasoline. provided assistance to the owner. no drains affected. |
| WAR044503 | 2/13/2024 | 2/13/2024 | Staff referral: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. | Yes, Notified Ecology | 3rd ave s / s holgate st | Seattle | 98134 | 47.586159 | -122.330027 | Sewage/septage/pet waste/human waste: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. | Unconfirmed, unspecified, or not identified: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa., Intentional dumping: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. | Not applicable: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. | Clean-up: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. | Complaint. planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa. |
| WAR044503 | 5/10/2024 | 5/10/2024 | ERTS referral: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. | Yes, Notified Ecology | 2401 utah ave s | Seattle | 98134 | 47.581811 | -122.335353 | Other: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. | Vehicle-related business: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. | Not applicable: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. | Clean-up: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted., Other: report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. | report of commercial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted. |
| WAR044503 | 4/16/2024 | 4/16/2024 | Pollution hotline (phone, web, app): bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. | Yes, Notified Ecology | alaskan way / columbia st | Seattle | 98104 | 47.602420 | -122.336971 | Fuel and/or vehicle related fluids: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. | Vehicle-related business: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. | Not applicable: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. | Clean-up: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew., Other: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. | bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew. |
| WAR044503 | 3/11/2024 | 3/11/2024 | Pollution hotline (phone, web, app): car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. | Yes, Notified Ecology | 1400 alaskan way | Seattle | 98101 | 47.607454 | -122.340753 | Fuel and/or vehicle related fluids: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. | Vehicle collision: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. | Not applicable: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. | Other: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. | car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found. |
| WAR044503 | 6/13/2024 | 6/13/2024 | Direct report to your staff: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. | Yes, Notified Ecology | 7242 seaweave ave nw | Seattle | 98117 | 47.682135 | -122.403613 | Sewage/septage/pet waste/human waste: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. | Intentional dumping: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. | Not applicable: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. | Clean-up: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. Education/technical assistance: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. | rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. |
| WAR044503 | 9/20/2024 | 9/20/2024 | Pollution hotline (phone, web, app): spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. | Yes, Notified Ecology | 12330 33rd ave ne | Seattle | 98125 | 0 | 0 | Fuel and/or vehicle related fluids: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. | nfa_spills, Intentional dumping: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. | Not applicable: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. | Clean-up: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. | spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-----------|-------------|-------------|--|---|---|--|---|
| WAR044503 | 2/29/2024 | 2/29/2024 | ERTS referral: no impact to ms4. construction self reported to ecology called site to confirm details. nfa. | Yes, Notified Ecology | 2500 lake washington blvd e | Seattle | 98112 | 47.641708 | -122.298168 | Sediment/soil: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa. | Construction activity: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa. | Not applicable: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa. | Clean-up: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa., Referred to other agency or department: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa., Other: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa. | Complaint. no impact to ms4. construction self reported to ecology. called site to confirm details. nfa. |
| WAR044503 | 9/19/2024 | 9/19/2024 | Pollution hotline (phone, web, app): spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed | Yes, No Notice Required | 7000 lincoln park way sw | Seattle | 0 | 0 | 0 | Sediment/soil: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed | Other accident/spill: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed | Not applicable: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed | Referred to other agency or department: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed | spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed |
| WAR044503 | 2/5/2024 | 2/5/2024 | Business inspection: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. | Yes, No Notice Required | 7777 7th ave s | Seattle | 98108 | 47.533256 | -122.325804 | Fuel and/or vehicle related fluids: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. | Other: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. | Not applicable: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. | Education/technical assistance: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up., Education/technical assistance: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. | conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up. |
| WAR044503 | 11/4/2024 | 11/4/2024 | Pollution hotline (phone, web, app): report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. | Yes, No Notice Required | 8498 seawave pl nw | Seattle | 98117 | 47.689763 | -122.402253 | Fuel and/or vehicle related fluids: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. | Unconfirmed, unspecified, or not identified: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. | Not applicable: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. | Referred to other agency or department: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. | report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa. |
| WAR044503 | 2/6/2024 | 2/6/2024 | Pollution hotline (phone, web, app): report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. | Yes, Notified Ecology | 16th ave sw / sw morgan st | Seattle | 47.544728 | -122.354896 | | Fuel and/or vehicle related fluids: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. | Unconfirmed, unspecified, or not identified: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. | Not applicable: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. | Clean-up: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline., Other: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. | report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline. |
| WAR044503 | 3/27/2024 | 3/27/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. | Yes, No Notice Required | sw 106th st / 41st ave sw | Seattle | 47.508262 | -122.384299 | | Fuel and/or vehicle related fluids: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. | Unconfirmed, unspecified, or not identified: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. | Not applicable: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. | Other: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. | spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed. |
| WAR044503 | 10/10/2024 | 10/10/2024 | Direct report to your staff: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. | Yes, No Notice Required | 2001 w garfield st | Seattle | 98119 | 47.630999 | -122.382825 | Fuel and/or vehicle related fluids: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. | Construction activity: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. | Not applicable: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. | Other: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. | construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill. |
| WAR044503 | 2/15/2024 | 2/15/2024 | ERTS referral: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. | Yes, Notified Ecology | 11011 greenwood ave n | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. | Other accident/spill: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. | Not applicable: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. | Clean-up: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted., Other: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. | Complaint. unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted. |
| WAR044503 | 10/3/2024 | 10/3/2024 | Pollution hotline (phone, web, app): spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. | Yes, Notified Ecology | 23rd ave s & s forest st | Seattle | 98144 | 47.577528 | -122.303334 | Unconfirmed, unspecified, or not identified: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. | Unconfirmed, unspecified, or not identified: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. | Not applicable: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. | Clean-up: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response., Other: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. | spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response. |
| WAR044503 | 9/16/2024 | 9/16/2024 | MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. | Yes, Notified Ecology | s angeline st & 38th ave s | Seattle | 98118 | 47.559460 | -122.284942 | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. | Not applicable: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. | Other: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. | Complaint. spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified. |
| WAR044503 | 12/10/2024 | 12/10/2024 | Pollution hotline (phone, web, app): sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. | Yes, Notified Ecology | 6800 rainier ave s | Seattle | 98118 | 47.541491 | -122.271489 | Sewage/septage/pet waste/human waste: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. | Other accident/spill: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. | Not applicable: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. | Clean-up: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. | sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wwsr for completion of sewer repair. |
| WAR044503 | 12/9/2024 | 12/9/2024 | Pollution hotline (phone, web, app): report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. | Yes, No Notice Required | 473 n 36th st | Seattle | 98103 | 47.651600 | -122.352516 | Food-related oil/grease: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Other: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. | Other: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. | Not applicable: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. | Clean-up: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Education/technical assistance: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Enforcement: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. | report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage. |
| WAR044503 | 6/28/2024 | 6/28/2024 | Pollution hotline (phone, web, app): responsible party provided pictures of adequate clean up. no impact to ms4. nfa | Yes, Notified Ecology | 7 s idaho st | Seattle | 98134 | 47.564499 | -122.314983 | Fuel and/or vehicle related fluids: responsible party provided pictures of adequate clean up. no impact to ms4. nfa | Other accident/spill: responsible party provided pictures of adequate clean up. no impact to ms4. nfa | Not applicable: responsible party provided pictures of adequate clean up. no impact to ms4. nfa | Clean-up: responsible party provided pictures of adequate clean up. no impact to ms4. nfa | responsible party provided pictures of adequate clean up. no impact to ms4. nfa |
| WAR044503 | 2/23/2024 | 2/23/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. | Yes, No Notice Required | 4542 university way ne | Seattle | 98105 | 47.662477 | -122.312762 | Fuel and/or vehicle related fluids: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. | Intentional dumping: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. | Not applicable: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. | Clean-up: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. | spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|----------------------------------|---------|-----------|-------------|-------------|---|--|---|--|---|
| WAR044503 | 5/1/2024 | 5/1/2024 | ERTS referral: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. | Yes, Notified Ecology | 7277 perimeter rd s | Seattle | 98108 | 47.536852 | -122.303928 | Other: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. | Other accident/spill: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. | Not applicable: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. | Other: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. | Complaint. over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4. |
| WAR044503 | 10/10/2024 | 10/10/2024 | Pollution hotline (phone, web, app): waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. | Yes, No Notice Required | 805 ne 115th st | Seattle | 98125 | 47.712030 | -122.320361 | Fuel and/or vehicle related fluids: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. | Vehicle-related business: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. | Not applicable: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. | Clean-up: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. , Other: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. | waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. |
| WAR044503 | 7/9/2024 | 7/9/2024 | Pollution hotline (phone, web, app): report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. | Yes, Notified Ecology | 3510 s holly st | Seattle | 98118 | 47.542721 | -122.288240 | Sewage/septage/pet waste/human waste: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. | Unconfirmed, unspecified, or not identified: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. | Not applicable: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. | Clean-up: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. , Other: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. | report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. |
| WAR044503 | 8/5/2024 | 8/5/2024 | MS4 inspection or screening: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. | Yes, Notified Ecology | s holly st & 44th ave s | Seattle | 98118 | 47.542465 | -122.278117 | Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. | Unconfirmed, unspecified, or not identified: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. | Not applicable: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. | Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. , Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. | Complaint. spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. |
| WAR044503 | 12/9/2024 | 12/9/2024 | Pollution hotline (phone, web, app): report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. | Yes, Notified Ecology | 458 n 44th st | Seattle | 98103 | 47.660376 | -122.352924 | Unconfirmed, unspecified, or not identified: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. | Unconfirmed, unspecified, or not identified: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. | Not applicable: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. | Clean-up: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. , Other: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. | Complaint. report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. |
| WAR044503 | 12/27/2024 | 12/27/2024 | ERTS referral: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. | Yes, No Notice Required | 5022 martin luther king jr way s | Seattle | 0 | 0 | 0 | Other: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. | Construction activity: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. | Not applicable: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. | Other: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. | Complaint. report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place. |
| WAR044503 | 1/30/2024 | 1/30/2024 | Pollution hotline (phone, web, app): spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. | Yes, No Notice Required | 1519 alaskan way s | Seattle | 98134 | 47.590172 | -122.338008 | Fuel and/or vehicle related fluids: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. | Other accident/spill: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. | Not applicable: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. | Education/technical assistance: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. | spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill. |
| WAR044503 | 1/20/2024 | 1/20/2024 | Pollution hotline (phone, web, app): gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 | Yes, No Notice Required | sw myrtle st / 23rd ave sw | Seattle | 98106 | 47.539147 | -122.361647 | Fuel and/or vehicle related fluids: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 | Intentional dumping: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 | Not applicable: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 | Clean-up: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 | gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4 |
| WAR044503 | 4/14/2024 | 4/14/2024 | Pollution hotline (phone, web, app): bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. | Yes, Notified Ecology | 26th ave sw / sw roxbury st | Seattle | 47.517362 | -122.365923 | 47.517362 | Fuel and/or vehicle related fluids: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. | Vehicle-related business: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. | Not applicable: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. | Clean-up: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. , Other: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. | bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. |
| WAR044503 | 5/20/2024 | 5/20/2024 | Pollution hotline (phone, web, app): report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. | Yes, Notified Ecology | 2500 15th ave s | Seattle | 98144 | 47.580818 | -122.313086 | Food-related oil/grease: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. | Intentional dumping: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. | Not applicable: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. | Clean-up: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. , Other: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. | Complaint. report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. |
| WAR044503 | 8/14/2024 | 8/14/2024 | Pollution hotline (phone, web, app): report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. | Yes, No Notice Required | 12815 aurora ave n | Seattle | 98133 | 47.722966 | -122.345478 | Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. | Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. | Not applicable: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. | Education/technical assistance: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. , Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. | Complaint. report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. |
| WAR044503 | 9/13/2024 | 9/13/2024 | Pollution hotline (phone, web, app): spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. | Yes, Notified Ecology | 9200 roosevelt way ne | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. | Vehicle-related business: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. | Not applicable: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. | Clean-up: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. | spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party. |
| WAR044503 | 6/23/2024 | 6/23/2024 | Pollution hotline (phone, web, app): report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. | Yes, Notified Ecology | 2527 29th ave s | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. | Unconfirmed, unspecified, or not identified: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. | Not applicable: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. | Clean-up: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. , Other: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. | report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. |
| WAR044503 | 4/4/2024 | 4/4/2024 | Pollution hotline (phone, web, app): sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. | Yes, Notified Ecology | 1401 madison st | Seattle | 98112 | 47.610650 | -122.321262 | Sewage/septage/pet waste/human waste: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. | Other accident/spill: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. | Not applicable: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. | Clean-up: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. , Other: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. | sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored. |
| WAR044503 | 6/14/2024 | 6/14/2024 | Direct report to your staff: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. | Yes, No Notice Required | rainer ave s/s cloverdale st | Seattle | 98118 | 47.526170 | -122.269994 | Sewage/septage/pet waste/human waste: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. | Intentional dumping: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. | Not applicable: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. | Clean-up: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. , Other: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. | rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. |
| WAR044503 | 1/2/2024 | 1/2/2024 | Pollution hotline (phone, web, app): large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. | Yes, No Notice Required | 823 madison st | Seattle | 98104 | 47.608150 | -122.327457 | Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. | Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. | Not applicable: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. | Clean-up: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. , Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. | large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. |
| WAR044503 | 11/15/2024 | 11/15/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. | Yes, Notified Ecology | 4009 stone way n | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. | Other accident/spill: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. | Not applicable: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. | Clean-up: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. , Other: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. | spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|---|--|---|
| WAR044503 | 11/7/2024 | 11/7/2024 | Pollution hotline (phone, web, app): report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. | Yes, Notified Ecology | 8580 sandpoint way | Seattle | 98115 | 0 | 0 | Other: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. | Vehicle-related business: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. | Not applicable: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. | Clean-up: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. Other: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. | Complaint. report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. |
| WAR044503 | 10/30/2024 | 10/30/2024 | ERTS referral: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. | Yes, Notified Ecology | 1300 e pine st | Seattle | 98122 | 47.615536 | -122.315170 | Fuel and/or vehicle related fluids: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. | Vehicle-related business: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. | Not applicable: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. | Clean-up: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. Other: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. | Complaint. report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. |
| WAR044503 | 1/22/2024 | 1/22/2024 | Pollution hotline (phone, web, app): report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. | Yes, No Notice Required | 11759 4th ave nw | Seattle | 98177 | 47.715904 | -122.362530 | Fuel and/or vehicle related fluids: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. | Vehicle-related business: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. | Not applicable: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. | Clean-up: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. Other: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. | report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. |
| WAR044503 | 2/29/2024 | 2/29/2024 | Pollution hotline (phone, web, app): report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. | Yes, Notified Ecology | 7433 california ave sw | Seattle | 98136 | 47.536070 | -122.387773 | Fuel and/or vehicle related fluids: report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. | Vehicle-related business: report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. | Not applicable: report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. | Other: report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. | report of leaking vehicle in row. investigated--minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4. |
| WAR044503 | 8/13/2024 | 8/13/2024 | MS4 inspection or screening: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. | Yes, Notified Ecology | s warsaw st & 39th ave s | Seattle | 98118 | 47.543182 | -122.283302 | Other: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. | Construction activity: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. | Not applicable: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. | Other: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. | Complaint. received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology. |
| WAR044503 | 9/28/2024 | 9/28/2024 | Pollution hotline (phone, web, app): vehicle accident spilled fluids to roadway. no drains impacted. | Yes, No Notice Required | 16th ave ne / ne 50th st | Seattle | 98108 | 47.664883 | -122.310812 | Fuel and/or vehicle related fluids: vehicle accident spilled fluids to roadway. no drains impacted. | Vehicle collision: vehicle accident spilled fluids to roadway. no drains impacted. | Not applicable: vehicle accident spilled fluids to roadway. no drains impacted. | Other: vehicle accident spilled fluids to roadway. no drains impacted. | vehicle accident spilled fluids to roadway. no drains impacted. |
| WAR044503 | 12/11/2024 | 12/11/2024 | ERTS referral: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated. | Yes, Notified Ecology | 3015 nw 54th st | Seattle | 98107 | 47.667437 | -122.396349 | Fuel and/or vehicle related fluids: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated. | Other accident/spill: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated. | Not applicable: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill was mitigated. | Clean-up: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated. | Complaint. spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated. |
| WAR044503 | 4/23/2024 | 4/23/2024 | ERTS referral: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. | Yes, Notified Ecology | 4700 denver ave s | Seattle | 98108 | 47.560685 | -122.332418 | Other: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. | Vehicle-related business: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. | Not applicable: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. | Clean-up: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. Other: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. | Complaint. report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. |
| WAR044503 | 6/13/2024 | 6/13/2024 | Pollution hotline (phone, web, app): report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. | Yes, No Notice Required | 4100 university way ne | Seattle | 98105 | 47.656978 | -122.312920 | Food-related oil/grease: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. | Intentional dumping: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. | Not applicable: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. | Clean-up: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. Other: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. | report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. |
| WAR044503 | 5/11/2024 | 5/11/2024 | Pollution hotline (phone, web, app): commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. | Yes, No Notice Required | 14th ave / e madison st | Seattle | 98108 | 47.613894 | -122.314231 | Fuel and/or vehicle related fluids: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. | Vehicle-related business: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. | Not applicable: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. | Clean-up: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. Other: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. | commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. |
| WAR044503 | 3/13/2024 | 3/13/2024 | Pollution hotline (phone, web, app): received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. | Yes, No Notice Required | s raymond st / 32nd ave s | Seattle | 98108 | 47.547965 | -122.291563 | Sewage/septage/pet waste/human waste: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. | Intentional dumping: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. | Not applicable: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. | Clean-up: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. | received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage. |
| WAR044503 | 3/27/2024 | 3/27/2024 | Pollution hotline (phone, web, app): spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. | Yes, No Notice Required | 709 n 94th st | Seattle | 98103 | 47.696126 | -122.348845 | Fuel and/or vehicle related fluids: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. | Other accident/spill: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. | Not applicable: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. | Clean-up: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. | spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage. |
| WAR044503 | 6/11/2024 | 6/11/2024 | Pollution hotline (phone, web, app): self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Yes, Notified Ecology | 6225 37th ave ne | Seattle | 98115 | 47.674722 | -122.288296 | Fuel and/or vehicle related fluids: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Vehicle-related business: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Not applicable: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | Clean-up: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. | self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. |
| WAR044503 | 2/21/2024 | 2/21/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. | Yes, No Notice Required | 8715 aurora ave n | Seattle | 98103 | 47.692440 | -122.345187 | Fuel and/or vehicle related fluids: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. | Intentional dumping: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. | Not applicable: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. | Clean-up: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. | spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue. |
| WAR044503 | 7/3/2024 | 7/3/2024 | MS4 inspection or screening: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. | Yes, Notified Ecology | s sullivan st & 42nd ave s | Seattle | 98118 | 47.526763 | -122.280874 | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. | Not applicable: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. | Other: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. | Complaint. spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. |
| WAR044503 | 8/5/2024 | 8/5/2024 | Direct report to your staff: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. | Yes, Notified Ecology | 1222 s weller st | Seattle | 98144 | 47.597808 | -122.316044 | Food-related oil/grease: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. | Other: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. | Not applicable: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. | Clean-up: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. Education/technical assistance: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. Education/technical assistance: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. | during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|---------------------------------|---------|-------|-----------|-------------|---|--|--|---|--|
| WAR044503 | 11/5/2024 | 11/5/2024 | Pollution hotline (phone, web, app): sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. | Yes, Notified Ecology | 12346 24th ave ne | Seattle | 98125 | 47.719003 | -122.303418 | Sewage/septage/pet waste/human waste: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. | Other: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. | Not applicable: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. | Education/technical assistance: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. , Referred to other agency or department: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. , Other: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. | sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. |
| WAR044503 | 11/4/2024 | 11/4/2024 | ERTS referral: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. | Yes, Notified Ecology | 13201 aurora ave n | Seattle | 98133 | 47.725456 | -122.346604 | Fuel and/or vehicle related fluids: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. | Vehicle collision: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. | Not applicable: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. | Clean-up: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted., Other: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. | Complaint. commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted. |
| WAR044503 | 3/25/2024 | 3/25/2024 | Pollution hotline (phone, web, app): self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. | Yes, Notified Ecology | 1206 university st | Seattle | 98101 | 47.612242 | -122.325772 | Fuel and/or vehicle related fluids: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. | Vehicle-related business: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. | Not applicable: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. | Clean-up: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact., Other: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. | self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact. |
| WAR044503 | 2/29/2024 | 2/29/2024 | Pollution hotline (phone, web, app): electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. | Yes, Notified Ecology | s riverside dr / s holden st | Seattle | | 47.534135 | -122.325435 | Sewage/septage/pet waste/human waste: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. | Construction activity: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. | Not applicable: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. | Referred to other agency or department: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. , Other: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. | electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. |
| WAR044503 | 10/12/2024 | 10/12/2024 | Pollution hotline (phone, web, app): bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. | Yes, Notified Ecology | sw spokane st / detridge way sw | Seattle | 98106 | 47.572094 | -122.360020 | Fuel and/or vehicle related fluids: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. | Vehicle-related business: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. | Not applicable: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. | Clean-up: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted., Other: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. | bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted. |
| WAR044503 | 3/20/2024 | 3/20/2024 | Direct report to your staff: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. | Yes, No Notice Required | military rd s & s othello st | Seattle | 98108 | 47.536692 | -122.296495 | nfa_spills, Sewage/septage/pet waste/human waste: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. | Intentional dumping: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. | Not applicable: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. | Referred to other agency or department: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. | Complaint. rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program. |
| WAR044503 | 8/6/2024 | 8/6/2024 | Pollution hotline (phone, web, app): report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. | Yes, No Notice Required | 2910 w smith st | Seattle | 98199 | 47.641409 | -122.394798 | Fuel and/or vehicle related fluids: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. | Vehicle-related business: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. | Not applicable: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. | Clean-up: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4., Other: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. | report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4. |
| WAR044503 | 4/9/2024 | 4/9/2024 | Pollution hotline (phone, web, app): diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. | Yes, No Notice Required | 1801 16th ave sw | Seattle | 98134 | 47.586026 | -122.353148 | Fuel and/or vehicle related fluids: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. | Other accident/spill: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. | Not applicable: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. | Clean-up: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4., Other: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. | diesel spilled from dock. containment and absorbent boom applied. no impact to ms4. |
| WAR044503 | 12/3/2024 | 12/3/2024 | ERTS referral: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. | Yes, Notified Ecology | 814 ne northlake pl | Seattle | 98103 | 47.655033 | -122.319035 | Fuel and/or vehicle related fluids: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. | Other accident/spill: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. | Not applicable: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. | Clean-up: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. | Complaint. hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa. |
| WAR044503 | 2/1/2024 | 2/1/2024 | Business inspection: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. | Yes, Notified Ecology | 2010 15th ave w | Seattle | 98119 | 47.637150 | -122.375695 | Fuel and/or vehicle related fluids: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. | Other accident/spill: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. | Not applicable: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. | Clean-up: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. , Education/technical assistance: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. , Enforcement: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. | a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. |
| WAR044503 | 8/29/2024 | 8/29/2024 | ERTS referral: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. | Yes, Notified Ecology | 5100 25th ave ne | Seattle | 98105 | 47.666677 | -122.300355 | Fuel and/or vehicle related fluids: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. | Other accident/spill: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. | Not applicable: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. | Other: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. | reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated. |
| WAR044503 | 1/31/2024 | 1/31/2024 | ERTS referral: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. | Yes, Notified Ecology | 33rd ave s / s dearborn st | Seattle | | 47.595768 | -122.290283 | Fuel and/or vehicle related fluids: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. | Other accident/spill: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. | Not applicable: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. | Clean-up: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted., Other: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. | above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted. |
| WAR044503 | 11/19/2024 | 11/19/2024 | Pollution hotline (phone, web, app): report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. | Yes, Notified Ecology | 4115 sw admiral way | Seattle | 98116 | 47.580959 | -122.384827 | Fuel and/or vehicle related fluids: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. | Other accident/spill: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. | Not applicable: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. | Clean-up: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4., Other: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. | report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4. |
| WAR044503 | 11/9/2024 | 11/9/2024 | Pollution hotline (phone, web, app): approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. | Yes, Notified Ecology | 4705 ne 54th st | Seattle | 98105 | 0 | 0 | Sewage/septage/pet waste/human waste: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. | Vehicle-related business: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. | Not applicable: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. | Clean-up: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. , Other: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. | approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. |
| WAR044503 | 12/27/2024 | 12/27/2024 | Pollution hotline (phone, web, app): spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. | Yes, Notified Ecology | 6th ave s & s holgate st | Seattle | 98108 | 47.586173 | -122.325985 | Fuel and/or vehicle related fluids: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. | Vehicle-related business: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. | Not applicable: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. | Referred to other agency or department: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. | spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. |
| WAR044503 | 8/14/2024 | 8/14/2024 | Pollution hotline (phone, web, app): spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. | Yes, Notified Ecology | 103 23rd ave | Seattle | 98122 | 47.601815 | -122.302731 | Other: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. | Other accident/spill: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. | Not applicable: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. | Clean-up: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. | spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|--|---|---|--|
| WAR044503 | 4/21/2024 | 4/21/2024 | Pollution hotline (phone, web, app): got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. | Yes, No Notice Required | 1001 fairview ave n | Seattle | 98109 | 47.629018 | -122.331739 | Fuel and/or vehicle related fluids: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. | Unconfirmed, unspecified, or not identified: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. | Not applicable: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. | Referred to other agency or department: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. | got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it. |
| WAR044503 | 3/19/2024 | 3/19/2024 | ERTS referral: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. | Yes, Notified Ecology | 10013 m l king jr way s | Seattle | 98178 | 47.511226 | -122.279262 | Fuel and/or vehicle related fluids: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. | Vehicle collision: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. | Not applicable: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. | Clean-up: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. | Complaint. received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains. |
| WAR044503 | 5/13/2024 | 5/13/2024 | Pollution hotline (phone, web, app): rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater | Yes, No Notice Required | 8850 9th ave sw | Seattle | 98106 | 47.523193 | -122.346471 | Sewage/septage/pet waste/human waste: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater | Intentional dumping: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater | Not applicable: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater | Clean-up: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater. Education/technical assistance: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater. Referred to other agency or department: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater | rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater |
| WAR044503 | 3/29/2024 | 3/29/2024 | Pollution hotline (phone, web, app): report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. | Yes, No Notice Required | 9102 fauntleroy way sw | Seattle | 98136 | 47.522442 | -122.392438 | Sediment/soil: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. | Construction activity: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. | Not applicable: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. | Other: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. | report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered. |
| WAR044503 | 7/10/2024 | 7/10/2024 | Pollution hotline (phone, web, app): received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. | Yes, No Notice Required | 520 s brandon st | Seattle | 98108 | 47.555152 | -122.327508 | Fuel and/or vehicle related fluids: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. | Vehicle-related business: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. | Not applicable: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. | Clean-up: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. Other: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. | received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. |
| WAR044503 | 8/31/2024 | 8/31/2024 | Pollution hotline (phone, web, app): report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. | Yes, No Notice Required | 2401 n northlake way | Seattle | 98103 | 47.651036 | -122.329963 | Other: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. | Unconfirmed, unspecified, or not identified: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. | Not applicable: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. | Referred to other agency or department: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. | report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4. |
| WAR044503 | 4/7/2024 | 4/7/2024 | Pollution hotline (phone, web, app): sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. | Yes, Notified Ecology | 2121 26th ave s | Seattle | 98144 | 47.584114 | -122.299112 | Sewage/septage/pet waste/human waste: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. | Other accident/spill: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. | Not applicable: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. | Clean-up: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa., Clean-up: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa., Referred to other agency or department: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa., Other: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. | sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. |
| WAR044503 | 12/12/2024 | 12/12/2024 | Pollution hotline (phone, web, app): report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. | Yes, No Notice Required | 1801 41st ave e | Seattle | 98112 | 47.634722 | -122.279875 | Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. | Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. | Not applicable: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. | Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. | report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact. |
| WAR044503 | 7/17/2024 | 7/17/2024 | Pollution hotline (phone, web, app): construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. | Yes, Notified Ecology | 1810 7th ave w | Seattle | 98119 | 47.635144 | -122.365946 | Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. | Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. | Not applicable: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. | Clean-up: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted., Enforcement: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted., Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. | construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. |
| WAR044503 | 10/28/2024 | 10/28/2024 | Pollution hotline (phone, web, app): drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. | Yes, No Notice Required | 12028 32nd ave ne | Seattle | 98125 | 0 | 0 | Fuel and/or vehicle related fluids: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. | Intentional dumping: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. | Not applicable: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. | Referred to other agency or department: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. | drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. |
| WAR044503 | 3/12/2024 | 3/12/2024 | Pollution hotline (phone, web, app): report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. | Yes, No Notice Required | 9211 7th ave nw | Seattle | 98117 | 47.696546 | -122.365029 | Fuel and/or vehicle related fluids: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. | Vehicle-related business: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. | Not applicable: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. | Clean-up: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. | report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. |
| WAR044503 | 5/3/2024 | 5/3/2024 | Pollution hotline (phone, web, app): spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. | Yes, Notified Ecology | 12600 stone ave n | Seattle | 98133 | 47.721334 | -122.341026 | Fuel and/or vehicle related fluids: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. | Other accident/spill: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. | Not applicable: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. | Clean-up: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. | spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required. |
| WAR044503 | 3/25/2024 | 3/25/2024 | Pollution hotline (phone, web, app): report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. | Yes, Notified Ecology | 1531 14th ave | Seattle | 98122 | 47.615102 | -122.314624 | Sewage/septage/pet waste/human waste: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. | Other accident/spill: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. | Not applicable: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. | Clean-up: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact., Clean-up: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact., Referred to other agency or department: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact., Other: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. | report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments | |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-----------|-------------|--|---|--|---|---|---|---|
| WAR044503 | 9/21/2024 | 9/21/2024 | Pollution hotline (phone, web, app): report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. | Yes, No Notice Required | 9640 16th ave sw | burien | 0 | 0 | 0 | nfa_spills | Food-related oil/grease: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. | Unconfirmed, unspecified, or not identified: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. | Not applicable: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. | Referred to other agency or department: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. | report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup. |
| WAR044503 | 4/10/2024 | 4/10/2024 | Direct report to your staff: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | Yes, No Notice Required | 213 nw 56th st | Seattle | 98107 | 47.699729 | -122.359969 | Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | Not applicable: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | Education/technical assistance: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. , Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | Complaint. report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. | |
| WAR044503 | 6/3/2024 | 6/3/2024 | Pollution hotline (phone, web, app): vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | Yes, No Notice Required | 41st ave sw & 100th st | Seattle | 98136 | 47.513765 | -122.384604 | Fuel and/or vehicle related fluids: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | Vehicle collision: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | Not applicable: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | Other: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted. | |
| WAR044503 | 7/25/2024 | 7/25/2024 | ERTS referral: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | Yes, Notified Ecology | 8011 faunterroy way sw | Seattle | 98136 | 47.531160 | -122.393211 | Fuel and/or vehicle related fluids: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | Vehicle-related business: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | Not applicable: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | Clean-up: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. , Education/technical assistance: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. , Other: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | Complaint. report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. | |
| WAR044503 | 11/4/2024 | 11/4/2024 | Pollution hotline (phone, web, app): found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | Yes, Notified Ecology | n 87th st & greenwood ave n | Seattle | 98103 | 47.692437 | -122.355317 | Fuel and/or vehicle related fluids: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | Unconfirmed, unspecified, or not identified: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | Not applicable: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | Clean-up: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa. | |
| WAR044503 | 9/13/2024 | 9/13/2024 | ERTS referral: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | Yes, Notified Ecology | 6733 east marginal way s | Seattle | 98108 | 47.541872 | -122.327148 | Fuel and/or vehicle related fluids: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | Intentional dumping: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | Not applicable: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | Clean-up: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. , Clean-up: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. , Other: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. | |
| WAR044503 | 2/28/2024 | 2/28/2024 | Pollution hotline (phone, web, app): report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | Yes, Notified Ecology | s brandon st / 50th ave s | Seattle | 47.553360 | -122.270915 | Unconfirmed, unspecified, or not identified: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | Unconfirmed, unspecified, or not identified: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | Not applicable: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | Other: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. , Other: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. | | |
| WAR044503 | 5/27/2024 | 5/27/2024 | Pollution hotline (phone, web, app): commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | Yes, Notified Ecology | 36th ave ne / ne 45th st | Seattle | 98105 | 47.661149 | -122.289231 | Fuel and/or vehicle related fluids: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | Vehicle-related business: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | Not applicable: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | Clean-up: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. , Other: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. | |
| WAR044503 | 10/8/2024 | 10/8/2024 | Pollution hotline (phone, web, app): vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | Yes, Notified Ecology | 57th ave sw / sw admiral way | Seattle | 0 | 0 | 0 | Sediment/soil: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | Other accident/spill: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | Not applicable: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | Clean-up: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. , Clean-up: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. , Other: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. | |
| WAR044503 | 6/20/2024 | 6/20/2024 | Pollution hotline (phone, web, app): received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | Yes, Notified Ecology | 2040 westlake ave n | Seattle | 98109 | 47.637336 | -122.339890 | Fuel and/or vehicle related fluids: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | Intentional dumping: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | Not applicable: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | Clean-up: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. , Other: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. | |
| WAR044503 | 4/4/2024 | 4/4/2024 | ERTS referral: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | Yes, Notified Ecology | n 90th st & stone ave n | Seattle | 98103 | 47.694169 | -122.341891 | Fuel and/or vehicle related fluids: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | Other accident/spill: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | Not applicable: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | Clean-up: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa. , Referred to other agency or department: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa. , Other: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa | |
| WAR044503 | 12/20/2024 | 12/20/2024 | Pollution hotline (phone, web, app): cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | Yes, No Notice Required | 1050 sw spokane st | Seattle | 98134 | 47.571928 | -122.347301 | Fuel and/or vehicle related fluids: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | Other accident/spill: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | Not applicable: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | Clean-up: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. , Referred to other agency or department: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. | |
| WAR044503 | 6/12/2024 | 6/12/2024 | ERTS referral: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | Yes, Notified Ecology | 905 ne 114th st | Seattle | 98125 | 47.711369 | -122.319051 | Fuel and/or vehicle related fluids: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | Vehicle-related business: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | Not applicable: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | Other: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | Complaint. commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4. | |
| WAR044503 | 9/16/2024 | 9/16/2024 | MS4 inspection or screening: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Yes, Notified Ecology | s pearl st & 39th ave s | Seattle | 98118 | 47.556207 | -122.283487 | Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Not applicable: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. , Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Complaint. spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | |
| WAR044503 | 9/30/2024 | 9/30/2024 | Pollution hotline (phone, web, app): report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | Yes, No Notice Required | 20th ave ne / ne 91st st | Seattle | 98115 | 47.694846 | -122.306828 | Sediment/soil: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | Other: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | Not applicable: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | Clean-up: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. , Other: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. | |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-------|-----------|-------------|--|--|--|---|--|
| WAR044503 | 6/5/2024 | 6/5/2024 | Pollution hotline (phone, web, app): fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. | Yes, Notified Ecology | 7242 seawave ave nw | Seattle | 98117 | 47.682135 | -122.403613 | Fuel and/or vehicle related fluids: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. | Vehicle-related business: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. Other accident/spill: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. | Not applicable: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. | Clean-up: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. | fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. |
| WAR044503 | 12/6/2024 | 12/6/2024 | Pollution hotline (phone, web, app): commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. | Yes, Notified Ecology | poplar pl s / s dearborn st | Seattle | | 47.595813 | -122.312831 | Fuel and/or vehicle related fluids: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. | Vehicle-related business: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. | Not applicable: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. | Other: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. | commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted. |
| WAR044503 | 2/6/2024 | 2/6/2024 | Pollution hotline (phone, web, app): self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. | Yes, No Notice Required | 401 alaskan way s | Seattle | 98104 | 47.597018 | -122.336580 | Other: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. | Construction activity: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. | Not applicable: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. | Clean-up: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. Other: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. | self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. |
| WAR044503 | 5/14/2024 | 5/14/2024 | Direct report to your staff: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. | Yes, No Notice Required | 1100 w ewing st | Seattle | 98119 | 47.656922 | -122.370603 | Fuel and/or vehicle related fluids: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. | Other: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. | Not applicable: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. | Other: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. | Complaint. marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4. |
| WAR044503 | 7/25/2024 | 7/25/2024 | Pollution hotline (phone, web, app): report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. | Yes, No Notice Required | 5209 shilshoe ave nw | Seattle | 98107 | 47.664262 | -122.383409 | Other: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. | Unconfirmed, unspecified, or not identified: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. | Not applicable: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. | Referred to other agency or department: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. | report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4. |
| WAR044503 | 5/19/2024 | 5/19/2024 | Pollution hotline (phone, web, app): hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. | Yes, Notified Ecology | 7 s idaho st | Seattle | 98134 | 47.564499 | -122.341983 | Fuel and/or vehicle related fluids: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. | Vehicle-related business: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. | Not applicable: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. | Clean-up: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. | hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4. |
| WAR044503 | 5/14/2024 | 5/14/2024 | Pollution hotline (phone, web, app): report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. | Yes, Notified Ecology | 47th ave sw / sw webster st | Seattle | | 47.535802 | -122.392588 | Fuel and/or vehicle related fluids: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Fuel and/or vehicle related fluids: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Food-related oil/grease: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. | Intentional dumping: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. | Not applicable: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. | Clean-up: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Other: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. | report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. |
| WAR044503 | 6/4/2024 | 6/4/2024 | Pollution hotline (phone, web, app): report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. | Yes, No Notice Required | 2858 13th ave w | Seattle | 98119 | 47.646557 | -122.373327 | Other: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. | Unconfirmed, unspecified, or not identified: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. | Not applicable: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. | Other: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. | Complaint. report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water. |
| WAR044503 | 5/3/2024 | 5/3/2024 | Pollution hotline (phone, web, app): commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Yes, No Notice Required | 611 20th ave s | Seattle | 98144 | 47.597259 | -122.306616 | Fuel and/or vehicle related fluids: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Vehicle-related business: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Not applicable: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Clean-up: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. , Other: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. |
| WAR044503 | 3/29/2024 | 3/29/2024 | Pollution hotline (phone, web, app): report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. | Yes, Notified Ecology | 500 s portland st | Seattle | 98108 | 47.533640 | -122.326701 | Other: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. | Other accident/spill: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. | Not applicable: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. | Clean-up: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. , Other: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. | report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. |
| WAR044503 | 9/12/2024 | 9/12/2024 | MS4 inspection or screening: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Yes, Notified Ecology | 35th ave s / s alaska st | Seattle | | 47.560752 | -122.288832 | Other: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Not applicable: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Other: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. | Complaint. spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary. |
| WAR044503 | 11/11/2024 | 11/11/2024 | Pollution hotline (phone, web, app): received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. | Yes, No Notice Required | 4115 sw admiral way | Seattle | 98116 | 47.580959 | -122.384827 | Other: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. | Other accident/spill: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. | Not applicable: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. | Clean-up: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. | Complaint. received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary. |
| WAR044503 | 1/10/2024 | 1/10/2024 | Pollution hotline (phone, web, app): diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. | Yes, Notified Ecology | 2325 harbor ave sw | Seattle | 98126 | 47.582353 | -122.374136 | Fuel and/or vehicle related fluids: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. | Other accident/spill: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. | Not applicable: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. | Clean-up: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. , Other: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. | diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. |
| WAR044503 | 3/20/2024 | 3/20/2024 | Pollution hotline (phone, web, app): self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Yes, Notified Ecology | 8748 25th pl ne | Seattle | 98115 | 47.693381 | -122.300622 | Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Vehicle-related business: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Not applicable: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Clean-up: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. | self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact. |
| WAR044503 | 8/23/2024 | 8/23/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. | Yes, No Notice Required | 1808 believee ave | Seattle | | 0 | 0 | Food-related oil/grease: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. | Unconfirmed, unspecified, or not identified: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. | Not applicable: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. | Other: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. | spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed. |
| WAR044503 | 10/16/2024 | 10/16/2024 | Pollution hotline (phone, web, app): report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. | Yes, Notified Ecology | 8512 nesbit aven n | Seattle | 98103 | 47.691033 | -122.343188 | Fuel and/or vehicle related fluids: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. | Intentional dumping: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. | Not applicable: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. | Clean-up: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. | Complaint. report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|------------|-------|-----------|-------------|---|---|--|---|---|
| WAR044503 | 2/15/2024 | 2/15/2024 | ERTS referral: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. | Yes, Notified Ecology | 1300 n 97th st | Seattle | 98103 | 47.699779 | -122.341618 | Other: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. | Other accident/spill: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. | Not applicable: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. | Clean-up: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. . Other: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. | Complaint. two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. |
| WAR044503 | 12/19/2024 | 12/19/2024 | Pollution hotline (phone, web, app): report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. | Yes, No Notice Required | 3207 point pl sw | Seattle | 98116 | 0 | 0 | Sewage/septage/pet waste/human waste: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. | Other accident/spill: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. | Not applicable: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. | Clean-up: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. . Other: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. | report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. |
| WAR044503 | 11/5/2024 | 11/5/2024 | Pollution hotline (phone, web, app): sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. | Yes, Notified Ecology | 4200 37th ave s | Seattle | 98118 | 47.565338 | -122.285808 | Unconfirmed, unspecified, or not identified: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Other: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. | Illicit connection: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. | Not applicable: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. | Education/technical assistance: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Referred to other agency or department: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Other: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. | sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. |
| WAR044503 | 11/8/2024 | 11/8/2024 | Direct report to your staff: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. | Yes, No Notice Required | 8830 lake city way ne | Seattle | 98115 | 47.692882 | -122.305179 | Soap or cleaning chemicals: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. | Other: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. | Not applicable: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. | Education/technical assistance: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. . Other: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. | Complaint. i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. |
| WAR044503 | 7/22/2024 | 7/22/2024 | MS4 inspection or screening: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. | Yes, Notified Ecology | 42nd ave s & s thistle st | Seattle | 98136 | 47.527864 | -122.280872 | Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. | Unconfirmed, unspecified, or not identified: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. | Not applicable: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. | Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. . Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. | Complaint. spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. |
| WAR044503 | 9/10/2024 | 9/10/2024 | ERTS referral: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. | Yes, Notified Ecology | 4501 27th ave ne | Seattle | 98105 | 47.661412 | -122.298009 | Other: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. | Vehicle-related business: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. | Not applicable: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. | Clean-up: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. . Other: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. | Complaint. report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. |
| WAR044503 | 9/26/2024 | 9/26/2024 | Pollution hotline (phone, web, app): unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. | Yes, Notified Ecology | 3902 s ferdinand st | Seattle | 98118 | 47.558067 | -122.283202 | Fuel and/or vehicle related fluids: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. | Unconfirmed, unspecified, or not identified: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. | Not applicable: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. | Clean-up: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. . Other: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. | unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. |
| WAR044503 | 4/6/2024 | 4/6/2024 | Pollution hotline (phone, web, app): sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa | Yes, Notified Ecology | 9540 4th ave nw | Seattle | 98117 | 47.699126 | -122.361744 | Sediment/soil: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa | Construction activity: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa | Not applicable: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa | Clean-up: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa. Education/technical assistance: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa. Other: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa | sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa |
| WAR044503 | 8/16/2024 | 8/16/2024 | Pollution hotline (phone, web, app): approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. | Yes, Notified Ecology | 1737 belmont ave | Seattle | 98122 | 47.617439 | -122.324830 | Firefighting foam: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. | Other: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. | Not applicable: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. | Other: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. | approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall. |
| WAR044503 | 9/9/2024 | 9/9/2024 | Pollution hotline (phone, web, app): spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. nfa_spills | Yes, No Notice Required | 2225 alaskan way | Seattle | 0 | 0 | nfa_spills | Food-related oil/grease: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. | Other accident/spill: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. | Not applicable: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. | Clean-up: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. | spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. |
| WAR044503 | 6/11/2024 | 6/11/2024 | Staff referral: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. | Yes, Notified Ecology | 14th ave nw / nw 50th st | Seattle | 98107 | 47.664751 | -122.373106 | Fuel and/or vehicle related fluids: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. | Intentional dumping: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. | Not applicable: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. | Clean-up: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. . Other: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. | cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. |
| WAR044503 | 8/17/2024 | 8/17/2024 | Direct report to your staff: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. | Yes, No Notice Required | 19901 cedar falls rd se | north bend | 98045 | 47.425844 | -121.775793 | Fuel and/or vehicle related fluids: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. | Other accident/spill: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. | Not applicable: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. | Clean-up: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. | Complaint. spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted. |
| WAR044503 | 8/19/2024 | 8/19/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. | Yes, No Notice Required | 2727 fairview ave e | Seattle | 98102 | 47.644948 | -122.328181 | Sediment/soil: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. | Construction activity: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. | Not applicable: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. | Other: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. | spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed. |
| WAR044503 | 9/14/2024 | 9/14/2024 | Pollution hotline (phone, web, app): report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. | Yes, No Notice Required | 2611 fairview ave e | Seattle | 98102 | 47.645946 | -122.327678 | Unconfirmed, unspecified, or not identified: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. | Unconfirmed, unspecified, or not identified: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. | Not applicable: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. | Referred to other agency or department: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. | report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel. |
| WAR044503 | 6/18/2024 | 6/18/2024 | Pollution hotline (phone, web, app): commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. | Yes, No Notice Required | 3rd ave s / s walker st | Seattle | 98134 | 47.583901 | -122.329486 | Fuel and/or vehicle related fluids: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. | Vehicle-related business: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. | Not applicable: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. | Clean-up: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. . Other: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. | commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. |
| WAR044503 | 9/3/2024 | 9/3/2024 | Direct report to your staff: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. | Yes, No Notice Required | 4523 5th ave ne | Seattle | 0 | 0 | 0 | Sewage/septage/pet waste/human waste: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. . Sewage/septage/pet waste/human waste: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. | Vehicle collision: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. | Not applicable: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. | Referred to other agency or department: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. . Other: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. | motor vehicle accident impacted an rv and released black and grey wastewater to pavement. |
| WAR044503 | 2/28/2024 | 2/28/2024 | Pollution hotline (phone, web, app): approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. | Yes, Notified Ecology | 6847 54th ave ne | Seattle | 98115 | 47.678966 | -122.270604 | Fuel and/or vehicle related fluids: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. | Vehicle-related business: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. | Not applicable: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. | Clean-up: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. . Other: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. | approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|----------------------------------|---------|-------|-----------|-------------|---|--|---|---|--|
| WAR044503 | 1/2/2024 | 1/2/2024 | Pollution hotline (phone, web, app): contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. | Yes, Notified Ecology | 11033 27th ave ne | Seattle | 98125 | 47.709543 | -122.289442 | Sediment/soil: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. | Other: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. | Not applicable: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. | Clean-up: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. | contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thomton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid. |
| WAR044503 | 1/20/2024 | 1/20/2024 | Pollution hotline (phone, web, app): small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. | Yes, No Notice Required | 2502 sw findlay st | Seattle | 98106 | 47.552103 | -122.364697 | Sewage/septage/pet waste/human waste: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. | Other accident/spill: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. | Not applicable: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. | Clean-up: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. | small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up. |
| WAR044503 | 6/20/2024 | 6/20/2024 | ERTS referral: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. | Yes, Notified Ecology | 3717 beach dr sw | Seattle | 98116 | 47.570538 | -122.411786 | Sewage/septage/pet waste/human waste: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. | Other accident/spill: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. | Not applicable: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. | Enforcement: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. | Complaint. we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued. |
| WAR044503 | 5/9/2024 | 5/9/2024 | Pollution hotline (phone, web, app): concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. | Yes, Notified Ecology | 3313 s oregon st | Seattle | 98118 | 47.562669 | -122.290262 | Other: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. | Other accident/spill: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. | Not applicable: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. | Clean-up: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. | concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted. |
| WAR044503 | 9/9/2024 | 9/9/2024 | MS4 inspection or screening: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. | Yes, Notified Ecology | s royal brougham way / 4th ave s | Seattle | 98134 | 47.592393 | -122.329059 | Other: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. | Unconfirmed, unspecified, or not identified: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. | Not applicable: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. | Other: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. | Complaint. spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary. |
| WAR044503 | 2/20/2024 | 2/20/2024 | Pollution hotline (phone, web, app): report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. | Yes, Notified Ecology | 7413 faunterroy way sw | Seattle | 98136 | 47.536607 | -122.392519 | Food-related oil/grease: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. | Intentional dumping: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. | Not applicable: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. | Clean-up: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. | Complaint. report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted. |
| WAR044503 | 10/3/2024 | 10/3/2024 | ERTS referral: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. | Yes, Notified Ecology | 5th ave s / s spokane st | Seattle | | 47.571419 | -122.327472 | Other: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. | Vehicle-related business: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. | Not applicable: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. | Clean-up: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. | Complaint. report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted. |
| WAR044503 | 10/24/2024 | 10/24/2024 | Pollution hotline (phone, web, app): commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Yes, Notified Ecology | 11606 3rd ave ne | Seattle | 98125 | 0 | 0 | Fuel and/or vehicle related fluids: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Vehicle-related business: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Not applicable: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Clean-up: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. |
| WAR044503 | 2/11/2024 | 2/11/2024 | Pollution hotline (phone, web, app): received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. | Yes, No Notice Required | portage bay | Seattle | | 47.647925 | -122.313170 | Fuel and/or vehicle related fluids: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. | Unconfirmed, unspecified, or not identified: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. | Not applicable: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. | Other: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. | received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact. |
| WAR044503 | 1/16/2024 | 1/16/2024 | Pollution hotline (phone, web, app): hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. | Yes, Notified Ecology | 4500 west marginal way sw | Seattle | 98106 | 47.563193 | -122.350679 | Fuel and/or vehicle related fluids: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. | Vehicle-related business: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. | Not applicable: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. | Clean-up: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. | hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted. |
| WAR044503 | 2/5/2024 | 2/5/2024 | Pollution hotline (phone, web, app): report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. | Yes, No Notice Required | 4115 sw admiral way | Seattle | 98116 | 47.580959 | -122.384827 | Fuel and/or vehicle related fluids: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. | Intentional dumping: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. | Not applicable: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. | Clean-up: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. | report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact. |
| WAR044503 | 10/9/2024 | 10/9/2024 | Direct report to your staff: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. | Yes, No Notice Required | 5512 22nd ave nw | Seattle | 98107 | 47.669257 | -122.384350 | Other: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. | Other accident/spill: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. | Not applicable: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. | Other: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. | Complaint. report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4. |
| WAR044503 | 2/21/2024 | 2/21/2024 | Pollution hotline (phone, web, app): spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. | Yes, No Notice Required | 4058 rainier ave s | Seattle | 98118 | 47.567014 | -122.288201 | Fuel and/or vehicle related fluids: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. | Other accident/spill: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. | Not applicable: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. | Clean-up: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. | spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up. |
| WAR044503 | 12/10/2024 | 12/10/2024 | Direct report to your staff: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. | Yes, No Notice Required | 6332 38th ave sw | Seattle | 98126 | 47.545530 | -122.377475 | Fuel and/or vehicle related fluids: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. | Unconfirmed, unspecified, or not identified: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. | Not applicable: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. | Clean-up: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. | Complaint. a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed. |
| WAR044503 | 1/17/2024 | 1/17/2024 | Pollution hotline (phone, web, app): oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. | Yes, Notified Ecology | 8601 aurora ave n | Seattle | 98103 | 47.691607 | -122.345006 | Fuel and/or vehicle related fluids: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. | Intentional dumping: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. | Not applicable: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. | Clean-up: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. | oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted. |
| WAR044503 | 8/5/2024 | 8/5/2024 | MS4 inspection or screening: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. | Yes, Notified Ecology | s garden st & 48th ave s | Seattle | 98118 | 47.537635 | -122.272645 | Other: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. | Unconfirmed, unspecified, or not identified: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. | Not applicable: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. | Clean-up: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. | Complaint. spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|--|---|---|---|--|
| WAR044503 | 8/11/2024 | 8/11/2024 | Pollution hotline (phone, web, app): solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. | Yes, Notified Ecology | aurora ave n / n 93rd st | Seattle | 98103 | 47.696349 | -122.344613 | Other: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. | Vehicle collision: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa., Other accident/spill: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. | Not applicable: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. | Clean-up: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa., Clean-up: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. | solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa. |
| WAR044503 | 3/10/2024 | 3/10/2024 | Pollution hotline (phone, web, app): caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. | Yes, Notified Ecology | 11th ave / e olive st | Seattle | | 47.616421 | -122.318189 | Fuel and/or vehicle related fluids: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. | Unconfirmed, unspecified, or not identified: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. | Not applicable: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. | Other: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. | caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain. |
| WAR044503 | 1/4/2024 | 1/4/2024 | Staff referral: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. | Yes, Notified Ecology | 11th ave nw / nw ballard way | Seattle | 98107 | 47.662927 | -122.370778 | Fuel and/or vehicle related fluids: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. | Intentional dumping: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. | Not applicable: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. | Clean-up: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. | Complaint. planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa. |
| WAR044503 | 6/7/2024 | 6/7/2024 | Pollution hotline (phone, web, app): reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. | Yes, Notified Ecology | 10344 fischer pl ne | Seattle | 98125 | 47.704241 | -122.299189 | Other: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. | Unconfirmed, unspecified, or not identified: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. | Not applicable: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. | Referred to other agency or department: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact., Other: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. | reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact. |
| WAR044503 | 9/3/2024 | 9/3/2024 | Pollution hotline (phone, web, app): report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. | Yes, No Notice Required | 6727 mlk jr way s | Seattle | 98118 | 0 | 0 | Food-related oil/grease: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. | Intentional dumping: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. | Not applicable: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. | Clean-up: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted., Other: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. | report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted. |
| WAR044503 | 1/6/2024 | 1/6/2024 | Pollution hotline (phone, web, app): received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. | Yes, No Notice Required | 3256 nw 54th st | Seattle | 98107 | 47.667980 | -122.400688 | Other: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. | Other accident/spill: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. | Not applicable: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. | Referred to other agency or department: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program., Other: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. | Complaint. received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program. |
| WAR044503 | 11/21/2024 | 11/21/2024 | Pollution hotline (phone, web, app): self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Yes, Notified Ecology | 14320 36th ave ne | Seattle | | 0 | 0 | Fuel and/or vehicle related fluids: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Other accident/spill: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Not applicable: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | Clean-up: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact., Referred to other agency or department: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact., Other: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. | self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. |
| WAR044503 | 12/23/2024 | 12/23/2024 | Pollution hotline (phone, web, app): report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. | Yes, No Notice Required | 1500 broadway | Seattle | 98122 | 47.614359 | -122.320288 | Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. | Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. | Not applicable: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. | Referred to other agency or department: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci., Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. | Complaint. report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci. |
| WAR044503 | 9/6/2024 | 9/6/2024 | Pollution hotline (phone, web, app): responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. | Yes, Notified Ecology | n 34th st & stone way n | Seattle | 98103 | 47.648525 | -122.342788 | Sewage/septage/pet waste/human waste: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. | Construction activity: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. | Not applicable: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. | Referred to other agency or department: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. | responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented. |
| WAR044503 | 5/19/2024 | 5/19/2024 | Pollution hotline (phone, web, app): small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. | Yes, Notified Ecology | e howell st & 15th ave | Seattle | 98122 | 47.617618 | -122.312778 | Fuel and/or vehicle related fluids: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. | Intentional dumping: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. | Not applicable: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. | Clean-up: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. | small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4. |
| WAR044503 | 1/21/2024 | 1/21/2024 | Pollution hotline (phone, web, app): sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. | Yes, No Notice Required | 5609 26th ave sw | Seattle | 98106 | 47.551611 | -122.366008 | Fuel and/or vehicle related fluids: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. | Intentional dumping: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. | Not applicable: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. | Clean-up: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product., Other: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. | sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product. |
| WAR044503 | 11/1/2024 | 11/1/2024 | Pollution hotline (phone, web, app): reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. | Yes, Notified Ecology | 2700 w commodore way | Seattle | 98199 | 47.663043 | -122.391705 | Fuel and/or vehicle related fluids: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. | Other accident/spill: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. | Not applicable: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. | Clean-up: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa., Referred to other agency or department: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa., Other: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. | reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa. |
| WAR044503 | 11/1/2024 | 11/1/2024 | ERTS referral: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. | Yes, Notified Ecology | 6718 21st ave sw | Seattle | 98106 | 47.542175 | -122.359287 | Other: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. | Construction activity: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. | Not applicable: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. | Education/technical assistance: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa., Other: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. | asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa. |
| WAR044503 | 7/15/2024 | 7/15/2024 | Pollution hotline (phone, web, app): commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. | Yes, Notified Ecology | 520 terry ave | Seattle | 98104 | 47.606003 | -122.323170 | Fuel and/or vehicle related fluids: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. | Vehicle-related business: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. | Not applicable: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. | Clean-up: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4., Other: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. | commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4. |
| WAR044503 | 9/18/2024 | 9/18/2024 | Pollution hotline (phone, web, app): spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. | Yes, Notified Ecology | 8316 35th ave sw | Seattle | 98126 | 47.528536 | -122.376284 | Fuel and/or vehicle related fluids: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. | Other accident/spill: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. | Not applicable: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. | Clean-up: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. | spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant. |
| WAR044503 | 12/6/2024 | 12/6/2024 | ERTS referral: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. | Yes, Notified Ecology | 7739 1st ave s | Seattle | 98106 | 47.533655 | -122.337336 | Fuel and/or vehicle related fluids: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. | Vehicle-related business: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. | Not applicable: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. | Other: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. | spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor. |
| WAR044503 | 1/22/2024 | 1/22/2024 | Pollution hotline (phone, web, app): leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. | Yes, No Notice Required | 9718 rainier ave s | Seattle | 98118 | 47.516262 | -122.254023 | Fuel and/or vehicle related fluids: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. | Vehicle-related business: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. | Not applicable: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. | Clean-up: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted., Education/technical assistance: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted., Other: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. | leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|---|--|---|
| WAR044503 | 12/10/2024 | 12/10/2024 | Direct report to your staff: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. | Yes, No Notice Required | 13751 lake city way | Seattle | 98125 | 47.729859 | -122.292790 | Other: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. | Other accident/spill: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. | Not applicable: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. | Other: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. | Complaint. a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4. |
| WAR044503 | 2/6/2024 | 2/6/2024 | ERTS referral: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. | Yes, Notified Ecology | 1009 e union st | Seattle | 98122 | 47.612694 | -122.318925 | Other: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. | Vehicle-related business: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. | Not applicable: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. | Other: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. | Complaint. report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4. |
| WAR044503 | 6/12/2024 | 6/12/2024 | Pollution hotline (phone, web, app): report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. | Yes, No Notice Required | palm ave sw & sw atlantic st | Seattle | 98116 | 47.590363 | -122.284618 | Fuel and/or vehicle related fluids: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. Fuel and/or vehicle related fluids: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. | Vehicle collision: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. | Not applicable: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. | Referred to other agency or department: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. Other: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. | report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdot to complete row cleanup of fluid and debris. |
| WAR044503 | 4/1/2024 | 4/1/2024 | Pollution hotline (phone, web, app): multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. | Yes, No Notice Required | 1001 fairview ave n | Seattle | 98109 | 47.629018 | -122.331739 | Other: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. | Other accident/spill: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. | Not applicable: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. | Other: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. | multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted. |
| WAR044503 | 7/9/2024 | 7/9/2024 | Pollution hotline (phone, web, app): unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. | Yes, No Notice Required | e garfield st / fairview ave e | Seattle | 98118 | 47.633858 | -122.326934 | Sewage/septage/pet waste/human waste: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. | Vehicle-related business: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. | Not applicable: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. | Clean-up: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. | unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4. |
| WAR044503 | 3/14/2024 | 3/14/2024 | Pollution hotline (phone, web, app): report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. | Yes, No Notice Required | 3820 rainier ave s | Seattle | 98118 | 47.569611 | -122.288821 | Fuel and/or vehicle related fluids: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. | Intentional dumping: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. | Not applicable: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. | Clean-up: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. | report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4. |
| WAR044503 | 4/24/2024 | 4/24/2024 | Staff referral: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. | Yes, No Notice Required | 25th ave s / s college st | Seattle | 98118 | 47.582933 | -122.300353 | Solid waste/trash: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. Other: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. | Intentional dumping: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. | Not applicable: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. | Clean-up: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. | Complaint. planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. |
| WAR044503 | 3/30/2024 | 3/30/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. | Yes, No Notice Required | 4401 4th ave s | Seattle | 98134 | 47.565299 | -122.330772 | Fuel and/or vehicle related fluids: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. | Vehicle collision: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. | Not applicable: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. | Referred to other agency or department: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. Other: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. | spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. |
| WAR044503 | 7/29/2024 | 7/29/2024 | Pollution hotline (phone, web, app): report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. | Yes, Notified Ecology | 2811 fairview ave e | Seattle | 98102 | 47.645946 | -122.327678 | Fuel and/or vehicle related fluids: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. | Unconfirmed, unspecified, or not identified: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. | Not applicable: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. | Other: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. | report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg. |
| WAR044503 | 6/10/2024 | 6/10/2024 | Pollution hotline (phone, web, app): report of pool contractor discharging water into row and it entered a drain. none found. | Yes, No Notice Required | 212 32nd ave s | Seattle | 98144 | 47.600428 | -122.291066 | Other: report of pool contractor discharging water into row and it entered a drain. none found. | Unconfirmed, unspecified, or not identified: report of pool contractor discharging water into row and it entered a drain. none found. | Not applicable: report of pool contractor discharging water into row and it entered a drain. none found. | Education/technical assistance: report of pool contractor discharging water into row and it entered a drain. none found. Other: report of pool contractor discharging water into row and it entered a drain. none found. | Complaint. report of pool contractor discharging water into row and it entered a drain. none found. |
| WAR044503 | 9/16/2024 | 9/16/2024 | MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. | Yes, Notified Ecology | s lucite st & 35th ave s | Seattle | 98118 | 47.552497 | -122.289330 | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. | Not applicable: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. | Other: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. | Complaint. spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined. |
| WAR044503 | 9/10/2024 | 9/10/2024 | MS4 inspection or screening: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Yes, Notified Ecology | s angeline st & 38th ave s | Seattle | 98118 | 47.559460 | -122.284942 | Other: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Not applicable: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Other: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. | Complaint. spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. |
| WAR044503 | 3/29/2024 | 3/29/2024 | Business inspection: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. | Yes, No Notice Required | 10711 aurora ave n | Seattle | 98133 | 47.707086 | -122.345321 | Fuel and/or vehicle related fluids: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. | Other accident/spill: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. | Not applicable: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. | Clean-up: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. | during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed. |
| WAR044503 | 2/1/2024 | 2/1/2024 | Pollution hotline (phone, web, app): report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. | Yes, Notified Ecology | 201 lake washington blvd | Seattle | 98122 | 47.603136 | -122.284965 | Sediment/soil: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. | Construction activity: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. Other: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. | Not applicable: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. | Education/technical assistance: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. Other: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. | report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. |
| WAR044503 | 12/4/2024 | 12/4/2024 | Pollution hotline (phone, web, app): sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. | Yes, Notified Ecology | 417 e union st | Seattle | 98122 | 47.612817 | -122.325919 | Sewage/septage/pet waste/human waste: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. | Other accident/spill: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. | Not applicable: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. | Clean-up: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. Other: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. | sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. |
| WAR044503 | 6/4/2024 | 6/4/2024 | Pollution hotline (phone, web, app): leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. | Yes, No Notice Required | 1300 n 97th st | Seattle | 98103 | 47.699779 | -122.341618 | Fuel and/or vehicle related fluids: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. | Vehicle-related business: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. | Not applicable: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. | Other: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. | leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop. |
| WAR044503 | 6/4/2024 | 6/4/2024 | Pollution hotline (phone, web, app): garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. | Yes, Notified Ecology | 1515 believe ave | Seattle | 98122 | 47.614528 | -122.327199 | Solid waste/trash: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. | Other: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. | Not applicable: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. | Clean-up: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. Other: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. | garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-------|-----------|-------------|--|---|--|---|--|
| WAR044503 | 2/1/2024 | 2/1/2024 | Pollution hotline (phone, web, app): report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. | Yes, Notified Ecology | s forest st / rainier ave s | Seattle | | 47.577529 | -122.297723 | Fuel and/or vehicle related fluids: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. | Vehicle-related business: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined., Intentional dumping: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. | Not applicable: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. | Clean-up: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. | report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined. |
| WAR044503 | 12/8/2024 | 12/8/2024 | Pollution hotline (phone, web, app): a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. | Yes, Notified Ecology | 49th ave s / s hudson st | Seattle | | 47.557068 | -122.271937 | Fuel and/or vehicle related fluids: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. | Intentional dumping: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. | Not applicable: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. | Clean-up: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel., Education/technical assistance: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel., Other: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. | a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel. |
| WAR044503 | 2/10/2024 | 2/10/2024 | Pollution hotline (phone, web, app): received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. | Yes, Notified Ecology | 3717 beach dr sw | Seattle | 98116 | 47.570538 | -122.411786 | Sewage/septage/pet waste/human waste: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. | Other accident/spill: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. | Not applicable: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. | Clean-up: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair., Education/technical assistance: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. | received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair. |
| WAR044503 | 5/16/2024 | 5/16/2024 | Pollution hotline (phone, web, app): investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. | Yes, Notified Ecology | 510 31st ave s | Seattle | 98144 | 47.597628 | -122.292438 | Fuel and/or vehicle related fluids: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. | Vehicle-related business: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. | Not applicable: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. | Clean-up: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. | investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4. |
| WAR044503 | 7/23/2024 | 7/23/2024 | Pollution hotline (phone, web, app): report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. | Yes, No Notice Required | 115 broadway e | Seattle | 98102 | 47.619412 | -122.321281 | Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. | Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. | Not applicable: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. | Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. | report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made. |
| WAR044503 | 4/6/2024 | 4/6/2024 | Pollution hotline (phone, web, app): oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. | Yes, Notified Ecology | renton ave s / 53rd ave s | Seattle | | 47.514812 | -122.266530 | Fuel and/or vehicle related fluids: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. | Vehicle-related business: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa., Other accident/spill: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa., Intentional dumping: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. | Not applicable: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. | Clean-up: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. | oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa. |
| WAR044503 | 8/22/2024 | 8/22/2024 | Pollution hotline (phone, web, app): spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. | Yes, Notified Ecology | 7 s idaho st | Seattle | 98134 | 47.564499 | -122.341983 | Fuel and/or vehicle related fluids: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. | Other accident/spill: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. | Not applicable: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. | Clean-up: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. | spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed. |
| WAR044503 | 9/4/2024 | 9/4/2024 | Pollution hotline (phone, web, app): report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. | Yes, Notified Ecology | portage bay | Seattle | | 47.647925 | -122.313170 | Fuel and/or vehicle related fluids: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. | Other: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. | Not applicable: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. | Referred to other agency or department: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. | report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4. |
| WAR044503 | 8/28/2024 | 8/28/2024 | ERTS referral: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. | Yes, Notified Ecology | s bangor st & renton ave s | Seattle | 98178 | 0 | 0 | Other: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. | Vehicle-related business: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. | Not applicable: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. | Clean-up: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4., Other: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. | Complaint. report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4. |
| WAR044503 | 1/2/2024 | 1/2/2024 | Pollution hotline (phone, web, app): container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. | Yes, No Notice Required | erskine way sw / lewis pl sw | Seattle | | 47.558836 | -122.387551 | Food-related oil/grease: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. | Other accident/spill: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. | Not applicable: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. | Clean-up: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. | container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4. |
| WAR044503 | 9/10/2024 | 9/10/2024 | Pollution hotline (phone, web, app): restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. | Yes, No Notice Required | 9447 rainier ave s | Seattle | 98118 | 47.519929 | -122.263149 | Soap or cleaning chemicals: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. | Other: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. | Not applicable: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. | Education/technical assistance: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4., Other: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. | restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4. |
| WAR044503 | 6/27/2024 | 6/27/2024 | ERTS referral: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. | Yes, Notified Ecology | 7277 perimeter rd s | Seattle | 98108 | 47.536852 | -122.303928 | Firefighting foam: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. | Other accident/spill: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. | Not applicable: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. | Clean-up: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4., Referred to other agency or department: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. | Complaint. aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4. |
| WAR044503 | 2/1/2024 | 2/1/2024 | Pollution hotline (phone, web, app): report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. | Yes, Notified Ecology | 14033 32nd ave ne | Seattle | 98125 | 47.731078 | -122.294228 | Fuel and/or vehicle related fluids: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. | Unconfirmed, unspecified, or not identified: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. | Not applicable: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. | Clean-up: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup., Education/technical assistance: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup., Other: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. | report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup. |
| WAR044503 | 9/30/2024 | 9/30/2024 | MS4 inspection or screening: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. | Yes, Notified Ecology | e pike st & 35th ave | Seattle | 98122 | 47.614045 | -122.288196 | Other: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. | Unconfirmed, unspecified, or not identified: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. | Not applicable: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. | Other: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. | Complaint. dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary. |
| WAR044503 | 7/4/2024 | 7/4/2024 | Pollution hotline (phone, web, app): spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. | Yes, No Notice Required | 10215 greenwood ave n | Seattle | 98133 | 47.703139 | -122.356047 | Fuel and/or vehicle related fluids: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. | Intentional dumping: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. | Not applicable: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. | Other: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. | spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|---|---|---|
| WAR044503 | 7/26/2024 | 7/26/2024 | Pollution hotline (phone, web, app): spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. | Yes, No Notice Required | 3950 leary way nw | Seattle | 98107 | 47.655098 | -122.360591 | Fuel and/or vehicle related fluids: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. | Intentional dumping: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. | Not applicable: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. | nfa_spills, Education/technical assistance: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. | Complaint, spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses. |
| WAR044503 | 3/6/2024 | 3/6/2024 | Pollution hotline (phone, web, app): sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. | Yes, Notified Ecology | 3031 ne 137th st | Seattle | 98125 | 47.727406 | -122.294779 | Sewage/septage/pet waste/human waste: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. | Other accident/spill: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. | Not applicable: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. | Clean-up: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. | sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact. |
| WAR044503 | 5/28/2024 | 5/28/2024 | Pollution hotline (phone, web, app): commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Yes, No Notice Required | sw avalon way / sw spokane st | Seattle | | 47.571366 | -122.370636 | Other: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Vehicle-related business: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Not applicable: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | Clean-up: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. | commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4. |
| WAR044503 | 1/22/2024 | 1/22/2024 | Pollution hotline (phone, web, app): fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. | Yes, Notified Ecology | 68th ave s / holyoke way s | Seattle | | 47.508632 | -122.247962 | Fuel and/or vehicle related fluids: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. | Intentional dumping: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. | Not applicable: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. | Clean-up: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. Referred to other agency or department: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. Other: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. | fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. |
| WAR044503 | 7/3/2024 | 7/3/2024 | Staff referral: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. | Yes, Notified Ecology | 21st ave s / s plum st | Seattle | 98144 | 47.585499 | -122.305577 | Sewage/septage/pet waste/human waste: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. | Intentional dumping: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. | Not applicable: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. | Clean-up: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. | Complaint, planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa. |
| WAR044503 | 2/15/2024 | 2/15/2024 | ERTS referral: report of an unknown amount of rusty water that entered into the bay. no impact to ms4. | Yes, Notified Ecology | 1801 18th ave sw | Seattle | 98134 | 47.586026 | -122.353148 | Other: report of an unknown amount of rusty water that entered into the bay. no impact to ms4. | Other accident/spill: report of an unknown amount of rusty water that entered into the bay. no impact to ms4. | Not applicable: report of an unknown amount of rusty water that entered into the bay. no impact to ms4. | Other: report of an unknown amount of rusty water that entered into the bay. no impact to ms4. | Complaint, report of an unknown amount of rusty water that entered into the bay. no impact to ms4. |
| WAR044503 | 11/5/2024 | 11/5/2024 | Pollution hotline (phone, web, app): spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. | Yes, Notified Ecology | water body | Seattle | | 47.650468 | -122.356126 | Fuel and/or vehicle related fluids: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. | Unconfirmed, unspecified, or not identified: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. | Not applicable: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. | Referred to other agency or department: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. | spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found. |
| WAR044503 | 3/21/2024 | 3/21/2024 | Pollution hotline (phone, web, app): self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. | Yes, No Notice Required | 19th ave e / boyer ave e | Seattle | | 47.637922 | -122.307288 | Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. | Vehicle-related business: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. | Not applicable: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. | Clean-up: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. Referred to other agency or department: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. | self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. |
| WAR044503 | 12/16/2024 | 12/16/2024 | Pollution hotline (phone, web, app): report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. | Yes, No Notice Required | 2525 14th ave s | Seattle | 98144 | 47.580234 | -122.315178 | Fuel and/or vehicle related fluids: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. | Unconfirmed, unspecified, or not identified: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. | Not applicable: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. | Clean-up: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. | report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact. |
| WAR044503 | 8/22/2024 | 8/22/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. | Yes, Notified Ecology | 2320 43rd ave e | Seattle | 98112 | 47.639927 | -122.276373 | Sewage/septage/pet waste/human waste: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. | Other accident/spill: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. | Not applicable: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. | Clean-up: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. Referred to other agency or department: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. | spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. |
| WAR044503 | 3/13/2024 | 3/13/2024 | Pollution hotline (phone, web, app): two car accident. no impact to drainage. | Yes, No Notice Required | aurora ave n / n 140th st | Seattle | | 47.730490 | -122.345067 | Fuel and/or vehicle related fluids: two car accident. no impact to drainage. | Vehicle collision: two car accident. no impact to drainage. | Not applicable: two car accident. no impact to drainage. | Other: two car accident. no impact to drainage. | two car accident. no impact to drainage. |
| WAR044503 | 8/27/2024 | 8/27/2024 | MS4 inspection or screening: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. | Yes, Notified Ecology | s dakota st & 37th ave s | Seattle | 98118 | 47.566167 | -122.286105 | Other: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. | Unconfirmed, unspecified, or not identified: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. | Not applicable: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. | Other: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. | Complaint, spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary. |
| WAR044503 | 12/13/2024 | 12/13/2024 | Pollution hotline (phone, web, app): spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area | Yes, Notified Ecology | 4700 denver ave s | Seattle | 98108 | 47.560685 | -122.332418 | Fuel and/or vehicle related fluids: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area | Vehicle-related business: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area | Not applicable: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area | Clean-up: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area. Education/technical assistance: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area. | spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|--|-------------------------|--|---------|-------|-----------|-------------|--|--|---|---|---|
| WAR044503 | 1/3/2024 | 1/3/2024 | Pollution hotline (phone, web, app): received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. | Yes, Notified Ecology | 2001 w garfield st | Seattle | 98119 | 47.630999 | -122.382825 | Fuel and/or vehicle related fluids: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. | Vehicle-related business: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. | Not applicable: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. | Clean-up: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. | received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact. |
| WAR044503 | 4/3/2024 | 4/3/2024 | Pollution hotline (phone, web, app): cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. | Yes, Notified Ecology | 14032 aurora ave n | Seattle | 98133 | 47.731434 | -122.344610 | Other wastewater: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Soap or cleaning chemicals: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. | Intentional dumping: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. | Not applicable: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. | Clean-up: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Education/technical assistance: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Other: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. | cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa. |
| WAR044503 | 4/12/2024 | 4/12/2024 | Pollution hotline (phone, web, app): commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. | Yes, Notified Ecology | 4100 mosevelt way ne | Seattle | 98105 | 47.657086 | -122.317499 | Sewage/septage/pet waste/human waste: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. | Other accident/spill: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. | Not applicable: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. | Clean-up: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4., Education/technical assistance: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4., Other: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. | commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4. |
| WAR044503 | 8/16/2024 | 8/16/2024 | Pollution hotline (phone, web, app): spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. | Yes, No Notice Required | beacon ave s/s graham st | Seattle | 0 | 0 | 0 | Fuel and/or vehicle related fluids: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. | Vehicle collision: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. | Not applicable: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. | Clean-up: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. | spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health. |
| WAR044503 | 8/15/2024 | 8/15/2024 | Pollution hotline (phone, web, app): spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. | Yes, No Notice Required | 8724 mary ave nw | Seattle | 98117 | 47.693222 | -122.374970 | Fuel and/or vehicle related fluids: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. | Intentional dumping: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. | Not applicable: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. | Clean-up: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. | spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted. |
| WAR044503 | 9/27/2024 | 9/27/2024 | ERTS referral: caller reported spill to parking lot. photos were provided to verify that no drains were impacted. | Yes, Notified Ecology | 3407 airport way s | Seattle | 98134 | 47.573503 | -122.322398 | Fuel and/or vehicle related fluids: caller reported spill to parking lot. photos were provided to verify that no drains were impacted. | Vehicle-related business: caller reported spill to parking lot. photos were provided to verify that no drains were impacted. | Not applicable: caller reported spill to parking lot. photos were provided to verify that no drains were impacted. | Clean-up: caller reported spill to parking lot. photos were provided to verify that no drains were impacted., Education/technical assistance: caller reported spill to parking lot. photos were provided to verify that no drains were impacted., Other: caller reported spill to parking lot. photos were provided to verify that no drains were impacted. | caller reported spill to parking lot. photos were provided to verify that no drains were impacted. |
| WAR044503 | 7/22/2024 | 7/22/2024 | Pollution hotline (phone, web, app): report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. | Yes, No Notice Required | water body | Seattle | | 47.636837 | -122.333631 | Fuel and/or vehicle related fluids: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. | Unconfirmed, unspecified, or not identified: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. | Not applicable: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. | Referred to other agency or department: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested., Other: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. | report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested. |
| WAR044503 | 6/26/2024 | 6/26/2024 | Pollution hotline (phone, web, app): drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. | Yes, Notified Ecology | 9622 25th ave ne | Seattle | 98115 | 47.699156 | -122.301317 | Other: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa., Other: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. | Vehicle-related business: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. | Not applicable: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. | Clean-up: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. | drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa. |
| WAR044503 | 10/30/2024 | 10/30/2024 | Pollution hotline (phone, web, app): car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. | Yes, Notified Ecology | i5 northbound / south of west Seattle bridge | Seattle | | 47.570667 | -122.320117 | Unconfirmed, unspecified, or not identified: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. | Vehicle collision: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. | Not applicable: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. | Referred to other agency or department: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. | car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction. |
| WAR044503 | 2/23/2024 | 2/23/2024 | Pollution hotline (phone, web, app): spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. | Yes, No Notice Required | 1210 38th ave e | Seattle | 98112 | 47.630147 | -122.283735 | Sediment/soil: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. | Construction activity: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. | Not applicable: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. | Referred to other agency or department: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. | spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue. |
| WAR044503 | 11/19/2024 | 11/19/2024 | Pollution hotline (phone, web, app): report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. | Yes, Notified Ecology | 10712 aurora ave n | Seattle | 98133 | 47.707554 | -122.344397 | Fuel and/or vehicle related fluids: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. | Other accident/spill: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. | Not applicable: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. | Clean-up: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out., Other: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. | report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out. |
| WAR044503 | 7/10/2024 | 7/10/2024 | Direct report to your staff: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. | Yes, No Notice Required | east marginal way s & 1st ave s | Seattle | 98108 | 47.548270 | -122.334319 | Firefighting foam: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. | Other: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. | Not applicable: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. | nfa_spills, Other: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. | spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck. |
| WAR044503 | 1/23/2024 | 1/23/2024 | Pollution hotline (phone, web, app): gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. | Yes, No Notice Required | 1240 ne 127th st | Seattle | 98125 | 47.721862 | -122.313819 | Fuel and/or vehicle related fluids: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. | Intentional dumping: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. | Not applicable: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. | Clean-up: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. | gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4. |
| WAR044503 | 6/18/2024 | 6/18/2024 | Staff referral: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. | Yes, Notified Ecology | 7242 seaview ave nw | Seattle | 98117 | 47.682135 | -122.403613 | Sewage/septage/pet waste/human waste: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. | Intentional dumping: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. | Not applicable: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. | Clean-up: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck., Other: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. | Complaint. approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck. |
| WAR044503 | 12/20/2024 | 12/20/2024 | Pollution hotline (phone, web, app): report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. | Yes, No Notice Required | 860 terry ave n | Seattle | 98109 | 47.627591 | -122.336623 | Other: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. | Unconfirmed, unspecified, or not identified: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. | Not applicable: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. | Other: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. | report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4. |
| WAR044503 | 11/5/2024 | 11/5/2024 | Pollution hotline (phone, web, app): vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. | Yes, Notified Ecology | 44th ave s / s bateman st | Seattle | 98118 | 0 | 0 | Fuel and/or vehicle related fluids: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. | Intentional dumping: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. | Not applicable: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. | Clean-up: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4., Other: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. | vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|--|---|--|
| WAR044503 | 2/8/2024 | 2/8/2024 | Pollution hotline (phone, web, app): spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. | Yes, No Notice Required | 450 ne 100th st | Seattle | 98125 | 47.701781 | -122.323526 | Solid waste/trash: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. | Intentional dumping: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. | Not applicable: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. | Clean-up: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. | spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper. |
| WAR044503 | 7/16/2024 | 7/16/2024 | Pollution hotline (phone, web, app): received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. | Yes, No Notice Required | 1748 nw market st | Seattle | 98107 | 0 | 0 | Food-related oil/grease: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. | Other accident/spill: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. | Not applicable: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. | Clean-up: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. , Education/technical assistance: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. | received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. |
| WAR044503 | 10/31/2024 | 10/31/2024 | Pollution hotline (phone, web, app): motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. | Yes, Notified Ecology | nw 50th st & 15th ave nw | Seattle | 98107 | 47.665098 | -122.376388 | Fuel and/or vehicle related fluids: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. | Vehicle collision: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. | Not applicable: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. | Clean-up: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. | motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil. |
| WAR044503 | 5/23/2024 | 5/23/2024 | Pollution hotline (phone, web, app): one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. | Yes, Notified Ecology | 1401 alaskan way | Seattle | 98101 | 0 | 0 | Other: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. | Other accident/spill: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. | Not applicable: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. | Clean-up: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. , Other: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. | one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. |
| WAR044503 | 11/15/2024 | 11/15/2024 | Pollution hotline (phone, web, app): report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. | Yes, No Notice Required | 6924 rainier ave s | Seattle | 98118 | 47.540046 | -122.270822 | Fuel and/or vehicle related fluids: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. | Other: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. | Not applicable: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. | Clean-up: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. , Education/technical assistance: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. | report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. |
| WAR044503 | 6/12/2024 | 6/12/2024 | Pollution hotline (phone, web, app): report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. | Yes, Notified Ecology | 1137 29th ave s | Seattle | 98144 | 47.592365 | -122.295722 | Sewage/septage/pet waste/human waste: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. | Unconfirmed, unspecified, or not identified: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. | Not applicable: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. | Clean-up: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. , Other: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. | Complaint. report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. |
| WAR044503 | 1/4/2024 | 1/4/2024 | Pollution hotline (phone, web, app): sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. | Yes, No Notice Required | 7124 s 115th st | Seattle | 98178 | 47.499874 | -122.244480 | Fuel and/or vehicle related fluids: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. | Vehicle-related business: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. | Not applicable: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. | Clean-up: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. , Other: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. | sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. |
| WAR044503 | 2/11/2024 | 2/11/2024 | Pollution hotline (phone, web, app): spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts | Yes, No Notice Required | 9748 densmore ave n | Seattle | 98103 | 47.700955 | -122.337403 | Fuel and/or vehicle related fluids: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts | Other accident/spill: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts | Not applicable: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts | Clean-up: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts | spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts |
| WAR044503 | 4/21/2024 | 4/21/2024 | Pollution hotline (phone, web, app): a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. | Yes, Notified Ecology | 1307 n 43rd st | Seattle | 98103 | 47.659034 | -122.341807 | Sewage/septage/pet waste/human waste: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. | Other accident/spill: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. | Not applicable: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. | Clean-up: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. , Other: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. | a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcp were notified of the incident. |
| WAR044503 | 3/14/2024 | 3/14/2024 | ERTS referral: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. | Yes, Notified Ecology | 1001 sw klickitat way | Seattle | 98134 | 47.569860 | -122.348970 | Other: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. | Other accident/spill: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. | Not applicable: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. | Other: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. | Complaint. report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4. |
| WAR044503 | 10/16/2024 | 10/16/2024 | MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. | Yes, Notified Ecology | 35th ave s / alaska st | Seattle | | 47.560752 | -122.288832 | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. | Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. | Not applicable: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. | Other: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. , Other: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. | Complaint. spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. |
| WAR044503 | 5/31/2024 | 5/31/2024 | Pollution hotline (phone, web, app): truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. | Yes, No Notice Required | 1811 38th ave e | Seattle | 98112 | 47.635025 | -122.284386 | Fuel and/or vehicle related fluids: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. | Vehicle-related business: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. | Not applicable: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. | Clean-up: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. | truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste. |
| WAR044503 | 8/6/2024 | 8/6/2024 | MS4 inspection or screening: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. | Yes, Notified Ecology | s warsaw st & 39th ave s | Seattle | 98118 | 47.543182 | -122.283302 | Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. | Unconfirmed, unspecified, or not identified: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. | Not applicable: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. | Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. , Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. | Complaint. spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. |
| WAR044503 | 6/27/2024 | 6/27/2024 | Pollution hotline (phone, web, app): water to water diesel release. no impact to ms4. nrc previously notified. nfa. | Yes, Notified Ecology | water body ballard locks | Seattle | | 47.665814 | -122.398974 | Fuel and/or vehicle related fluids: water to water diesel release. no impact to ms4. nrc previously notified. nfa. | Unconfirmed, unspecified, or not identified: water to water diesel release. no impact to ms4. nrc previously notified. nfa. , Other accident/spill: water to water diesel release. no impact to ms4. nrc previously notified. nfa. | Not applicable: water to water diesel release. no impact to ms4. nrc previously notified. nfa. | Referred to other agency or department: water to water diesel release. no impact to ms4. nrc previously notified. nfa. | water to water diesel release. no impact to ms4. nrc previously notified. nfa. |
| WAR044503 | 2/12/2024 | 2/12/2024 | Pollution hotline (phone, web, app): report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. | Yes, No Notice Required | 9416 1st ave ne | Seattle | 98115 | 47.697502 | -122.327619 | Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. | Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. | Not applicable: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. | Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. | Complaint. report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4. |
| WAR044503 | 12/16/2024 | 12/16/2024 | ERTS referral: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills | Yes, Notified Ecology | 3409 stone way n | Seattle | 98103 | 47.648950 | -122.343126 | Other: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills | Unconfirmed, unspecified, or not identified: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills | Not applicable: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills | Clean-up: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills. , Education/technical assistance: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills. Other: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills | Complaint. report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--|---------|-------|-----------|-------------|--|--|--|--|--|
| WAR044503 | 9/9/2024 | 9/9/2024 | ERTS referral: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. | Yes, Notified Ecology | 925 seneca st | Seattle | 98101 | 47.609857 | -122.327750 | Fuel and/or vehicle related fluids: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. | Vehicle-related business: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. | Not applicable: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. | Other: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. | Complaint. spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler. |
| WAR044503 | 12/23/2024 | 12/23/2024 | Pollution hotline (phone, web, app): report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. | Yes, No Notice Required | 3902 s ferdinand st | Seattle | 98118 | 47.558067 | -122.283202 | Fuel and/or vehicle related fluids: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. | Intentional dumping: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. | Not applicable: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. | Clean-up: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. . Other: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. | Complaint. report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. |
| WAR044503 | 4/30/2024 | 4/30/2024 | Pollution hotline (phone, web, app): two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. | Yes, Notified Ecology | m l king jr way s / s massachusetts st | Seattle | | 47.588311 | -122.298061 | Fuel and/or vehicle related fluids: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. Fuel and/or vehicle related fluids: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. | Vehicle collision: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. | Not applicable: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. | Clean-up: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. . Other: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. | two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. |
| WAR044503 | 3/14/2024 | 3/14/2024 | Pollution hotline (phone, web, app): sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. | Yes, Notified Ecology | western ave / union st | Seattle | | 47.607362 | -122.340226 | Sewage/septage/pet waste/human waste: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. | Other accident/spill: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. | Not applicable: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. | Clean-up: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. | sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired. |
| WAR044503 | 12/6/2024 | 12/6/2024 | Pollution hotline (phone, web, app): rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. | Yes, Notified Ecology | 8400 10th ave sw | Seattle | 98106 | 46.807974 | -127.390431 | Sewage/septage/pet waste/human waste: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. | Intentional dumping: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. | Not applicable: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. | Clean-up: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. | rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program. |
| WAR044503 | 8/27/2024 | 8/27/2024 | Pollution hotline (phone, web, app): spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. | Yes, Notified Ecology | i-5 hwy & james st | Seattle | 98104 | 47.607048 | -122.330224 | Fuel and/or vehicle related fluids: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. | Vehicle collision: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. | Not applicable: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. | Clean-up: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. . Other: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. | spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. |
| WAR044503 | 5/1/2024 | 5/1/2024 | Direct report to your staff: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. | Yes, No Notice Required | nesbit ave n / n 88th st | Seattle | | 47.692372 | -122.343478 | Fuel and/or vehicle related fluids: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. | Intentional dumping: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. | Not applicable: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. | Clean-up: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. | Complaint. spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted. |
| WAR044503 | 8/30/2024 | 8/30/2024 | Pollution hotline (phone, web, app): spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified | Yes, No Notice Required | boykston ave / e pine st | Seattle | | 47.615230 | -122.323426 | Other: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified | Unconfirmed, unspecified, or not identified: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified | Not applicable: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified | nfa-spills, Referred to other agency or department: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified | spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified |
| WAR044503 | 1/31/2024 | 1/31/2024 | ERTS referral: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. | Yes, Notified Ecology | 1801 18th ave sw | Seattle | 98134 | 47.586026 | -122.353148 | Sewage/septage/pet waste/human waste: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. | Other accident/spill: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. | Not applicable: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. | Clean-up: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. | customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume. |
| WAR044503 | 4/25/2024 | 4/25/2024 | ERTS referral: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. | Yes, Notified Ecology | 1000 ne 135th st | Seattle | 98125 | 47.728586 | -122.316635 | Fuel and/or vehicle related fluids: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. | Other accident/spill: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. | Not applicable: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. | Clean-up: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. | Complaint. spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property, parks cleaned affected catch basin. no evidence that receiving water body was impacted. |
| WAR044503 | 2/5/2024 | 2/5/2024 | Pollution hotline (phone, web, app): report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. | Yes, Notified Ecology | 1st ave nw / nw 85th st | Seattle | | 47.690609 | -122.357992 | Fuel and/or vehicle related fluids: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. | Unconfirmed, unspecified, or not identified: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. | Not applicable: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. | Clean-up: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. . Other: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. | report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|--------------------------------|---------|-------|-----------|-------------|---|---|--|--|--|
| WAR044503 | 5/20/2024 | 5/20/2024 | ERTS referral: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. | Yes, Notified Ecology | 4224 university way ne | Seattle | 98105 | 47.659101 | -122.313008 | Food-related oil/grease: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. | Other accident/spill: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. | Not applicable: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. | Referred to other agency or department: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. , Other: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. | report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. |
| WAR044503 | 2/2/2024 | 2/2/2024 | Pollution hotline (phone, web, app): spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. | Yes, Notified Ecology | 5300 24th ave nw | Seattle | 98107 | 47.666541 | -122.387565 | Fuel and/or vehicle related fluids: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. | Construction activity: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. | Not applicable: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. | Clean-up: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. , Education/technical assistance: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. , Other: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. | spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. |
| WAR044503 | 4/9/2024 | 4/9/2024 | Pollution hotline (phone, web, app): used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. | Yes, Notified Ecology | 4139 university way ne | Seattle | 98105 | 47.657969 | -122.313509 | Food-related oil/grease: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. , Other: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. | Other accident/spill: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. | Not applicable: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. | Clean-up: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. , Clean-up: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. , Education/technical assistance: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. | used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. |
| WAR044503 | 2/23/2024 | 2/23/2024 | Pollution hotline (phone, web, app): spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. | Yes, Notified Ecology | 3711 ne 44th st | Seattle | 98105 | 47.660344 | -122.287639 | Fuel and/or vehicle related fluids: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. | Intentional dumping: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. | Not applicable: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. | Clean-up: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. , Education/technical assistance: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. | spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill. |
| WAR044503 | 4/2/2024 | 4/2/2024 | Pollution hotline (phone, web, app): spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills | Yes, No Notice Required | 6th ave s / s massachusetts st | Seattle | 98119 | 47.588249 | -122.325965 | Fuel and/or vehicle related fluids: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills | Vehicle collision: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills | Not applicable: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills | Clean-up: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills | spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills. nfa_spills |
| WAR044503 | 2/9/2024 | 2/9/2024 | Pollution hotline (phone, web, app): received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. | Yes, Notified Ecology | 1177 fairview ave e | Seattle | 98102 | 47.630806 | -122.329192 | Fuel and/or vehicle related fluids: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. | Intentional dumping: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. | Not applicable: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. | Clean-up: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. , Education/technical assistance: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. | received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. |
| WAR044503 | 8/12/2024 | 8/12/2024 | Pollution hotline (phone, web, app): gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. | Yes, Notified Ecology | 33rd pl s / s holly pl | Seattle | | 47.542169 | -122.290090 | Fuel and/or vehicle related fluids: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. | Intentional dumping: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. | Not applicable: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. | Clean-up: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. , Other: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. | gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa. |
| WAR044503 | 7/17/2024 | 7/17/2024 | ERTS referral: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. | Yes, Notified Ecology | 1829 10th ave w | Seattle | 98119 | 47.635587 | -122.370641 | Other: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. | Vehicle-related business: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. | Not applicable: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. | Clean-up: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. , Other: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. | Complaint. commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4. |
| WAR044503 | 9/26/2024 | 9/26/2024 | Pollution hotline (phone, web, app): vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. | Yes, Notified Ecology | 847 hiawatha pl s | Seattle | 98144 | 47.594847 | -122.309627 | Fuel and/or vehicle related fluids: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. | Other accident/spill: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. | Not applicable: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. | Clean-up: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. , Other: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. | vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. |
| WAR044503 | 4/8/2024 | 4/8/2024 | Pollution hotline (phone, web, app): hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. | Yes, Notified Ecology | 1008 ne 105th st | Seattle | 98125 | 47.705118 | -122.317291 | Other: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. | Other accident/spill: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. | Not applicable: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. | Other: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. | hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa. |
| WAR044503 | 3/22/2024 | 3/22/2024 | Pollution hotline (phone, web, app): report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. | Yes, Notified Ecology | 2700 airport way s | Seattle | 98134 | 47.579183 | -122.320757 | Fuel and/or vehicle related fluids: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. | Unconfirmed, unspecified, or not identified: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. | Not applicable: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. | Clean-up: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. , Other: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. | report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery. |
| WAR044503 | 8/29/2024 | 8/29/2024 | Direct report to your staff: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. | Yes, No Notice Required | 4760 denver ave s | Seattle | 98134 | 0 | 0 | Solid waste/trash: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. | Intentional dumping: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. | Not applicable: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. | Referred to other agency or department: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. , Other: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. | Complaint. two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. |
| WAR044503 | 11/17/2024 | 11/17/2024 | Pollution hotline (phone, web, app): report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. | Yes, Notified Ecology | 1600 pike pl | Seattle | 98101 | 47.609696 | -122.341779 | Other: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. | Other accident/spill: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. | Not applicable: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. | Clean-up: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. , Other: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. | report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. |
| WAR044503 | 2/1/2024 | 2/1/2024 | ERTS referral: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. | Yes, Notified Ecology | 1519 alaskan way s | Seattle | 98134 | 47.590172 | -122.338008 | Fuel and/or vehicle related fluids: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. | Vehicle-related business: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. | Not applicable: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. | Clean-up: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. , Other: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. | Complaint. motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved. |
| WAR044503 | 8/19/2024 | 8/19/2024 | Pollution hotline (phone, web, app): commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Yes, Notified Ecology | 1630 43rd ave e | Seattle | 98112 | 47.634287 | -122.276526 | Fuel and/or vehicle related fluids: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Vehicle-related business: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Not applicable: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | Clean-up: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. , Other: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. | commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-------------------------|-------------------------------------|---------|-------|-----------|-------------|---|---|--|---|--|
| WAR044503 | 3/15/2024 | 3/15/2024 | Pollution hotline (phone, web, app): pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. | Yes, No Notice Required | n 38th st / winslow pl n | Seattle | | 47.652744 | -122.346615 | Other: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. | Vehicle collision: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. | Not applicable: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. | Other: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. | pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4. |
| WAR044503 | 5/10/2024 | 5/10/2024 | Pollution hotline (phone, web, app): arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. | Yes, No Notice Required | rainier ave s / 57th ave s | Seattle | | 47.520263 | -122.261593 | Fuel and/or vehicle related fluids: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. | Vehicle collision: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. | Not applicable: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. | Clean-up: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. | arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4. |
| WAR044503 | 7/17/2024 | 7/17/2024 | ERTS referral: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. | Yes, Notified Ecology | 853 lake washington blvd s | Seattle | 98144 | 47.595165 | -122.289109 | Fuel and/or vehicle related fluids: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. | Other accident/spill: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. | Not applicable: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. | Clean-up: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. | Complaint. report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4. |
| WAR044503 | 8/2/2024 | 8/2/2024 | Direct report to your staff: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. | Yes, No Notice Required | 8850 9th ave sw | Seattle | 98106 | 47.523193 | -122.346471 | Sewage/septage/pet waste/human waste: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. | Vehicle-related business: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. | Not applicable: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. | Clean-up: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. | Complaint. investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party. |
| WAR044503 | 7/1/2024 | 7/1/2024 | Pollution hotline (phone, web, app): found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. | Yes, Notified Ecology | 406 broadway e | Seattle | 98102 | 47.622248 | -122.320603 | Food-related oil/grease: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. | Other accident/spill: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. | Not applicable: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. | Clean-up: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. | found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa. |
| WAR044503 | 11/14/2024 | 11/14/2024 | Pollution hotline (phone, web, app): received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. | Yes, Notified Ecology | 3919 18th ave w | Seattle | 98119 | 47.655611 | -122.380643 | Fuel and/or vehicle related fluids: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. | Vehicle-related business: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. | Not applicable: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. | Clean-up: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. | received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste. |
| WAR044503 | 1/25/2024 | 1/25/2024 | Pollution hotline (phone, web, app): report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. | Yes, Notified Ecology | s hanford st / 27th ave s | Seattle | | 47.575085 | -122.298277 | Fuel and/or vehicle related fluids: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. | Vehicle-related business: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. | Not applicable: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. | Clean-up: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. | Complaint. report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb. |
| WAR044503 | 7/1/2024 | 7/1/2024 | Pollution hotline (phone, web, app): sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. | Yes, Notified Ecology | 2710 ne 105th st | Seattle | 98125 | 47.704918 | -122.298314 | Sediment/soil: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. | Construction activity: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. | Not applicable: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. | Education/technical assistance: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. | sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl. |
| WAR044503 | 8/16/2024 | 8/16/2024 | Pollution hotline (phone, web, app): report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. | Yes, No Notice Required | n 94th st / stone ave n | Seattle | | 47.697071 | -122.341914 | Sewage/septage/pet waste/human waste: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. | Intentional dumping: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. | Not applicable: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. | Clean-up: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. | Complaint. report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program. |
| WAR044503 | 6/21/2024 | 6/21/2024 | Pollution hotline (phone, web, app): received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. | Yes, Notified Ecology | m l king jr way s & s henderson st | Seattle | 98118 | 47.523245 | -122.279219 | Fuel and/or vehicle related fluids: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. | Vehicle collision: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. | Not applicable: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. | Other: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. | received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology. |
| WAR044503 | 7/10/2024 | 7/10/2024 | Pollution hotline (phone, web, app): received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. | Yes, Notified Ecology | 5958 east marginal way s | Seattle | 98134 | 47.549189 | -122.334802 | Other: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. | Construction activity: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. | Not applicable: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. | Other: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. | received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary. |
| WAR044503 | 2/5/2024 | 2/5/2024 | Pollution hotline (phone, web, app): self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Yes, Notified Ecology | golden gardens dr nw / loyal ave nw | Seattle | | 47.693734 | -122.399329 | Fuel and/or vehicle related fluids: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Vehicle-related business: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Not applicable: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. | Clean-up: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. | self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact. |
| WAR044503 | 10/3/2024 | 10/3/2024 | Pollution hotline (phone, web, app): report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. | Yes, No Notice Required | east marginal way s & s horton st | Seattle | 98134 | 47.574387 | -122.339944 | Fuel and/or vehicle related fluids: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. | Unconfirmed, unspecified, or not identified: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. | Not applicable: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. | Clean-up: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. | report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact. |
| WAR044503 | 2/21/2024 | 2/21/2024 | Pollution hotline (phone, web, app): hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. | Yes, No Notice Required | 130 s kenyon st | Seattle | 98108 | 47.533212 | -122.333036 | Fuel and/or vehicle related fluids: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. | Other: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. | Not applicable: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. | Clean-up: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. | hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste. |
| WAR044503 | 12/23/2024 | 12/23/2024 | Pollution hotline (phone, web, app): report of construction company pumping muddy water from property after each rain event. no impact to ms4. | Yes, No Notice Required | 9547 wallingford ave n | Seattle | 98103 | 47.699190 | -122.336810 | Other: report of construction company pumping muddy water from property after each rain event. no impact to ms4. | Other: report of construction company pumping muddy water from property after each rain event. no impact to ms4. | Not applicable: report of construction company pumping muddy water from property after each rain event. no impact to ms4. | Referred to other agency or department: report of construction company pumping muddy water from property after each rain event. no impact to ms4. | report of construction company pumping muddy water from property after each rain event. no impact to ms4. |

| Permit number | Date incident discovered | Date beginning response | How was the incident discovered or reported to you | Discharge to MS4 | Street Address or Intersection | City | Zip | Latitude | Longitude | Pollutants Identified | Source or Cause | Source tracing approach(es) used | Correction/elimination methods used | Field notes, explanations, and/or other comments |
|---------------|--------------------------|-------------------------|---|-----------------------|--------------------------------|---------|-------|-----------|-------------|--|--|--|--|--|
| WAR044503 | 2/2/2024 | 2/2/2024 | Pollution hotline (phone, web, app): report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. | Yes, Notified Ecology | 1700 sturgus ave s | Seattle | 98144 | 47.588313 | -122.311296 | Sewage/septage/pet waste/human waste: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. | Other accident/spill: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. | Not applicable: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. | Clean-up: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair., Other: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair., Other: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. | report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair. |