Summary of URM Retrofit Laws California Jurisdictions

California State Law

Defines "potentially hazardous bldg" as constructed before bldg code required earthquake-resistant design of unreinforced masonry. Warehouses and other bldgs not used for human habitation are excluded unless emergency services equipment or supplies are stored there. Buildings having 5 or fewer living units are also excluded.

Law requires local jurisdictions in seismic zone 4 (the zone with the highest earthquake risk) to:

- identify all potentially hazardous buildings; and
- establish a mitigation program that includes notice to bldg owners. Local programs may include measures to strengthen bldgs, change use to acceptable occupancy level, demolish bldgs, tax incentives and low-cost loans for seismic rehabilitation.

Owners who have actual or constructive notice that their bldg located in seismic zone 4 is URM, and if building isn't retrofitted by 12/31/2004, must post a large sign at entrance "Earthquake Warning. This is an unreinforced masonry building. You may not be safe inside or near unreinforced masonry buildings during an earthquake."

Leases and rental agreements for bldgs subject to the law entered into after 1/1/2005 must contain the statement "This building, which you are renting or leasing, is an unreinforced masonry building. Unreinforced masonry buildings have proven to be unsafe in the event of an earthquake. Owners of unreinforced masonry buildings are required to post in a conspicuous place at the entrance of the building, the following statement: 'Earthquake Warning. This is an unreinforced masonry building. You may not be safe inside or near an unreinforced masonry building during an earthquake.' "

Sign and lease provisions don't apply to URMs if walls are nonload bearing with steel or concrete frame, or to buildings retrofitted according to local ordinance.

Penalties for not complying with sign and lease requents include administrative fine of \$250, plus add'l \$1000 if not in compliance within 30 days of the first fine.

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|---------------|--------------------------------------|-----------------------------------|--|--------------------------------------|
| San | One or more | Bldg Official must issue notices | Comply with Chapter 16C of SF Building Code (not the standards | Notice and inventory filed with |
| Francisco | URM bearing | by 2/15/1993 | for new bldgs) | property records until bldg complies |
| | walls and | Up to 13 years to complete | | |
| 2000 URMs; | Bldg is entirely | alterations, depends on level of | Essential & hazardous facilities per ASCE Std req'd to comply | Barricade or abate & recover costs |
| apx 150 not | residential; ≥ 5 | risk. Measured from 2/15/1993 | with new code. | |
| in compliance | units | • 3.5 yrs for Level 1 (high) risk | | \$500 per day penalty |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|---------------|---|---------------------------------------|--|--------------------------|
| as of Feb | Not accessory to | = assemblies \geq 300 occupants, | Historic bldgs can choose Chap 16B or State Historic Bldg Code | 6 months in jail per day |
| 2008; apx | previous | schools, or > 3 stories on poor | | |
| 100 demo'd | Not already in compliance | soil (areas of poor soil are mapped) | Specific provisions for mixed construction (e.g. part URM, part wood) | |
| Bonds used to | | • 5 yrs for Level 2 = non-Level | | |
| fund loans to | | 1 on poor soil in certain | Bolts Plus* allowed if justified by engineer according to Section | |
| bldg owners, | | mapped locations | 1609C.2 and <u>not</u> : | |
| but program | | • 11 yrs for Level 3 = buildings | • Assembly with ≥ 300 occupants, | |
| was too | | in Level 2 mapped areas not | • School, | |
| complex for | | on poor soils | • > certain amount of hazardous materials, | |
| most owners | | • 13 yrs for Level 4 = all other URMs | • > 6 stories | |
| | | Phasing may be allowed | *Bolts Plus is the installation of shear and tension anchors at the roof and floors and, when required, the bracing of the unreinforced masonry bearing walls upon evaluation of the | |
| | | | height-to- thickness ratio of these walls. | |
| | | | Energy Code only applies if change of use, increase in conditioned space, or alteration to mechanical or lighting system. | |
| | | | Specifically states there is no exemption from state and federal accessibility reqmts. | |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|-----------------|--|--|--|---------------------------------------|
| Berkeley | • URM built before | 2 yrs: engineering report due | More stringent of Bldg Code for new construction or | File notice with property title that |
| | 1956 approved as | Timeline for retrofit depends on | "performance standard". | transfer of title or refinancing reqs |
| 700 URMs | commercial or | level of risk. Measured from | | compliance with retrofit requents |
| identified; all | mixed use; or | 1/15/2001. | Prescriptive standards can be used for "simple bldgs" rectangular | |
| but 22 are | URM built before | • 3/1/1997: Risk Category (RC) | or square bldgs ≤ 2 stories | Properties not retrofitted are public |
| retrofitted. | 1956 containing ≥ | I = commercial bldgs* with | | nuisances |
| Some | 5 living units; or | occupant load ≥ 1000 ; | 1997 Uniform Code for Building Conservation Appendix Chapter | |
| assistance is | Bldg with at least | hospitals, fire & police | 1 as amended is adopted | Notice of Violation ordering |
| available— | one brick infill | stations, govt admin offices | | abatement |
| see Bay Area | wall located in | • 3/1/1997: RC II = Commercial | Historic bldgs comply with more stringent of State Historical Bldg | |
| Best Practices | high pedestrian | bldgs with occupant load ≥ | Code or UCBC | |
| summary | traffic corridor; or | 300; Residential bldgs with > | | |
| | Bldg with brick | 100 living units/bedrooms; | Essential and hazardous facilities as defined by Bldg Code comply | |
| | veneer $\geq 10'$ | Mixed use with combined | with more restrictive of UCBC & reqmts for new construction. | |
| | above grade | occupancy load > 300 | | |
| | located in high | • 6/30/1997: RC III = | | |
| | pedestrian traffic | Commercial bldgs with | | |
| | corridor; or | occupancy load ≥ 100 ; | | |
| | • Bldg with | Residential bldgs with ≥ 50 | | |
| | unreinforced | living units/bedrooms; Mixed | | |
| | parapet with | use with combined occupancy load > 100 | | |
| | height/depth ratio > 1:1/2 located in | • 12/31/1997: RC IV = | | |
| | high pedestrian | Commercial bldgs with | | |
| | traffic corridor | occupancy load \geq 50; | · | |
| | traffic collidor | Residential bldgs with < 50 | | |
| | | living units/bedrooms; Mixed | | |
| | | use with combined occupancy | | |
| | | load > 50. | | |
| | | | | |
| | | load > 50. • 12/31/1998: RC V = | | |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|--------------|-------|--|------------------------|-------------------------|
| Jurisurcuon | Scope | Commercial bldgs with occupancy load ≤ 50; Residential bldg with ≤ 20 living units/bedrooms; Mixed use with combined occupancy load ≤ 50 • 12/31/2001: RC VI = Nonresidential bldg used < 20 hrs per week; any bldg with masonry veneer ≥ 10′ in height; any bldg with masonry parapet with ratio > 1½; bldg with masonry infill located in high pedestrian traffic corridor *Commercial bldg includes businesses, assembly bldgs, educational and institutional occupancies Hardship extensions for up to 18 months City could order immediate retrofit in specified circumstances | Standard for Ketronis | T charties & Emorcement |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|----------------|---------------------------------------|------------------------------------|---|--|
| Oakland | URMs built prior to | Bldg Dept req'd to identify | Bearing wall bldgs: UCBC applied except that current code | \$1000 for failure to file timely bldg |
| | 11/26/1948 Bldg | priority bldgs based on soil type, | applied to parapets & nonstructural falling hazards | permit application & engineering |
| Bay Area | Code | # stories, adjacent pedestrian & | | analysis; \$5000 max per bldg (unclear |
| Best Practices | Except: | vehicle traffic, use, # of | Req'd to upgrade the following elements "to mitigate potential | how the fine accumulates) |
| summary says | Detached single | occupants, complexity of retrofit | falling hazards": | |
| Oakland | family residence | work. 3 levels established. | Secure roof & floor to exterior walls, design connections for out | \$2000 per month for failure to |
| minimum | or duplex | | of plane forces on the walls | complete upgrade; \$10,000 max per |
| standard is | Detached | Bldgs with URM bearing walls | Brace or reinforce parapets to current code, | bldg |
| Bolts Plus. If | multifamily with | req'd to apply for bldg permit | Remove or upgrade nonstructural falling hazards to comply | |
| voluntary | \leq 5 units; | within 1-3 yrs & complete | with current code, | City can file lien. |
| upgrade to | • Bldgs accessory to | construction in 2-4 yrs, | Stairways, corridors, exit balconies, exit courts, exit | |
| UCBC, more | the above; | depending on priority level | passageways req'd to be protected from falling hazards | Additional enforcement actions: |
| lucrative uses | Bldg structurally | | | Notify all parties with financial |
| allowed in the | upgraded after | Frame bldgs with URM infill | Frame bldgs with URM walls & bldgs with URM veneer: | interest in property; |
| building, such | 11/26/48 to | walls & bldgs with URM veneer | Brace or reinforce parapets to current code, | Record statement with property |
| as live-work | comply with | req'd to apply for bldg permit in | Remove or upgrade nonstructural falling hazards to comply | records; |
| | earthquake stds in | 3-5 years, & complete | with current code, | Post a sign designating bldg as |
| 1612 URMs; | effect at the time. | construction in 5-7 yrs, | Stairways, corridors, exit balconies, exit courts, exit | potentially hazardous; |
| by 2003 89% | | depending on priority level | passageways req'd to be protected from falling hazards | Revoke Certificate of Occupancy & |
| demo'd or | | | | evacuate bldg 3 yrs after date work |
| retrofitted. | | | | was due |
| 200+ met | | | | Declare public nuisance |
| UCBC | | | | • Injunction |
| standard. | | | | Withhold other bldg permits for the |
| | | | | property |
| | | | | • Charge bldg owner with an |
| | | | | infraction |
| | | | | |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|--------------|---|---|--|--|
| Los Angeles | Bldgs with URM bearing walls built, under construction, or having a bldg permit prior to Oct 6, 1933 Doesn't apply to: • one- and two- family dwellings • detached apartment houses with less than 5 dwellings used only for residence • Historic bldgs comply with Division 84 (Div 84 not found in current code) and California Historical Bldgs Code | Structural analysis and plans for retrofit are due within 270 days¹ Plan for wall anchors is due within 120 days¹ Demolition plan is due within 270 days¹ time is measured from date of service of order Alterations or demo complete within 3 years² Wall anchor installation complete within 1 year² Time extensions possible for wall anchor installations. time is measured from issuance of building permit. There were intermediate deadlines for obtaining bldg permit, commencing construction Different rules for vacant buildings— For one-story bldg with wall anchors that is being retrofitted, Plans & structural analysis within 180 days of service of notice | As specified in the ordinance (Sec. 91.8808, .8809, .8811) Parapets & exterior wall appendages req'd to be removed, stabilized or braced. Max height of unbraced parapet is 1.5 x thickness. | City files notice with property records that bldg is subject to retrofit reqmts. City may order bldg to be vacated; if owner doesn't comply within 90 days after order to vacate, city can order demolition of bldg. Failure to comply is misdemeanor. Demolition of building by city allowed for vacant bldgs. |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|--------------|-------|--|------------------------|-------------------------|
| | | Bldg permit for alterations | | |
| | | • issued within 270 days of | | |
| | | service of notice. | | |
| | | • Work to commence within 90 | | |
| | | days of issuance of bldg | | |
| | | permit | | |
| | | • Complete work within 18 | | |
| | | months of date of notice | | |
| | | | | |
| | | For one-story bldg with wall | | |
| | | anchors that is being demolished, | | |
| | | Application for demo due | | |
| | | within 180 days of service of | | |
| | | notice | | |
| | | Permits for demo issued | | |
| | | within 210 days of notice | | |
| | | • Commence demolition within | | |
| | | 21 days of obtaining permit | | |
| | | • Complete demolition within | | |
| | | 300 days of service of notice | | |
| | | | | |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|--------------|-------------------------------------|---|---|-------------------------|
| San Diego | Bldgs constructed or | Essential and hazardous facilities | Essential and hazardous facilities have to comply with standards | Bldg may be vacated |
| | with bldg permit | demolish or retrofit by 1/1/2006 | for new bldgs. | Bldg may be demolished |
| | issued before | | | |
| | 3/24/1939 | Remodels > 100% value of bldg | Remodels > 100% value of bldg in 5 yr period after $1/1/2001$; | |
| | Doesn't apply to: | in 5 yr period after 1/1/2001 | Change to higher hazard category either comply with Historical | |
| | • one- and two- | must complete seismic retrofit | Bldg Code, 2007 Building Code, or regs for archaic unreinforced | |
| | family dwellings | within 10 years from issuance of | masonry | |
| | detached | permit that puts it over 100% | | |
| | apartment houses | | Remodels $> 50\%$ value of bldg in 5 yr period after $1/1/2001$; floor- | |
| | with less than 5 | Change to higher hazard | to-wall and roof-to-wall anchors on perimeter | |
| | dwellings used | $\underline{\text{category}}$ of $> 33\%$ of floor area | | |
| | only for residence | & occupant load of bldg | Wall anchorage and parapet bracing must meet Section A113.1 of | |
| | bldgs that have | increases (Table 145-26A lists | 2007 CA Existing Bldg Code or State Historical Bldg Code | |
| | been retrofitted to | hazards—high includes | | |
| | certain standards | assembly, education, hospitals, | Historical bldgs comply with State Historical Bldg Code; strength | |
| | before 1/1/2008 | nursing homes, restaurants with | values for existing materials from 2007 CA Existing Bldg Code | |
| | | more than 50 occupants; | | |
| | Applies to wall | residential uses are second | Bldgs of "archaic unreinforced masonry" (is there any other kind | |
| | anchorage and | highest) must complete seismic | of unreinforced masonry?) For walls of unreinforced unburned | |
| | bracing of parapets | retrofit within 10 years of date of | clay, adobe or stone masonry: | |
| | and other exterior | change of use | Height or length-to-thickness ratio is limited by 2007 CA | |
| | objects that have | | Existing Bldg Code; bond beam req'd | |
| | potential to give way | Wall anchorage and parapets | • Exterior bearing wall minimum thickness of 18". | |
| | internally or onto | within scope must either be | No adobe or stone structure > 1 story without historic | |
| | lower adjacent | stabilized, removed, or braced by | evidence | |
| | property, exits or | 1/1/2006 | Newly reconstructed walls must have reinforced concrete | |
| | public way, and | | foundations 50% wider than the wall. Less is OK if facing | |
| | extend above either | Remodels > 50% value of bldg | is needed for authenticity | |
| | the closest adjacent | in 5 yr period after 1/1/2001; by | New or existing unstabilized brick and adobe brick | |
| | roof-to-wall anchors | 1/1/2006 | | |

| Jurisdiction | Scope | Timeline for compliance | Standard for Retrofits | Penalties & Enforcement |
|--------------|------------------------|-------------------------|--|-------------------------|
| | or the roof sheathing. | | masonry shall test to 75% of compressive strength req'd | |
| | | | for new materials. | |
| | | | Strength values for existing and new materials from 2007 | |
| | | | CA Existing Bldg Code | |

