



STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

*Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000*

September 8, 2015

TO: TCP File

FROM: Donna Musa  
Ecology NWRO Initial Investigations Coordinator

SUBJECT: Initial Investigation: No Further Action (NFA) Determination  
**Seattle City Light Dumar Substation**  
1605 SW Holden St  
Seattle, WA 98106  
Parcel # 2113200005  
Facility Site ID: 14030  
Cleanup Site ID: 12769

Ecology has determined that no further action is necessary (at the Initial Investigation stage) due to independent remediation.

Ecology reviewed the following report:

- Construction Completion Report, Seattle City Light Dumar Substation Property, 1605 SW Holden St, Seattle, Washington. Hart Crowser, Inc., Seattle, WA. April 7, 2014.

The above report provides sufficient documentation that this cleanup was conducted to MTCA Method A cleanup levels for unrestricted land use.

Additional information about Ecology's review of this site cleanup may be accessed here: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=12769>.

To view the documentation Ecology has available electronically, on the right-hand side of the page, click on [View Electronic Documents](#).