Gas Works Park Kite Hill Restoration - Turnaround Landmarks Preservation Board

David Graves, Strategic Advisor | February 5, 2025





Kite Hill Erosion



Kite Hill Erosion

CHALLENGE

Ongoing maintenance and annul reseeding practice has not been able to keep up with heavy use and program demands. It has caused:


- · Lost of Soil cover required for landfill, especially around top of Kitehill.
- · Damage to the sundial from eroded sand.




Kite Hill Erosion

REMEDIATION PROPOSAL


- · Restore Kite Hill to landmarked elevation for required soil cover.
- · Apply asphalt surfacing with Streetbond coating on berms surrounding Sundial plaza .
- · Erosion control blanket, hydroseeding and turf re-establishment for damaged turf areas.
- · Adding turnaround to reduce turf damage at lower meadow area east of Kite Hill.



Kite Hill – Original Grading Plan




Kite Hill – Restoration






Kite Hill – Restoration Study



Kite Hill – Restoration Option

Proposed Area to apply FlexiPave






KBI FLEXI-PAVE COLOR CHART



Kite Hill – Restoration Plan

WORK SCOPE INVOLVES:


- · Balance earthwork on site for berm restoration
- · Approximate Asphalt paving area at berms: 3,700 sq. ft.
- · Proposed Erosion Control & turf restoration: 5,000 sq. ft.
- · Asphalt Turnaround paving addition: 1,510 sq. ft



Kite Hill – Restoration Plan 3D

WORK SCOPE INVOLVES:


- · Balance earthwork on site for berm restoration
- · Estimated Asphalt paving: 3,700 sq. ft.
- · Erosion Control & turf restoration: 5,000 sq. ft.



Kite Hill – Restoration Plan Details

ASPHALT SURFACING on Kite Hill

- Pavement Coating: Streetbond Pro220
- · Color alternatives: Avocado to simulate grass green or Irish Cream for contrast
- · Concrete edge at end of asphalt paving for stabilization




Kite Hill – Streetbond Pro Details



Kite Hill – Asphalt/Concrete Details

ASPHALT/CONCRETE EDGE DETAILS







Vehicle Turnaround

ASPHALT SURFACING - Service Road turnaround

- · Partial widening ex. asphalt paving to 11': 170 sq ft
- · Enlarge turning corner to 20' radius: 90 sq ft
- New 10' wide asphalt paving for turnaround: 1,250 sq ft



Turnaround – Detail



ASPHALT PAVING NOTES:

- 1. HMA CLASS $\c N_2$ " PG58-22 FOR ALL WEARING COURSE THICKNESS: 3" FOR SERVICE VEHICLE
- TYPE 1 BASE AGGREGATE THICKNESS: MIN 4" FOR PATHWAYS; 6" FOR VEHICLE TRAFFIC
- UNDISTURBED SOIL OR COMPACTED SUBGRADE PER SECTION 31 00 00 EARTHWORK SPECIFICATION.
- TYPE 1 AGGREGATE SHOULDER MIN. WIDTH "D" EQUALS TO THICKNESS OF ASPHALT AND BASE AGGREGATE.
- 5. CONDITION BEYOND PAVEMENT SECTION VARIES PER PLAN.
- 2 ASPHALT PAVING SERVICE ROAD TURNAROUND
 NOT TO SCALE

Thank you!



