



**LOCATION OF PROPOSED
GLAZING REPLACEMENT**

**LOCATION OF PROPOSED
GLAZING REPLACEMENT**






ENLARGED
EXISTING WINDOW
SCALE: 1/2" = 1'-0"



NEW INSERT DOUBLE HUNG WINDOWS





EXISTING WINDOWS - AS VIEWED FROM THE EXTERIOR

CAFE WINDOW ELEVATIONS

DATE: 02.14.2020

DELAURENTI FOOD AND WINE

SCALE: 1/4" = 1'-0"



CAFE WINDOWS - JAMB SECTION A-A


DATE: 02.14.2020

DELAURENTI FOOD AND WINE


SCALE: 6" = 1'-0"

Section Details: Operator


Scale: 3" = 1' 0"




Head Jamb, Checkrail, with Beveled Sill
installed in existing frame




Head Jamb, Checkrail, with Flat Sill Option
installed in existing frame




Jambs installed in existing frame




ENLARGED
EXISTING WINDOW
SCALE: 1/2" = 1'-0"



NEW CASEMENT WINDOWS - CONFIGURATION - B



NEW CASEMENT WINDOWS - CONFIGURATION - A




EXISTING WINDOWS - AS VIEWED FROM THE EXTERIOR

OFFICE WINDOW ELEVATIONS


DELAURENTI FOOD AND WINE

DATE: 10.26.2020

SCALE: 3/8" = 1'-0"



MODIFIED WINDOW - JAMB CONDITION



EXISTING WINDOW - JAMB CONDITION

OFFICE WINDOW - JAMB SECTION A-A

DATE: 10.26.2020



DELAURENTI FOOD AND WINE

SCALE: 6" = 1'-0"



Section Details: Casement Push Out Narrow Frame / Picture

Scale: 3" = 1' 0"

UWCANFPO



UWCANFPOP



NOTE: CE mark is not available with narrow frame.

Packet to be revised
with additional details
prior to April 14, 2021
MHC meeting