

PIONEER SQUARE HISTORIC DISTRICT AREAWAYS SURVEY MAP

LEGEND
(Based on 2001 Survey)

Structural Ratings

- █ Critical Sidewalk
- █ Restorable Sidewalk
- █ Adequate Sidewalk
- █ Light-Weight Concrete Filled Arealway


- Critical Street Wall
- Restorable Street Wall
- Adequate Street Wall
- * Critical Street Wall if Fill is Removed
- Restorable Street Wall if Fill is Removed

Historical Ratings

- 405 (1) Substantially Intact, Notable
- 405 (2) Minor Alterations, or Notable Features
- 405 (3) Substantially Altered
- 405 (4) New, or Significantly Altered

- PSHD Boundaries
- Inaccessible Arealway
- No Known Arealway
- City Light Vault

RATING EXAMPLE



AREAWAYS BASE MAP DATE: 12/30/08



AREAWAY CONSTRUCTION STATUS

- 1) 904, 1401, 1403A, 1404, 1501: FILED PRE-2000.
- 2) 905: FILED 1/2001.
- 3) 1003, 6000, 6002, 6003, 6004: PARTIAL FILED, 9/2002-2/2003. 906: FILED, 9/2002-2/2003.
- 4) 601C, 2202B: RECONSTRUCTED 9/2002-7/2003.
- 5) 907, 908, 1403B: PARTIAL FILED, 1/2004-4/2004. 1002B, 1103, 8000A, 8003: FILED, 1/2004-4/2004.
- 6) 5000: STREETWALL ON PILES.
- 7) 903: STREETWALL ON MICROPILES, 12/2007. 1806: PARTIAL FILED, 12/2007.

MONITORING PROGRAM

AREAWAYS INCLUDED IN MONITORING PROGRAM PHASE 1 (4/2004) ARE SHOWN HIGHLIGHTED AS