

The City of Seattle

Pioneer Square Preservation Board

Mailing Address: PO Box 94649, Seattle WA 98124-4649 Street Address: 600 4th Avenue, 4th Floor

PSB 158/22

Staff REPORT

for Board meeting Aug 3, 2022

Board Members Please Note: The citations from the District Ordinance, Rules for the Pioneer Square Preservation District, and Secretary of the Interior's Standards listed below are for your consideration in addition to any other citations you find relevant in considering each application.

080322.41 <u>Metropole Building</u> 423 2nd Ave Matt Aalfs

Briefing regarding alterations to the areaway

Staff report: The rehabilitation of the building was approved with PSB6221. At the time the areaway was still being evaluated so was not included in the C of A plans. This is substantially intact areaway. However, there are openings indicating that prism light were there originally. Replacement of the missing or damaged prism glass panels has been common in the district. While the prisms would have originally come clear the magnesium in the glass made them turn purple with age. Typically, the Board has approved the replacement glass to be in purple. Each areaway in the district was built differently and requires different solutions to their repair, The Board has typically looked for the least impactful solutions.

SMC 23.66.030 Certificates of Approval required

Pioneer Square Preservation District Rules

III. GENERAL GUIDELINES FOR REHABILITATION AND NEW CONSTRUCTION

In addition to the Pioneer Square Preservation District Ordinance and Rules, The Secretary of the Interior's Standards for Rehabilitation with Guidelines for Rehabilitating_Historic Buildings, and the complete series of Historic Buildings Preservation Briefs developed by the National Park Service shall serve as guidelines for proposed exterior alterations and treatments, rehabilitation projects, and new construction. (7/99)

"Printed on Recycled Paper"

Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values. (7/99) In considering rehabilitation projects, what is critical is the stabilization of significant historical detailing, respect for the original architectural style, and compatibility of scale and materials.

XVII. SIDEWALK TREATMENT

A. Standards

Sidewalk paving and improvements shall be completed with one pound lampblack per cubic yard of concrete, scored at two-foot intervals. This material shall be used for all projects of 1/4 block or greater size. On small projects, if it is feasible, sidewalk material may be selected as for all projects of 1/4 block or greater size. On small projects, if it is feasible, sidewalk material may be selected to match adjacent sidewalks in color, pattern and texture.

B. Sidewalk Prism Lights

The glass sidewalk prism lights are one of the unique elements in the District, and their retention is required. The Board maintains the right to require applicants for sidewalk repair to repair sidewalk prism light panels and individual prism lights that have deteriorated into a state of disrepair. (7/99)

XVIII. AREAWAYS

Areaways are usable areas constructed under the sidewalk between the building foundation and street wall. Areaways were created after the Great Seattle Fire of 1889 when the District was rebuilt and the street elevations were raised. Building standards adopted shortly after the fire required fireproof sidewalk construction to replace the pre-fire wooden sidewalks. Areaways are part of the City's right-of-way area, however, the space is often available for use by the adjacent building owner. (7/03)

The most significant qualities of an areaway are its volume of space, which provides a record of its history, and the architectural features that render its form, character, and spatial quality. These features include use of unit materials (brick or stone), bays articulated by arches and/or columns, ceiling vaults, and other special features including tilework or skylights (sidewalk prism lenses). The historic characteristics of areaways shall be preserved. (7/03)

In 2001, the Seattle Department of Transportation completed a survey of approximately 100 areaways in the District. Each areaway was rated in terms of its structural condition and presence of original historic characteristics. A range of structural repairs options were proposed based on the structural and historical ratings. The 2001 Seattle Department of Transportation Areaway Survey shall serve

as a guide for the Board's decision making on future alterations or repairs to

areaways in the District. (7/03)

Secretary of Interior's Standards

6. Deteriorated historic features will be repaired rather than replaced. Where the severity

of deterioration requires replacement of a distinctive feature, the new feature will

match the old in design, color, texture and, where possible, materials. Replacement of

missing features will be substantiated by documentary and physical evidence.

Issued:

July 13, 2022

Genna Nashem

Pioneer Square Preservation Board Coordinator