





# OBJECTIVES

**RESPECT & REHABILITATE** 

2. AMPLIFY & CELEBRATE

**REVITALIZE & ENRICH** 

# 01

# RESPECT & REHABILITATE

Respect & Rehabilitate the distinctive character of the historic landmarks.

# RESPECT & REHABILITATE HISTORIC TIMELINE



1st Denny Regrade 1908-1911



Wilson Modern Business College Building was Built 1927

1914 Sheridan Building was Built



1929-1939

The Great Depression



## RESPECT & REHABILITATE HISTORIC TIMELINE



Griffin Business College Took Over the Building 1940s




Monorail Opened One Month Before World's Fair

1962

### 1961

Monorail Construction Commenced



Sheridan Building

-Griffin Building


### Present

Griffin Building & Sheridan Apartments



RESPECT & REHABILITATE GRIFFIN BUILDING RESPECT | AMPLIFY | REVITALIZE CHAINQUI DEVELOPMENT | M Z A | 2005 5TH AVE | ARCHITECTURAL REVIEW COMMITTEE | 09.14.2020 6

## COLLEGIATE GOTHIC IN SEATTLE



UW Home Economics Hall 1901 Chelan Lane



Terminal Sales Annex Building 2nd Ave. & Virginia St.



The Mann Building 3rd Ave. & Union St.



1926 4th & Pike Building 4th Ave. & Pike St.

- Pointed Arches
- Vertical Expression
- Decorative
- Stepped Parapets
- Finials

## GRIFFIN: DISTINCTIVE CHARACTER

- Vertical Expression
- Stepped Parapet
- 3 Turned Wood Window Stiles
- 4 Ornate Retail Entrance
- Ornate Gothic Arch Entry
- 6 Terracotta Cladding
- 7 Green Marble Base



## GRIFFIN: PAST & PRESENT


### PAST



### PRESENT



## GRIFFIN BUILDING RESTORATION



Install New Operable Steel Sash Windows Based on Original Drawings



Replace Spalling Terracotta



Repair Settlement Damage


## GRIFFIN BUILDING RESTORATION



Remove Modern Signage & Canopies




Replace Cracked Terracotta




Remove Paint & Reglaze

## RESPECT & REHABILITATE GRIFFIN BUILDING RESTORATION



Exposed Rebar




SHERIDAN BUILDING

1908 Frye Hotel 3rd Ave. & Yesler Way



Arctic Building 3rd Ave. & Cherry St.



1909 Public Safety Building 5th Ave. & Yesler Way




Dexter Horton Building 2nd Ave. & Cherry St.

## RESPECT & REHABILITATE BEAUX ARTS IN SEATTLE

- Symmetrical Facade
- Masonry Exterior
- Distinct Base, Middle, and Top
- Ornamental Cornice
- Punched Openings

# RESPECT & REHABILITATE SHERIDAN: DISTINCTIVE CHARACTER

- 1 Distinct Base
- 2 Denticulated Entablatures
- 3 Symmetric Facade Design
- 4 Key Stones
- 5 Ornate Cornice




# SHERIDAN: PAST & PRESENT

### PAST



### PRESENT



## SHERIDAN BUILDING RESTORATION



Replace Spalling Terracotta




Install Wood Clad True Divided Lite Upper Sash Windows
-Full Window Study Will Be Provided



Remove Canopy


### SHERIDAN BUILDING RESTORATION



Reset & Regrout Terracotta



Spiderwebbing: Reglaze to Seal



Remove & Resecure Cornice Elements



P.O. Box 70110 Seattle, WA 98127

11/19/2019

To: Chainqui Development Virginia

3601 Fremont Ave. N #314

Seattle, WA 98103

Jenny Tsen 206.660.4300 Attn:

jenny.tsen@chainqui.com

Joel Vaughn Our Phone: (206) 782-4331 From:

Re: 5th and Virginia - Full exterior façade restoration and renovation. South and East Elevations

Item	Qty	Unit	Unit Cost	Total
Mobilization, Safety, GC's, Parking, etc.				50,000
Scaffold and access				70,000
				0
South Building parapet rebuild and repairs				300,000
North Building cornice rebuild				280,000
				0
South Building terra cotta pinning				32,000
North Building terra cotta pinning				30,000
				0
South Building 100% tuck pointing				32,000
North Building 100% tuck pointing				70,000
				0
South Building terra cotta patching				50,000
North Building terra cotta patching				40,000
				0
South Building caulking, terra cotta touch up				15,000
North Building caulking, terra cotta touch up				15,000
				0
				0
Total				\$984,000

\* If veneer requires a full removal and replace, the estimated budget would increase to \$1,500,000.


# 02

# AMPLIFY & CELEBRATE


Amplify & Celebrate the historic identity for centuries to come.

# PRECEDENTS


# AMPLIFY & CELEBRATE PRECEDENTS




Recess
Create a gasket between existing and new.



Line up existing and new building elevations.



color, etc.




## PROJECT HISTORY

# AMPLIFY & CELEBRATE PROJECT TIMELINE

ARC 1 2017-08-30

TOWER PROPOSED




FEEDBACK

FINANCIAL FEASIBILITY ANALYSIS SHOULD BE PROVIDED TO SUPPORT THE HEIGHT

### ARC 2 2018-02-02

TOWER AND ALTERNATIVES PROVIDED WITH FINANCIAL FEASIBILITY ANALYSIS




### FEEDBACK

AGREEMENT THAT ALTERNATIVES ARE NOT ECONOMICALLY FEASIBLE, BUT TOWER LOCATION SHOULD BE OFF THE GRIFFIN

### AMPLIFY & CELEBRATE PROJECT TIMELINE

ARC 3 2018-06-29

60' SETBACK FROM VIRGINIA ST 20' SETBACK FROM 5TH AVE




#### **FEEDBACK**

CANTILEVERING OVER GRIFFIN IS ACCEPTABLE; TOWER MASSING NEEDS IMPROVEMENT AND TOWER SEPARATION OF 32' NOT PREFERRED BY PLANNING DIRECTOR

ARC 4 2018-09-14

REFINED MASSING AND TOWER LOCATION




FEEDBACK


TOWER SPACING NEEDS REFINEMENT; PRESENT TO LPB

LPB 2019-03-20

CONCEPT 1: STACKS OF DRYING LUMBER

CONCEPT 2: CEDAR DUGOUT CANOES





FEEDBACK

TOWER FACADE SHOULD ECHO THE RHYTHM AND VERTICALITY OF GRIFFIN BUILDING

FEEDBACK


BRING NEW TOWER TO STREET LEVEL, CREATE FRAMES TO ECHO GRIFFIN'S VERTICALITY


### Old Scenario Revised as of December 2019 (with 45-foot Tower separation)

CONCEPT 1: STACKS OF DRYING LUMBER

ARC 5 2019-09-13

CONCEPT 2: CEDAR DUGOUT CANOES





### FEEDBACK


THE STEPPED EDGE IS NOT WORKING IN THIS SITUATION.

### FEEDBACK


PREFERRED OPTION. THE BOARD SUPPORTS THE 45' TOWER SEPARATION ASSUMING THE GRIFFIN BUILDING IS PRESERVED.

	5th and Virginia Tower Site	e - One 43-story Scenar	rio (45-foot tower s	pacing)
		Stabilized &Selling as o		
	Scenario	Levels	Option 1	Option 2
	Use		Apts	Condos
	Story		43	43
	Amenity		multiple levels	
	Apt Units		390	
	Condo Units			390
Net	Residential SF		272,320	272,320
	Average SF		698	698
	Commercial SF-Retail		5,120	5,120
	Commercial SF-Office		88,209	88,209
	Total Rentable/Sellable SF		365,649	365,649
Gross	Total GBA		573,180	573,180
Total	Parking stalls		91	91
	Storage lockers		78	78
Revenue	Effective Gross Income	Apt+Retail	\$18,680,631	
	Aggregate Retail Value	Condo+Retail		\$410,779,850
		a parking		\$5,600,000
		a storage		\$780,000
	Expenses	Apt+Retail	\$4,338,587	
	Net Operating Income		\$14,342,044	
	Blended Cap Rates		4.44%	
	Market Value	Apt & Retail	\$322,750,000	
		Condo & Retail		\$417,159,850
Total Marke	et Value (R)		\$322,750,000	\$417,159,850
Proj. Costs	DMC 240/290-440	Land Area	\$1,733	\$1,733
Purchase	Land Base	19,440	\$33,690,000	\$33,690,000
Estimated	MHA Fees		\$4,450,999	\$4,450,999
	<b>Demolition Costs (Interior</b>	)	\$500,000	\$500,000
	Total Land Costs		\$38,640,999	\$38,640,999
		per Land SF	\$1,988	\$1,988
Hard Costs			\$235,905,325	\$240,416,785
		per GSF	\$412	\$419
		per NSF	\$645	\$658
Soft Costs			\$53,968,731	\$44,749,250
Financing Co	ost - Condo			\$60,364,349
Condo	Sales Costs @	7.00%		\$29,201,190
Total Costs	-		\$328,515,055	\$413,372,572
Gross Profit	t (R)		(\$5,765,000)	\$3,787,000

# AMPLIFY & CELEBRATE PREVIOUS FLOOR PLANS



- 16 PARKING STALLS ON EACH LEVEL
- PARKING EFFICIENCY IS 810 SF/STALL




- INSUFFICIENT SPACE FOR LOADING
- INSUFFICIENT SPACE FOR TRASH

RESPECT | AMPLIFY | REVITALIZE CHAINQUI DEVELOPMENT | M Z A | 2005 5TH AVE | ARCHITECTURAL REVIEW COMMITTEE | 09.14.2020 27

VIRGINIA

## MASSING STUDIES

## AMPLIFY & CELEBRATE MASSING STUDIES




#### **PROS**

• GRIFFIN'S ENTIRE INTEGRITY IS PROTECTED

#### CONS

- GRIFFIN ALIENATED
- VISUAL WEIGHT ON SHERIDAN
- UNDESIRABLE OFFICE PLATES
- PARKING/SERVICE/GARBAGE NOT FEASIBLE
- TOWER SEPARATION NOT SUPPORTED BY SDCI




#### **PROS**

BETTER TOWER SEPARATION

#### CONS

- VISUALLY UNPROPORTIONATE
- SOFFIT ADDS VISUAL WEIGHT
- MASSING ABOVE GRIFFIN




#### **PROS**

- SUFFICIENT PODIUM BASE
- HORIZONTALS BREAK DOWN MASSING
- ADDITIONAL TOWER SEPARATION

#### CONS

- SOFFITS AND MASSING ADD VISUAL WEIGHT ON BOTH SHERIDAN AND GRIFFIN
- THE TOWER IMPACTS BOTH LANDMARKS




#### **PROS**

- SUFFICIENT PODIUM BASE
- TAPERED TOWER SITS LIGHTLY
- INHERIT GRIFFIN'S FEATURES ALLOWING THE VERTICAL **EXPRESSION TO CONTINUE** UPWARD
- RELIEVE VISUAL WEIGHT


#### CONS

 THE TOWER LIGHTLY TOUCHES **BOTH LANDMARKS** 

# AMPLIFY & CELEBRATE DESIGN APPROACH



# AMPLIFY & CELEBRATE DIMENSIONS



362'

66'

56'


Œ

East Elevation


South Elevation

# AMPLIFY & CELEBRATE

## NEW FORMALISM



UW SUZZALO ADDITION BY BINDON AND WRIGHT 1963



RAINIER TOWER BY YAMASAKI 1977




PACIFIC SCIENCE CENTER BY YAMASAKI 1962

- Emerged in the 1950's
- Symmetry
- Rich materials
- Set on a podium
- Designed to achieve modern monumentality
- Embraces classical precedents
- Delicacy of details


# AMPLIFY & CELEBRATE DESIGN PARTI











D: BUILDING STRUCTURE

# AMPLIFY & CELEBRATE STREETSCAPE















#### 03

#### REVITALIZE & ENRICH

Revitalize & Enrich the landmarks to meet modern-day utilization.


## REVITALIZE & ENRICH CHALLENGES



- 3 Disconnected Spaces
- Small Floorplates for Office Use
- Mismatching Floor Elevations
- Insufficient Natural Light for Office

#### 5TH ANE

# OPPORTUNITIES



- Maintain Original Floor Plates
- Maintain Original Program: Office(Griffin) and Residential(Sheridan)
- Differentiate Residential and Office space with different Floor Height
- Interpretive Reconstruction of Walls & Columns




#### REVITALIZE & ENRICH SECTION A





Sheridan Floor Elevations

# REVITALIZE & ENRICH SECTION B




7日代

Sheridan Floor Elevations

LVL1


Griffin Floor Elevations

## REVITALIZE & ENRICH LANDSCAPE



#### REVITALIZE & ENRICH PARKING (PREFERRED)

#### 5TH AVE





RESPECT | AMPLIFY | REVITALIZE

1/16" = 1'0"



GRIFFIN L2/ SHERIDAN L2 1/16" = 1'0"






GRIFFIN L3/ SHERIDAN L3 1/16" = 1'0"






GRIFFIN L4/ SHERIDAN L4 1/16" = 1'0"






SHERIDAN L5 1/16" = 1'0"





GRIFFIN ROOF/ SHERIDAN L6 1/16" = 1'0"






LEVEL 6 (SHERIDAN ROOF) 1/16" = 1'0"



#### REVITALIZE & ENRICH TOWER RESIDENTIAL





PENTHOUSE LEVEL 8 UNITS



Residential - 1 BED


Residential - 1 BED+

Residential - 2 BED

MZA Option (Based on achieving FAR 8)

#### REVITALIZE & ENRICH TABULATION

Chainqui Development 2005 5th Avenue 30-Jan-20






#### 04


#### ADDITIONAL STUDIES

#### REVITALIZE & ENRICH LEVEL 1 STUDY



\* Loading trucks can easily block tenant vehicles in and out of the alley and cause traffic on Virginia.

#### REVITALIZE & ENRICH PARKING STUDIES



TOWER SEPARATION = 80' PARKING STALLS = 51





