

Seattle Landslide Study
Seattle Public Utilities
Seattle, Washington

Madrona

Groundwater Blowout Landslides

January 2000 W-7992-01

SHANNON & WILSON, INC.
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

FIG. B-21

sls_appxb.apr