


Map Color	Classification Number	Classification (based on information/data/documentation available at time of this survey)
	1	Areas where no storage, release, or disposal of hazardous substances or petroleum products has occurred (including no migration of these elements to adjacent areas).
	2	Areas where only storage of hazardous substances or petroleum products has occurred (but no release, disposal, or migration from adjacent areas has occurred).
	3	Areas where only storage of hazardous substances or petroleum products has occurred, but at concentrations that do not require a removal or remedial action.
	4	Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred and all remedial actions necessary to protect human health and the environment have been taken.
	5	Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred and removal and/or remedial actions are under way, but all required remedial actions have not yet been taken.
	6	Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but required response actions have not yet been implemented.
	7	Areas that have not been evaluated or require additional evaluation

MAGNUSON PARK



⊗ No cleanup is required at this time. However, deed restrictions will accompany property transfer documentation defining land use actions that will require cleanup at these areas.

LEGEND	
	Fence Line
	Foundation Only
	Bldg Location and Number
	Elevation Contours in Feet Above Mean Sea Level
	Avgas Line
	Underground Storage Tanks

<p>CLEAN COMPREHENSIVE LONG-TERM ENVIRONMENTAL ACTION NAVY</p>	<p>CTO 0104 NAVSTA PS, Seattle Seattle, Washington EBS</p>
	<p>Figure 6-1 Environmental Risk Classifications, NAVSTA PS, Seattle</p>