



Sketch C - Drilled Drains



Sketch D - Replacement Earth Buttress



SKETCHES NOT TO SCALE

LEGEND

-  Potential Movement
-  Perched Water
-  Seepage

Seattle Landslide Study
Seattle Public Utilities
Seattle, Washington

**TYPICAL GROUNDWATER
BLOWOUT LANDSLIDE
STABILITY IMPROVEMENTS**

July 1999

W-7992-01

SHANNON & WILSON, INC.
Geotechnical and Environmental Consultants

FIG. 2-2
Sheet 2 of 2