



NW 100th Street – Intersections at 9th Ave NW, 11th Ave NW, and 13th Ave NW



NW 100th Street – Intersections at 9th Ave NW, 11th Ave NW, and 13th Ave NW



Project ID # 2007-461

Type of Improvement: Pedestrian Improvement
Neighborhood: Crown Hill

Approximate Length: 180 feet
Street Classification: Collector Street

Applicant Description of Problem and/or Project:

Problem: Pedestrian safety-difficult to cross arterial.

Suggested Project: Add crosswalks, pedestrian crossing signs and crossing flags at the following locations: NW 100th St & 13th Ave NW, NW 100th St & 11th Ave NW, NW100th St & 9th Ave NW.

Potential Solution and/or Comments:

NW 100th Street – Intersections at 9th Ave NW, 11th Ave NW, and 13th Ave NW

- Install ADA ramps; curb bulbs to reduce pedestrian crossing distance, and pedestrian crossing signs.

Challenges/Tradeoffs:

- Overlaps with Project 464, will need to adjust costs if one or the other project is implemented.
- Crosswalks would need to be evaluated by SDOT after other pedestrian improvements are constructed.
- SDOT does not install pedestrian crossing flags.

Preliminary Range of Cost: \$210,000 to \$270,000