ArcGIS Metadata Form

Stairways

Data Set Summary

Data Cat Basina				
Data Set Basics				
Title	Stairways			
Abstract	Stairways in the City of Seattle.			
Description	Known stairways within the City limits, and basic Stairway attributes. Due to the many hills throughout Seattle, there are numerous locations where it becomes too steep for a street or sidewalk. The city built stairways to maintain the connection between adjacent neighborhoods and to provide an interconnected network of sidewalks.			
Supplemental Information				
Update Frequency	Weekly			
Keyword(s)	SDOT, Seattle, Transportation, Asset, Stairway, Structure			
Contact Information	Contact Information			
Contact Organization	SDOT CPRS Division, Roadways Structures Section			
Contact Person	SDOT GIS Analyst			
Contact Email	DOT_IT_GIS@seattle.gov			

Attribute Information

Attribute	Data type,	Description
	length	
OBJECTID	ObjectID	ESRI unique identifier
СОМРТҮРЕ	Long	Asset type code assigned by the Hansen
		asset management system.
UNITID	Text, 20	Alpha-numeric Hansen unique identifier
UNITDESC_ASSET	Text, 255	Structured description of the Stairway
		location
STAIRWAYCONDITION	Text, 10	Stairway condition:
		(Good, Fair, Poor, Not Rated)

ArcGIS Metadata Form

Attribute	Data type, length	Description
СОМРТҮРЕ	Short	Asset type code assigned by the Hansen
		asset management system.
SEGKEY	Long	Foreign key to the primary key (compkey)
		of the associated street segment asset.
UNITDESC_SEG	Text, 255	Structured description of the
LINUTTYPE	T	corresponding Stairway segment location
UNITTYPE	Text, 10	Stairway category, enhanced for the City of Seattle.
INSTALL_DATE	Date	Install date of the Stairway
OWNERSHIP	Text	The organization that owns the Stairway
CURRENT_STATUS	Text, 10	Current Staiway status: INSVC = in service
PRIMARYDISTRICTCD	Text, 10	The code for the primary council district in which this Stairway is located.
SECONDARYDISTRICTCD	Text, 10	The code for the secondary council district in which this Stairway is located if applicable.
OVERRIDEYN	Text, 1	Council District override flag
MAINTAINED_BY	Double	The organization responsible for Stairway maintenance
MAINTFINANCIALRESP	Text, 10	The organization financially responsible for Stairway maintenance
STAIRWAYRATING	Double	Stairway rating out of 100
RAILRATING	Double	Stairway railing rating out of 100
RAILCONDITION	Text, 10	Stairway railing condition:
		(Good, Fair, Poor, Not Rated)
INSPECTIONKEY	Double	Stairway retaining wall inspection identification number
INSPCOMPDATE	Date	Date/time of last inspection
SLIDEPRONE	Text, 10	Whether the Stairway retaining wall is prone to landslides
STAIRWAYTYPE	Text, 30	Stairway built material
RAILTYPE	Text, 30	Stairway railing material
STAIRWAYLENGTH	Double	Stairway length in feet
STAIRWAYWIDTH	Double	Stairway width in feet
NBR STAIRLANDING	Long	Number of stair landings in Stairway
NBR_STAIRRISER	Long	Number of stair risers in Stairway
BIKERUNNEL	Text, 10	Whether the Stairway contains a Bike Runnel (Y/N)

ArcGIS Metadata Form

Attribute	Data type, length	Description
OVERRIDECOMMENT	Text, 255	Council District override comment
SHAPE_Length	Double	ESRI field that stores information about the length of a feature in GIS