


Eckstein Middle School - 3003 NE 75th St.



2019-2020 School Year Crossing Conditions

- | | | | |
|--|----------------------------|--|--|
| | Crossing Guard Assignment* | | Overhead Crosswalk Sign |
| | School Patrol* | | Stairway |
| | Traffic Signals | | Multi Use Path |
| | All Way Stop Intersection | | Neighborhood Greenway |
| | Crossing Beacon | | Protected Bike Lane |
| | Designated School Crossing | | Neighborhood Street with Sidewalk |
| | Bridge | | Neighborhood Street with no Sidewalk |
| | | | Busy Street with Sidewalk |
| | | | Busy Street with no Sidewalk (not recommended) |

Walking and Biking Conditions

Community Facilities

- | | |
|--|------------------|
| | Community Center |
| | Library |
| | Police Station |
| | Fire Station |
| | Park |

0 500 1,000 2,000 3,000 4,000 5,000 Feet



©2019, THE CITY OF SEATTLE. All rights reserved. Produced by the Seattle Department of Transportation. No warranties of any sort, including accuracy, fitness or merchantability, accompany this product.

Coordinate System: State Plane, NAD83-91, Washington, North Zone
Orthophoto Source: Pictometry 2007

Plot Date : 8/22/2019
Author : PhamD
School_Walking_Maps2019

* Crossing guard and school patrol locations are subject to change.