


Madrona Elementary - 1121 33rd Ave.



2019-2020 School Year Crossing Conditions

- | | |
|----------------------------|--|
| Crossing Guard Assignment* | Overhead Crosswalk Sign |
| School Patrol* | Stairway |
| Traffic Signals | Multi Use Path |
| All Way Stop Intersection | Neighborhood Greenway |
| Crossing Beacon | Protected Bike Lane |
| Designated School Crossing | Neighborhood Street with Sidewalk |
| Bridge | Neighborhood Street with no Sidewalk |
| | Busy Street with Sidewalk |
| | Busy Street with no Sidewalk (not recommended) |

Walking and Biking Conditions

Community Facilities

- | |
|------------------|
| Community Center |
| Library |
| Police Station |
| Fire Station |
| Park |

* Crossing guard and school patrol locations are subject to change.



©2019, THE CITY OF SEATTLE. All rights reserved. Produced by the Seattle Department of Transportation. No warranties of any sort, including accuracy, fitness or merchantability, accompany this product.

Coordinate System: State Plane, NAD83-91, Washington, North Zone
Orthophoto Source: Pictometry 2007

Plot Date : 8/22/2019
Author : PhamD
School_Walking_Maps2019