CULTURAL RESOURCES REPORT COVER SHEET

Author: Natalie K. Perrin, M.S.; Heather Lee Miller, Ph.D.; Lynn Compas, M.A.
Title of Report: Cultural Resources Assessment of the Proposed Burke-Gilman Trail
Extension Project, Segment 4, Seattle, King County, Washington
Date of Report: September 2010
County(ies): King Section: 11Township: 25N Range: 3E
Quad: Seattle North Acres: approx. 35
PDF of report submitted (REQUIRED) X Yes
Historic Property Export Files submitted? ☐ Yes ☐ No
Archaeological Site(s)/Isolate(s) Found or Amended? Tyes No
TCP(s) found? ☐ Yes ☒ No
Replace a draft? Yes No
Satisfy a DAHP Archaeological Excavation Permit requirement? Tyes # No
DAHP Archaeological Site #: • Submission of paper copy is required.
Please submit paper copies of reports unbound.
Submission of PDFs is required.
Please be sure that any PDF submitted to DAHP has its cover sheet, figures, graphics, appendices, attachments, correspondence, etc., compiled into one single PDF file.
Please check that the PDF displays

correctly when opened.



Cultural Resources Assessment of the Proposed Burke-Gilman Trail Extension Project, Segment 4, Seattle, King County, Washington

Washington Department of Archaeology and Historic Preservation Reference No. 070308-02-FHWA

Submitted to

Submitted by



Seattle, Washington

Historical Research Associates

Natalie K. Perrin, M.S. Heather Lee Miller, Ph.D. Lynn Compas, M.A., R.P.A. Seattle, Washington

September 2010

This report was prepared by HRA Principal Investigator Natalie K. Perrin, M.S. (architectural history), Project Manager Heather Lee Miller, Ph.D. (history), and Project Archaeologist Lynn Compas (archaeology), who meet the Secretary of the Interior's professional qualifications standards for their respective disciplines. This report is intended for the exclusive use of the Client and its representatives. It contains professional conclusions and recommendations concerning the potential for project-related impacts to archaeological resources based on the results of HRA's investigation. It should not be considered to constitute project clearance with regard to the treatment of cultural resources or permission to proceed with the project described in lieu of review by the appropriate reviewing or permitting agency. This report should be submitted to the appropriate state and local review agencies for their comments prior to the commencement of the project.

Management Summary

The Seattle Department of Transportation (SDOT) Burke-Gilman Trail Extension Project (the project) seeks to complete the missing link between two existing portions of the Burke-Gilman Trail between 11th Avenue NW and 30th Avenue NW (at the Hiram M. Chittenden Locks) in Seattle. SDOT issued a Determination of Nonsignificance for the project under the State Environmental Policy Act (SEPA) on November 26, 2008, which was appealed. Now, upon remand by the King County Superior Court, SDOT has revised its description of the project to include Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place in Seattle.

This document serves as an addendum to the original Cultural Resources Assessment dated November, 2008, which was approved by the Federal Highway Administration as part of a documented Categorical Exclusion under NEPA on February 26, 2009 for the project (STPE-1140(041). The earlier version of the project had an Area of Potential Effects (APE) that included three discontiguous segments labeled 1, 2, and 3. This report assesses a new segment, Segment 4, which links Segments 1 and 2 of the original project. Segment 4 is defined as Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place.

The Washington State Historic Preservation Officer concurred that the archaeological APE for Segment 4 is contained horizontally within the Shilshole Avenue NW right-of-way and its sidewalks, and vertically to an estimated depth of 12 feet where new drainage trenches may be dug. The architectural APE for Segment 4 is defined as those properties on either side of Shilshole Avenue NW not previously evaluated for Segments 1, 2, and 3.

HRA identified, inventoried, and evaluated twenty-five historic-period buildings within the architectural APE for Segment 4. Historic Property Inventory Forms were prepared for all twenty-five buildings. None are recommended eligible for listing in the National Register of Historic Places (NRHP), the Washington Heritage Register (WHR), or the city of Seattle Landmarks Register (SLR).

Since the archaeological APE of Segment 4 is paved, no fieldwork (other than pedestrian survey, which also was completed for Segments, 1, 2, and 3) was conducted for Segment 4; however, background research conducted during evaluation of Segments 1, 2, and 3 suggest that all four segments of the Burke-Gilman Trail Extension Project have a high probability for the presence of prehistoric, ethnographic period, and historic Native American archaeological resources to exist in previously undisturbed areas, including beneath fill soils (see Kaehler and Gillespie 2008). As recommended for Segments 1, 2, and 3, HRA recommends that a professional archaeologist monitor all ground-disturbing activities that may occur in previously undisturbed areas or penetrate the depth of fill soils, such as for stormwater vaults that may be excavated to 8 ft (2.4 m). HRA also recommends that after consultation with the Washington Department of Archaeology and Historic Preservation (DAHP) and the affected tribes, SDOT develop an archaeological monitoring plan that addresses construction monitoring and unanticipated discoveries.

Table of Contents

Manag	gement Summary
1.0 1.1 1.1 1.1	
2.0	Methodology7
3.2	Field Results
4.0 4.1 A 4.2 5.0	Conclusions11Archaeological Resources11Architectural Resources11References Cited12
Appe	endices
Histori	ic Property Inventory Forms
APE C	Concurrence

List of Figures

Figure 1. Burke-Gilman Extension Project Area.	3
Figure 2. Burke-Gilman Extension archaeological APE.	4
Figure 3. Burke-Gilman Extension Segment 4 architectural APE, showing tax parcels to be included	5
Figure 4 . Burke-Gilman Extension Segment 4 architectural APE overlaid on the Ballard Avenue Histor District map. Image courtesy of the City of Seattle and included in the NRHP nomination form for t Ballard Avenue Historic District, with APE overlay added by HRA	he
Figure 5. Map showing locations of architectural resources evaluated within the Burke-Gilman Trail Extension Project APE.	10
List of Tables	
Table 1. Resources (note: tax parcels in grey were not assessed because they are void of buildings or structures).	9

1.0 Introduction

The Seattle Department of Transportation (SDOT) Burke-Gilman Trail Extension Project (the project) seeks to complete the missing link between two existing portions of the Burke-Gilman Trail between 11th Avenue NW and 30th Avenue NW (at the Hiram M. Chittenden Locks) in Seattle. SDOT issued a Determination of Nonsignificance for the project under the State Environmental Policy Act (SEPA) on November 26, 2008, which was appealed. Now, upon remand by the King County Superior Court, SDOT has revised its description of the project to include Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place in Seattle.

This document serves as an addendum to the original Cultural Resources Assessment dated November, 2008 (Kaehler and Gillespie 2008), which was approved by the Federal Highway Administration as part of a documented Categorical Exclusion under NEPA on February 26, 2009 for the project (STPE-1140(041). The earlier version of the project had an Area of Potential Effects (APE) that included three discontiguous segments labeled 1, 2, and 3. This report assesses a new segment, Segment 4, which links Segments 1 and 2 of the original project. Segment 4 is defined as Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place and is located in Section 11, Township 25 North, Range 3 East, Willamette Meridian on the Seattle North, Washington Quadrangle (U.S. Geological Survey 1983) (Figure 1).

Project construction along Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place would take place within the existing street right-of-way and would involve the same type of work and improvements involved in project construction for the other portions of the project route. Specifically, all construction along Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place would involve removal of existing concrete, asphalt, and compact gravel to be replaced with a 10- to 12-foot-wide multi-use pathway; additional improvements such as railway crossings, stormwater drainage controls, relocation of underground utilities, and reconstruction of existing driveways; and installation of traffic controls, warning signs, and signals to direct motor-vehicle, bicycle, and pedestrian traffic.

Proposed ground disturbance is expected to be minimal, approximately 1.5 feet (ft) in depth for construction of railroad crossings and grading for new asphalt-paved parking areas, and 12 ft for stormwater drainage facilities and trail lighting.

1.1 Area of Potential Effects

Implementing regulations for Section 106 of the National Historic Preservation Act (36 CFR 800) define a project's APE as the geographic area where an undertaking has the potential to directly or indirectly alter the character or use of historic properties, should such properties exist. HRA previously surveyed segments 1, 2, and 3 of the proposed Burke-Gilman Trail Extension Project (HRA 2008). The APE for the new Segment links Segments 1 and 2 of the original project and is referred to here as Segment 4, defined as:

• Segment 4: Shilshole Avenue NW from 17th Avenue to Vernon Place.

The Segment 4 APE was approved by Washington Department of Archaeology and Historic Preservation (DAHP) Transportation Archaeologist Lance Wollwage, Ph.D., on August 2, 2010 Cultural Resources Assessment of the Proposed Burke-Gilman Trail

(Appendix B). The Segment 4 APE includes both the archaeological and architectural APEs as defined below (Figures 1-3).

1.1.1 Archaeological Area of Potential Effects

Project construction within the Segment 4 APE will involve ground disturbance of previously developed areas from 1.5 ft to 3 ft deep for drainage controls, asphalt paving, concrete paving, railroad crossings, gravel resurfacing, and utility removal and relocation. In addition, ground disturbance for the installation of drainage elements including catch basins and trench drains may extend to between 3 and 12 ft deep. As a result, the vertical archaeological APE is defined as 12 ft below grade. The horizontal extent of the archaeological APE is located within the current road bed and sidewalk areas of Segment 4 (Figure 2), all within existing City of Seattle street right-of-way.

The proposed ground disturbance will be similar or identical to the ground disturbance activities proposed within Segments 1, 2, and 3. Although the project falls within the historic shoreline zone, HRA sees little potential for the project to affect *intact* subsurface archaeological resources since this ground disturbance will occur within previously disturbed areas.

1.1.2 Architectural Area of Potential Effects

The architectural APE for Segment 4 takes into consideration buildings, structures, objects, sites, or districts twenty-five years old or older located on either side of Shilshole Avenue NW (Figure 3). Parcels located on the northeast and northwest corners of Shilshole Avenue NW at the intersection of NW Vernon Place, and parcels located on the southeast and southwest corners of Shilshole Avenue NW at the intersection of 17th Avenue NW were previously evaluated during the cultural resource assessment of Segments 1, 2, and 3 of the proposed Burke-Gilman Trail Extension Project (Kaehler and Gillespie 2008), and so are not reevaluated here.

There are no known listed or eligible historic properties within the current architectural APE. However, many of the tax parcels in the APE are immediately adjacent to the Ballard Avenue Historic District (known locally as the Ballard Landmark District), which was listed in the National Register of Historic Places (NRHP) in 1976 (Figure 4) (Potter 1976).




Figure 1. Burke-Gilman Extension Project Area.




Figure 2. Burke-Gilman Extension archaeological APE.




Figure 3. Burke-Gilman Extension Segment 4 architectural APE, showing tax parcels to be included.




Figure 4. Burke-Gilman Extension Segment 4 architectural APE overlaid on the Ballard Avenue Historic District map. Image courtesy of the City of Seattle and included in the NRHP nomination form for the Ballard Avenue Historic District, with APE overlay added by HRA.

2.0 Methodology

The methodology utilized in completing archaeological and architectural evaluation of Segment 4 were identical to those utilized in evaluating Segments 1, 2, and 3 of the project. The Washington Information System for Architectural and Archaeological Records Data (WISAARD) online database was reviewed to determine if any archaeological surveys or previously recorded archaeological sites are known to exist within the Segment 4 APE. WISAARD was also reviewed to identify properties currently listed on the National Register of Historic Places (NRHP) or the Washington Heritage Register (WHR) located within the APE. No previous cultural resource studies, recorded archaeological sites or properties currently listed on the NRHP or WHR were found to be located within the APE. The Seattle Landmarks Register (SLR) designated properties were also reviewed. No known properties listed on the SLR are within the Segment 4 APE.

HRA architectural historian Natalie Perrin, M.S., conducted tax parcel research on the King County Tax Assessor website to determine the age of resources located within the Segment 4 APE. Research historian Dawn Vogel conducted research in the King County Property Card collection housed at the Washington State Archives, Puget Sound Regional Branch, at Bellevue College. Associate historian Heather Lee Miller, Ph.D., conducted a field evaluation on May 18, 2010. Perrin and Miller evaluated resources built prior to 1985 (to take into consideration the city of Seattle's twenty-five year threshold for historic resources) for historic significance to the NRHP, the WHR, and the SLR. HRA historians conducted additional research in the Hugh and Jane Ferguson Seattle Room at the Seattle Public Library on historic-period resources contained within the architectural APE.

Because Segment 4 is located contiguously with Segments 1 and 2 of the Project, this report relies heavily on the archaeological and historic context already researched and developed as part of the original analysis in 2008. Please see the original Cultural Resources Assessment (Kaehler and Gillespie 2008) for a complete discussion of the history and ethnography of the area.

3.0 Field Methods and Results

3.1 Field Methods

The field methods utilized in completing archaeological and architectural evaluation of Segment 4 were identical to those utilized in evaluating Segments 1, 2, and 3 of the project. Please see the original Cultural Resources Assessment (Kaehler and Gillespie 2008) for a complete discussion of the field methods.

3.1.1 Historic Districts

Many of the tax parcels in the Segment 4 APE are immediately adjacent to the Ballard Avenue Historic District, which was listed in the National Register in 1976. The Ballard Avenue Historic District is a linear district encompassing a half block on either side of Ballard Avenue between NW Market Street and NW Dock Place. The area is the equivalent of four blocks,

approximately ten acres, including streets. HRA reviewed the district nomination, specifically the district boundaries justification, which notes:

The reason for the district's undeviating lineal character is simply that, taken as a whole, the significant properties are those fronting on the greater portion of Ballard Avenue. This is where the streetscape is most cohesive, the historical and architectural integrity most nearly intact. The southeasterly segment of Ballard Avenue is less well preserved overall and, therefore, is excluded from the district. It does contain some significant buildings, but these are few and distinctly separated from the greater aggregate by intrusions. For the most part, properties fronting on streets paralleling and intersecting with Ballard Avenue are similarly eroded. (Potter 1976:7-23)

In general, HRA concurs with the assessment of buildings and structures outside of the Ballard Avenue Historic District boundaries as lacking in overall integrity, as illustrated in the evaluation of architectural resources section of this report.

3.2 Field Results

The field results for Segment 4 were evaluated using the same National Register of Historic Places, Washington Heritage Register, and City of Seattle Landmarks Register criteria as for Segments 1, 2, and 3. Please see the original Cultural Resources Assessment (Kaehler and Gillespie 2008) for a complete discussion of the criteria for evaluation used to evaluate the Segment 4 Field Results.

3.2.1 Archaeological Resources

No archaeological resources were identified within the archaeological APE. As a result no archaeological sites were evaluated in Segment 4.

3.2.2 Historic Buildings and Structures

Twenty-five tax parcels are included in the architectural APE of Segment 4 (Table 1). Of these, eight are vacant lots and one is a parking lot. Of the remaining sixteen parcels, all had at least one building over twenty-five years of age; therefore, all were evaluated for the SLR.

HRA inventoried and evaluated twenty-six buildings of historic ages for all registers and recorded them on a total of sixteen historic property inventory forms (Figure 5). Two buildings were under twenty-five years of age, but in both cases shared the tax parcel with a building over fifty-years of age and so were evaluated for eligibility to all registers. Of the twenty-six buildings evaluated, HRA recommends that none are eligible for listing in the NRHP, WHR, or SLR.

Table 1. Resources (note: tax parcels in grey were not assessed because they are void of buildings or structures).

Survey #	Tax Parcel	Building(s)/ Address	Year Built
1312.02-001	2767702645	Hattie's Hat Parking	Vacant (Parking)
1312.02-002	2767702640	Salmon Bay Sand & Gravel / 5256 Shilshole Ave. NW	1916
1312.02-003	2767702630	Salmon Bay Sand & Gravel / 5242 Shilshole Ave. NW	1926
1312.02-004	2767702620	C&C Paint Co / 5232 Shilshole Ave. NW	1926
1312.02-005	2767702615	Salmon Bay Sand & Gravel / 5228 Shilshole Ave. NW	1920
1312.02-006	2767702605	Salmon Bay Sand & Gravel / 5218 Shilshole Ave. NW	Bldg 1 – 1940
			Bldg 2 – 1920
1312.02-007	2767702591	Salmon Bay Sand & Gravel / 4819 20th Ave. NW	1924
1312.02-008	2767702320	Covich & Williams / 4800 20th Ave. NW	Bldg 1 – 1951
			Bldg 2 – 1951
			Bldg 3 – 1989
1312.02-009	2767702471	Metro Pumping Station	Vacant (Utility)
1312.02-010	2767702470	Storage Lot	Vacant
1312.02-011	2767702460	Marine Works Inc. / 5100 Shilshole Ave. NW	1918
1312.02-012	2767702445	Dantrawl U.S. / 4776 Shilshole Ave. NW	1908
1312.02-013	2767702355	Ballard Sheet Metal	Vacant
1312.02-014	2767702357	Ballard Hardware	Vacant
1312.02-015	2767702360	Ballard Hardware / 4749 Ballard Ave. NW	Bldg 1 – 1928
			Bldg 2 – 1927
1312.02-016	2767702420	Kolstad's	Vacant
1312.02-017	2767702410	Salmon Bay Sand & Gravel	Vacant
1312.02-018	2767702483	Salmon Bay Sand & Gravel	Vacant
1312.02-019	2767702400	Canvas Supply Co. / 4711 Ballard Ave. NW	Bldg 1 – 1900
1010.00.000	0=0=00400	A . B . L . B / / / / / / / / / / / / / / / /	Bldg 2 – 2004
1312.02-020	2767702480	Art Books Press / 4703 Ballard Ave. NW	1948
1312.02-021	0467000475	Sagstad Marina / 5109 Shilshole Ave. NW	Bldg 1 – 1960
			Bldg 2 – 1942
4242.02.022	0407000470	Const Cove Marine / 5200 Chilabala Ava NIM	Bldg 3 – 1959
1312.02-022	0467000476	Canal Cove Marina / 5209 Shilshole Ave. NW	Bldg 1 – 1938
1312.02-023	0467000445	Williams & Covich, Fuel Dock / 5219 Shilshole Ave.	Bldg 2 – 1990 Bldg 1 – 1930
1312.02-023	0467000445	NW	Bldg 1 – 1930 Bldg 2 – 1983
1312.02-024	0467000421	Salmon Bay Sand & Gravel / 5231 Shilshole Ave. NW	Bldg 1 – 1916
1312.02-024	0407000421	Saimon Day Sand & Graver / 5251 Sinishble Ave. NVV	Bldg 2 – 1960
1312.02-025	0467000427	Stimson Industrial Park	Vacant
1012.02-020	0407000427	Carrison industrial i art	vacant




Figure 5. Map showing locations of architectural resources evaluated within the Burke-Gilman Trail Extension Project APE.

4.0 Conclusions

This report serves as an addendum to the original Cultural Resources Assessment completed in 2008 for the Burke-Gilman Trail Extension Project, which will extend the Burke-Gilman Trail from 11th Avenue NW to the Hiram M. Chittenden Locks. The potential for impacts to cultural and historic resources was analyzed for construction of the Burke-Gilman Trail along Shilshole Avenue NW between 17th Avenue NW and NW Vernon Place, defined as Segment 4. Evaluation of Segments 1, 2, and 3 was conducted in the original Cultural Resources Assessment (Kaehler and Gillespie 2008).

4.1 Archaeological Resources

The Segment 4 APE, like the Segments 1, 2, and 3 APE, lies adjacent to or on old shorelines of Salmon Bay. With this in mind HRA recommends that a monitor that meets the Secretary of the Interior Standards and Guidelines for a professional archaeologist be present during ground disturbing activities that are to occur in previously undisturbed areas or that will penetrate beneath the depth of fill soil. As previously reported, the depth of fill soil is unknown; native soils were not reached during 2005 examinations of backhoe trenches to a depth of 5 feet (1.5 m) (Kaehler and Gillespie 2008:7). Archaeological monitoring is therefore recommended during ground disturbing activities that may penetrate beneath fill soils (e.g., stormwater vaults that may be excavated to 8 ft [2.4 m]). This recommendation for Segment 4 is the same as that recommended for Segments 1, 2, and 3 in Kaehler and Gillespie 2008.

An archaeological monitoring plan that outlines the procedures to follow during monitoring, as well as the procedures to follow in the event of an inadvertent discovery or the discovery of human remains, was included in the original Cultural Resources Assessment (Kaehler and Gillespie 2008) as Appendix B; the plan was concurred on by both DAHP and the Washington Department of Transportation. HRA recommends the previously proposed monitoring plan and procedures for inadvertent discovery be adopted for Segment 4.

4.2 Architectural Resources

Of the twenty-five tax parcels located within the Segment 4 APE, twenty-six buildings were evaluated for the NRHP, the WHR, and the SLR. Of the twenty-six buildings reviewed, HRA evaluated no historic resources as eligible for listing in any of the historic registers. Since no historic properties are present within the APE, HRA recommends a finding of *no historic properties affected*.

5.0 References Cited

Kaehler, Gretchen, and Ann Gillespie.

2008 "Cultural Resources Assessment of the Proposed Burke-Gilman Trail Extension Project, King County, Washington." Submitted to SVR Designs by Historical Research Associates, Inc. November 2008. On file with the Washington Department of Archaeology and Historic Preservation, Olympia, Washington.

King County

2010 Landmark Designation and Certificate of Appropriateness Process. *Technical Paper No. 4*. http://www.kingcounty.gov/exec/bred/historic.aspx (accessed June 1, 2010).

Potter, Elisabeth Walton

1976 "Ballard Avenue Historic District." National Register of Historic Places Nomination form. Listed April 27, 1976. On file at Washington Department of Archaeology and Historic Preservation, Olympia.

Seattle.gov

- 2010 Department of Neighborhoods. Landmarks and Designation. Nomination and Designation Process. http://www.cityofseattle.net/neighborhoods/preservation/designation_process.htm (accessed June 1, 2010).
- U. S. Department of the Interior, National Park Service.
 - 1997 "National Register Bulletin: How to Apply the National Register Criteria for Evaluation." Washington, D.C.: Department of the Interior.

Washington State

2010 Department of Archaeology and Historic Preservation. "Historic Sites: Washington Heritage Register." 2010 http://www.dahp.wa.gov/pages/HistoricSites/WashingtonHeritageRegister.htm (accessed June 1, 2010).



Appendix A Historic Property Inventory Forms

at 5256 Shilshole Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: <u>1312.02-002</u>

OAHP No.:

Historic Name:

Common Name: Salmon Bay Sand & Gravel (CC Paints)

Property Address: 5256 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec <u>11</u>

Quadrangle

SHILSHOLE BAY

Coordinate Reference

King

T25R03E

Zone: 10 Spatial Type: Point Sequence:

Acquisition Code: Unknown

1 Easting: 546284

Northing: <u>5279348</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

2767702640

Gilman Park Blocks 050 thru 94, Plat block 71, plat lot 29

Acreage <u>.11</u>

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Halco Properties, LLC

PO Box 512

Auburn, WA 98071

Classification: Building

Resource Status

Comments

Within a District? No

Survey/Inventory

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: Rectangle No. of Stories: 1

Structural System: Concrete - Block

Changes to windows: Intact

Changes to plan: Intact

Changes to interior: Unknown

Style None

Changes to original cladding: Intact Changes to other:

Other (specify):

View of west oblique, viewing southeast

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

7094

Comments:

Form/Type Utilitarian

at 5256 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
Concrete - Block	Concrete - Poured	Asphalt / Composition	Flat with Parapet
		Metal - Standing Seam	
NARRATIVE :	SECTION	Date Of Construction: 1916	
Study Unit	Other	Architect:	
Community Plant	ning/Development	Builder:	
		Engineer:	
	Property appears to meet criteria for the National Regist	ter of Historic Places: No	
	Property is located in a potential historic district (Nation	al and/or local): <u>No</u>	
	Property potentially contributes to a historic district (Na	tional and/or local):	
Statement of Significance	to the broad patterns of local, state, or national history; it is record persons, and is recommended ineligible under Criterion B. The brepresent the work of a master or possess high artistic values, a therefore is recommended ineligible under Criterion C. The build recommended ineligible under Criterion D. None of the Criteria Clisting in the National Register of Historic Places. The building appears to retain good integrity of design, materials	mmended ineligible under Criterion A. The bouilding does not embody the distinctive chaind does not represent a significant and distilling is unlikely to yield further information imponsiderations is applicable, as the building s, workmanship, feeling, setting, location, an	r to be associated with events that have made a significant contribution building is not known to be associated with the lives of significant tracteristics of a type, period, or method of construction, does not inguishable entity whose components may lack individual distinction, and portant in understanding local, regional, or national history, and is does not appear to be eligible under any of the eligibility criteria for association. The building is recommended ineligible to the National Seattle Landmarks Register due to an inability to meet any of the
Description of Physical Appearance	flat roof with parapet. The parapet has standing-seam metal flas	hing and asphalt roofing material. The buildi	nstructed of concrete masonry units (CMU, concrete block), and has a ing maintains three banks of original eight-light metal sash windows on parn-style door on a track. The building is attached on the southeast and
Major Bibliographic References			

Page 2 of 2 Printed on 6/2/2010 2:16:37 PM



View of west oblique, viewing east

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7093

Comments:



View of warehouse door, viewing east

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7095

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

LOCATION SECTION

Field Site No.: 1312.02-003

OAHP No.:

Historic Name:

Common Name: Salmon Bay Sand & Gravel, Warehouse No. 7

Property Address: 5242 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

<u>11</u>

Quadrangle **Coordinate Reference**

King

T25R03E

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

1 Easting: 546297

Northing: <u>5279331</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

Acreage

2767702630

Gilman Park Blks 050 thru 94, Plat block 71, Plat lot 15 & 25

.23

thru 28

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Halco Properties LLC

PO Box 512

Auburn, WA 98071

Classification: Building

Resource Status

Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: Rectangle No. of Stories: 1

Structural System: Clay Tile

Changes to original cladding:

Changes to plan: Intact Changes to interior: Unknown

Intact

Changes to other: Moderate

Style <u>None</u> Form/Type Industrial

Changes to windows: Intact Other (specify):

View of southwest elevation, viewing southeast

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

7096

Comments:

Page 1 of 2

Printed on 6/2/2010 2:16:56 PM

at 5242 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
<u>Other</u>	Concrete - Poured	Asphalt / Composition	Flat with Parapet
NARRATIVE S	SECTION	Date Of Construction: 1926	
Study Unit	Other	Architect:	
Community Plann	1	Builder:	
		Engineer:	
	Property appears to meet criteria for the National Register	r of Historic Places: No	
	Property is located in a potential historic district (Nationa	l and/or local): <u>No</u>	
	Property potentially contributes to a historic district (Nation	onal and/or local):	
Statement of Significance	made a significant contribution to the broad patterns of local, state with the lives of significant persons, and is recommended ineligible construction, does not represent the work of a master or possess individual distinction, and therefore is recommended ineligible uncentained in the ligible under Criterion D. eligibility criteria for listing in the NRHP. The building appears to retain fair integrity of design, materials, we	e, or national history; it is recommende e under Criterion B. The building does high artistic values, and does not reproder Criterion C. The building is unlikely None of the Criteria Considerations is orkmanship, feeling, setting, location, a	It tile. The building does not appear to be associated with events that have a ineligible under Criterion A. The building is not known to be associated not embody the distinctive characteristics of a type, period, or method of esent a significant and distinguishable entity whose components may lack to yield further information important in understanding local, regional, or applicable, as the building does not appear to be eligible under any of the and association. The building is recommended ineligible to the National the Seattle Landmarks Register due to an inability to meet any of the
Description of Physical Appearance	southwest elevation is clad in hollow clay tiles and has a roll-up ga	arage door and a large pedestrian entr	constructed of hollow clay tiles and has a flat roof clad in asphalt. The rance door, as well as two twelve-light wood-sash windows. The southeast ding is attached to adjacent buildings on the northeast and northwest
Major Bibliographic References			

Printed on 6/2/2010 2:16:57 PM



View of south oblique, viewing north

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7098

Comments:



View of 12-light wood sash window

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7097

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

LOCATION SECTION

Field Site No.: 1312.02-004

OAHP No.:

Historic Name:

Common Name: C&C Paint Co., Warehouse No. 4

Property Address: 5232 Shilshole Ave NW, Seattle, WA 98017

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

T25R03E King

<u>11</u>

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

1 Easting: 546322

Northing: <u>5279301</u>

Tax No./Parcel No.

Plat/Block/Lot

2767702620

Gilman Park Blocks 050 thru 94, Plat block 71, plat lot 15 & 25

Supplemental Map(s)

Acreage .20

thru 28

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Halco Properties LLC

PO Box 512

Auburn, WA 98071

Classification: Building

Resource Status

Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: L-Shape No. of Stories: 2

Structural System: Concrete - Block

Changes to plan: Slight Changes to original cladding: Slight Changes to interior: Unknown

Style None

Form/Type

7099

Changes to windows: Extensive

Other (specify):

Changes to other:

View of west oblique, viewing southeast

Photography Neg. No (Roll No./Frame No.):

taken 5/18/2010

Comments:

Industrial

at 5232 Shilshole Ave NW, Seattle, WA 98017

Cladding	Foundation	Roof Material	Roof Type
Concrete - Block	<u>Concrete - Poured</u>	Asphalt / Composition	Flat with Parapet
NARRATIVE S	SECTION	Date Of Construction: 1926	
Study Unit	Other	Architect:	
Community Plann		Builder:	
		Zuildon.	
		Engineer:	
	Property appears to meet criteria for the National Registe	r of Historic Places: No	
	Property is located in a potential historic district (Nationa	ıl and/or local): <u>No</u>	
	Property potentially contributes to a historic district (Nati	onal and/or local):	
Significance	significant contribution to the broad patterns of local, state, or natilives of significant persons, and is recommended ineligible under construction, does not represent the work of a master or possess individual distinction, and therefore is recommended ineligible under criterion D. eligibility criteria for listing in the NRHP. The building appears to retain fair integrity of design, materials, w	ional history; it is recommended ineligible Criterion B. The building does not embod high artistic values, and does not represeder Criterion C. The building is unlikely to None of the Criteria Considerations is approximanship, feeling, setting, location, and	e building does not appear to be associated with events that have made a under Criterion A. The building is not known to be associated with the ly the distinctive characteristics of a type, period, or method of ent a significant and distinguishable entity whose components may lack yield further information important in understanding local, regional, or oplicable, as the building does not appear to be eligible under any of the dissociation. The building is recommended ineligible to the National is Seattle Landmarks Register due to an inability to meet any of the
Description of Physical Appearance	has a flat roof with asphalt roofing. The building has an attached s	single-story addition on the northwest corr s. The northwest elevation has on six-light	ructed of and clad in concrete masonry units (CMU, concrete block) and ner clad in standing seam metal and also with a flat parapet roof. The t wood sash window on the single0-story addition, and a roll-up garage ortheast elevations.
Major Bibliographic References			

Page 2 of 2 Printed on 6/2/2010 2:17:20 PM

LOCATION SECTION

Field Site No.: <u>1312.02-005</u>

OAHP No.:

Historic Name:

Property Address: 5228 Shilshole Ave NW, Seattle, WA 98107

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

T25R03E

<u>11</u>

Quadrangle

SHILSHOLE BAY

Coordinate Reference

Common Name:

Zone: 10 Spatial Type: Point Sequence: 1 Easting: 546330

Comments:

Salmon Bay Sand and Gravel, Warehouse No. 1

Acquisition Code: Unknown

Northing: <u>5279287</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

Acreage <u>.11</u>

2767702615

King

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

IDENTIFICATION SECTION

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Nerdrun Calvin W

5909 Seaview Ave NW

Seattle, WA 98107

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: Rectangle No. of Stories: 2

Structural System: Unknown

Changes to plan: Intact Changes to original cladding: Changes to interior: Unknown

Style

Changes to other:

None



View of southwest elevation, viewing northeast

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

Comments:

Form/Type Commercial

Changes to windows: Extensive

Extensive

Other (specify):

Page 1 of 2

Printed on 6/2/2010 2:17:29 PM

at 5228 Shilshole Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type		
Veneer - Brick		Concrete - Poured	Asphalt / Composition	Flat with Parapet		
Veneer - Permast	<u>tone</u>					
	- — — — — — –					
NARRATIVE SECTION		Date Of Construction: 1920				
Study Unit		Other	Architect:			
Community Planning/Development		Builder:				
			Engineer:			
	Property appear	s to meet criteria for the National Re	gister of Historic Places: No			
Property is located in a potential historic district (National and/or local): No						
	Property potentially contributes to a historic district (National and/or local):					
Statement of Significance	Built in 1970, the building has been significantly affered on the main facage, likely in multiple phases based on the variety of materials. The building does not appear to					
Description of Physical Appearance	tile on the southwest	elevation. The building features two ba		elad in a combination of stucco, brick veneer, stone veneer, and ceramic por surrounded by glass block on the main entry, as well as a roll-up stions.		
Major Bibliographic References						

Page 2 of 2 Printed on 6/2/2010 2:17:30 PM

LOCATION SECTION

Field Site No.: 1312.02-006

OAHP No.:

Historic Name:

Salmon Bay Sand & Gravel and Warehouse No. 5 Common Name:

Property Address: 5218 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec <u>11</u>

Quadrangle

Coordinate Reference

King

T25R03E

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

1 Easting: 546344

Northing: <u>5279270</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

2767702605

Gilman Park Blocks 050 thru 94, Plat block 71, PLat lot 22-23

Acreage

taken 5/18/2010

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

John Inc

PO Box 70497

Seattle, WA 98127

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Commerce/Trade - Business

Current Use: Commerce/Trade - Business

Plan: Rectangle No. of Stories: 2

Structural System: Unknown

Changes to plan: Intact

Changes to interior: Unknown

Style

Photography Neg. No (Roll No./Frame No.): Comments:

View of northwest elevation, viewing southeast

Form/Type

Changes to original cladding: Changes to windows: Extensive

Extensive

Changes to other: Other (specify):

None

Commercial

Page 1 of 2

Printed on 6/2/2010 2:17:44 PM

at 5218 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type			
<u>Veneer - Stucco</u>	Concrete - Poured	Asphalt / Composition	Flat with Parapet			
Wood - T 1-11						
	·					
NARRATIVE SECTION		Date Of Construction:	<u>1920, 1940</u>			
Study Unit	Other	Architect:				
Community Planning/Development		Builder:				
		Engineer:				
Property appears to meet criteria for the National Register of Historic Places: No						
	Property is located in a potential historic district (National and/or local): No					
Statement of Significance	Property potentially contributes to a historic district (National and/or local):					
	Built in 1920 and expanded in 1940, the building has been significantly altered on the main facade. The building does not appear to be associated with events that have made a significant contribution to the broad patterns of local, state, or national history; it is recommended ineligible under Criterion A. The building is not known to be associated with the lives of significant persons, and is recommended ineligible under Criterion B. The building does not embody the distinctive characteristics of a type, period, or method of construction, does not represent the work of a master or possess high artistic values, and does not represent a significant and distinguishable entity whose components may lack individual distinction, and therefore is recommended ineligible under Criterion C. The building is unlikely to yield further information important in understanding local, regional, or national history, and is recommended ineligible under Criterion D. None of the Criteria Considerations is applicable, as the building does not appear to be eligible under any of the eligibility criteria for listing in the NRHP.					
	The building appears to retain poor integrity of design, materials, workmanship, feeling, and association and good integrity of setting and location. The building is recommended ineligible to the National Register of Historic Places, the Washington Heritage Register, King County Landmarks designation and the Seattle Landmarks Register due to an inability to meet any of the eligibility criteria.					
Description of Physical Appearance	This tax parcel contains two buildings which are attached. The first building, located on the north side, was constructed in 1920; the second, located on the south side, was constructed in 1940. Both segments are two story and rectangular in plan, on poured concrete foundations with flat roofs. Both buildings are clad in stucco and T1-11 siding. Both have vinyl windows and storefronts that have either been significantly altered and/or boarded over.					
Major Bibliographic References						

Printed on 6/2/2010 2:17:45 PM



View of main entry taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7103

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

at 4819 20th Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-007

OAHP No.:

Historic Name:

Common Name: Salmon Bay Sand & Gravel, Warehouse No. 6

Property Address: 4819 20th Ave NW, Seattle, WA 98107

Comments:

Supplemental Map(s)

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

T25R03E King

<u>11</u>

SHILSHOLE BAY

Zone: 10 Spatial Type: Point Sequence:

Acquisition Code: Unknown

Northing: <u>5279245</u>

Tax No./Parcel No.

Plat/Block/Lot

<u>1</u> Easting: <u>546367</u>

2767702591

Acreage

Gilman Park Blocks 050 Thru 94, Plat block 71, Plat lot 19-20-21

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Salmon Bay Sand & Gravel

PO Box 70328

Seattle, WA 98127

Classification: Building

Resource Status

Comments

Within a District? No

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

Historic Use: Industry/Processing/Extraction - Industrial Storage

Plan: Irregular No. of Stories: 2

Structural System: Unknown

Changes to plan: Extensive

Changes to interior: Unknown

Style None

Changes to original cladding:

Changes to windows: Extensive

Extensive

Changes to other:

Other (specify):

Survey/Inventory

Contributing?



Current Use: Industry/Processing/Extraction - Industrial Storage

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

View of southwest elevation

7105

Comments:

Form/Type

Commercial - Flatiron

at 4819 20th Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type
Concrete - Block		<u>Concrete - Poured</u>	Asphalt / Composition	Flat with Parapet
NARRATIVE :	SECTION		Date Of Construction: <u>1924</u>	
Study Unit		Other	Architect:	
	ning/Development		Builder:	
			Engineer:	
	Property appears t	o meet criteria for the National Re	egister of Historic Places: No	
	Property is located	l in a potential historic district (Na	ational and/or local): <u>No</u>	
	Property potential	y contributes to a historic distric	t (National and/or local):	
Statement of Significance	significant contribution t lives of significant perso construction, does not re individual distinction, an national history, and is re eligibility criteria for listing The building appears to	o the broad patterns of local, state, ons, and is recommended ineligible represent the work of a master or pod therefore is recommended ineligible ecommended ineligible under Critering in the NRHP. retain poor integrity of design, mate Register of Historic Places, the Wa	or national history; it is recommended ineligible un under Criterion B. The building does not embody the ssess high artistic values, and does not represent ble under Criterion C. The building is unlikely to yie irion D. None of the Criteria Considerations is applitations, workmanship, feeling, and association and of	does not appear to be associated with events that have made a order Criterion A. The building is not known to be associated with the he distinctive characteristics of a type, period, or method of a significant and distinguishable entity whose components may lack all further information important in understanding local, regional, or icable, as the building does not appear to be eligible under any of the good integrity of setting and location. The building is recommended rks designation and the Seattle Landmarks Register due to an inability
Description of Physical Appearance			north and a corner "flat-iron" section. Both segment has vinyl windows on the first floor and four-ligh	ents are two-story, with exposed concrete block cladding and flat roofs. It wood sash windows on the second floor.
Major Bibliographic References				

Page 2 of 2 Printed on 6/2/2010 2:18:07 PM




View of southwest elevation

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7104

Comments:



View of Loading Dock interior

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7107

Comments:



View of Loading Dock

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7106

Comments:



View of south oblique, viewing north

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.):

<u>7109</u>

Comments:

at 4800 20th Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-008

OAHP No.:

Historic Name:

Common Name: Covich & Williams

Property Address: 4800 20th Ave NW, Seattle, WA 98107

<u>11</u>

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

T25R03E King

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

<u>1</u> Easting: <u>546407</u>

Northing: <u>5279210</u>

Tax No./Parcel No.

Plat/Block/Lot

2767702320

Supplemental Map(s)

Acreage

Gilman Park Blks 050 thru 94, Plat block 70, Plat lot 3-4 & 35

.36

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Williams Mson J+Linda

PO Box 17913

Seattle, WA 98107

Classification: Building

Resource Status

Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: Irregular No. of Stories: 2

Structural System: Unknown

Changes to plan: Extensive

Changes to interior: Unknown

Style

Comments:

View of west elevation

Photography Neg. No (Roll No./Frame No.):

Changes to original cladding:

Extensive

Changes to other:

None

Form/Type Commercial

Changes to windows: Extensive

Other (specify):

Page 1 of 2

Printed on 6/2/2010 2:18:28 PM

at 4800 20th Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type
<u> Veneer - Vinyl Sic</u>	ding	Concrete - Poured	Asphalt / Composition	Flat with Eaves
				Flat with Parapet
	- — — — — —			
NARRATIVE S	SECTION		Date Of Construction: <u>1951, 1989</u>	
Study Unit		Other	Architect:	
Community Plann	ning/Development		Builder:	
			Engineer:	
	Property appea	ars to meet criteria for the National Reg	gister of Historic Places: No	
	Property is loca	ated in a potential historic district (Nat	ional and/or local): <u>No</u>	
	Property poten	tially contributes to a historic district (National and/or local):	
Statement of Significance	significant contribution lives of significant per construction, does not individual distinction national history, and eligibility criteria for the building appear.	on to the broad patterns of local, state, or ersons, and is recommended ineligible unot represent the work of a master or poss, and therefore is recommended ineligible is recommended ineligible under Criteric listing in the NRHP. s to retain poor integrity of design, materional Register of Historic Places, the Wasi	r national history; it is recommended ineligible un- nder Criterion B. The building does not embody the sess high artistic values, and does not represent the under Criterion C. The building is unlikely to yie on D. None of the Criteria Considerations is application.	ding does not appear to be associated with events that have made a lider Criterion A. The building is not known to be associated with the he distinctive characteristics of a type, period, or method of a significant and distinguishable entity whose components may lacked further information important in understanding local, regional, or cable, as the building does not appear to be eligible under any of the good integrity of setting and location. The building is recommended rks designation and the Seattle Landmarks Register due to an inability
Description of Physical Appearance				ilding is sited on a corner lot and was constructed in at least three hat the current vinyl windows and façade alterations were completed at
Major Bibliographic References				

Page 2 of 2 Printed on 6/2/2010 2:18:29 PM

at 5100 Shilshole Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-011

OAHP No.:

Historic Name:

<u>11</u>

Common Name: Marine Works Inc

Property Address: 5100 Shilshole Ave NW, Seattle, WA 98107

Comments:

County King

T25R03E

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle SHILSHOLE BAY **Coordinate Reference**

Sequence:

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Northing: <u>5279163</u>

Tax No./Parcel No.

Plat/Block/Lot

1 Easting: 546426

Supplemental Map(s)

2767702460

Gilman Park Blocks 050 thru 94, Plat block 70, Plat lot 32

Acreage .06

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

King County R/E Section

500 4th Ave #500

Seattle, WA 98104

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Vacant/Not in Use

Plan: Rectangle No. of Stories: 1

Structural System: Platform Frame

Changes to plan: Intact

Changes to interior: Unknown

Style

Form/Type

Changes to original cladding: Extensive

Changes to windows: Unknown

Changes to other:

Western False Front

Commercial

Page 1 of 2

Other (specify):

Photography Neg. No (Roll No./Frame No.): Comments:

View of south oblique, viewing north

at 5100 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
Wood - T 1-11	<u>Unknown</u>	Asphalt / Composition	Flat with Parapet
NARRATIVE S	SECTION	Date Of Construction: 1	918
Study Unit	Other	Architect:	
Community Plann	ing/Development	Builder:	
		Engineer:	
	Property appears to meet criteria for the National Registe	er of Historic Places: No	
	Property is located in a potential historic district (National	al and/or local): <u>No</u>	
	Property potentially contributes to a historic district (Nati	ional and/or local):	
Statement of Significance	accurate assessment of integrity of materials, design, workmans. The building does not appear to be associated with events that he ineligible under Criterion A. The building is not known to be associated with events that he ineligible under Criterion A. The building is not known to be associated with events that he ineligible under criterion A. The building is not known to be associated with events that he ineligible under any of the eligible under any of	thip, feeling and association is not ave made a significant contribution ciated with the lives of significant pd of construction, does not repress k individual distinction, and therefor national history, and is recommend gibility criteria for listing in the NR of Historic Places, the Washington	1 siding. Additionally, all windows are currently covered with plywood and so an possible. The building appears to retain good integrity of setting and location. In to the broad patterns of local, state, or national history; it is recommended persons, and is recommended ineligible under Criterion B. The building does not tent the work of a master or possess high artistic values, and does not represent a pore is recommended ineligible under Criterion C. The building is unlikely to yield ded ineligible under Criterion D. None of the Criteria Considerations is applicable, HP. Heritage Register, King County Landmarks designation and the Seattle
Description of Physical Appearance	This rectangular building has a flat roof with a false-front eave on centrally-located entry door is a single panel wood door.	the main (southwest) elevation. T	The building is clad in T1-11 siding and all windows have been boarded over. The
Major Bibliographic References			

Page 2 of 2 Printed on 6/2/2010 2:18:39 PM

at 4776 Shilshole Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: <u>1312.02-012</u>

OAHP No.:

Historic Name:

Common Name: DANTRAWL U.S. (NEBAR Hose & Fittings)

Property Address: 4776 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

King

T25R03E

<u>11</u>

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

1 Easting: 546456

Northing: <u>5279138</u>

Tax No./Parcel No.

Plat/Block/Lot

2767702445

Gilman Park Blks 050 thru 94, Plat block 70, Plat lot 11 & 28

Supplemental Map(s)

Acreage

BALL ARD HARD

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Hopkins Ballard Ice LLC

500 S Myrtle St

Seattle, WA 98108

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: Rectangle No. of Stories: 1

Structural System: Unknown

Changes to plan: Unknown Changes to original cladding: <u>Unknown</u> Changes to interior: Unknown

Style None

View of west oblique, viewing east

Photography Neg. No (Roll No./Frame No.):

Comments:

Form/Type Commercial

Changes to windows: Extensive

Other (specify):

Changes to other:

Page 1 of 2

Printed on 6/2/2010 2:18:53 PM

at 4776 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
Concrete - Poure	<u>Concrete - Poured</u>	Asphalt / Composition	<u>Hip</u>
NARRATIVE	SECTION	Date Of Construction: 1908	
Study Unit	Other	Architect:	
Community Plan	ning/Development	Builder:	
		Engineer:	
	Property appears to meet criteria for the National Reg	ister of Historic Places: No	
	Property is located in a potential historic district (Nati	ional and/or local): <u>No</u>	
	Property potentially contributes to a historic district (I	National and/or local):	
Statement of Significance	significant contribution to the broad patterns of local, state, or lives of significant persons, and is recommended ineligible un construction, does not represent the work of a master or poss individual distinction, and therefore is recommended ineligible national history, and is recommended ineligible under Criterio eligibility criteria for listing in the NRHP.	national history; it is recommended ineligible of the Criterion B. The building does not embody sess high artistic values, and does not represed under Criterion C. The building is unlikely to you D. None of the Criteria Considerations is apparent of Historic Places, the Washington Heritage	does not appear to be associated with events that have made a under Criterion A. The building is not known to be associated with the vithe distinctive characteristics of a type, period, or method of int a significant and distinguishable entity whose components may lack yield further information important in understanding local, regional, or plicable, as the building does not appear to be eligible under any of the exercise. King County Landmarks designation and the Seattle
Description of Physical Appearance	Located on the southeast corner of the intersection of NW Do has double-doors on the west corner and no windows.	ck Place and Shilshole Ave NW, the building i	s a single-story and has a hip roof. Clad in poured concrete , the building
Major Bibliographic References			

Printed on 6/2/2010 2:18:54 PM

Historic Property Inventory Report for

at 4749 Ballard Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-015

OAHP No.:

Historic Name:

<u>11</u>

Common Name: Ballard Hardware

Property Address: 4749 Ballard Ave NW, Seattle, WA 98107

Comments:

County King

T25R03E

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle SHILSHOLE BAY **Coordinate Reference**

Zone: 10 Spatial Type: Point Sequence:

Acquisition Code: Unknown

Tax No./Parcel No.

1 Easting: 546498

Northing: <u>5279086</u>

Plat/Block/Lot

Supplemental Map(s)

2767702360

Gilman Park Blks 050 thru 94, Plat block 70, Plat lot 13-14-25-26

Acreage

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller Owner's Name:

Owner Address:

Date Recorded: 5/18/2010

Freyberg James W+Anna

City/State/Zip:

PO Box 70585

Seattle, WA 98107

K Hartje L F

Classification: Building

Resource Status

Comments

Within a District? No

Survey/Inventory

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: Irregular No. of Stories: 4.5

Structural System: Unknown

Changes to plan: Intact

Changes to original cladding: Extensive

Changes to interior: Unknown

Style

Commercial

Changes to windows: Extensive

Other (specify):

Changes to other:

View of northeast elevation

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

Comments:

Form/Type Commercial

Page 1 of 2

Printed on 6/2/2010 2:19:04 PM

at 4749 Ballard Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type
<u>Veneer - Brick</u>		<u>Concrete - Poured</u>	Asphalt / Composition	<u>Flat with Parapet</u>
Concrete - Poured	<u>d</u>			
<u>Other</u>				
			Date Of Construction:	
NARRATIVE S	SECTION		Date of Construction.	1921, 1929
Study Unit		Other	Architect:	
			Builder:	
			Engineer:	
	Property a	appears to meet criteria for the National Register of	Historic Places: No	
	Property i	s located in a potential historic district (National an	d/or local): <u>No</u>	
	Property p	potentially contributes to a historic district (Nationa	l and/or local):	
Statement of Significance	Initially constructed in 1927 with the wateriouse addition added in 1928, the building has been significantly affered and retains boor integrity of design, materials, workman			be associated with events that have made a significant contribution to the broad ding is not known to be associated with the lives of significant persons, and is istics of a type, period, or method of construction, does not represent the work of a tity whose components may lack individual distinction, and therefore is ortant in understanding local, regional, or national history, and is recommended not appear to be eligible under any of the eligibility criteria for listing in the NRHP.
Description of Physical Appearance	the large warel windows. The	house to the southwest has a flat roof with an elevator I warehouse is clad in a combination of poured concrete an assortment of metal doors and roll-up doors. A warel	house. The storefront-side is , brick, and hollow clay tile. T	ry rectangular building on the southwest elevation. Both segments have flat roofs; clad in a combination of structural brick and plywood with a series of wood the building has metal sash windows on the second, third and fourth floors. The side of the building was constructed in 1928, but is currently being expanded and
Major Bibliographic References				

Page 2 of 2 Printed on 6/2/2010 2:19:05 PM



View of west oblique, viewing east

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): <u>7126</u>

Comments:



View of detail of windows and cladding

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7130

Comments:



View of south oblique, viewing north

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7129

Comments:



View of Warehouse (under construction)

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): <u>7132</u>

Comments:

at 4711 Ballard Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-019

OAHP No.:

Historic Name:

Canvas Supply Company Common Name:

Property Address: 4711 Ballard Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

King

T25R03E

<u>11</u>

SHILSHOLE BAY

Zone: 10 Spatial Type: Point Sequence:

Acquisition Code: Unknown

Northing: <u>5279018</u>

Tax No./Parcel No.

Plat/Block/Lot

1 Easting: 546594

2797702400

Supplemental Map(s)

Gilman Park Blocks 050 thru 94, Plat block 70, Plat lot 20-21

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

McLauchlan Brian

4711 Ballard Ave NW

Seattle, WA 98107

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: Rectangle No. of Stories: 1.5

Structural System: Unknown

Changes to plan: Intact Changes to original cladding: **Extensive** Changes to interior: Unknown

Style None Comments:

Acreage

CO. CANVAS

View of northeast elevation

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

Form/Type Commercial

Changes to windows: Extensive

Other (specify):

Changes to other:

at 4711 Ballard Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type
Metal - Corrugate	<u>ed</u>	Concrete - Poured	Asphalt / Composition	<u>Gable</u>
				Shed
	_ — — — — — — -			
NARRATIVE	SECTION		Date Of Construction: 190	<u>00</u>
Study Unit		Other	Architect:	
Community Plan	ning/Development		Builder:	
			Engineer:	
	Property appears to	o meet criteria for the National Re	gister of Historic Places: No	
	Property is located	in a potential historic district (Na	tional and/or local): No	
	Property potentially	contributes to a historic district	(National and/or local):	
Statement of Significance				ot appear to be associated with events that have made a significant contribution a. The building is not known to be associated with the lives of significant cive characteristics of a type, period, or method of construction, does not and distinguishable entity whose components may lack individual distinction, and attion important in understanding local, regional, or national history, and is building does not appear to be eligible under any of the eligibility criteria for
Description of Physical Appearance	vertical wood boards. Th		tal sash windows and a metal entryway	outh. The building is clad in a combination of brick, corrugated metal siding and door, as does the opposite (southwest) elevation. A detached warehouse
Major Bibliographic References				

Printed on 6/2/2010 2:19:30 PM



View of west oblique, viewing east taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7138

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:

LOCATION SECTION

Field Site No.: 1312.02-020

OAHP No.:

Historic Name:

Common Name: Art Books Press

Property Address:

Comments:

County

Tax No./Parcel No.

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

King

T25R03E

<u>11</u>

SHILSHOLE BAY

Plat/Block/Lot

Survey Name: 1312.02 Burke-Gilman Trail Extension

IDENTIFICATION SECTION Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

Art Books Building LLC 4703 Ballard Ave NW City/State/Zip: Seattle, WA 98107

Classification: Building

Resource Status

Comments

Within a District? No

Survey/Inventory

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: T-Shape No. of Stories: 1.5

Structural System: Unknown

Changes to plan: Unknown

Changes to interior: Unknown

Style

Changes to original cladding: Extensive Changes to other: None

Supplemental Map(s)

Acreage

View of south oblique, viewing north

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.):

7140

Comments:

Form/Type None

Changes to windows: Extensive

Other (specify):

Cladding	Foundation	Roof Material	Roof Type
Veneer - Brick	<u>Concrete - Poured</u>	Metal - Standing Seam	<u>Gable - Side Gable</u>
Wood - T 1-11			
<u>Wood</u>			
NARRATIVE S	SECTION	Date Of Construction: 1948	
Ct. d. Huit	Other	Architect:	
Study Unit Community Plann	Other ing/Development	7	
Community Fidin	ming Bovelopment	Builder:	
		Engineer:	
	Property appears to meet criteria for the National Regi	eter of Historic Places: No	
		-	
	Property is located in a potential historic district (Nation	onal and/or local): <u>No</u>	
	Property potentially contributes to a historic district (N	lational and/or local):	
Statement of Significance	setting and location. The building does not appear to be assoc recommended ineligible under Criterion A. The building is not building does not embody the distinctive characteristics of a tyldoes not represent a significant and distinguishable entity who	iated with events that have made a significant known to be associated with the lives of significate, per, period, or method of construction, does not se components may lack individual distinction, erstanding local, regional, or national history, a o be eligible under any of the eligibility criteria er of Historic Places, the Washington Heritage	•
Description of Physical Appearance		ll board siding, and T1-11. The building has a s	half story section on the north end and a one-story section to the south. side-gable roof clad in standing-seam metal roofing with a central ng has vinyl windows and doors throughout.
Major Bibliographic References			

LOCATION SECTION

Field Site No.: 1312.02-021

OAHP No.:

Historic Name:

Common Name: Sagstad Marina, the Salmon Bay Cafe

Property Address: 5109 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

King

T25R03E <u>11</u> SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence: 1 Easting: 546352 Northing: <u>5279180</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

0467000475

Ballard Tide Lands Blks 01-20. Plat block 7, Plat lot 9-10-11

Acreage 1.18

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Explorere Properties LLC

1959 NW Dock PI #3000

Seattle, WA 98107

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: L-Shape No. of Stories: 2

Structural System: Unknown

Changes to plan: Extensive

Changes to interior: Unknown

Style

Changes to original cladding:

Extensive

Changes to other:

None

Form/Type

View of southeast elevation, viewing northwest

Photography Neg. No (Roll No./Frame No.):

Comments:

None

Changes to windows: Extensive

Other (specify):

Page 1 of 2

at 5109 Shilshole Ave NW, Seattle, WA 98107

Cladding		Foundation	Roof Material	Roof Type
Veneer - Vinyl Sic	ding	Concrete - Poured	Asphalt / Composition	<u>Gable</u>
Wood - Plywood				<u>Flat with Eaves</u>
NARRATIVE	SECTION		Date Of Construction:	1942, 1959, 1960
Study Unit		Other	Architect:	
Community Plann	ning/Development		Builder:	
			Engineer:	
	Property appears to	o meet criteria for the National Reg	gister of Historic Places: No	
	Property is located	in a potential historic district (Nat	tional and/or local): No	
	Property potentially	contributes to a historic district ((National and/or local):	
Statement of Significance	industrial building was not has been somewhat alte None of the buildings ap ineligible under Criterion not embody the distinctive significant and distinguis yield further information in the building is recomme	ot clearly visible form the right-of-way red. The restaurant, built in 1960, ap pear to be associated with events the A. The buildings are not known to be re characteristics of a type, period, o hable entity whose components may important in understanding local, reg	y, but based on the construction date opears to retain good integrity of material thave made a significant contribution associated with the lives of significal or method of construction, do not reprovate individual distinction, and there gional, or national history, and are received.	kmanship, feeling, and association and good integrity of setting and location. The e of 1959 and the current cladding of vinyl siding, it is assumed that the building serials, design, workmanship, feeling, association, setting and location. Solve the broad patterns of local, state, or national history; they are recommended cant persons, and are recommended ineligible under Criterion B. The buildings do resent the work of a master or possess high artistic values, and do not represent a sefore are recommended ineligible under Criterion C. The buildings are unlikely to commended ineligible under Criterion D.
Description of Physical Appearance	building, rectangular in p way was constructed in	lan with vinyl siding and windows, wat 1959; the building is two-story, rectar	as constructed in 1942. An attached ngular in plan, has a gable roof, and	gstad Marina and Salmon Bay Café. The warehouse, a two-story side gable I industrial building west of the warehouse and not clearly visible from the right-of-appears to be clad in vinyl siding. South of and adjacent to the warehouse is the sash picture windows. The restaurant was constructed in 1960.
Major Bibliographic References				

Page 2 of 2 Printed on 6/2/2010 2:20:05 PM

at 5209 Shilshole Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: <u>1312.02-022</u>

OAHP No.:

Historic Name:

Common Name: Canal Cove Marina

Property Address: 5209 Shilshole Ave NW, Seattle, WA 98107

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle

Coordinate Reference

Sequence:

King

T25R03E

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

<u>11</u>

1 Easting: 546292

Northing: <u>5279171</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

0467000476

Acreage

ballard Tide Lands, Blks 01-20, Plat Block 7, Plat lot 7-8

<u>.82</u>

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Canal Cove Marina LLC

22430 SE 231st Street

Maple Valley, WA 98038

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Commerce/Trade - Business

Current Use: Commerce/Trade - Business

Plan: Rectangle No. of Stories: 1

Structural System: Unknown

Changes to plan: Intact Changes to original cladding: **Extensive** Changes to interior: Unknown

Style

Photography Neg. No (Roll No./Frame No.):

View of east elevation, viewing west

Comments:

Changes to other:

None

Form/Type None

7182

Changes to windows: Intact

Other (specify):

Page 1 of 2

Printed on 6/2/2010 2:20:17 PM

at 5209 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
Metal - Corrugate	d <u>Concrete - Poure</u>	<u>Metal - Corrugated</u>	Gable - Side Gable
NARRATIVE S	Other	Date Of Constructio	on: <u>1938</u>
Community Plann	ing/Development	Builder:	
		Engineer:	
	Property appears to meet criteria for the N	ational Register of Historic Places: No	
	Property is located in a potential historic of	listrict (National and/or local): No	
	Property potentially contributes to a histor	ic district (National and/or local):	
Statement of Significance The office was built in 1938, but has been expanded with the addition of the shed to the southwest. The shed addition was likely added in 1990 when to constructed. None of the buildings appear to be associated with events that have made a significant contribution to the broad patterns of local, state, or recommended ineligible under Criterion A. The buildings are not known to be associated with the lives of significant persons, and are recommended in buildings do not embody the distinctive characteristics of a type, period, or method of construction, do not represent the work of a master or possess he represent a significant and distinguishable entity whose components may lack individual distinction, and therefore are recommended ineligible under Criterion D. No Considerations are applicable, as the buildings do not appear to be eligible under any of the eligibility criteria for listing in the NRHP. The buildings are recommended ineligible to the National Register of Historic Places, the Washington Heritage Register, King County Landmarks desit Landmarks Register due to an inability to meet any of the eligibility criteria.			gnificant contribution to the broad patterns of local, state, or national history; they are in the lives of significant persons, and are recommended ineligible under Criterion B. The auction, do not represent the work of a master or possess high artistic values, and do not tinction, and therefore are recommended ineligible under Criterion C. The buildings are tory, and are recommended ineligible under Criterion D. None of the Criteria eligibility criteria for listing in the NRHP.
Description of Physical Appearance	Windows appear to be original, multi-light metal s	ash, though this was difficult to determine for	nd roofed in corrugated metal siding, and has a roll-up door on the east elevation. from the right-of-way due to the building's location set far back from the street. The ding. West of the office is a series of boat sheds, all with gable roofs and clad in
Major Bibliographic References			

Printed on 6/2/2010 2:20:18 PM

at 5219 Shilshole Ave NW, Seattle, WA 98107

LOCATION SECTION

Field Site No.: 1312.02-023

OAHP No.:

Historic Name:

Williams and Covich, Fuel Dock Common Name:

Property Address: 5219 Shilshole Ave NW, Seattle, WA 98107

Comments:

Supplemental Map(s)

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec <u>11</u>

Quadrangle

Coordinate Reference

King

T25R03E

SHILSHOLE BAY

Zone: 10 Spatial Type: Point

Acquisition Code: Unknown

Sequence:

1 Easting: 546282

View of Williams and Covich Fuel Dock, viewing west

Photography Neg. No (Roll No./Frame No.):

Comments:

Northing: <u>5279188</u>

Tax No./Parcel No.

Plat/Block/Lot

0467000445

Ballard Tide Lands, Blks 01-20, Plat block 7, Plat lot 5-6

Acreage .85

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Williams Mason J+Linda E

PO Box 17913

Seattle, WA 98107

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Unknown

Current Use: Commerce/Trade - Business

Plan: Rectangle No. of Stories: 1

Structural System: Unknown

Changes to plan: Unknown

Changes to interior: Unknown

Style

Form/Type

Changes to original cladding: Changes to windows: Unknown

Unknown

Changes to other:

Unknown

Unknown

Page 1 of 2

Other (specify):

Printed on 6/2/2010 2:20:30 PM

Historic Property Inventory Report for

at 5219 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type	
<u>Unknown</u>	<u>Unknown</u>	Asphalt / Composition	<u>Gable</u>	
NARRATIVE S	SECTION Other	Date Of Construction: 1930, 19		
Community Plann		Builder:		
	_ -	Builder.		
		Engineer:		
	Property appears to meet criteria for the National Regist	ter of Historic Places: No		
	Property is located in a potential historic district (Nation	nal and/or local): No		
	Property potentially contributes to a historic district (Na	tional and/or local):		
Statement of Significance	The warehouse, built in 1930, and the office, built in 1983, were not visible from the right of way and therefore an evaluation of integrity and significance was not possible. Based on similar sites in the vicinity, it is unlikely that the warehouse retains sufficient integrity to qualify it for the NRHP, nor is it likely eligible under any of the eligibility criteria. Based on its age, the office may be eligible only for the Seattle Landmarks Register (SLR); however, it is doubtful that a single-story building constructed as an office for a fuel dock is significant and would therefore be evaluated as eligible to the SLR. The buildings are recommended ineligible to the National Register of Historic Places, the Washington Heritage Register, King County Landmarks designation and the Seattle Landmarks Register due to an inability to meet any of the eligibility criteria.			
Description of Physical Appearance	The Williams and Covich Fuel Dock is a collection of fuel tanks, storage sheds, and shipping containers located on a paved lot. According to tax records a warehouse was constructed on the tax parcel in 1930 and an office building was constructed in 1983; neither of these buildings were visible from the right of way. Based on aerial photography, both the warehouse and office are rectangular in plan.			
Major Bibliographic References				

Page 2 of 2 Printed on 6/2/2010 2:20:31 PM

LOCATION SECTION

Field Site No.: 1312.02-024

OAHP No.:

Historic Name:

Common Name: Salmon Bay Sand & Gravel

Zone: 10 Spatial Type: Point

Property Address: 5231 Shilshole Ave NW, Seattle, WA 98107

<u>11</u>

Comments:

County

Township/Range/EW Section 1/4 Sec 1/4 1/4 Sec

Quadrangle **Coordinate Reference**

Acquisition Code: Unknown

King

T25R03E

SHILSHOLE BAY

Sequence: 1 Easting: 546279

View of southeast elevation, viewing northwest

Photography Neg. No (Roll No./Frame No.):

Northing: <u>5279266</u>

Tax No./Parcel No.

Plat/Block/Lot

Supplemental Map(s)

Acreage 1.55

0467000427

Ballard Tide Lands Blks 01-20, Plat Block 7, portion

IDENTIFICATION SECTION

Survey Name: 1312.02 Burke-Gilman Trail Extension

Field Recorder: Heather Miller

Date Recorded: 5/18/2010

Owner's Name:

Owner Address:

City/State/Zip:

Salmon Bay Sand & Gravel

PO Box 70328

Seattle, WA 98127

Classification: Building

Resource Status Survey/Inventory

Comments

Within a District? No

Contributing?

National Register Nomination:

Local District:

National Register District/Thematic Nomination Name:

DESCRIPTION SECTION

Historic Use: Industry/Processing/Extraction - Industrial Storage

Current Use: Industry/Processing/Extraction - Industrial Storage

Plan: Irregular No. of Stories: 1.5

Structural System: Unknown

Changes to plan: Extensive

Changes to interior: Unknown

Style

Comments:

Changes to original cladding: **Extensive**

Changes to other:

None

Form/Type

None

Changes to windows: Intact

Other (specify):

Page 1 of 2

Printed on 6/2/2010 2:20:43 PM

at 5231 Shilshole Ave NW, Seattle, WA 98107

Cladding	Foundation	Roof Material	Roof Type
<u>Metal</u>	Concrete - Poured	Asphalt / Composition	Gable - Side Gable
NARRATIVE :	SECTION Other	Date Of Construction: 1916,	<u>1960</u>
Study Unit Community Plant		D. W.L.	
Serimanny Field		Builder: Engineer:	
	Property appears to meet criteria for the National Regist		
	Property is located in a potential historic district (Nation	nal and/or local): <u>No</u>	
	Property potentially contributes to a historic district (Na	tional and/or local):	
Statement of Significance The original warehouse was expanded in 1960, altering the massing and materials, leading to poor integrity of materials, design, workmanship, feeling building does not appear to be associated with events that have made a significant contribution to the broad patterns of local, state, or national history under Criterion A. The building is not known to be associated with the lives of significant persons, and is recommended ineligible under Criterion B. The distinctive characteristics of a type, period, or method of construction, does not represent the work of a master or possess high artistic values, and significant and distinguishable entity whose components may lack individual distinction, and therefore is recommended ineligible under Criterion C. The further information important in understanding local, regional, or national history, and is recommended ineligible under Criterion D. None of the Criteria as the building does not appear to be eligible under any of the eligibility criteria for listing in the NRHP. The building is recommended ineligible to the National Register of Historic Places, the Washington Heritage Register, King County Landmarks design Landmarks Register due to an inability to meet any of the eligibility criteria.			oad patterns of local, state, or national history; it is recommended ineligible recommended ineligible under Criterion B. The building does not embody a master or possess high artistic values, and does not represent a recommended ineligible under Criterion C. The building is unlikely to yield religible under Criterion D. None of the Criteria Considerations is applicable,
Description of Physical Appearance		the south is a large addition, built in 1960	al 1916 warehouse. The building is clad in standing seam metal and has an 0, with an irregular plan which houses gravel and sand crushing and loading
Major Bibliographic References			

Printed on 6/2/2010 2:20:44 PM



View of northeast oblique, viewing southwest

taken <u>5/18/2010</u>

Photography Neg. No (Roll No./Frame No.): 7191

Comments:



View of partial northeast elevation

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7190

Comments:



View of southwest elevation

taken 5/18/2010

Photography Neg. No (Roll No./Frame No.): 7189

in raine No.j.

Comments:

View of taken

Photography Neg. No (Roll No./Frame No.):

Comments:



Appendix B APE Concurrence



AUG 03 2010

Olympia, WA

STATE OF WASHINGTON

DEPARTMENT OF ARCHAEOLOGY & HISTORIC PRESERVATION

1063 S. Capitol Way, Suite 106 • Olympia, Washington 98501 Mailing address: PO Box 48343 • Olympia, Washington 98504-8343 (360) 586-3065 • Fax Number (360) 586-3067 • Website: www.dahp.wa.gov

August 2, 2010

Mr. Trent de Boer Archaeologist WSDOT, Highways & Local Programs PO Box 47390 Olympia, WA 98504-7390

In future correspondence please refer to:

Log: 070308-02-FHWA

Property: Burke Gilman Trail Extension Re: Archaeology - APE Concur

Dear Mr. de Boer:

We have reviewed the materials forwarded to our office for the Burke Gilman Trail Extension project. Thank you for your description of the revised area of potential effect (APE) for segment 4 of the project. We concur with the definition of the APE. We look forward to the results of your cultural resources survey efforts, your consultation with the concerned tribes, and receiving the survey report. We would appreciate receiving any correspondence or comments from concerned tribes or other parties that you receive as you consult under the requirements of 36CFR800.4(a)(4) and the survey report when it is available.

These comments are based on the information available at the time of this review and on behalf of the State Historic Preservation Officer in conformance with Section 106 of the National Historic Preservation Act and its implementing regulations 36CFR800. Should additional information become available, our assessment may be revised.

Thank you for the opportunity to review and comment. If you have any questions, please feel free to contact me.

Sincerely,

Lance Wollwage, Ph.D.

Transportation Archaeologist

Lava hollin

(360) 586-3536

lance.wollwage@dahp.wa.gov

